

DEVELOPMENT OF A MODIFIED AIDS TO NAVIGATION
MANAGEMENT INFORMATION SYSTEM FOR THE
UNITED STATES COAST GUARD WITH AN
ILLUSTRATED APPLICATION THROUGH COST-
EFFECTIVENESS AND MALFUNCTION ANALYSES

Robert Marshall Stephan

Library
Naval Postgraduate School
Monterey, California 93940

NAVAL POSTGRADUATE SCHOOL

Monterey, California



THESIS

DEVELOPMENT OF A MODIFIED AIDS TO NAVIGATION
MANAGEMENT INFORMATION SYSTEM FOR THE
UNITED STATES COAST GUARD WITH AN
ILLUSTRATED APPLICATION THROUGH COST-
EFFECTIVENESS AND MALFUNCTION ANALYSES

by

Robert Marshall Stephan, Jr.

March 1975

Thesis Advisor:

William C. Giauque

Approved for public release; distribution unlimited.

T167947

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Development of a Modified Aids to Navigation Management Information System for the U.S. Coast Guard with an Illustrated Application Through Cost-Effectiveness and Malfunction Analyses		5. TYPE OF REPORT & PERIOD COVERED Master's Thesis March, 1975
7. AUTHOR(s) Robert Marshall Stephan, Jr.		6. PERFORMING ORG. REPORT NUMBER
9. PERFORMING ORGANIZATION NAME AND ADDRESS Naval Postgraduate School Monterey, CA 93940		8. CONTRACT OR GRANT NUMBER(s)
11. CONTROLLING OFFICE NAME AND ADDRESS Naval Postgraduate School Monterey, CA 93940		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
14. MONITORING AGENCY NAME & ADDRESS (If different from Controlling Office) Naval Postgraduate School Monterey, CA 93940		12. REPORT DATE March, 1975
		13. NUMBER OF PAGES 295
		15. SECURITY CLASS. (of this report) Unclassified
16. DISTRIBUTION STATEMENT (of this Report) Approved for public release; distribution unlimited.		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) Aids to Navigation - NAVAIDS SRAN Management Information System - MIS SANDS Cost-effectiveness Analysis		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) The purpose of this project is to identify, examine, and evaluate certain cost-effectiveness relationships of the Short Range Aids to Navigation (SRAN) Sub-System developed, established, operated, and maintained by the United States Coast Guard. While attempting to achieve this objective, it was determined that a need exists to modify the present Aids to Navigation Management Information System. The Simplified Aids to Navigation Data System SANDS is the present information system. The Aids to Navigation Work Report		

20. Abstract (continued)

(CG-4429), which is the basic source of raw data, is prepared by Coast Guard units at the scene during the time a navigational aid (navaid) is serviced. In addition to providing information, this report becomes a legal and historical record of the navaid. The present content and format of the work report has remained essentially unchanged since its inception in 1967. Questions have been raised as to whether the content and format of this report should be amended, and if so, how? The Annual Aids to Navigation Assignment List (CG-4500) is the main source of information prepared for operating units engaged in servicing nav aids. It is also questioned whether the information contained in this list is responsive to the needs of servicing personnel, and whether potential information available to the Management Information System is being fully developed. A modified Management Information System is presented and its application illustrated through selected cost-effectiveness analyses.

Development of a Modified
Aids to Navigation Management Information
System for the United States Coast Guard
With An Illustrated Application
Through Cost-Effectiveness and Malfunction Analyses

by

Robert Marshall Stephan, Jr.
Lieutenant Commander, United States Coast Guard
B.S., U.S. Coast Guard Academy, 1965

Submitted in partial fulfillment of the
requirements for the degree of

MASTER OF SCIENCE IN MANAGEMENT

from the

NAVAL POSTGRADUATE SCHOOL
March 1975

ABSTRACT

The purpose of this project is to identify, examine, and evaluate certain cost-effectiveness relationships of the Short Range Aids to Navigation (SRAN) Sub-system developed, established, operated, and maintained by the United States Coast Guard. While attempting to achieve this objective, it was determined that a need exists to modify the present Aids to Navigation Management Information System. The Simplified Aids to Navigation Data System (SANDS) is the present information system. The Aids to Navigation Work Report (CG-4429), which is the basic source of raw data, is prepared by Coast Guard units at the scene during the time a navigational aid (navaid) is serviced. In addition to providing information, this report becomes a legal and historical record of the navaid. The present content and format of the work report has remained essentially unchanged since its inception in 1967. Questions have been raised as to whether the content and format of this report should be amended, and if so, how? The Annual Aids to Navigation Assignment List (CG-4500) is the main source of information prepared for operating units engaged in servicing navaid. It is also questioned whether the information contained in this list is responsive to the needs of servicing personnel, and whether potential information available to the Management Information System is being fully developed. A modified Management Information System is presented and its application illustrated through selected cost-effectiveness analyses.

TABLE OF CONTENTS

I.	INTRODUCTION - SELECTION OF AREAS OF STUDY-----	12
II.	DEVELOPMENT OF SHORT RANGE AIDS TO NAVIGATION----	24
A.	AN HISTORICAL REVIEW-----	24
B.	DESCRIPTION OF A LIGHTED BUOY BY COMPONENT---	25
C.	HIGHLIGHTS OF MAJOR INNOVATIONS AND DEVELOPMENTS BY THE COAST GUARD-----	26
1.	Standard Buoys-----	26
2.	Mechanical Chain Stopper for Buoy Tenders	38
3.	Electric Power with Primary Batteries----	38
4.	Standard Solid State Flashers-----	40
5.	Use of Radar Reflectors-----	40
6.	Replacement of Lightships-----	40
7.	Servicing Remotely Located, Difficult to Service Aids-----	41
8.	Acrylic Lantern Optical Assemblies-----	41
9.	Procurement of Short Range Aids to Navigation Components-----	42
D.	AREAS WITH POTENTIAL FOR FURTHER DEVELOPMENT-	43
1.	Booz, Allen Applied Research Inc., Studies	43
a.	Administration-----	45
b.	Aids to Navigation Teams (ANTS)-----	46
c.	Miscellaneous-----	47
2.	Sound Signals-----	47
3.	Multi-seasonal use of Primary Batteries in the Ninth Coast Guard District-----	49
4.	Examination of a Major Aids to Navigation Problem Area Involving Question of Coast Guard Liability Based on Buoy Positioning	50

E.	A PROJECTION-----	59
III.	DEVELOPMENT OF MODIFICATIONS TO THE AIDS TO NAVIGATION MANAGEMENT INFORMATION SYSTEM-----	61
A.	INFORMATION NEEDS IN THE AIDS TO NAVIGATION AREA-----	61
B.	THE PRESENT SYSTEM-----	65
C.	AREAS FOR FURTHER DEVELOPMENT-----	72
1.	An Experimental Aids to Navigation Work Report-----	73
2.	Examination of the Present Aids to Navigation Work Report-----	75
3.	Important Information Not Being Provided For With the Present Work Report-----	78
D.	SUGGESTED IMPROVEMENTS-----	79
1.	Aids to Navigation Work Report Modifications-----	79
a.	Power Units (Batteries)-----	79
b.	Lampchangers-----	82
c.	Reason for Replacing Components-----	82
d.	Continuity of Reports-----	83
e.	Exchange of Reports by Servicing Units-----	83
f.	Equipment Lost or Damaged During Servicing-----	84
g.	Report Format-----	84
2.	Selection of an Additional Processing Method-----	85
E.	DATA ORGANIZATION-----	87
F.	APPLICATION OF A MODIFIED MANAGEMENT INFORMATION SYSTEM-----	88
IV.	EXAMINATION OF AIDS TO NAVIGATION RELIABILITY, HAZARD, AND FAILURE RELATIONSHIPS-----	95

A.	PURPOSE-----	95
B.	AREAS OF EXAMINATION-----	95
C.	SUMMARIZATION OF RESULTS-----	102
D.	AREAS FOR FURTHER RESEARCH-----	115
1.	Reliability Model Building-----	115
2.	Sensitivity Analysis of Flasher Inventory Policies-----	115
V.	CONCLUSIONS AND RECOMMENDATIONS-----	121
A.	MODIFICATION OF THE AIDS TO NAVIGATION MANAGEMENT INFORMATION SYSTEM-----	121
B.	STATISTICAL PACKAGE FOR THE SOCIAL SCIENCES (SPSS)-----	126
C.	FUTURE RESEARCH-----	126
APPENDIX A:	NUMBER OF VARIOUS SHORT RANGE AIDS IN SERVICE ON 31 DECEMBER 1973-----	128
APPENDIX B:	SUMMARY OF ERRORS IN 79 AIDS TO NAVIGATION WORK REPORTS FOR 25 LIGHTED BUOYS LOCATED IN THE THIRTEENTH COAST GUARD DISTRICT----	129
APPENDIX C:	CALCULATION OF RATED BATTERY DISCHARGE TIME FOR A POWER UNIT, LAMP, AND FLASHER COMBINATION WITH 2000 A-H CAPACITY, .55 AMP LAMPS, AND A QKFL (0.3) CHARACTERISTIC-----	132
APPENDIX D:	AN ILLUSTRATION OF SANDS MONITORING AND SEARCHING-----	135
APPENDIX E:	PROCEDURES UTILIZED IN COMPUTING FOR POWER UNITS, THE PERCENTAGE OF EXPECTED TOTAL USEFUL OPERATING LIFE CONSUMED AT THE TIME OF REPLACEMENT OR RETIREMENT-----	139
APPENDIX F:	RESULTS FROM EXAMINATION OF 20 SOLID STATE FLASHERS FOR 18 LIGHTED AIDS TO NAVIGATION IN THE NINTH COAST GUARD DISTRICT (1967 - 1973)-----	140

COMPUTER OUTPUT-----	141
COMPUTER PROGRAM-----	263
BIBLIOGRAPHY-----	291
INITIAL DISTRIBUTION LIST-----	294

LIST OF TABLES

TABLE I	List of Navigational Aids Within Each Aids to Navigation Subsystem-----	16
TABLE II	Lighted Buoy Support System-----	30
TABLE III	Lighted Buoy Visual Signal Sub-System-----	33
TABLE IV	Summary of Major Types of Errors Detected in 79 Work Reports for the 13th CG District 1972 - 1973-----	76
TABLE V	Summary of Key Data Base Statistics for 100 Lighted Buoys and Their Components Located in the Thirteenth Coast Guard District as of December 31, 1973-----	103
TABLE VI	Summary of the Primary Causes for Aid and Aid Component Malfunctions and Other Significant Reasons for Replacement-----	108
TABLE VII	Statistics Concerning Buoys Reported as Adrift, Washed Ashore, or Missing-----	111
TABLE VIII	Summary of Solid State Flasher Performance for 18 Lighted Aids to Navigation in the Ninth Coast Guard District (1967-1973)----	119

LIST OF FIGURES

FIGURE 1	A typical Lighted Buoy Showing Principal Parts and Appendages With Non-Scale Blowup Drawings of Components-----	27
FIGURE 2	Power Assembly Clamp, Battery Pack, Primary Battery-----	28
FIGURE 3	12 volt lamp, fresnel lens section, 155 mm lantern, lampchanger, CG-181 solid state flasher-----	29
FIGURE 4	Routine visits to each unlighted buoy per year; Routine visits to each unmanned light per year; Routine visit to each lighted buoy per year	48
FIGURE 5	Buoy Positioning-----	52
FIGURE 6	Aids to Navigation Work Report-----	66
FIGURE 7	Aids to Navigation Management Information System for United States Coast Guard-----	71
FIGURE 8	U.S. Coast Guard Photograph with caption from Piloting, Seamanship, and Small Boat Handling, Chapman, p. 287.-----	99
FIGURE 9	Reliability Block Diagram for a Typical Lighted Buoy-----	116

ACKNOWLEDGEMENT

For most Coastguardsmen engaged in Aids to Navigation operations, there is barely enough time to get the job done to satisfaction, even if time is used wisely. Seldom is there sufficient time left over to pursue, in depth, various areas of interest associated with the work. The opportunity to look intensively at some existing and potential Aids to Navigation problems is thus most challenging and welcome.

Many have contributed a great deal to this phase of the research project. The author would particularly like to extend his appreciation to LCDR Darwyn Buettner CCGD13(oan), LCDR John Overath CCGD9(oan), LCDR Guy Clark (GWAN-1), Mr. Frank Thompson (GEOE-3), LT James Ingham (GLCL), ENS Mark Werneke (GWAN-2) and to the thesis advisors of the Naval Postgraduate School. The author would also like to mention that without the stimulation and guidance of CDR Daniel Mania and LCDR Stanley Powers in the field, and the many hours of data keypunching assistance from his wife Pat, this project would not have been possible.

I. INTRODUCTION - SELECTION OF AREAS OF STUDY

Ever since colonial times, when buoyage of navigable waterways in this country was begun, constantly expanding and more effective marine aids to navigation have played an important role in successful navigation. The United States Coast Guard is the federal agency which "shall develop, establish, maintain, and operate, with due regard to the requirements of national defense, aids to maritime navigation, icebreaking facilities, and rescue facilities for the promotion of safety on, under, and over the high seas and waters subject to the jurisdiction of the United States."¹ Today the Coast Guard maintains over 46,000 aids to navigation in the Aids to Navigation System. Specific statutory authority for Aids to Navigation is contained in 14U.S.C.81:

"In order to aid navigation and to prevent disasters, collisions, and wrecks of vessels and aircraft, the Coast Guard may establish, maintain and operate:

- (1) aids to maritime navigation required to serve the needs of the armed forces or of the commerce of the United States:
- (2) aids to air navigation...

¹TITLE 14 - Coast Guard, United States Code, Section 2 (14U.S.C.2), U.S. Code Volume Three, January 20, 1971, with SUPPLEMENT III, January 21, 1971, to January 20, 1974, p. 2888. Section 2 defines the Primary Duties of the Coast Guard which have been organized into ten separate missions or functions. Three of the missions, including Aid to Navigation, are described in the above passage.

(3) electronic aids to navigation systems..."²

The Commandant, who heads the Coast Guard from Headquarters at Washington, D.C., has been charged with the development, establishment, operation, and maintenance of the Federal Aids to Navigation System by delegation from the Secretary of the Department of Transportation. Under the Commandant's direction these aids to navigation functions, as well as other functions, are carried on by twelve geographically separated district organizations, each under the supervision of a District Commander. A District Commander is assisted by staff, support units, and field units in the operation and maintenance of aid to navigation within his district. In addition to these aids to navigation maintained under the Federal Aids to Navigation System, there are also about 31,000 state and privately maintained aids to navigation in the United States established under the authority of the Coast Guard.

Regulations for the general public, intended to promote safe and economic movement on the waterways and seas, are promulgated by the Commandant in the Code of Federal Regulations. The Aids to Navigation Regulations, which pertain to federal, state, and privately maintained aids to

²U.S. Code, Volume Three, p. 2894.

navigation, are contained in ten parts of Subchapter C of Chapter 1, of TITLE 33 - Navigation and navigable waters, of the Code.³

An Aid to Navigation "is any signal device external to a vessel or aircraft specifically intended to assist a navigator to determine his position or safe course, or to warn him of dangers or obstructions to navigation."⁴ An aid to navigation system "is a group of reference devices acting together to provide information to assist an operator in directing the motion and defining the position of his craft."⁵ A device can be a floating buoy that is moored at the bottom or a structure which is fixed to the bottom. Active signals that may be transmitted to the navigator are visual (light), audio (sound), a radiobeacon pulse, or a LORAN Pulse.

³The Code of Federal Regulations is a codification of general and permanent rules published in the Federal Register by Executive Departments and Federal Agencies. The Code is compiled under 50 broad area titles each of which is divided into chapters, usually concerning a particular agency. Each volume of the Code is revised at least once a year and is kept up-to-date by individual issues of the Federal Register which is published daily. Subpart 1.46 of Title 49-Transportation describes the delegation of authority by the Secretary of Transportation to the Commandant of the Coast Guard. Section 1.01-1 of Title 33 contains the general provisions whereby delegation of authority by the Commandant is vested in the District Commanders.

⁴TITLE 33 - Navigation and Navigable Waters, Code of Federal Regulations, Chapter 1 - Coast Guard, Department of Transportation, Subpart 60.01-5 (33CFR 60.01-5), revised July 1, 1974, p. 234.

⁵Coast Guard Aids to Navigation Manual, Book 1, Administration (CG-222-1), 17 May 1972, amended through Change 3 of 1 August 1974, p. 3-1.

There are four basic Aid to Navigation Sub-systems within the overall Federal Aids to Navigation System. Table I shows a breakdown of the various types of navigational aids (navaids) within each sub-system. Appendix A shows total numbers of various Short Range Navaids.

There are four basic programs within the total Aids to Navigation System, relating directly to the four sub-systems. Each program includes, in addition to its own sub-system of navaids, all ships, boats, personnel, facilities, equipment, and devices that collectively operate and maintain a particular sub-system.⁶

Important to the overall usefulness of the Aids to Navigation System are different forms of related marine information which are prepared and issued by several federal agencies including the Coast Guard. Charts, which are prepared in various scales for navigable bodies of water, contain a wide variety of general information, including information and positions of navaids in the area, enabling a navigator to plot and keep accurate track of his position. Coast Pilots, which is printed in ten volumes, provides detailed information for the navigation of coastal waters to

⁶This structure is established as part of the Federal Planning-Programming-Budgeting System (PPBS), introduced in the mid 1960's which requires federal agencies to structure their activities into programs devoted to the same end and measure the resources of each program. Where no measure of the amount of output is available, program comparisons may be permitted on a heuristic or intuitive basis. Public Microeconomics, Neil M. Singer; Little, Brown and Company, (Boston), 1972, p. 207.

TABLE I

LIST OF NAVIGATIONAL AIDS WITHIN
EACH AIDS TO NAVIGATION SUBSYSTEM

1. Short Range Aids:
 - a. Non-electric audio and visual aids:
 - 1) Lighted buoys
 - 2) Unlighted buoys
 - 3) Light structures (unmanned)
 - 4) Day beacons (unlighted and unmanned structures)
 - 5) Sound signals (1 manned station, remainder part of other nav aids)
 - b. Electronic short range radionavigation aids (radio beacons, 1 manned station, remainder part of other nav aids).
 - c. Aids with dual non-electric and electronic capabilities:
 - 1) Lightship stations (manned)
 - 2) Lighthouses (unmanned or manned) and Light Stations (manned)
 - 3) Large Navigational Buoys (LNB) (usually unmanned)
 - 4) Offshore platforms (manned or controlled remotely)
2. LORAN-A: Medium range electronic radionavigational system intended for general use.
3. LORAN-C: Medium range electronic radionavigational system intended for Department of Defense applications.
4. Omega: Long-range, worldwide, radionavigation system.

supplement the limited information given on charts, while The Great Lakes Pilot provides similar information for the Great Lakes. The Coast Guard publishes annually, in five volumes, Light Lists with complete details regarding all aids to navigation it maintains or which are under its authority. The lists include the official name, signal characteristics, location, and a general description for each navaid. The Coast Guard continually updates this information through broadcasts and documents. "Broadcast Notices to Mariners" made from Coast Guard or U.S. Navy radio stations report warnings that contain information of importance to the safety of maritime navigation, such as significant changes or deficiencies of navigational aids or hydrographic information received too late to be published in Local Notices to Mariners. Weekly or more often as needed, Coast Guard District Offices issue "Local Notices to Mariners" containing local waterway information deemed necessary in the interest of public safety.⁷ Mariners enhance the effectiveness of these marine information networks by reporting suspected navigational aid deficiencies, errors in charts or light lists, or any potential navigational hazard encountered in transit.

Short range aids, which form the focus of this research, are made up of two separate groups of components: physical support, and signal equipment systems. For a buoy, required

⁷ 33 CFR 72.01

physical support components include the buoy body (floatation source) and chain, shackles, and sinker (moorings) which anchor a buoy in a certain position. A bridle and swivel are used with lighted buoys and a ballast ball is sometimes used with large unlighted buoys. A buoy's position is certain only within limits, as its length of chain is somewhat greater than the depth of water at its charted position to facilitate free floatation. Thus, a buoy will drift within a small circle, following wind and current. Furthermore, buoys may be missing, adrift, or off charted position due to collisions or storms. For a fixed structure the support system is the ground it is built upon (ashore or at a marine site) and the structure itself. The optional signal equipment system for buoys and structures usually contains similar visual equipment but different audio equipment. Components used to transmit an active visual signal are batteries or other power source such as commercial power (used solely by structures), the lamps and a lampchanger, a flasher which turns a lamp on and off in a distinctive pattern called the characteristic, a lantern which refracts and directs light from the lamp and gives it a green, white, or red color, and a daylight control. Active audio signal components for buoys include bells and gongs with clappers and whistles that are activated by buoy movement in the water. Lighted buoys also can transmit electric bell, horn, or whistle sound signals. Sound signals for structures are usually powered electrically or by compressed air and have more distant

range capabilities than buoys. Passive signal features that may be built into a buoy are strongly contrasting colors, retro-reflective materials, numbers or letters, an easily identified shape or profile, or a radar reflector.⁸ Radar reflectors are inherent in structures. Other passive features for a structure are displayed on a daymark which is secured to the structure. A daymark is a board that may possess distinctive characteristics of shape, color, and retro-reflective materials, numbers or letters. For a lighted structure a daymark is the daytime aid to navigation: its features must be consistent with the nighttime light color and characteristic.⁹

Selection of Areas of Study: This project will focus in particular on the Lighted Buoy Group of the Short Range Aids to Navigation (SRAN) Sub-System. Lighted buoys were selected as the primary area of study for the following reasons:

1. Their relatively significant number and importance within the overall Aids to Navigation System.

⁸The lateral system of buoyage used to mark waters of the United States employs a simple arrangement of shapes, numbers, colors, and light characteristics to indicate on which side a buoy or structure should be passed when proceeding in a given direction. Directions vary depending upon the area of the United States being transited. 33 CFR 62.20 and 62.25.

⁹A Buoy Tender Manual, Aids to Navigation School, U.S. Coast Guard Training Center, Governors Island, N.Y., p. 4, April 1971.

2. Of all short range aids, they include characteristics and features that present the most opportunities for failure. For example, lighted buoys combine standard visual signal components of most light structures with the unfixed position trait of unlighted buoys.

The project was completed in five phases: study selection, data collection, data examination, information system modification, and study completion.

Phase One involved the identification of certain Aids to Navigation (A-to-N) reliability and optimization relationships. The primary area chosen for analysis was the relative importance of various relationships between Aids to Navigation reliability (the probability that an aid functions 24 hours a day) and causes of nonfunctioning. An aid may be nonfunctional due to administrative errors, personnel errors, logistic errors, technological errors, hazards of weather, collision, and vandalism, and manufacturing errors -- failures due to defects in workmanship or premature wearout. Initially batteries alone and subsequently all lighted buoy components were selected in examining the frequencies of various causes for aid malfunctions and determining hazard, failure, or error proneness.

Phase Two of the project involved collection of data pertaining to the selected areas of study. Data were collected from the Thirteenth and Ninth CG Districts, serving the Pacific Coast states of Oregon and Washington and the Great Lakes area respectively. Data from the Thirteenth

District were collected because they often included recorded closed circuit voltage battery readings. This is a voluntary recording procedure in the current SANDS program and although taking such readings is practiced throughout the Coast Guard, the Thirteenth District is unusual in that the readings are recorded. Additional data were collected from Aids to Navigation, Ocean Engineering, Data Systems, and Claims and Litigation Division Branches of CG Headquarters, and from the CG Supply Center in Brooklyn, N.Y. Visits were made to the Aids to Navigation School, Governors Island, N.Y. and Eleventh and Twelfth CG District Aids to Navigation Branch Offices.

Phase Three consisted of examining the data collected to ascertain its suitability for the areas of study. During this phase and after many telephone conversations to the Thirteenth District and Headquarters, it became apparent that a need exists to modify the current Aids to Navigation Management Information System. This contention is supported by the fact that, in a separate effort, an Aids to Navigation Work Report Form with major revisions currently is being tested on an experimental basis in the First CG District.

Substantial evidence that modifications to the Management Information System are desirable has been provided as a result of studies conducted by the management consultant-research firm Booz, Allen Applied Research, Inc. In their systems analysis studies of the servicing and support systems for Coast Guard Short Range Aids to Navigation, Booz, Allen concluded:

"...Additional effort should be applied to make the Simplified Aids to Navigation Data System (SANDS) fully operational..."¹⁰

"Additional statistical information on outages and servicing frequencies is needed from SANDS to identify ways of increasing efficiency with which aids to navigation are serviced, and also provide data for the design and acquisition of new aid-to-navigation systems and servicing facilities."¹¹

"In addition to additional computer facilities and capabilities, deficiencies discovered through experience with the current SANDS Program require a thorough program evaluation and revision to provide the information that is desired by both operational units and administrators..."¹²

It was decided that a separate study into determining feasible modification alternatives to the present Aids to Navigation Management Information System was compatible with the original purpose of this research. This decision led to the search for modification procedures with the following goals:

1. Modification of all phases of the Management Information System in such a manner as to save time where possible for all Aids to Navigation personnel, especially the time of field servicing and reporting units.

2. In view of the major effort already being put into the SANDS Program, further develop potential information available to the Management Information System.

¹⁰Evaluation of Plastic versus Steel for Buoy Hulls,
Contract Number DOT-CG-90506-A, January 7, 1970, p. 9.

¹¹Evaluation of Minor Marine Structures versus Buoys,
Contract Number DOT-CG-90506-A, May 15, 1970, p. 9.

¹²Servicing System for Short-Range-Aids to Navigation,
Contract Number DOT-CG-90506-A, November 7, 1970, p. 74.

Phase Four involved determination of a model Aids to Navigation Management Information System. To achieve both goals, several Aids to Navigation Work Report content changes were envisioned, leading to recommendations for future modifications of the SANDS reporting form. In order to obtain the second goal, an additional processing method for SANDS data was deemed desirable. A pre-packaged computer program suitable for this purpose was found. Feasible acquisition and installation of the package discussed is particularly timely in that the Coast Guard and other DOT agencies¹³ with headquarters in the DOT, Departmental Headquarters Building anticipate consolidation of present data processing facilities in the near future. The procurement cost of the package in question is under \$1,000.00.

Phase Five consisted of the completion of the selected areas of study using the package during various stages.

Because of the limitations in the empirical data, capabilities of the author, time, and scope of this project, this research should be regarded as preliminary. It is suggested that a team of personnel possessing expertise in analysis and information systems design complete a thorough evaluation of the issues raised and presented. The author believes that effective implementation of Aids to Navigation Management Information System modification procedures similar to those presented will contribute to the sound policies of standardization, simplification, and cost-effectiveness.

¹³These include the Federal Highway Administration and the Federal Railway Administration.

II. DEVELOPMENT OF SHORT RANGE AIDS TO NAVIGATION

A. AN HISTORICAL REVIEW

The official beginning for the Aids to Navigation System was the Ninth Act of Congress of August 7, 1789, which provided for the erection and maintenance of lighthouses. Lighthouses built by the colonies were ceded to the Federal Government; and, together with wooden buoys already in use, these lighthouses became the nucleus of the present Aids to Navigation System. By the 1850's buoys built with iron and improved wooden buoys, employing black or red color and numerical significance standards (which eventually became the present lateral marking system) were marking channels. A lighted buoy using Pintsch gas under mantle was introduced in New York Harbor in 1881, but subsequent attempts to electrify buoys in New York Lower Bay through shore cables from 1888 to 1903 proved to be impractical. Meanwhile buoys built with whistles and buoys with mounted bells struck by clappers were successfully used to produce sound signals when a buoy was set in motion by the sea. Further attempts to redesign buoys led to taller can and nun shaped unlighted buoys which were first mentioned at the turn of the century. In 1910, lighted buoys were developed which used acetylene gas compressed inside tanks that were stored within buoy pockets. These buoys were the forerunner of the type of

lighted buoy in general use today.¹⁴ By the early 1920's buoys equipped with gongs and clappers joined whistle and bell buoys in producing sound signals.

On July 1, 1939, the responsibilities for Federal Aids to Navigation which had formerly been carried out by the U.S. Lighthouse Service were permanently transferred to the United States Coast Guard.¹⁵

B. DESCRIPTION OF A LIGHTED BUOY BY COMPONENT

Development of the Aids to Navigation System into a reliable network promoting safe and economic navigation has required not only technological progress by our society, but also major development, operation, and maintenance efforts by the Coast Guard. Despite these efforts, the Aids to Navigation System is subject to failure in terms of hardware malfunctions, incorrect positioning of aids, and incorrect or incomplete information dissemination. Of all navigational aids, lighted buoys include characteristics and features that present the most opportunities for failure. A discussion of hardware malfunctions and positioning errors, and methods of preventing and correcting them, presupposes some familiarity with the components and operation of a

¹⁴ Piloting Seamanship and Small Boat Handling, Charles F. Chapman, The Hearst Corporation (New York), 1961, p. 299.

¹⁵ At this time the Coast Guard was serving within the Treasury Department. In 1967 the Coast Guard and all functions, powers and duties relating to the Coast Guard were transferred to the Secretary of Transportation by STATUTE AT LARGE (80STAT 931) which created the Department of Transportation.

lighted buoy. The description of a typical lighted buoy equipped with standard components is presented in Figures 1, 2, and 3 and corresponding Tables II and III. An explanation of each component's function and general terminology are included.

Buoys are classified by their size, type, and equipment composition. For example, an 8 x 26 LBR description would classify the buoy as being eight feet in diameter through the buoy and twenty-six feet long, lighted, having a bell, and having a radar reflector. Unlighted buoys are broken down into six classes of sizes, first class being the largest. A 5NR description would classify the buoy as being fifth class, nun-shaped, and built with a radar reflector. Larger buoys are used in exposed locations since they ride better in rough seas or bar areas, and can support needed heavier chain. The lamp size, flasher type, and length of daylight determine how many ampere hours per day of a battery are consumed. The lamp size, type and height above water, lantern type, atmosphere transmissivity (clear, haze, fog) and height of the user determine how far a light may be seen at night. Only group flashing, red, or green lights indicate lateral significance.

C. HIGHLIGHTS OF MAJOR INNOVATIONS AND DEVELOPMENTS BY THE COAST GUARD

1. Standard Buoys (1940-1962)

In 1940 the decision was made to standardize the more than 400 different variations of buoy types in order

A Typical Lighted Buoy Showing Principal Parts and Appendages
With Non-scale Blowup Drawings of Components




FIGURE 1

Power Assembly Clamp



Battery Pack




FIGURE 2




FIGURE 3

TABLE II
LIGHTED BUOY SUPPORT SYSTEM

<u>Part</u>	<u>Purpose</u>
Buoy Body (Hull)	A steel body providing a floatation source and platform to support all other components or parts.
Counterweight Tube	Lowers center of gravity so that the buoy floats in an upright position at its designed waterline.
Cage (Tower)	Structure mounted on top of the body to support the signal system.
Pockets	Two hollow watertight tubes, built symmetrically into the body, which hold power units that provide DC energy to the signal system.
Pocket Closure	Coupling, gasket, and pocket cover to provide watertightness of a pocket.

Air Circulation and Venting Sub-system

Vent Lines	Piping 3/4" in diameter for air venting of each pocket.
Crossover Pipe	Crossover line between the two pockets to enable circulation of air.
Vent Valve	Gravity-operated device consisting of a valve seat, valve body, and two weights. This device closes to provide watertightness as a buoy heels over and rolls under water, then opens as the buoy approaches or remains in an upright position.

Mooring Sub-system

Appendage - any component part of the mooring sub-system

Bridle	Two lengths of chain attached to arms on opposite sides of the buoy and linked together with a large center ring that is tied in with the mooring system. The ring rides just above the bottom of the counterweight tube to prevent entangling. There are wooden fenders attached lengthwise to the tube to prevent wear from rubbing.
--------	--

TABLE II. (continued)

Swivel	Device that permits free twisting of the buoy without causing the chain to kink or twist.
Chain	Welded steel links of up to 1 7/8" in diameter joined in series to connect appendages at the buoy to the sinker at the bottom. The riser section runs from the buoy to the bottom. A chafe section, usually made of heavier chain than other sections because it wears first, lies on or near the bottom and is dragged about depending upon buoy movement. The bottom section near and connected to the sinker is usually mudded or sand- ed in and undergoes little wear. Normally the total length of chain used to moor a buoy is 1 1/2 to 5 times the depth of the water at its position. The weight of the chain helps to hold a buoy in position but it cannot be so heavy that it causes the buoy to float low in the water. In some areas with very deep water, nylon line has been successfully used as a riser section of the mooring.
Shackle, Pin, and Key	Hardware used to fasten various mooring appendages together and tie moorings into the buoy. Shackles use split key pins or riveted pins. Split keys, used only once, are designed to work similar to conventional cotter keys. Stainless steel split keys are most often used.
Sinker	Concrete or cast iron weight that provides the brute holding strength to moor the buoy to the bottom. Sinker weights vary according to exposure, with heavier sinkers used to moor buoys encountering rough seas or strong currents. Sometimes more than one sinker will be used to moor a buoy. Weights range from 9 tons down to less than 100 lbs.

TABLE II (continued)

Passive Features

Radar Reflector	Device built into the cage that is especially designed to reflect high frequency radio waves transmitted by radar transceivers. This device is also designed to promote a wind suction force for the air circulation and venting sub-system.
Retro-reflective Materials	Material made in panels, numerals, and letters that reflects light from an outside source back along the same path it traveled in reaching the reflective material.

Sources: A Buoy Tender Manual, p. 15-33.
U.S. Coast Guard Ocean Engineering Report No. 38B (CG-250-38B), "Buoy Classification and Description," 9 Sept. 69.

TABLE III

LIGHTED BUOY VISUAL SIGNAL SUB-SYSTEM

<u>Part</u>	<u>Purpose</u>
Battery	Basic non-rechargeable primary cell or group of cells providing DC energy from a self-contained source. A battery contains carbon cathodes that require a dust free surface and air flow, zinc anodes, a caustic potash electrolyte, and breathing apparatus. While outer cases have been made of polyethelene, transparent acrylic plastic cases were recently developed. A battery is activated by the addition of water to each cell.*
Power Unit (rack, pack)	A combination of primary batteries in a disposable container. Batteries are connected in series or parallel to form a 12-volt bank, depending upon ampere-hour capacities desired. If only one power pack is utilized for a buoy, the empty pocket normally contains ballast equivalent in weight to the pack in the other pocket. Batteries come in 1000 and 3000 ampere-hour capacities. By connecting in parallel, 2000 and 6000 ampere-hour capacities can be obtained. Batteries are securely housed inside a wooden rack to make up a unit. 1000 ampere-hour units weigh about 200 pounds; 3000 ampere-hour units weigh about 500 pounds.

* Primary batteries are not rechargeable and used only once or through multi-seasonal use until battery capacity has been consumed. They have no salvage value and after use are to be disposed of at proper shore facilities. Secondary batteries are similar to the conventional automobile battery (lead-acid), being rechargeable and having a small salvage value. Except for a few shore aids, the use of secondary batteries with lighted aids to navigation was terminated in 1969. Occasionally 6-volt hotshot batteries (similar to 'D' cell batteries) are used to temporarily provide a source of energy to lighted aids.

TABLE III (Continued)

Power Assembly Clamp (PAC)	A non-disposable holding device utilized to secure a power unit in a buoy pocket. The PAC weighs approximately 45 pounds.
Flasher (CG-181)	Watertight, solid state, electronic device that times the flash sequence, switches a circuit to operate the lamp for a pre-set contact time, regulates the output voltage so that within each sequence 12 volts are not exceeded, and upon sensing a burned out or defective lamp switches a circuit to operate the lampchanger so a new lamp is rotated into the operating position. The flasher weighs under 2 1/2 pounds.
Lampchanger (CG-6P)	A spring loaded, hand wound device with a turret that supports six lamps, only one lamp of which operates at any given time. Upon receiving a pulse from the flasher it lights the operational (uppermost) lamp for the duration of that pulse. When a lamp is burned out, the lampchanger's circuit is open and upon receiving a pulse from the flasher the lampchanger rotates a new lamp into the operating position. If the new lamp is operative, the system functions normally; if the new lamp is defective, the process continues until an operative lamp is found or the lampchanger has rotated the sixth and last lamp into the operating position.
Lamp (Marine Signal)	A source of light consisting of a filament (tungsten wire of high melting point that becomes incandescent when heated by electric current) that is enclosed in a glass envelope (bulb) preventing oxidation but enabling light radiation. Lighted buoy lamps are equipped with clear bulbs, type S-8 or S-11, and type C-8 helical coiled filaments. These lamps use 12 volts and come in six different sizes: .25 ampere, .55 ampere, .77 ampere,

TABLE III (continued)

	1.15 ampere, 2.03 amperes, and 3.05 amperes.
Lantern (155mm plastic 200mm glass)	An acrylic or glass optical (green clear, or red fresnel drum lens), that provides a watertight housing for all visual signal components. This is mounted on top of the cage. It refracts and directs all light rays from the lamp towards the horizontal direction to be observed as a red, green, or white light. The buoy lantern weighs no more than 8 pounds.
Daylight Control	A photoconductive device attached to the flasher that enables the flasher to control visual signal transmissions during periods of darkness. It is current policy to replace daylight controls at the time a power unit is replaced or every two years, whichever is less.
Rated Life of Lamp	The average number of hours that a batch tested particular type of lamp will burn at rated voltage before failure. The rated life of all lighted buoy lamps is 500 hours.
Rated Battery Discharge Time (RBDT) (days)	The RBDT is the expected total useful operating life of an activated battery or combination of activated batteries under a specific load and operating characteristic. The RBDT is established using battery ratings and the ampere-hour-per-day consumption of 12-volt lighting equipment for standard light phase characteristics. The consumption value includes allowances for surge factor, solid-state flasher regulator dissipation, and operation using daylight controls. The RBDT for certain locations is adjusted for environmental variances from standard conditions such as extreme temperatures, shaded daylight controls, and cloud cover.

TABLE III (continued)

Battery Shelf Life Period	The battery shelf life period is the amount of time that a battery or power unit may remain in storage without deteriorative action occurring to the point that the battery rating is reduced. The shelf life period commences upon departure of the batteries from manufacturer.
Battery Service Life	The battery life is the RBDT plus the battery shelf life period, or three years in operation plus the battery shelf life period, whichever is less.
Characteristic	The pattern in time of flashes of light alternating with eclipses of darkness exhibited by a light during one period.
Standard Characteristics	Characteristics in accordance with the International Association of Lighthouse Authorities' Standards:
Fixed (F)	A continuous steady light.*
Flashing (Fl)	Showing a single flash at regular intervals; duration of light always less than duration of darkness. Not more than 30 flashes per minute.
Group flashing (Gp.Fl.)	Showing at regular intervals 2 or more flashes.
Quick flashing (Qk.Fl.)	Shows not less than 60 flashes per minute.
Interrupted quick flashing (I.Qk.Fl)	Shows quick flashes for about 5 seconds, followed by a dark period of about 5 seconds.

* Fixed lights are not used with buoys since they are uneconomical for battery powered aids, and not as conspicuous as rhythmic lights.

TABLE III (continued)

Equal Interval (E. Int.)	Light with all duration of light and darkness equal.
Occulting (Occ.)	A light totally eclipsed at regular intervals, the duration of light always greater than the duration of darkness.
Morse Code - Mo. (A)	Light in which flashes of different duration are grouped in such a manner as to produce a Morse character A.
Duty Cycle	For a given characteristic, the ratio of the total time during which the flasher allows current to flow to the lamp during one period to the duration of one period.
Sources:	<p>COMMANDANT INSTRUCTION 10500.32A 1973 <u>Light List</u>, Volume III, Pacific Coast and Pacific Islands <u>Ocean Engineering Report No. 37</u> (CG-250-37), "Visual Signalling: Theory and Application to Aids to Navigation," 22 June 1970.</p> <p><u>Purchase Description No. 191A</u>, "Primary Batteries for Aids to Navigation," 14 February 1974.</p> <p><u>Purchase Description No. 181B</u>, "12-Volt, Solid-State, Flasher for Maritime Aids to Navigation," 13 May 1968.</p> <p><u>Purchase Description No. 195A</u>, "12-Volt, Six-Place Lampchanger for Maritime Aids to Navigation," April 1971.</p> <p><u>Purchase Description No. 234</u>, "CG-234 Daylight Controls for Solid-State Flashers," February 1973.</p> <p><u>Purchase Description No. 243</u>, "Marine Signal Lamps," April 1973.</p> <p><u>Purchase Description No. 205B</u>, "Buoy Lantern for Maritime Aids to Navigation," March 1972.</p>

to simplify maintenance and reduce the required number of spare parts, components, specifications, and prints. After many years of development efforts, the Coast Guard finally achieved significant design changes in 1962, which have culminated in higher levels of lighted buoy effectiveness, efficiency, and safety. These changes, known as the 1962 Buoy Standards, have enabled subsequent standardization of other buoy components.

2. Mechanical Chain Stopper for Buoy Tenders (1950's)

Although not a direct improvement to aids, the mechanical chain stopper was a major innovation for buoy servicing operations. This device which was adopted service-wide during the early 1950's, consists of a spring loaded mechanism mounted in the forward end of the buoyport of a buoy tender. Through positive reception of buoy mooring chain and easy disconnection when desired, the mechanical chain stopper has led to easier and more certain shiphandling during hazardous buoy servicing operations.¹⁶

3. Electric Power with Primary Batteries (1950-1969)

Although battery powered lighted buoys were first introduced in 1935, their superiority over acetylene gas buoys was not determined until the late 1940's. The decision to electrify all lighted buoys with secondary lead-acid batteries was made in 1950. While these batteries could be

¹⁶In 1950, LCDR Niels P. Thomsen, then Commanding Officer of the USCGC TUPELO, developed and built a prototype of the mechanical chain stopper. A Buoy Tender Manual, p. 62.

recycled eight times or more, the required semi-annual recharge procedures, consisting of returning exhausted batteries to support bases for unranking, recharging, and reracking, were many times the initial cost of the batteries themselves. Furthermore, the danger of explosion from gas accumulation inside a buoy body, previously encountered with acetylene gas lighted buoys, was lessened but not eliminated since lead-acid batteries emit explosive hydrogen gas. In 1962 the first experimental use of primary zinc-air batteries lead to a new era for lighted aids to navigation, as the primary batteries eliminated the massive and costly support requirements of secondary batteries. The initial cost of primary batteries was, incidently, slightly lower than equivalent secondary batteries. Primary batteries can be acquired with capacity combinations providing 1 to 3 years of power, enabling less frequent servicing of aids and enabling battery servicing to coincide with other component service periods. The danger of explosion from gas accumulation was also eliminated. By 1969, when use of secondary batteries was terminated, lighted buoys could be recharged with primary battery power units that weighed much less than the old secondary units. This weight reduction was sufficient to permit recharging of a lighted buoy with 1000 ampere-hour power units by small boat, thus providing new operational flexibility for servicing units. Although the dumping of primary batteries at an aid site was practiced initially, the Coast Guard since 1970 has taken a leadership role in

protecting the marine environment, and most of the damage done to battery powered navigational aid surroundings in the 1960's has been corrected. Appropriate procedures for disposing of primary batteries at suitable shore facility locations have been instituted; however, in some locations proper disposal is becoming increasingly complicated.

4. Standard Solid-State Flashers (1960's)

The decision to standardize light characteristics was made in 1966, as the hundreds of different flashers then in use required massive procurement and inventory procedures. Effective implementation of this policy has provided mariners with uniform and easy to identify visual signals. Because only twelve types of flashers are now generally in use, aids to navigation personnel have an easier task in selecting desirable power-equipment combinations.

5. Use of Radar Reflectors (1952-1962)

Until the 1940's when vessels and aircraft were commonly equipped with radar transceivers, buoy construction offering minimum wind resistance was desired. However, the ability to transit buoyed channels by radar during periods of poor visibility became a reality during the 1950's leading to a provision for basic radar reflectors in the 1962 Buoy Standards.

6. Replacement of Lightships (1960's)

As technology advanced during the 1960's, many lightship stations and their functions were replaced by

offshore platforms that were either manned by vastly smaller personnel complements or controlled remotely. Large Navigational Buoys (LNB) forty feet in diameter have replaced other lightships since the last offshore platform was built.

7. Servicing Remotely Located, Difficult to Service Aids (1960's-1970's)

With commencement of the Lighthouse Automation and Modernization Project (LAMP) in the late 1960's, efforts were initially made to automate remotely located, isolated, or difficult to support lighthouses. This effort has been largely successful. Coast Guard Aircraft have been used to service aids to navigation where aids are not easily accessible, in such areas as offshore islands.

8. Acrylic Lantern Optical Assemblies (1960's-1970's)

The first lenses used extensively for lighthouses were made of cut glass. This process was very expensive and eventually gave way to the less expensive pressed glass method. Pressed glass optical assemblies became common on most lighted aids to navigation even though the optical efficiency of cut glass was superior.¹⁷ For many years the standard buoy lantern was made of pressed glass with an

¹⁷ While some larger size (order) cut glass (classical) lenses remain in service today, many of these masterpieces (primarily imported from France during the 1800's) have been preserved in museums throughout the United States. Augustin Fresnel (1788-1827) is credited with having developed large cut glass lenses by building separate ring prisms of glass. Eventually 9,000,000 candle power capability was attained through this method. Encyclopedia Americana, Volume 17, 1969, p. 506.

inside diameter of 200 mm. By introducing modern acrylic lenses into service, greater optical efficiency was regained because sharper corners could be molded into plastics than in pressed glass. While the 155 mm acrylic plastic lantern has been utilized as standard for lighted buoys since the early 1970's, some 200 mm glass lanterns have been retained in rough service locations encountering ice or breaking waves.

9. Procurement of Short Range Aids to Navigation Components (1960's-1970's)

Most aid components are peculiar solely to aids to navigation and must be specifically manufactured for the Coast Guard. Procurement is now primarily through one year term contracts with commercial manufacturers listed on the Coast Guard Qualified Products List (QPL). The Coast Guard after determining needs, writes detailed specifications for each product required then encourages companies to submit prototypes of the components to be produced for testing and evaluation. If specified standards are met, the manufacturer is placed on the QPL and becomes eligible to bid on a contract. Hopefully more than one manufacturer will have qualified for each product, thus allowing competitive bidding. When bids are solicited from the QPL, the Coast Guard guarantees a minimum number of items that will be purchased during the term of the contract. The manufacturing firm offering the lowest price is awarded the contract. Contracts are then utilized by the Brooklyn Supply Center (The Inventory Control Point for small SRAN components) to

procure desired numbers of components for inventory and subsequent distribution. Periodically servicing units order components, such as flashers, directly from the Supply Center to provide sufficient quantities of spare components to correct potential aid deficiencies in addition to meeting routine servicing requirements. Through competitive bidding of solid-state flashers the original price of \$278.00 per flasher was reduced to \$59.20 each in 1969, the current price being \$69.30.

Because no interest exists in building steel buoys commercially, the Coast Guard Yard constructs buoys for the Aids to Navigation Mission. Once built, buoys are turned over to Headquarters Controlled Material (HQCM) for inventory control along with all other buoys on station or maintained under HQCM authority by support bases. Sinkers are generally fabricated locally by support bases.

D. AREAS WITH POTENTIAL FOR FURTHER DEVELOPMENT

1. Booz, Allen Applied Research Studies

As a result of studies concerning support and service systems, significant changes have been and will continue to be made in the Coast Guard Aids to Navigation System. Booz, Allen Applied Research, Inc., conducted this research during 1970 in three tasks:

"Evaluate plastic versus steel buoy hulls."

"Examine the tradeoffs between floating aids and fixed structures."

"Examine the servicing system, including facilities

ashore and afloat, considering possible changes in buoy material and buoy-structure mix."¹⁸

Based upon these studies, Booz, Allen recommended that the Coast Guard develop the SRAN Sub-system to include:

"Establishment of trained and mobile A-to-N teams for servicing actions that do not require lifting of buoys and moorings."

"Design and construction of specific new classes of boats and tenders and modernization of some existing tenders."

"Reduction of servicing schedules for all types of aids supported by an effective SANDS program and maintainability analysis."

"Use of minor marine structures instead of buoys wherever local conditions are favorable."

"Use of lightweight plastic buoys for all floating aids except those in icy conditions."

"Development and engineering to support the program."¹⁹

In addition the following essential initial projects were defined:

"Buoy-position device

Aerial photography

Discrepancy buoy and mooring

Tender modernization

Operating Manuals

District Operating Plans ..."²⁰

¹⁸ Servicing System for Short-Range Aids to Navigation, Booz, Allen Applied Research, p. 1.

¹⁹ Ibid., p. 1.

²⁰ Ibid., p. 7.

As a result of the Booz, Allen studies, much progress has been made in some of these areas.

a. Administration

Until 1972 there were hundreds of directives and publications issued by Headquarters prescribing Coast Guard internal policies and procedures to be followed in the establishment, development, maintenance, and operations of the Aids to Navigation System. In a complete revision and consolidation of the previous partially obsolete or redundant paper empire, the revised Aids to Navigation Manual is being issued. The manual is divided into four books and several appendices. Book 1, "Administration," was completed 17 May 1972 and has been amended through Change 3 of 1 August 1974. Book 2, "Seamanship," was completed 12 June 1973, and Book 4, "Radio Navigation," was subsequently issued. Book 3, "Maintenance," and Appendix D, "SANDS Manual," are still in the process of being developed, so certain portions of the 1964 version of the Aids to Navigation Manual remain effective. At the district level directives are promulgated to prescribe guidelines specifically meeting district requirements. Overall guidance is contained in the District Operations Plans.

Informal communications between Headquarters, field, and staff organizations and units are printed periodically by the Headquarters Aids to Navigation Division in "Aids to Navigation Bulletins." These publications include, among other items, articles about solving common problems, helpful hints

or reminders, innovations, and summaries, seminars, or surveys involving aids to navigation. A similar publication, "The Coast Guard Engineer's Digest," contains scientific and technological articles which occasionally feature aids to navigation.

b. Aids to Navigation Teams (ANTS)

As a result of the studies and subsequent favorable experimental evaluation, the Coast Guard has established several shore based Aids to Navigation Teams (ANTS). Two generations of related Aids to Navigation Boats (ANBS) have been constructed and delivered. The ANT concept is based upon the fact that much work being performed by tenders could be successfully accomplished by smaller, less expensive craft. Related to the implementation of Aids to Navigation Teams has been an ongoing effort to develop discrepancy buoys. Discrepancy buoys are lightweight lighted buoys that can be utilized by ANT units or other shore based units to temporarily correct lighted buoy discrepancies that would ordinarily require a tender to correct. Discrepancy buoys have been made in many different ways, primarily using small unlighted buoys as a platform. Eventually about seventy ANT units are to be established if the program continues to be successful.²¹

²¹Aids to Navigation Bulletins: (Oct. 1971 - Mar. 1972) p. 19; (May - Dec. 1973) p. 28. Success appears probable. Actually ANT is a proven concept practiced as early as the late 1960's by buoy tender personnel as a direct result of reduced weight primary battery power units. Tender personnel using their own cargo boat or borrowing trailerized boats and vehicles from nearby stations, serviced aids including buoy power unit replacement.

c. Miscellaneous

Also of significance resulting from the studies has been implementation of the 180' Buoy Tender Modernization and Renovation Program, and the ongoing testing and evaluation of plastic buoys. The reduced frequency of servicing aids to navigation for other than discrepancy situations has contributed to cost-effectiveness. Progress towards attaining reduced frequency goals for routine visits is indicated in Figure 4. Most importantly the studies themselves have guided the Coast Guard into formulating policies that examine cost-effectiveness and consider alternative courses of action.

2. Sound Signals

During periods of low visibility, reliable sound signals may be the only warning provided a mariner approaching danger. Methods depending on wave action also fail to operate in dead calm seas. Attempts to power buoy sound signals have met with only mixed success. The following comments address this area most appropriately.

"The ultimate in reliability is still beyond our grasp. We are searching for a highly dependable sound signal with the fewest possible moving parts and the least amount of circuitry. One that can sustain the shock of open water without failure, that is cheap and easy to maintain, and one that runs on the least amount of power. When this horn is developed, then bells, gongs, whistles and bell strikers will join the great amount of aids hardware already in historical limbo."²²

²²"Buoy Tender Manual," p. 32.






FIGURE 4

3. Multi-seasonal Use of Primary Batteries in the Ninth Coast Guard District

Since 1969, the servicewide use of primary batteries has provided for flexible and longer service intervals between routine power unit replacements. This has enabled actual operating conditions to be matched with potential battery capabilities. However, for several years full potential has never been realized on the Great Lakes (Ninth District), due to the seasonal operation of these aids to avoid ice hazards. In an attempt to obtain more effective use of power unit capabilities, the Ninth District decided to use batteries for second and third seasons provided the power unit in question met visual inspection, closed circuit voltage, and remaining capacity requirements. Because of interim stowage and handling problems associated with the extremely cold temperatures encountered in the Great Lakes Area during the winter, a tradeoff between potential battery savings and increased probability of battery failure for the ensuing season exists. Recently a smaller capacity battery of 600 ampere-hours that is currently used only with shore aids, has been placed on the market at a proportionate reduction of the cost of 1000 ampere-hour batteries. Should a corresponding power unit of 600 a-h capacity be developed, many buoys currently operating with multi-seasonal power units will be powered with one season units, hopefully resulting in greater battery consumption before replacement without an increase in probability failure.

4. Discussion of a Major Aids to Navigation Problem
Area Involving questions of Coast Guard Liability
Based on Buoy Positioning

The purpose of this discussion is to illustrate an additional approach toward improving buoy positioning accuracy. The position aspect of buoys is currently the subject of court litigation where judgements in excess of \$127 million dollars are being sought.²³

a. Background

Normally under suits in Admiralty, the plaintiff stands to collect damages from the Federal Government if negligence in maintaining the Aids to Navigation System can be proven against the Coast Guard. Negligence can be in the performance of work or failure to correct a discrepancy. Two ways the latter category can be predicated include actual notice, discrepancies actually discovered or reported, and constructive notice, discrepancies not observed or reported but within the Coast Guard's purview to have been reasonably acted upon.

Once a buoy is established in a position delineating the limits of best water, this position information is given to appropriate agencies for charting. From then on buoys must be placed accurately on the charted position. Should bottom contour changes be detected and it is determined that a buoy is to be relocated, immediate dissemination of this information is required with Broadcast Notice to Mariners. Continuous advertisement in Local Notices to

²³Aids to Navigation Bul. (May 73 - Dec. 73), p. 10.

Mariners is required until charts can be corrected to reflect the new location.

In essence the Federal Tort Claims Act exposes the Coast Guard to suit should a vessel collide or ground as a result of reliance upon a charted buoy. It is then up to the Coast Guard to prove that the system had been maintained in a reasonable manner. Unless a buoy's proper position can be proved, no assumption about subsequent movement by heavy weather can be made. Even if positioning was properly and accurately accomplished, mistakes such as reversed left and right angles discredit the competence of the Coast Guard for the entire operation.

The Coast Guard has put a major effort into alleviating this increasingly occurring problem. There are a multitude of procedures and instructions concerning buoy positioning and position reporting processes as these operations are precise and demanding. Because of uncontrollable circumstances, such as poor visibility, the most precise method or combination of methods available must be used to accomplish the task, even though these methods may not be the most preferred method. The comprehensive procedures and instructions include the following considerations:

- (1) Buoy positioning instruments are properly calibrated and in a good state of repair. These instruments include sextants and other inherent systems aboard a servicing unit used to determine buoy positions such as visual bearings, radar ranges, and depth soundings.

Positioning with horizontal sextant angles combines simplicity with extreme accuracy; however, certain limitations such as poor visibility preclude their use at all times. A buoy's position can be defined with two angles obtained by using the sextant in the horizontal position instead of the usual vertical position. The left and right angles are determined from three objects - left and right objects using a mutual center object. The buoy's position and center object's location are defined where two imaginary circles intersect. Care must be exercised in selecting objects in order to avoid "swinger angles" (angles obtained from objects located such that the two imaginary circles approach overlaying one another).




FIGURE 5

(2) The most precise means available are used in buoy positioning operations supplemented with additional angles, bearings, and ranges. Particular attention to quality of angles is important.

(3) Appropriate charts are fully corrected and accurate depth determination is obtained such as with leadlines (hand employed).

(4) Check that the buoy serves purpose intended (hydrography changes) when on charted position, and that all information in the Light List is accurate and up to date. A buoy found off station is either reset on charted position or promptly reported as off station.

(5) A continuous training and maintenance program to support the above.

In a separate effort, research and development work involving an electronic buoy positioning device or equipment is being conducted. One such system, costing \$47,000 for one vessel, is to be tested in the future. In a special project, Commandant (GWAN) is attempting to develop new techniques to assist in accurate positioning of buoys.²⁴ It is a response to this endeavor that an additional approach is presented.

²⁴ LCDR G. Clark (GWAN-1) is working on this project. In a recent Aids to Navigation Bulletin, LCDR Clark contributed a detailed discussion of gyro errors and their relationships to latitude and vessel speed, and resultant quality of visual lines of position (bearings). Aids to Navigation Bulletin (May 1973 - December 1973), pp. 31-34.

b. The Environment

When a tanker runs aground near a channel marked by Coast Guard buoys that were relied upon while transiting the channel, the potential legal implications are enormous. Besides structural damage sustained by the tanker there are the possibilities of loss of life, oil discharge, and blockage of the channel so that other maritime traffic is delayed. For this scenario, three alternative reactions are presented.

Definitions:

Buoy Reliability: the ability of a buoy to survive hazards, including component failures such that the buoy does what the Coast Guard intends for it to do 24 hours a day.

Charted Object: a light structure, tower, tank, spire, chimney, or any definite and distinct object that is accurately located on a chart for buoy positioning.

Assumptions:

(1) The continuing need and therefore use of buoys to accomplish SRAN Mission goals.

Justification:

(a) Booz-Allen conclusion which takes into account the economics of minor light structures versus buoy flexibility resulting in total numbers of buoys that are essentially stable for the foreseeable future.

(b) Need for temporary aids.

(c) Future adoption of plastic buoy hulls and solar energy as a power source will not alleviate the need for buoys.

(2) The cost to operate and maintain buoys will be no less in the future than in the past.

Justification:

(a) Revised lower cost servicing schedules and procedures reflecting greater reliability of aid components and the Booz-Allen studies are already in effect.

(b) Inflation.

(c) Energy crisis.

(d) Personnel - ending of the draft has led to sharply higher recruiting costs.

(3) Buoy component reliability will be at least the same in the future as in the past.

Justification:

(a) Signal Engineers and technological personnel will continue to make major contributions in this area. The solid-state flasher is an example of the progress already accomplished in component reliability.

(b) Continued strong QPL standards and procurement control.

(4) Overall buoy reliability will be at least the same in the future as in the past.

Justification:

(a) Overall weather conditions will average out the same in the future as in the past.

(b) Increased Professionalism - The Coast Guard will continue a fairly successful effort in training personnel and maintaining traditional buoy position apparatus in an acceptable state of repair. As a result, there is no reason to believe that the use of wise and prudent selection of available objects or sextant angles and accurately adjusted apparatus will not continue to result in sufficient expertise with sextant use, plotting positions, and buoy seamanship proficiency. The Aids to Navigation School, Manual and Bulletins will contribute to this effort.

(c) High personnel turnover rate - this is a negative factor that to some extent can be overcome by increased professionalism. Although high turnover among personnel is undesirable because learning capabilities are usually never developed to full potential, it is somewhat necessary in view of the Coast Guard's ten separate missions and significant amount of isolated duty stations. The ending of the draft has also raised questions about the quality of present day recruits. While it is assumed that CG personnel habits will not so change, and thus personnel errors will be related to a high turnover rate.

c. Alternative 1 - Management Approach

This approach will eliminate the implicit assumption that objects used to determine buoy positions are actually located as charted. Although extremely uncommon, chart production errors not detected and surveys of objects charted that were not conducted or recorded accurately can lead to buoy positioning errors. This factor has been a major issue in one of the largest pending suits against the Coast Guard. Furthermore, it will be assumed that those objects used for positioning buoys are not always of high quality or available in sufficient number or location. Thus within budget and time constraints and under the assumptions already stated, there is the opportunity to improve upon charted objects that are relied upon for important buoy positioning functions. The following areas are considered within the realm of the Coast Guard.

(1) Servicing units are able to identify and report on objects that are used by necessity even though their charted position may be suspect, as well as potential objects of high quality already in existence but not charted.

(2) Servicing units can identify and in some convenient cases directly improve upon objects in need of enhanced visibility by use of reflective materials or brush clearing similar to the manner in which shore aids are maintained. In some situations, due to inaccessibility or property restrictions, servicing units will require high

level assistance in obtaining approval and affecting desired object visibility improvements.

(3) In some locations available charted objects are insufficient for buoy positioning purposes. Were servicing units able to identify these areas, high level authority could look into the possibility and verify the need for creating new objects in view of deed or easement restrictions.

(4) In rough service areas, where aids of rugged components have a consistent history of not being able to survive hazards of the environment for entire season, consider going to seasonal operation similar to the CG Ninth District facing ice hazards each winter.

(5) In those areas identified as particularly vulnerable to claims litigation due either to marine traffic patterns or court trends, consider an intensive effort in applying this management approach.

d. Alternative 2 - Technological Approach

Conceptually this approach would involve the development of an accurate positioning device. Such a device would have an advantage over the management approach by being effective during periods of poor visibility. However, the cost of such a device or system of devices might become constraining. A system costing \$47,000 for one vessel, that was requested in the Fiscal Year 1975 Budget, was eliminated due to other priorities.

e. Alternative 3 - Aerial Photography

This method, which was presented in the Booz, Allen Studies as a project for consideration, could help alleviate buoy positioning problems, but primarily from a defensive point of view. Such a technique, appears to be well suited for areas well defined, such as rivers, that have been the place of previous or current claims and litigation.

f. Summary

Of the three alternative approaches discussed, primary emphasis has been placed upon the Management Approach since it is believed that certain areas of this method could be easily implemented at a relatively small cost. The real problem presented, which would require extensive analysis to evaluate thoroughly, is determining what it would be worth to the Coast Guard in a Risk-Return tradeoff comparison to effectively implement each alternative. It is left for further study to determine the estimated cost of each alternative, and compare this with the expected benefit to be realized as a result of decreasing probabilities of buoy positioning failures, and thus potential claims and litigation.

E. A PROJECTION

The Coast Guard is in the midst of continuing Aids to Navigation evolution. While possible, the complete extinction of buoys in the future appears remote. More likely

the future may see long service life buoys equipped with solid-state components, indestructible moorings, and long life Flash Tubes. Moreover, these lightweight heavy duty buoys may be accurately positioned anywhere by a special device and powered indefinitely by solar energy.

III. DEVELOPMENT OF MODIFICATIONS TO THE AIDS TO NAVIGATION MANAGEMENT INFORMATION SYSTEM

A. INFORMATION NEEDS IN THE AIDS TO NAVIGATION AREA

The Simplified Aids to Navigation Data System (SANDS) is the present information system for the Aids to Navigation Mission. SANDS was implemented on a partially operational basis during the mid 1960's. Utilizing the advancing technology and spectacular growth in the use of electronic computers characteristic of the period, it was specifically designed to reduce the number of reports required, enable easier preparation of those reports retained, and to provide more and better information than previously available.

Because of the importance of the Short Range Aids to Navigation Sub-system in promoting safe and economic maritime navigation, short range aids have to be developed, operated, and maintained within high levels of reliability for prolonged periods and sometimes under adverse circumstances. In order to satisfy this general need of the public adequately, Coast Guard personnel involved with Aids to Navigation duties require an information system that generates a rapid flow of wide varieties of developed information suited for all levels of management in carrying out their particular functions.

The functions can be divided as follows:

- Operations and minor aid maintenance of servicing units.

- Heavy hardware stowage and major buoy maintenance support of bases or depots.
- Inventory and distribution of SRAN components by the Supply Center.
- Procurement and development of aids and aid components by Headquarters and District technical staffs.
- Construction of aids to navigation boats and buoys by the Yard.
- Training of personnel by the Aids to Navigation School.
- Budget presentation by aids to navigation Program Managers.
- The overall supervision, assignment of responsibilities, and policy formulation of Headquarters and District Aids to Navigation staffs.

Of primary importance to the effectiveness of aids and usefulness of the information system are the prevention, early detection, and correction of aid deficiencies known as discrepancies; such as buoys not on charted position and lighted buoys that are extinguished. Most critical are discrepancies involving aspects of an aid that may confuse or mislead the mariner into situations where the non-functioning aid is more dangerous to navigation than no aid at all. In these cases, immediate information dissemination and corrective action within 24 hours is usually desired, as well as any other considerations deemed appropriate. The effective coordination of the different aids to navigation functions is essential in successfully responding to and reducing discrepancies.

Administrative personnel and program managers need information about aids and aid systems in order to

continually review their effectiveness in meeting both the needs of the mariner and budget constraints, their justification as a necessary part of the overall system, and their maintenance and operation in conformance with established policies. Information is used by administrative staffs to coordinate aid responsibility assignments and maintenance schedules among servicing units. Procurement and technical personnel need special types of information relating to aid performance in order to evaluate the best types or combinations of types of equipment. This task is complicated due to the complex and peculiar characteristics of most aid components. Yard personnel have need for similar information about buoys and the performance of aids to navigation boats. The Aids to Navigation School utilizes information with regard to personnel errors to emphasize training against such mistakes in the future. In order to correct and prevent discrepancies, operating units need the support of logistics units to insure a sufficient supply of spare equipment and components is on hand or readily available to meet potential discrepancies as well as routine servicing requirements. Because of the uncertain nature of discrepancies, timely information about hardware replacements is important to supply managers in attempting to determine desirable purchase quantities. In carrying on aids to navigation operations, personnel of servicing units have, almost without exception, been kept fully occupied in doing their job. These duties have left little

if any time for intensive review of each aid or groups of aids under their responsibility. This is rightly so, because the Commanding Officer and other key personnel of a buoy tender, for example, spend many long hours on the bridge, buoy deck, or in the engineroom doing their jobs while engaged in hazardous operations near dangerous waters. One mistake such as a navigational one and operations are over. Thus the information system should enable servicing personnel who complete and review the work report to do so accurately within time constraints. Moreover, the information developed from the system should help servicing personnel in maintaining and operating their aids, and where possible prevent aid discrepancies due to oversights.

In describing specific provisions of the SANDS System in 1970, Booz, Allen indicated:

"...a fully operational and adequately funded and staffed program should provide for:

Verification and refinement of planned servicing intervals, scheduling of optimum unit servicing trips by keeping track of expected component life on each aid planning of material requirements, and allocation of support facilities for the servicing of A-to-N equipment;

Analysis of the A-to-N system in order to assess the reliability of the system and individual aids and aid components within the system, evaluation of alternative mixes of aids, and review of the support system requirements;

Accurate identification and inventory of A-to-N equipment, and accurate and timely cataloging of aids for both internal Coast Guard use and external use by mariners, charting agencies, etc.;

Input to simulation model of the A-to-N system;

Identification of weak areas where research and engineering emphasis should be concentrated."²⁵

B. THE PRESENT SYSTEM

The Aids to Navigation Work Report (CG-4429), which is the basic source of raw data, is prepared by Coast Guard units at the scene during the time an aid is serviced. The present content and format of the work report has remained essentially unchanged since its inception. Required information includes the description and condition of an aid, reason for the work, work performed, and component, equipment, and aid inventory information. In addition to providing information, this report becomes a legal and historical record of the aid and, as an official document, the Aids to Navigation Work Report can be admitted as evidence in a court of law.

A detailed discussion of the present work report assumes some familiarity with its format. A blank of the present Aids to Navigation Work Report, revised May 1969, is provided as Figure 6 for this purpose.

Instructions and codes used in preparing the Aids to Navigation Work Report are contained in Appendix D to the 1964 Aids to Navigation Manual (CG-222). Appendix D, which is referred to as the SANDS Manual, also provides rules and reference material for operation of the entire SANDS System. The work report is formed with an original and two

²⁵ Servicing System for Short-Range Aids to Navigation,
p. 74.

DEPARTMENT OF THE ARMY
TRANSFORMATION
U.S. COAST GUARD
CG 4425 Rev 5-69

AIDS TO NAVIGATION WORK REPORT (DO NOT TYPE)

PART I																									
1 AID NAME																									
2 AID CLASS																									
3 AID DESCRIPTION																									
4 LIGHT LIST																									
5 AID IDENTIFIER																									
6 WORK SITE																									
7 LIGHT PIN NUMBER																									
8 BUOY SERIAL NO.																									
9 LAMP																									
10 OPTIC																									
11 AMP																									
12 SERIAL NO.																									
13 SERIAL NO.																									
14 SERIAL NO.																									
15 SERIAL NO.																									
16 RESERVED																									
17 FOG SIGNAL																									
18 BOTTOM																									
19 HAND PILE																									
Card column 1																									
1 Routine																									
2 Seasonal Change																									
Card columns 3-5																									
3 Routine																									
4 Routine																									
5 Routine																									
Card columns 6-8																									
6 Routine																									
7 Routine																									
8 Routine																									
Card columns 9-11																									
9 Routine																									
10 Routine																									
11 Routine																									
Card columns 12-14																									
12 Routine																									
13 Routine																									
14 Routine																									
Card columns 15-17																									
15 Routine																									
16 Routine																									
17 Routine																									
Card columns 18-20																									
18 Routine																									
19 Routine																									
20 Routine																									
Card columns 21-23																									
21 Routine																									
22 Routine																									
23 Routine																									
Card columns 24-26																									
24 Routine																									
25 Routine																									
26 Routine																									
Card columns 27-29																									
27 Routine																									
28 Routine																									
29 Routine																									
Card columns 30-32																									
30 Routine																									
31 Routine																									
32 Routine																									
Card columns 33-35																									
33 Routine																									
34 Routine																									
35 Routine																									
Card columns 36-38																									
36 Routine																									
37 Routine																									
38 Routine																									
Card columns 39-41																									
39 Routine																									
40 Routine																									
41 Routine																									
Card columns 42-44																									
42 Routine																									
43 Routine																									
44 Routine																									
Card columns 45-47																									
45 Routine																									
46 Routine																									
47 Routine																									
Card columns 48-50																									
48 Routine																									
49 Routine																									
50 Routine																									
Card columns 51-53																									
51 Routine																									
52 Routine																									
53 Routine																									
Card columns 54-56																									
54 Routine																									
55 Routine																									
56 Routine																									
Card columns 57-59																									
57 Routine																									
58 Routine																									
59 Routine																									
Card columns 60-62																									
60 Routine																									
61 Routine																									
62 Routine																									
Card columns 63-65																									
63 Routine																									
64 Routine																									
65 Routine																									
Card columns 66-68																									
66 Routine																									
67 Routine																									
68 Routine																									
Card columns 69-71																									
69 Routine																									
70 Routine																									
71 Routine																									
Card columns 72-74																									
72 Routine																									
73 Routine																									
74 Routine																									
Card columns 75-77																									
75 Routine																									
76 Routine																									
77 Routine																									
Card columns 78-80																									
78 Routine																									
79 Routine																									
80 Routine																									
Card columns 81-83																									
81 Routine																									
82 Routine																									
83 Routine																									
Card columns 84-86																									
84 Routine																									
85 Routine																									
86 Routine																									
Card columns 87-89																									
87 Routine																									
88 Routine																									
89 Routine																									
Card columns 90-92																									
90 Routine																									
91 Routine																									
92 Routine																									
Card columns 93-95																									
93 Routine																									
94 Routine																									
95 Routine																									
Card columns 96-98																									
96 Routine																									
97 Routine																									
98 Routine																									
Card columns 99-101																									
99 Routine																									
100 Routine																									
101 Routine																									
Card columns 102-104																									
102 Routine																									
103 Routine																									
104 Routine																									
Card columns 105-107																									
105 Routine																									
106 Routine																									
107 Routine																									
Card columns 108-110																									
108 Routine																									
109 Routine																									
110 Routine																									
Card columns 111-113																									
111 Routine																									
112 Routine																									
113 Routine																									
Card columns 114-116																									
114 Routine																									
115 Routine																									
116 Routine																									
Card columns 117-119																									
117 Routine																									
118 Routine																									
119 Routine																									
Card columns 120-122																									
120 Routine																									
121 Routine																									
122 Routine																									
Card columns 123-125																									
123 Routine																									
124 Routine																									
125 Routine																									
Card columns 126-128																									
126 Routine																									
127 Routine																									
128 Routine																									
Card columns 129-131																									
129 Routine																									
130 Routine																									
131 Routine																									
Card columns 132-134																									
132 Routine																									
133 Routine																									
134 Routine																									
Card columns 135-137																									
135 Routine																									
136 Routine																									
137 Routine																									
Card columns 138-140																									
138 Routine																									
139 Routine																									
140 Routine																									
Card columns 141-143																									
141 Routine																									
142 Routine																									
143 Routine																									
Card columns 144-146																									
144 Routine																									
145 Routine																									
146 Routine																									
Card columns 147-149																									
147 Routine																									
148 Routine																									
149 Routine																									
Card columns 150-152																									
150 Routine																									
151 Routine																									
152 Routine																									
Card columns 153-155																									
153 Routine																									
154 Routine																									
155 Routine																									
Card columns 156-158																									
156 Routine																									
157 Routine																									
158 Routine																									
Card columns 159-161																									
159 Routine																									
160 Routine																									
161 Routine																									
Card columns 162-164																									
162 Routine																									
163 Routine																									
164 Routine																									
Card columns 165-167																									
165 Routine																									
166 Routine																									
167 Routine																									
Card columns 168-170																									
168 Routine																									
169 Routine																									
170 Routine																									
Card columns 171-173																									
171 Routine																									
172 Routine																									
173 Routine																									
Card columns 174-176																									
174 Routine																									
175 Routine																									
176 Routine																									
Card columns 177-179																									
177 Routine																									
178 Routine																									
179 Routine																									
Card columns 180-182																									
180 Routine																									
181 Routine																									
182 Routine																									
Card columns 183-185																									
183 Routine																									
184 Routine																									
185 Routine																									
Card columns 186-188																									
186 Routine																									
187 Routine																									
188 Routine																									
Card columns 189-191																									
189 Routine																									
190 Routine																									
191 Routine																									
Card columns 192-194																									
192 Routine																									
193 Routine																									
194 Routine																									
Card columns 195-197																									
195 Routine																									
196 Routine																									
197 Routine																									
Card columns 198-200																									
198 Routine																									
199 Routine																									
200 Routine																									

DISTRICT COPY

copies with interleaved carbons. At the time an aid is serviced the aid description, characteristics, and components are entered by hand where applicable, using direct reading codes from the SANDS Manual.²⁶ Normally only changes in this information need to be entered as this data is pre-printed based upon the last report. If an aid requires servicing more than once within a short period, the preprinted new form most likely will not be on hand, and all of this information must be filled in. The work reason, work completed, condition of an aid, and cause of condition are entered using check marks. Servicing data, aid position, and general remarks are completed in long hand. Upon completion and signing of the report, the original is forwarded promptly by mail to the District Aids to Navigation Branch Office. The first copy is to be filed by the unit with primary responsibility for the aid, usually the unit that serviced the aid. If a secondary unit serviced the aid, the first copy is forwarded to the primary unit. The second copy is to accompany repairable defective components returned to a support base or depot. If the second copy is not so used, the SANDS Manual indicates it is to be destroyed.

²⁶To describe an aid's characteristic in Part I, Item 10 for example, the number code "404" is used to indicate a flashing light of 0.4 second duration, showing a flash every 4 seconds. This description is referred to as a FL4(0.4) characteristic. The letter "G" indicates that the color of the light is green.

Aids to Navigation Work Reports received at district offices are reviewed and, if required, returned to units for appropriate verification or correction. Data from certain portions of each work report are entered onto punched cards, which are identified as updating cards or work performance cards. At the end of a month, the cards are divided into two categories and forwarded to Commandant Data Systems Division (GCDS). Transactions cards are made up of routine updating cards and work performance cards, while correction cards are previously transmitted transaction cards that have been corrected. Commandant (GCDS) edits and processes the cards, revising the Headquarters Master Record File. Data not conforming to SANDS Manual codes and procedures are rejected and turned over to Commandant Aids to Navigation Division (GWAN) who has overall responsibility for the operation of the SANDS System. Rejected data are reviewed and may be returned to District Commanders for correction.

Quarterly, and Aids to Navigation Assignment List (CG-4500) is prepared and used locally by District Offices. This list contains unit schedules for servicing, recharging, and relieving aids assigned to them. It is used as a tool in revising schedule dates in consideration of emergencies and unscheduled trips. Annually, at the end of March, the Aids to Navigation Assignment List is prepared for and sent to primary and secondary servicing units and a copy is

forwarded to Commandant (GWAN). This list serves as a catalog responsibility list and authorized equipment list for each servicing unit, as well as a complete listing for secondary units in the case of emergencies.

The Quarterly Report of Operation of Aids to Navigation (Program 03844C) is designed to produce periodic aid inventory reports and certain aid servicing statistics. This report is prepared at Headquarters utilizing SANDS master and history files, and may be run for any time period that is designated to the program by a control card. Results of the program are divided into four tables that contain information for each district followed by a summary for the entire Coast Guard. Table I includes aid inventory information for each basic type of aid including a total for the beginning of the period selected, number established and disestablished, and a total for the end of the period. Table II reports an analysis of work performed, aid operations including the number of visits to each type of aid, and the total and average time on site for the period selected. Table III examines visit information and separates visits into routine and discrepancy classifications. Discrepancies are further divided into three categories: 1) reported-found to be actual, 2) reported-found to be false, and 3) discovered by the reporting unit. Table IV provides similar information to Table III but excludes environmental hazards such as weather, ice, collision, and vandalism. The Quarterly

of Operation specifically emphasizes visit information in order to examine the impact of servicing policies in reducing the cost of maintaining and operating aids.²⁷

Special SANDS inventory information (SANDS Inventory Utility Program) is available from three data sources, Headquarters Master File (Program 03824C), Headquarters History File (Program 03828C), and District Terminal Master File (Program 03836C). This additional information developed from the SANDS System similarly to the Quarterly Report of Operation, may be used as a guide for supply and support units, engineering personnel, and any other personnel with duties related to Aids to Navigation. Thus personnel responsible for primary battery management, the Power Section of Commandant Ocean Engineering Division (GEOE), might desire information pertaining to primary batteries.

Figure 7 depicts the flow of data and information in the present SANDS system.

Since its original implementation only minor permanent changes have been made to the SANDS reporting system. The following lists contain dates and substance of those changes applying to the Aids to Navigation Work Report and the SANDS Manual

Aids to Navigation Work Report Changes

March 1967	The report form was changed to reflect transfer of the Coast Guard to the Department of Transportation.
------------	---

²⁷Operating Instructions for Quarterly Report of Operation of Aids to Navigation (Program 03844C), pp. 1-4.

Aids to Navigation Management Information System for United States Coast Guard




FIGURE 7

May 1969

Block 83 of the report form, "Primary Cause of Failure" was modified so that an entry here was required "for all discrepancies" in lieu of "for equipment only."

Provision was made for entering a Fog Detector type and serial number.

Provision was made for a separate entry to include Bottom Description characteristic, and the charted depth of water.

July 1971

Use of Block 30, Part I, was eliminated because the risk level classifications (Urgency Codes) generated by an aid non-functioning were determined to be unrealistic. These classifications reflected The Shore Units Plan (CG-380) and consequently were designed solely as guidance for shore units in maintaining aids closeby.

SANDS Manual Changes

18 Mar 1968

The Manual was amended to reflect changes in the distribution of the completed report and give instructions on standby or duplicate components that would require use of a second work report set.

26 Sep 1969

The Manual was completely revised to correspond to changes in the work report and update new codifications for recent additions of navigational aid hardware.

C. AREAS FOR FURTHER DEVELOPMENT

In addition to the comments about the SANDS System previously described, Booz, Allen reported in their 1970 studies:

"SANDS is a management information system that has been partially operational for over 3 years. The system was developed by the Coast Guard to assist its managers and operators in the persormance of their A-to-N responsibilities. SANDS is a necessary and workable system. However, its full potential has not been realized, primarily because of delays in installation of proper computer facilities at both District Offices and Headquarters and a lack of trained personnel and financial resources.

With support from higher levels of management, including the availability of adequate funds and trained personnel the SANDS Program could be developed into an effective management tool."²⁸

As a result of the Booz, Allen studies and subsequent evaluation the Coast Guard determined that:

"The increased reliability of buoy components has made the probability of an aid discrepancy due to equipment failure in less than 12 months very small. Analyses of buoy discrepancies have shown that the more frequently buoys are visited, over and above that dictated by sound engineering maintenance practices, the higher the probability of a discrepancy. Some causes of buoy discrepancies can be prevented by routine maintenance, however, discrepancies which are caused by uncontrollable events such as weather, collisions, vandalism, etc., cannot be prevented by routine visits. Routine maintenance, therefore, has an impact in the prevention of only certain types of discrepancies, and visits to buoys for unnecessary component inspections can no longer be justified in view of the costs associated with such visits."²⁹

1. An Experimental Aids to Navigation Work Report

In connection with this policy change, the Quarterly Report of Operation of Aids to Navigation was developed to closely analyze servicing visits and related procedures. The program is well designed for this purpose; however, the usefulness of the information generated is limited by the present deficiencies in the SANDS reporting system. Supporting this contention is the fact that an Aids to Navigation Work Report form with major revisions is currently

²⁸Booz, Allen Applied Research, Inc., Servicing System for Short-Range Aids to Navigation, pp. 73-74.

²⁹This passage was contained in COMDTNOTE 3261, 31 July 72, which was officially cancelled when its basic content was included in Book One, "Administration," Aids to Navigation Manual (CG-222-1).

being used on an experimental basis in the First Coast Guard District. This form features a plain language format in lieu of partial coding used with the present report. Some check boxes are included to enable easier preparation. Inspection and service note areas have been added so handwritten messages can be computer printed on subsequent forms. A general comment area has been retained. Probably the most significant change is the addition of last date, projected date, and service interval used spaces for various types of services to be performed. Where scheduled dates are listed in Julian date format in the present report, these and other dates are in month, year format in the experimental form. On the revised form certain sections are different in the unit and district copies, such as the last date, projected date and service interval used spaces which appear only on the unit copy.³⁰

While the Quarterly Report of Operation is being used to meet most administrative, engineering, and supply personnel needs, at the present time only the Annual Aids to Navigation Assignment List is being used on a regular basis to feed back information to servicing units. Briefly, servicing units get back from the system what they put in along with any predetermined equipment authorization changes. Since the routine servicing frequency of aids has been

³⁰Aids to Navigation Bul. (May-December 1973), p. 4.

extended while the feedback information provided to servicing units has remained limited, a special information system, which would monitor SANDS data and feedback to servicing units information found to be questionable about aids under their responsibility, seems to hold much potential. Thus, simple oversights could be detected and potential discrepancies or unnecessary waste of aid hardware could be avoided. The chances are good for reducing the overall number of visits to a particular aid so monitored. This special information system would be most useful in monitoring lighted buoys because they present the most opportunities for non-functioning.

Although the present SANDS System is working and provides ample information to most personnel, full potential has yet to be developed. This is understandable since the system has been in operation for less than 10 years and the Coast Guard has been faced with budget constraints in developing the Management Information System.

2. Examination of Present Aids to Navigation Work Report

Since the work report serves two very important functions, as a primary data source and a legal record, its format and content must be designed to meet both objectives. In addition SANDS files provide an effective management tool for operating units, especially those using the remarks section for their own use. Taking into consideration the author's familiarity with the present form from past experience an attempt was made to identify common errors or omissions in required information on the SANDS Report. For this purpose

reports for 25 lighted buoys from the Thirteenth CG District were examined. The reports were for calendar year 1972-1973. Because most work reports in the Thirteenth District included extra information in the general remarks section, such as closed circuit battery voltage readings, they were judged to be at least as complete as the average report completed in the Coast Guard. This data sample consisted of a total of 79 visits to service aids, consequently 79 work reports were examined. A detailed listing of the errors detected is contained in Appendix B; a brief summary of the major types of errors is provided in Table IV.

TABLE IV

Summary of Major Types of Errors Detected in 79 Work
Reports for the 13th CG District 1972 - 1973

<u>Absolute Frequency</u>	<u>Type of Error</u>
14	Missing entries
14	Incomplete entries
6	Incompatible entries; content errors
5	Incorrect entries; used wrong codes, checked wrong blocks, redundant entry
<hr/> 39	
Total	

Since there were a total of 39 errors observed, there was an average of one error for each two work reports examined. In some cases up to three errors were noted in the completion of one report. While only some of the errors would result in erroneous information in the Master Record File maintained at Headquarters, all errors and inconsistencies would tend to discredit the Coast Guard should the report be produced as evidence in a court.

In assessing these results it must be noted that it is extremely difficult to interpret information that is inconsistent or incomplete, especially when examined after a year or more has elapsed. An attempt was made to resolve those entries or lack of entries in question through discussion with the Thirteenth District Aids to Navigation Office. In a few situations where the inconsistencies could not be resolved, the information presented reflects the author's opinion, with due consideration being given to the overall nature of the report and any comments in the remarks section.³¹

Errors frequently encountered involved the indication of component replacement in the aid description section while replacement of the component in the work performed section was left blank (unchanged) or vice versa. Other entries or missing entries appeared to be simple oversights. Some errors could be directly attributed to the use of SANDS

³¹These procedures were also used in verifying or determining the data processed throughout this project.

Manual alphanumeric "direct reading" codes which have little association with the type of data they represent. For example, the code '47', meaning primary cause of failure was the lampchanger, was used by mistake for code '46' meaning the flasher was the primary cause of failure of an aid.

3. Important Information not Being Provided For with the Present Work Report

Several types of important information are not being provided for in the content of the present work report. For power units or batteries there is only a scheduled recharge data. This information was adequate when the present form was first implemented because secondary batteries, predominantly in use then, were normally recharged every six months. With the permanent change to primary batteries in 1969, power units were used with various lamp and flasher characteristic combinations for flexible periods of up to three years. Thus, there is a need to indicate the last recharge (replacement) date and the service period used. This interval, which is the expected total useful operating life for a primary battery or combination of primary batteries, is referred to as the Rated Battery Discharge Time (RBDT).

In many cases it was extremely difficult to determine the reason a component was replaced because the present form does not provide for such indication. Exceptions to this problem occur only when a particular component replaced is also the aid's primary cause for failure or, when amplifying replacement comments are entered in the remarks section.

Of the work reports examined, a substantial number indicated the loss of components during servicing or the salvaging of buoys previously washed ashore during a storm. This information, which is optional, was entered in the remarks section. By providing for uniform recording of this information, better analysis of aid hardware consumption and performance can be attained.

D. SUGGESTED IMPROVEMENTS

1. Aids to Navigation Work Report Modifications

Many of the SANDS errors detected can be reduced or avoided, and additional desirable information can be included by redesigning the Aids to Navigation Work Report.

a. Power Units (Batteries)

It is projected by COMDT (GEOE) that batteries will account for over 2.5 million dollars in expenditures during Fiscal Year 1975. Most power units and batteries are purchased directly by servicing units and bases from McGraw Edison Company and Union Carbide Corporation. Batteries come preactivated or are activated using prepackaged electrolyte at the time they are placed in service. Because of recent problems with the user-activated variety, increased use has been made of the preactivated type, which now comes in transparent cases. Batteries begin deteriorating while on the shelf and thus a 12-month maximum storage period has been designated to preclude retention of batteries beyond the expiration of their specified shelf life. Once placed in

service "all batteries shall be capable of providing sufficient voltage for a period of three years or RBDT, whichever is less, starting from the end of recommended shelf life, without maintenance, providing the electrical loading characteristics ...have not been exceeded."³² The average in-service failure rate of batteries and power units is not to exceed 5% per year. Because power units and batteries are particularly vulnerable to manufacturing errors, strict quality control testing and procedures are specified. In order to disseminate the necessary information required by units in servicing aids and obtaining an accurate RBDT for each assigned aid, Commandant Instruction 10500.32A (Primary Batteries for Aids to Navigation) was promulgated. This directive consolidates applicable sections of the Battery Specifications (GEOE Purchase Description 191A), Flasher Specifications (GEOE Purchase Description 187B), and Visual Signalling (GEOE Report CG-250-37). By redesigning the present Aids to Navigation Work Report this valuable information could be readily recorded and fully utilized:

(1) Because the present form does not indicate when the aid was last recharged and the RBDT used, if the scheduled recharge date is calculated in error it is likely that either the batteries will be replaced unnecessarily early or the batteries will be exhausted when normally due and result in unexpected discrepancy visits. It is essential

³²Purchase Description No. 191A, "Primary Batteries for Aids to Navigation," Office of Ocean Engineering, U.S. Coast Guard, paragraph 3.15.4.

to know the last date of replacement because the RBDT can be automatically determined for any specific power capacity, lamp, and characteristic combination. For power units and batteries it would also be desirable to indicate the source of the information used in determining the RBDT because of policy changes regarding safety or correction factors and occasional equipment changes.

(2) It is normal procedure to check a battery's condition by visually inspecting the vital parts such as carbons, zincs, and breathing apparatus, and by taking measurements such as closed circuit voltage readings. If space were provided for this information on the report form, expected life curves of actual battery performance in the field could be obtained for various operating conditions. While most units apparently take such readings, they are not generally being recorded.

(3) The experimental Aids to Navigation Report Form, developed as a result of the research by Booz, Allen and subsequent determination by the Coast Guard leading to present testing in the First Coast Guard District, allows for some of these changes. Space for entries for last date of battery replacement, interval used (RBDT), and projected date of replacement are provided on the new form. However, the district copy must also contain this information if batteries or power units are to be monitored by data processing.

b. Lampchangers

The number of successful changes or rotations performed by a lampchanger are possibly more important to its useful life than time in service. . However, at present no recording is being made of these successful changes although the information is readily available. Usually the standard CG-6P Lampchanger is left in the #1 position, which has a red mark. If upon the next visit the operating lamp is found normal in the #5 position, 4 successful changes were executed. If this lamp is burned out, 4 successful changes and 1 unsuccessful change were performed.

c. Reason for Replacing Component

Probably the most difficult information to determine from the present work report is the reason a particular component was replaced. In many cases the primary cause of failure has nothing to do with another component being replaced. By providing for the recording of this information more accurate analysis of component usage and consumption could be obtained. According to an article appearing in the Aids to Navigation Bulletin,³³ COMDT (GEOE) has determined that a significant number of flashers and lampchangers were erroneously being replaced at the expiration of their two-year warranty period. If component replacement reasons were indicated on the work report, misperceptions of replacement policies could be readily identified.

³³Aids to Navigation Bulletin (December 1972 - April 1973), p. 11.

d. Continuity of Reports

While there is no evidence to support the assumption that work reports are inadvertently mishandled or lost in the main, it is possible that these events could occur. Neither the present nor the experimental forms have provision for consecutively numbering reports, whereby missing report forms could be noted.

e. Exchange of Reports by Servicing Units

For many years aid servicing responsibilities have been assigned to primary and secondary units. Normally most servicing of a particular aid has been accomplished by the primary unit. Occasionally the responsible secondary unit has serviced the aid in order to correct a discrepancy while the primary unit was not in the area. This included the completion and appropriate distribution of the work report. The current SANDS system does not provide for copies of work reports to be retained by the secondary units. Recently the primary-secondary concept has been modified in that mobile Aids to Navigation Teams (ANTS) and buoy tenders have a dual responsibility for jointly assigned aids, as aid servicing functions not requiring the larger buoy tender are accomplished by the less expensive ANT. It is important that these units provide each other with copies of work reports for jointly assigned aids so each unit is kept fully advised of aid status.

f. Equipment Lost or Damaged During Servicing

The present work report contains no provisions for indicating equipment lost or damaged during servicing. Some servicing units have made local use of this information, which can be indicated in the remarks section. For example should a buoy be known to be sunk near its aid position and never located, knowledge of this information would be important to subsequent aid servicing in the same area. During extremely cold weather a power unit is given rough handling such that it is damaged. A lantern assembly fully equipped with other visual signal components is accidentally lost over the side or damaged during servicing; while working a buoy moorings part and are lost. These and other instances occur frequently, but only after several months have elapsed is their loss picked up in a survey report. Some of this information never enters the present SANDS System. By providing for the recording of such information on the work report, better and more timely estimates of actual aid hardware usage can be obtained.

g. Report Format

A distinct format advantage of the experimental form over the present form is the use of a plain language format by the reporting unit. This emphasizes the use of abbreviations and acronyms easily associated with the type of data they represent. This feature not only would eliminate common direct reading code errors, but also would permit

easier and more rapid completion of the report. Well designed check mark entries can save time and promote accuracy.

2. Selection of Additional Processing Method

The current SANDS data processing system uses Common Business-Oriented Language (COBOL). The primary output, Quarterly Report of Operation of Aids to Navigation (Program 03844C), provides a detailed source of periodic aid inventory information and servicing statistics. It was designed in view of the fact that the greatest cost in operating aids to navigation lies in personnel, vessels, and facilities rather than aid hardware. Through statistical analysis of the visits made to aids it was hoped that A-to-N operating costs could be reduced.

In order to supplement the current Quarterly Report of Operation, it was desired to find a simple method for statistical analyses and a way to monitor short range aids to navigation, in particular lighted buoys and their power units. According to recent Quarterly Reports of Operation, the vast majority of all discrepancy visits occur because of power or battery failures. The monitoring process would be primarily designed to detect inadvertent SANDS reporting errors at the field level and simple oversights at all levels. Thus enhancing aid reliability and decreasing the number of controllable discrepancy visits. Discussion of a new data processing method is timely because the Coast Guard is anticipating consolidation of its present EDP equipment with other DOT agencies within the next year.

The search for such a data processing method led to the selection of the Statistical Package for the Social Sciences (SPSS),³⁴ one of several statistical analysis packages in existence. SPSS is a system of prepackaged program (sub-programs) that can process raw data in a variety of tasks under any sequence of circumstances. It was especially designed to process survey questionnaires which are, in certain ways, similar to SANDS Reports. Input data can be read from disk, tape, or data cell files in addition to punched cards. Besides being flexible and inexpensive, SPSS is simple to use.

The SPSS system can accommodate up to 500 variables. Features include, one-way frequency distributions, with descriptive statistics and histograms, crosstabulation between two or more variables, correlation, multiple regression, scalogram, and factor analyses. SPSS has provisions for user written internal programs. Optional data modification routines allow one to select variables meeting specified circumstances, a feature especially well suited for SANDS searching procedures. It has provisions for taking a random sample from a file, so that if one is maintaining a file of considerable size, a smaller random sample can be taken

³⁴ SPSS was developed by two social scientists, Norman Nie and Dale H. Bent, at Stanford University in 1965. Together with C. Hadlai Hull, they co-authored Statistical Package for the Social Sciences in 1970. The National Opinion Research Center at the University of Chicago currently maintains and distributes SPSS. The package can be purchased for under \$1,000.00 by nonprofit organizations.

to produce statistically significant results at a reduced cost. Another feature involves a weighing process whereby estimated population parameters can be assigned to each case. Because SPSS enables value labels of up to 20 characters in length to be associated with each variable value, this processing method appears well designed to handle a plain language work report format should this form be implemented.

E. DATA ORGANIZATION

1972 and 1973 SANDS data of 100 lighted buoys located within the Thirteenth Coast Guard District were transferred to standard 80-column punch cards. Each visit to an aid was considered a case and contained data on description, status and service, and analysis cards. There were a total of 402 visits made to the 100 buoys. Routine visits without component replacement were consolidated with other data yielding a final file of 268 cases. Light List (LL) numbers of the aids examined were taken from the 1973 Light List, Volume III, Pacific Coast and Pacific Islands and compared with the work reports. Codes contained in the SANDS Manual and on the work reports were used where possible. Because additional questions were desired reflecting some of the changes mentioned for the work report, appropriate codes were assigned for these new variables. A listing of all codes with explanations is contained within the programs. Testing and rearranging of format and types of data were accomplished with two initial runs. Subsequent runs of the

100 buoys were deemed suitable for the selected studies. The computer program listings and related output have been appended.

In order to accurately analyze battery performance, last recharge data information prior to 1972 was obtained from the Thirteenth CG District. This was necessary because of the problems in determining RBDT's for primary batteries as discussed above. Complicating the situation was the fact that policy changes for RBDT safety and correction factors were implemented since 1972. Thus by using the present standard RBDT policies contained in COMDTINST 10500.32A and indicating the previous known recharge data in 1970 or 1971, an accurate measure of power unit performance was accomplished. The only exception to this was that COMDTINST 10500.32A does not contain RBDT information for nonstandard characteristics and the few aids operating with nonstandard flashers were eliminated from this analysis.

F. APPLICATION OF A MODIFIED MANAGEMENT INFORMATION SYSTEM

The primary purpose of this discussion is to illustrate how utilization of an additional processing method similar to that already presented and a modified aids to navigation work report, including some of the suggested changes, can be effectively combined to improve the operation of the Short Range Aids to Navigation Subsystem. A secondary purpose is to illustrate the complexity of the procedures involved in determining RBDT.

On August 1, 1973, Commandant Instruction 10500.32A was promulgated in order to disseminate essential information relating to primary batteries for aids to navigation. A previous directive in this series was cancelled. Enclosure (2) of this instruction contains a service guide for primary batteries including tables of Rated Battery Discharge Times for approved power, lamp, and characteristic combinations. This directive is an official source from which units can obtain RBDT's for their lighted aids. The instruction was issued with six errors present in the Tables of Enclosure (2), four involving lamp life and two involving incorrect RBDT's. One of the RBDT errors (2000 ampere-hour battery capacity with .55 amp lamps and a QKFL 0.3 characteristic) was almost a year in error: 1 year and three days (1003) in lieu of 1 year and 358 day (1358). On August 5, 1974, Change One to the basic instruction transmitted changes correcting the original six errors.

When consideration is given to the many tables and sources of information contained in COMDTINST 10500.32A, it is easy to understand how such errors occurred. In order to demonstrate the complexity of an RBDT computation and verify that 1358 is the correct basic RBDT for the combination in question, a detailed description of the procedures and calculations involved has been presented in Appendix C. As a result of this computation it was verified that the basic RBDT for subject component is 723 days (1358 Julian days). Servicing units relying upon the RBDT Tables and replacing power units for a

2000 a-h power capacity, .55 amp lamps, and QKFL (0.3) characteristic combination between August 1973 and August 1974, would possibly use the wrong RBDT (1003) in calculating the replacement date. When change one was issued, it indicated to make pen and ink number corrections to the tables and thus it is possible that the real impact of the error was not even understood then because no written explanation was included.

In addition to determining appropriate RBDT's at the time of power unit replacement, servicing units will occasionally need to adjust the RBDT period. Interim adjustments are necessary when an aid's lamps or flasher are replaced with components of a different lamp size (load) or characteristic respectively.

There are two different approaches in compensating for the simple oversight errors involved in the situations previously described. These approaches are SANDS monitoring and SANDS searching. SANDS monitoring of lighted buoy power units could be accomplished if the present work report were modified to include at least the last power unit replacement date. Given this replacement date and determining the RBDT based upon the existing battery capacity, lamp, and characteristic combination, a correct scheduled power unit replacement date can be projected for each buoy monitored through use of SPSS data-transformation cards. Periodically by use of SPSS data-selection cards the scheduled power unit replacement date for each buoy as indicated on the SANDS

report can be compared with the related correct projected date. Depending upon the prespecified variance range desired, buoys not within the tolerance so specified would be identified. For example, a buoy is equipped with a 2000 a-h power capacity, .55 amp lamps, and a QKFL (0.3) characteristic. Upon being recharged and having a scheduled recharge date determined in error due to the error in COMDTINST 10500.32A, if prespecified monitoring limits were 90 days, this buoy would be readily identified because the error involved was 355 days. Once this buoy is identified and subsequently examined closely, it would be determined that an error existed and other buoys equipped with an identical power-lamp-characteristic combination might also be scheduled for power unit replacement in error. At this time SANDS searching procedures could then be utilized through SPSS data-selection cards to actually identify all buoys with the wrong scheduled replacement date. It is possible that all the process need entail would be to select the desired combination of circumstances using SPSS and then, in association with other processing methods, have letters automatically printed and addressed to the units in need of the particular information.

This application of SANDS monitoring could also be used periodically to identify all lighted aids with questionable scheduled recharge dates in order to prevent discrepancies. For that matter, SANDS monitoring could be set up to detect all types of potential errors or omissions as well. It

could also be used by administrative or procurement personnel to search out aids with special circumstances to effectively disseminate information about them.

The following illustration is a summary of potential application of SANDS monitoring and searching routines. A detailed explanation and analysis is contained in Appendix D.

Through a simulated SANDS monitoring routine using buoys located in the Thirteenth CG District, it was determined that an aid, Coos Bay Channel Lighted Buoy 18 (LL 1279) had a scheduled recharge date not falling within the limits specified. Through SANDS searching routines all aids with identical power, lamp, and characteristic combinations were located. Three such aids with potential errors were found but only Coos Bay CH LB 18 actually contained an RBDT error. This was 33.3% of the aids under examination. In effect, the error involved early replacement of a power unit and approximately \$195 worth of unused battery capacity forgone.³⁵ If a modified SANDS Report for Coos Bay CH LB 18 had been monitored periodically, the error could have been discovered before the power unit was replaced. Similarly, once the error had been discovered through SANDS monitoring or other means, COMDT (GEOE) could have searched out all remaining

³⁵For this analysis presented in Appendix D, the 30-day cloud cover factor applying solely to the 13th District was not included in order to make a more reasonable extension of potential impact service-wide.

aids with the potential error using SPSS to prevent potential early recharging of other aids under identical circumstances.

According to SANDS data of January 1974, there were approximately 115 buoys in service equipped with 2000 a-h power capacity, .55 amp lamps, and QKFL (0.3) flasher characteristic combination. Assuming that 33.3% of all such buoys were erroneously recharged under similar circumstances, the amount of battery capacity wasted would be about \$7,475.00. Even if only 10% of these buoys were recharged early, the expected waste of battery capacity alone would be over \$2,200.00, or more than twice as much as the cost of the SPSS package itself.

There were also 616 light structures with the flasher characteristic-lamp combination of QKFL (0.3) and .55 amp respectively. Since some of these aids were powered by 3000 a-h battery combinations, no error was involved in them. However, since the error was not detected or corrected for over a year, it is likely that a significant number of the light structures equipped with 2000 a-h battery capacity were also recharged early. When considering that the \$7,475 potential loss is related to just one instance of simple oversight at the administrative and field levels, the magnitude of all potential undetected errors for all battery powered lighted aids, taking into account special discrepancy correction or unnecessary visits, can be fully appreciated.

Besides being especially vulnerable to nonfunctioning, lighted buoys are being maintained by servicing units that have been increasingly burdened in getting the job done, due to rapid turnover of personnel and other unfavorable circumstances such as the sharply higher fuel costs. In addition the servicing frequency of aids has been recently extended. By modifying the management information system and SANDS Report so that lighted buoys could be monitored, not only field personnel but other personnel as well would stand to benefit from the new flow of information in carrying on their aids to navigation functions.

IV. EXAMINATION OF AIDS TO NAVIGATION RELIABILITY, HAZARD, AND FAILURE RELATIONSHIPS

A. PURPOSE

The purpose of this study is to demonstrate the usefulness of the SPSS processing method in examining the frequencies of various causes for Short Range Aids to Navigation malfunctions, and the potential for determining hazard, failure, or error prone combinations or circumstances of components.

B. AREAS OF EXAMINATION

Information to be examined during the study were divided into the following four general areas:

1. Routine inventory information and visit statistics.
This provides a population data base for subsequent analysis.
2. Major causes for nonfunctioning and or replacement (relief) of each aid and selected aid components.
3. Significant trends among the following specific combinations of components and or circumstances indicating failure, hazard, or error propensities.
 - a. Buoys relieved due to weather or collision as a function of aid location and time of the year.
 - b. Buoys relieved due to various reasons as a function of percentage of expected total useful

operating life of power units consumed at the time of replacement or retirement.

- c. Buoys relieved for other than routine reasons as a function of buoy size.
- d. Power units replaced due to environmental hazards, personnel errors, or manufacturing errors as a function of aid location, buoy size, vent valves, light characteristic, power source, lampchanger, flasher, sound signal, daylight control, bottom description, bridle size, swivel size, first chain size, and Rated Battery Discharge Time (RBDT).
- e. Percentage of power units lives realized at the time of replacement or retirement as a function of aid location, buoy size, vent valves, light characteristic, power source, lampchanger, flasher, sound signal, daylight control, bottom description, bridle size, swivel size, first chain size, RBDT, and power units replaced for various reasons.
- f. Flashers replaced due to environmental hazards, personnel errors, or manufacturing errors as a function of buoy size, lantern, lampchanger, flasher, and sound signal.
- g. Flashers replaced due to collision identified by Aid Light List (LL) Number.

- h. Lampchangers replaced due to environmental hazards, personnel errors, or manufacturing errors as a function of lamp size (type) and sound signal.
 - i. Daylight controls replaced due to environmental hazards, personnel errors, or manufacturing errors as a function lantern color, lantern and sound signal.
 - j. Lanterns replaced due to environmental hazards, personnel errors, and manufacturing errors as a function of aid location, lantern, and sound signal.
 - k. Failure of lamps of various sizes of a particular aid as a function of aid location, buoy size, lamp size, lantern, and sound signal.
 - l. Replacement of entire moorings due to preventive maintenance (normal wear) or weather as a function of aid location and bottom description.
4. Special types of information or questions.
- a. What is the actual percentage of expected total useful operating lives consumed by power units at the time of replacement or disposal due to lighted buoy withdrawals, discontinuances, or temporary relief by unlighted buoys?
 - b. Identification of buoys and moorings lost or damaged while on station or being serviced, due to being adrift, washed ashore, sunk, or reported as missing.

The region being examined is the Oregon Coast and the Columbia River. It is noted that the coastal environment which includes several bay, harbor, and inlet areas, is normally subjected to severe storm conditions throughout the winter season (Figure 8). The Columbia River, which separates the states of Oregon and Washington, is navigable for ocean-going vessels for about 100 miles. Because of its great importance to commerce, transportation, and recreation, the Columbia River is at times a place of very heavy marine traffic.

As a result of the facts described above, it would be expected that weather would have significant influence upon the maintenance of aids along the Oregon Coast. It would also be reasonable to expect that the severity of weather would contribute to a higher than servicewide average percentage of in-service failures due to manufacturing errors, since this environment represents some of the most adverse circumstances under which aid components are required to operate. Presumably collisions with passing vessels would be a factor in the operation of buoys along the Columbia River.

Considering this environment, it was felt that weather, power unit failure, and collisions would be the major causes of aid failure, in that order. For buoys it was believed that location and type of operation would determine the frequency of reliefs, times found or reported off station and subsequently lost, missing, or salvaged. Due to previous

U.S. Coast Guard Photograph with caption from *Piloting, Seamanship, and Small Boat Handling*, Chapman, p. 287.



Left: Tillamook Rock Lighthouse, standing a mile offshore at Tillamook Head, Oregon, is one of the most exposed stations on the Pacific Coast. The protecting glass of the light, 133 feet above sea level, has been smashed several times by stones driven by great storm waves. Landing at this station is often difficult, if not impossible.

FIGURE 8

seasonal weather patterns, it was anticipated that lighted buoys operating on a permanent (remaining in service year round) basis at exposed locations, would be relieved for other than routine reasons primarily during the months of November through March. For the replacement or failure of components, it was expected that aid location would be the dominant factor since location would dictate whether the aid the components were installed upon was exposed, protected, and or subject to heavy marine traffic. In subsequent trial analyses this expectation was very strongly evidenced. Therefore, it was decided to examine component and operation data as a function of aid location in order to determine combinations significantly prone to problems. Despite the presence of environmental hazards (location), it was hypothesized that buoy size and the presence and type of sound signals would be a significant factor upon overall component performance, that RBDT intervals and related power capacities would have an impact upon percentage of power unit consumption realized, that vent valve configuration would be important to power unit performance, that sound signals would have a substantial, detrimental effect upon lamps, and that lantern color (red or green) and type (plastic or glass) would have an effect upon daylight control failures. It was expected that smaller lamp sizes would result in a greater relative percentage of lamp failures than larger sizes. Of all visual signal components, it was hypothesized that solid-state flashers would be replaced the fewest total

number of times (excepting projects), due to their strict design, lack of moving parts, watertightness, and projected long lives. It was believed that the CG-6P Lampchangers (six-place) would perform better than FU-1297 (four-place) Lampchangers, and that both types of lampchangers would be adversely affected by sound signals. It was also anticipated that appendages (moorings) would be rigorously tested along the coastal region, especially, chain of 1 7/8" size, which is the largest size that can be accommodated by the mechanical chain stopper. Finally, it was suspected that less than 50% of potential power unit lives were being consumed at the time of replacement or disposal, in view of all factors presented concerning this environment.

Two SPSS computer runs were conducted for this study. Both runs utilized a file containing data on 402 visits made to 100 buoys during calendar years 1972 and 1973. Routine visits without component replacement were consolidated with other data, yielding a final file of 268 cases. The first analysis provided visit and inventory data base statistics, and organized aid hardware replacement data for specific replacement reasons, namely routine servicing, improper installation, water damage, defective, collision, weather or vandalism etc. Due to the number of possible reasons for replacement and the limited amount of data examined, the reasons for replacement categories were consolidated into nine categories for a second analysis, the consolidated categories being: routine servicing, environmental hazards,

technical-administrative errors, personnel errors, failures caused by another component, convenient or conjunctive servicing, manufacturing errors, corrosion, and projects, directives, or experimental testing. Specific analyses were conducted in both studies. The programs and related outputs, which are contained in the Appendices, include comments with explanation of the procedures and coding utilized throughout the study, SANDS Manual and Work Report codes have been used where applicable.

C. SUMMARIZATION OF RESULTS

A summary tabulation of key data base statistics is provided in Table V. Tabulations of all data base statistics are contained in Computer Output (before recoding) pages 11 to 57. One aid was discontinued during 1973. Since there were a total of 402 visits during the two year study period, an average of about two visits per year were made to each aid. Of interest was the observation that three aids were visited 9 times and three other aids 8 times. All six of these aids were located along the Oregon Coast, with most of the visits being related to environmental damage. Of importance to ensuing analyses was the fact that 35% of all aid locations were classified as Exposed Sea Coast (Oregon Coast), and 30% as Protected River (Columbia River). Thus a combined total of 65 buoys were located in the areas expected to be most vulnerable to environmental or traffic hazards.



Summary of Key Data Base Statistics for 100 Lighted Buoys and their Components
 Located in the Thirteenth Coast Guard District as of December 31, 1973.

<u>Type of Component or Operation</u>	<u>Number and Percentage of Total Population</u>	<u>Percentage of Total Population at Locations Classified as Exposed Sea Coast Protected River</u>
Operation:		
Permanent	91	77
Seasonal (no replacement)	4	100
Seasonal (with winter replacement)	4	100
Location:		
Exposed Sea Coast	35	100
Protected River	30	0
Buoy Size:		
10 x 39	5	14.3
9 x 38	9	20.0
9 x 32	10	20.0
8 x 26	35	45.7
7 x 17	11	0
7 x 15	13	0
6 x 20	9	0
Construction:		
Welded, standard pockets, large vents, radar reflector	72	-

* One buoy was discontinued during 1973.

TABLE V (Continued)

Vent Valves			
1 per pocket, balls installed	78	97.1	73.3
1 per pocket, no balls installed	18	0	26.7
Light Characteristic:			
Fl 4 (0.4)	73	60.0	83.3
QKFL (0.3)	13	8.6	16.7
Light Color:			
Green	17	17.6	16.7
Red	34	17.1	46.7
White	48	74.3	36.7
Lamp Size			
1.15 amp 12 volt	49	100	10.0
0.77 amp 12 volt	47	0	90.0
Lantern-Optic			
155 mm Acrylic Plastic	79	68.6	96.7
200 mm Pressed Glass	16	31.4	0
Power Unit Capacity and Type:			
60E2 (6000 a-h, two 30E2 Units)	12	25.7	6.7
30E2 (3000 a-h)	4	5.7	0
20S1 (2000 a-h, two 10S1 Units)	7	8.6	3.3
20E2 (2000 a-h, two 10E2 Units)	36	34.3	40.0
10S1 (1000 a-h)	4	2.9	6.7
10E2 (1000 a-h)	28	5.7	40.0

TABLE V (Continued)

Lampchanger:			
CG-6P (six-place)	36	42.9	40.0
FU-1297 (four-place)	62	54.3	60.0
Flasher:			
CG-181	72	80.0	60.0
C-R S-1065 SS	22	11.4	36.7
Sound Signal:			
None	56	11.4	90.0
Whistle, 4 Ball	22	51.4	3.3
Bell, 1962 Tapper Arrangement	7	11.4	6.7
Daylight Control:			
C - For use with Clear Lanterns (Glass and Plastic)	47	74.3	36.7
R - For Colored, Plastic Lanterns	39	17.1	56.7
B - For Colored, Glass Lanterns	11	8.6	3.3
Bottom Description:			
Sand	51	68.6	36.7
Mud	24	2.9	53.3
Rock	9	14.3	10.0
Bridle Size:			
1 1/4" x 15'	63	45.7	73.3

TABLE V (Continued)

Swivel Size:			
1 3/4" Second Class	66	51.4	76.7
2" First Class	23	48.6	3.3.
First Chain Size:			
1 1/4"	27	0	66.7
1 1/4"	36	25.7	30.0
1 5/8" and larger	35	74.3	3.3

It was noted from flasher data base statistics that 73 flashers were of the FL 4 (0.4) characteristic, 1 flasher of the FL 2.5 (0.5) characteristic, and none were of the FL 6 (1.0) characteristic. This finding was found to be indicative of lighted buoys and light structures service-wide during the same period:

"In 1966 three simple, slow flash characteristic (flashing every 2.5, 4, and 6 seconds) were designated for standard use in minor aids to navigation. This standardization was intended to provide the mariner with a uniform, easy to identify system while simplifying the selection of equipment to meet operational requirements. Equal use of these three characteristics would maximize the ability of mariners to differentiate between nearby aids. However, in the past six years the Flashing 4 second characteristic has become so common that it is now found on 87% of all simple, slow flashing aids.

The popularity of the Flashing 4 second characteristic is due to its low 10% duty cycle. The Flashing 2.5 and 6 second characteristics have duty cycles of 20% and 16.7% respectively, with proportionately higher battery consumption. To encourage greater use of these latter characteristics their flash lengths have been shortened to produce more favorable duty cycles. The new FL 2.5 (0.3) and FL 6 (0.6) characteristics are economically competitive with the FL 4 (0.4) characteristic and should therefore see greater use without imposition of required use quotas."

In addition nine flashers were found to be nonstandard, and aids equipped with these flashers were not included in the power unit life analyses as standard RBDT intervals for such flashers are not available.

Table VI contains the major causes for aid and aid component malfunctions, as well as other significant reasons for component replacement. As expected, weather and collisions, dominated the primary causes for aid malfunctions,

TABLE VI

Summary of the Primary Causes for Aid and Aid Component Malfunctions
And Other Significant Reasons for Replacement

Aid - Component	*Denotes Recoded Category Major Cause of Nonfunctioning		Total Number of Times Replaced	
	Other Reason Replaced		Other Reason Replaced	
All aids	Weather	41 times	False alarm	8 times
	Collisions	19 times	Third consecutive	
	Power Unit Failure	13 times	similar discrepancy	12 times
Buoys (relieved)	Weather	23 times		66
	Collisions	5 times		
	Corrosion	2 times		
Power Units (replaced)	Environmental Hazards*	37 times	Routine Servicing	41 times
	Weather	22 times		124
	Collisions	7 times	Convenience-Followup	18 times
	Personnel Errors*	15 times		
	Manufacturing Errors*	10 times		
		(8.1%)		

TABLE VI (Continued)

Flashers (replaced)	Environmental hazards*	40 times	No indicated reason	94
	Weather	20 times	17 times	
	Collisions	12 times		
	Manufacturing Errors*	7 times (7.5%)		
	Improper Installation	2 times		
Lampchangers (replaced)	Environmental hazards*	40 times	No indicated reason	91
	Weather	20 times	17 times	
	Collisions	12 times		
	Personnel Errors*	19 times		
	Manufacturing Errors*	7 times (7.7%)		
Daylight Controls (replaced)	Environmental hazards*	36 times		85
	Manufacturing Errors*	6 times (7.1%)		
Lanterns (replaced)	Environmental hazards*	40 times		87
	Manufacturing Errors*	1 time (1.1%)		
Lamps (all failed) (replaced)	Manufacturing Errors*	7 times	(Burned out or Defective Only)	165
	Improper Installation	1 time		
Entire Moorings (replaced)	Weather	23 times		35

41 and 19 cases occurring respectively. Buoys were relieved due to weather 23 times, with 95.7% of these occurrences taking place at exposed sea coast locations. The percentage of power unit life expended at the time of relief in such locations was always less than 40%. In 12 instances, weather was the primary cause of failure for at least three consecutive discrepancy visits to the same buoy. When considering the time of year associated with the relief of buoys due to weather, a definite pattern was detected as follows:

10 reliefs during the period January to March 1972

1 relief during April 1972

1 relief during November 1972

8 reliefs during the period January to March 1973

2 reliefs during December 1973

It should be noted that some of the reliefs indicated for January, were actually the result of buoys being washed ashore during December. These occurrences subsequently led to the search, testing and evaluation of new mooring employment methods to reduce the loss of aid hardware and frequency of buoys off station.³⁶ Table VII reflects optional data

³⁶One of the methods was evaluated with four lighted buoys at coastal bar locations utilizing a shock sinker system. This concept provided for a shock sinker which would occasionally be lifted off the bottom due to buoy movement and a heavier submerged sinker weighing 9 tons. The mooring included 1 5/8" chain between the bridle and the shock sinker and one shot of 1 7/8" chain between the two sinkers. CCGDTHIRTEEN Operation Order 094/72 of 9 June 1972.

provided in SANDS Report remarks sections concerning such losses.

TABLE VII

Statistics Concerning Buoys Reported As Adrift,
Washed Ashore, or Missing

Buoys either lost or not salvaged	7 times
Buoys located and or salvaged	13 times
Buoys never located	1 time
Moorings lost; includes above	24 times

After obtaining mixed results with special mooring appendages, the District changed the operation of several lighted buoy locations (two located in Yaquina Bay) which had experienced repeated problems in maintaining buoys on station, from permanent to seasonal. This procedure involves withdrawing the lighted buoy during part of the year. Sometimes the lighted buoy is replaced with an unlighted buoy. This system has become routine for the Great Lakes during the winter, when no or little marine traffic exists. As a result, significant savings of aid hardware were realized during the winter-spring season of 1974.

Eighty percent of the buoys relieved due to being involved in collisions with passing vessels were located on the Columbia River, 3 and 1 instances respectively. Also, 10 of the 12 flasher replacements resulting because of collisions took place along the Columbia River, but only

one buoy was involved in more than one incident, that one being involved twice. Thus no aids which should be considered collision prone were identified in this study.

An unexpected and surprizing observation was the fact that 17 flashers were replaced for no indicated reason of a total of 94 replaced during the two year period. This observation will be further discussed in Part B (AREAS OF FURTHER RESEARCH). The results shown in Table VI also indicate that lampchangers were replaced for no indicated reason the same number of times.

Examination of power units replaced due to personnel errors revealed that the light characteristic, QKFL (0.3), is associated with an unusually high number of such errors. While the FL 4 (0.4) characteristic was found on 73 aids and related to 60% of the personnel errors, the QKFL (0.3) type found on only 13 aids accounted for more than 33% of all power units replaced for this reason. It was also recalled from Chapter III Part F (APPLICATION OF A MODIFIED MANAGEMENT INFORMATION SYSTEM), that the QKFL (0.3) characteristic was involved in RBDT Table errors; possibly the consequences of this problem are stronger than originally anticipated. It is also likely that personnel are more familiar with the most common FL4 (0.4) type and its related RBDT intervals than the less frequently used QKFL (0.3) characteristic.

The study of power unit replacements afforded a good comparison of the magnitude of hazard associated with location. For example, 73% of the power units replaced due to environmental hazards were in service at exposed sea coast locations, more than twice the percentage of aids at these locations. Protected River sites accounted for only 16% of the replacements, while about half of the aids were at this class of location. This suggests the clear dominance of weather over collision as an environmental hazard. In looking at the impact of buoy size upon power unit replacement due to environmental hazards, buoy sizes 10 x 39 and 8 x 26 were compared. As shown in Table V, although 14.3% of buoys located along the exposed sea coast were 10 x 39 buoys, a much smaller percentage (2.7%) were associated with these events. 8 x 26 buoys accounted for 62.2% of such replacements although comprising only 45.7% of the buoys in exposed sea coast locations. Thus the larger size buoy appears to be better able to cope with its environment. No meaningful comparison of percentage of power unit life realized could be made with these two buoy sizes as 3 out of 5 of the 10 x 39 type were equipped with nonstandard flashers. Unexpectedly, lighted buoys with built in whistles of the 4 ball variety were involved with only 27% of the power units replaced due to environmental hazards despite comprising over 51% of the lighted buoys in exposed sea coast locations. It may be that its unique design built into the buoy tube provides a good platform upon which to

ride out rough seas, with less harm being done to components installed.

Surprisingly, all 10 power units replaced due to manufacturing errors were linked to the FU-1297 (four-place) lampchanger. This type of lampchanger was installed on 62 buoys but only 19 of those were at exposed sea coast locations. While the CG-6P (six-place) lampchanger is known to be of better design, no trend could be detected with lampchangers replaced for various reasons and the type of lampchanger. It may be that the FU-1297 has a special effect upon batteries, such as heavy drainage.

Overall power unit performance was better than the predicted 50% estimate, with the mean percentage of expected total useful operating life consumed at the time of replacement or retirement for 96 power units examined being 63.82%. A brief summary of the special procedures utilized in conducting this analysis is contained in Appendix E. The range for this datum was 3% to 121%, with one additional aid identified with the unusually high percentage of 164%. Upon further examination it seemed likely that an error involving last replacement date information or a SANDS oversight existed, although such a long life is not impossible.

While only 34% of all types of lanterns were colored red, this same color was attributed with 67% of the daylight controls replaced due to manufacturing errors. The fact that a lantern was fabricated with glass or plastic appeared to have little effect upon these daylight control malfunctions.

As was anticipated from previous servicewide evaluations, the larger size 1.15 amp lamps were more reliable than the smaller 0.77 amp lamps. The 1.15 amp lamp type comprised 49% of the lamp size population and was installed on all exposed sea coast buoys. Yet despite this exposure, 57.1% of all lamp failures (all lamps failed), were with 0.77 amp lamps. However, there was no clear relationship between lamp failures and the presence and type of sound signals.

D. AREAS FOR FURTHER RESEARCH

1. Reliability Model Building

As shown in Figure 9, a reliability block diagram for a typical lighted buoy, failure of any one component (except for a lamp, provided a good spare is available and the lampchanger is functioning), means the buoy has failed. While it is a matter of opinion whether failure of a day-light control, leading to 24 hour per day operation of the buoy's visual signal system, constitutes a failure, eventually the resulting extra battery drain will result in battery failure if not corrected. If all components are new, the component with the least minimum time to failure (again excepting lamps), will most likely be the cause of an aid nonfunctioning. A full analysis of reliability however, can be quite difficult because of the complex nature and interdependence of components.

2. Sensitivity Analysis of Flasher Inventory Procedures

It may be recalled from the summarization of results

Reliability Block Diagram for a Typical Lighted Buoy




FIGURE 9

presented in Section 3, that a finding of special interest concerned the replacement of 17 flashers for no indicated reason. It was also noted that lampchangers were replaced for the same unknown reason the same number of times.

Because these findings indicated a significant problem, this situation was further examined. A logical explanation for many of these instances appears to have been found:

Contributed by: Commandant (GEOE)

"...The guarantee expiration date shown on the nameplate of certain aids-to-navigation equipment indicates that date after which the manufacturer is no longer required to repair or replace a defective unit at no cost - it is not an indication as to when the unit will no longer operate reliably. The design life of flashers, lampchangers and similar aids-to-navigation equipment is many times the guaranteed period. These equipments must be used until failure rates indicate that continued use is no longer justified. New equipments should be placed into service as soon as practicable so as to take full advantage of the manufacturer's repair or replacement guarantee."³⁷

Contributed by: Aids to Navigation School

"The original predicted half-life of the CG-181 was 13 years. This means that at the end of 13 years, 50% of the flashers would still be operating. It was based on the known reliability of the components used in the flasher. However, we now have an appreciable amount of operating data indicating that the half-life appears to be 20 years. There is no test that can be applied to a solid state flasher to determine when failure is about to occur. A large portion of failures that do occur during the half-life will be in the infancy of the flasher and replacement is covered by guarantee. Therefore, the long life expectancy of the majority of flashers that survive infancy reduces the need to place an arbitrary age limit on the flasher. Flashers recovered from damaged or destroyed aids should be replaced if they

³⁷Aids to Navigation Bulletin (December 1972 - April 1973), p. 11.

have lost their watertightness, or have been subjected to physical damage."³⁸

The solid state flasher is designed as a long life, nonrepairable item emphasizing simplicity and maximum reliability. The circuitry of the CG-181 Flasher is contained in a factory sealed watertight metal case weighing under 2 1/2 pounds. Each flasher is constructed to withstand shock and vibrations incident to service on lighted buoys. The flasher has built-in electronic reversed polarity and short circuit protection features in addition to standard external electrical connections. The reversed polarity feature prevents damage that might otherwise be sustained when batteries occasionally reverse their polarity internally. The short circuit feature not only prevents damage but also will prevent a flasher from falsely functioning if all connections are not made. Thus the flasher is designed to preclude improper installation due to simple oversights. Each flasher is guaranteed against failure for two years from the last date of shipment of the last flasher procured under a particular contract. As specified, the failure rate of all flashers in service is not to exceed 5% per year. At this failure rate and after 10 years of operation for example, 59.8% of the flashers that were originally installed would still be in service.

In an attempt to further highlight the extent of still-born and infancy failures of flashers, SANDS data from the

³⁸Aids to Navigation Bulletin (April-June 1970), p. 16.

Ninth, CG District for 18 lighted aids and 20 flashers were analyzed. For these aids, solid-state flashers were installed during 1967, 1968, or 1969. Their performance was observed each season through the 1973 winter withdrawals. The consolidated results shown in Table VIII were obtained from the above data. A detailed listing of the results is contained in Appendix F.

TABLE VIII

Summary of Solid State Flasher Performance for 18 Lighted Aids to Navigation in the Ninth Coast Guard District (1967-1973)

<u>Flasher Status</u>	<u>Frequency</u>	<u>Range (years)</u>	<u>Average Time In Service</u>
Remaining in service at the end of 1973 or functional but temporarily out of service due to buoy withdrawals.	13	4.29 - 6.63	5.36 years
Replaced due to failure	2	0.16 - 0.98	0.57 year
Replaced due to projects or other reasons not related to the flasher	5	1.58 - 5.89	3.87 years

While only 18 aids were examined due to time constraints, a brief review of other data for the same area and period indicated similar patterns. Results substantiated the contention that if a flasher is to fail, it most likely will do so within the two year warranty period. Otherwise the flasher will probably remain in service until unable to survive environmental hazards or personnel errors.

These results indicate that present flasher inventory policies may be suboptimal. A study in this area for the CG Supply Center was recently conducted.³⁹ It would appear that further research, such as flasher sensitivity analyses considering the overall Aids to Navigation Mission and related factors, is also warranted.

³⁹Development of an Optimal Inventory System for Selected Aids to Navigation Components of the United States Coast Guard Supply System, R. Castler, J. Kissinger, and R. Pokress, George Washington University, O.R. 291. July 1974.

V. CONCLUSIONS AND RECOMMENDATIONS

A. MODIFICATION OF THE AIDS TO NAVIGATION MANAGEMENT INFORMATION SYSTEM

A need exists to modify the current Aids to Navigation Management Information System. Supporting this contention are findings made in 1970 by the management-consultant firm, Booz, Allen Applied Research, Inc., concerning the Short Range Aids to Navigation support and servicing systems. As a result of the Booz, Allen studies and subsequent Coast Guard evaluation, several Aids to Navigation Management Information System (SANDS System) modifications have been implemented, including the Quarterly Report of Operation of Aids to Navigation (Program 03844C). This report is designed for the purpose of extracting aid inventory and visit statistics data, and even though it has become an effective management tool, its usefulness is limited by the present SANDS Reporting System. The Aids to Navigation Work Report (CG-4429), which is the heart of the reporting system, has remained essentially unchanged since its inception in 1967. This is so despite the fact that many changes in aids to navigation policy, development, and hardware have occurred. In addition to being the primary source of raw data, the work report becomes a legal and historical record for each aid. Errors detected in any part of a report produced as evidence in a court, discredit the entire report and Coast Guard. Supporting the contention that the present

work report needs modification is the fact that an Aids to Navigation Work Report with major revisions is being currently tested on an experimental basis.

The findings presented in Table IV (Summaries of Major Types of SANDS Errors Detected in 79 Work Reports for the Thirteenth CG District 1972-1973) indicated an average of one error for each two work reports examined. Furthermore it was noted that inconsistent, incomplete, or missing information which were frequently encountered, hampered the interpretation of reports to the extent that questionable data had to be resolved with the Thirteenth District. It was determined that many of the errors detected could be attributed to either the content or format of the current SANDS Report. Based on the examination of the present and experimental work reports, several important provisions and changes require consideration for inclusion in future work report revisions.

1. Power Units and Batteries

The addition of space for information on last date of replacement or service, projected date of next service, and service interval to the SANDS reporting form is desirable, as then the service period could be easily determined from the report form. The mere addition of data concerning the last replacement date would enable verification of projected service dates through SANDS System monitoring by using existing report inventory information and known

related intervals. For power units or batteries there is only a scheduled recharge date. This information was adequate when the present form was first implemented because secondary batteries, predominantly in use then, were normally recharged every six months.

However this data is especially important for the primary batteries in use today, since their long and flexible service interval requires complicated computations and multiple table lookups in order to compute the projected replacement data. In addition, power units and battery failures are the primary cause of most aids to navigation discrepancies.

2. Exchange of Reports by Servicing Units

In view of the anticipated increased utilization of Aids to Navigation Teams (ANTS) in servicing aids on a dual basis with other units (tenders), the need for these operating units to provide each other with information of work performed to jointly assigned aids exists.

3. Work Report Format

A distinct format advantage of the experimental form over the present form is the use of a plain language format by the reporting unit. This emphasizes the use of abbreviations and acronyms easily associated with the type of data they represent. This feature not only would eliminate many common errors, but also would permit easier and more rapid completion of the report.

While the experimental version of the SANDS report allows for desired format changes and inclusion of last date, service interval, and projected date information on the unit copy, this latter feature must also be provided on the district copy. This is necessary so that such information is available for data processing, thus enabling SANDS monitoring and searching routines, which are especially desirable for lighted buoy power units, one of the most prevalent component problem areas.

A need exists to further exploit the potential information available in SANDS data. A particular need for feedback of useful information to field units exists. Two current information sources available to field units are the Annual Aids to Navigation Assignment List (CG-4500) and informal Aids to Navigation Bulletins. The Aids to Navigation Bulletins are an information source of immense value to all personnel involved with aids to navigation duties. It is suggested that a cumulative index for Aids to Navigation Bulletins be included with each addition. This would facilitate more effective utilization of this valuable source of communications by providing an easy way to rapidly identify all articles appearing in various bulletins that deal with a particular subject.

Because of recently extended servicing intervals, a special information system which would monitor SANDS data and feed back questionable information to servicing units

appears to be of much unrealized value. Thus, simple oversights could be detected and potential discrepancies or unnecessary waste of aid hardware could be avoided.

Based upon the illustration provided in Chapter III (APPLICATION OF A MODIFIED MANAGEMENT INFORMATION SYSTEM), it is believed that there is sufficient evidence in support of SANDS monitoring and searching procedures to warrant their inclusion into the SANDS System. Justification appears to stem in appreciation of the magnitude of all potential undetected errors involving battery powered lighted aids alone.

It is recommended that consideration be given to evaluating some sort of system to monitor routine data to identify exceptional circumstances. Modification and implementation could be undertaken by Headquarters on a temporary and experimental basis. This program would be designed for the approximate 3927 Lighted Buoys in service at the present time, the short range aids most vulnerable to malfunctions. Such a program would partially compensate for simple oversights, time constraints, high turnover rate of personnel and the recently extended aid servicing intervals. The conception of this limited program is very timely because the Coast Guard's electronic data processing facilities are to be consolidated and modified in the near future and feasible since the additional processing method presented (SPSS) is inexpensive and easily utilized in conjunction with other computer program languages. .

B. STATISTICAL PACKAGE FOR THE SOCIAL SCIENCES (SPSS)

The results set forth in Chapter IV, demonstrates the performance of the SPSS data processing method in examining the frequencies of various causes for Short Range Aids to Navigation (SRAN) malfunctions. SPSS demonstrated considerable potential for determining hazard, failure or error prone combinations or circumstances of components. The cost of this statistical package is approximately \$1000.00 to non-profit organizations.

It is recommended that this package, or a similar one capable of SANDS searching and monitoring functions, be procured in association with Department of Transportation EDP facilities consolidation and modification.


C. FUTURE RESEARCH

This project has been envisioned as a preliminary investigation into an area in which a good deal of further investigation is warranted. Many of the longer term goals in the overall research have been met only in a cursory fashion due to time constraints. Because of the complex nature and interdependency of aids to navigation and aid components, a thorough evaluation of all of the issues and questions presented would require extensive and detailed analysis. Therefore this project should be considered as a beginning rather than as an end.

In order to thoroughly evaluate the issues and question discussed in this preliminary research, it is suggested that

a team of personnel possessing expertise in information system design and statistical analysis be designated. Possible additional methods for such analysis could include reliability model building with provisions for component dependence, sensitivity analysis of flasher inventory policies, and decision tree modelling for buoy positioning procedures.

APPENDIX A: NUMBER OF VARIOUS SHORT RANGE
AIDS IN SERVICE ON 31 DEC. 1973



Source: Quarterly Report of Operation of Aids to Navigation
31 December 1973

APPENDIX B: SUMMARY OF ERRORS IN 79 AIDS TO NAVIGATION
WORK REPORTS FOR 25 LIGHTED BUOYS LOCATED
IN THE THIRTEENTH COAST GUARD DISTRICT

<u>Absolute Frequency</u>	<u>Part</u>	<u>Section</u>	<u>Comment</u>
3	I	6	Daylight controls were found in- operative such that the buoy's visual signal system was operating day and night; battery scheduled recharge date remained unchanged.
1	I	General	A component indicated as replaced in the work performed section appeared as unchanged in the des- cription section because the serial number remained the same.
3	I	18	While replacing colored glass lanterns with acrylic lanterns, the daylight control for colored glass lanterns was not indicated as changed. In these cases it was later determined that the daylight controls had been correctly changed but that the appropriate entries were omitted.
3	I	General	A component indicated as replaced in the work performed section appeared as unchanged in the des- cription section because the new types were not compatible with with remaining components.
1	I	6	Schedules were not revised.
1	I	1	Content of aid name was in error.

1	I	6	Rated Battery Discharge Time (RBDT) used for lamp, flasher and battery capacity was more than 90 days in error as reflected in the recharge date.
1	I	General	Some entries in the Aid Description section on a hand-filled form were missing.
5	III	General	Entry of aid condition was missing.
1	V	General	Redundant entries such as checks for replaced entire moorings and replaced second chain on same report.
4	V	General	Component indicated as changed in the description section was not checked as replaced in the work performed section.
2	V	General	Checked wrong blocks as adjacent blocks were inadvertently checked.
2	VI	83	The wrong number code was used as a primary cause of failure as indicated by components replaced and remarks.
6	VI	83	Entry in the primary cause of failure block was missing although discrepancy was checked as the work reason.
1	VI	84	An entry was made in the date and time CG informed block although the discrepancy was discovered by the reporting unit.

1	VI	85	The hour worked was missing.
1	VI	85	The year digit of the Julian date work performed was missing.
2	VI	82	The number of defective or burned out lamps replaced was not indi- cated although replaced lamps entry in the work performed section was checked.

39	Total
----	-------

***** GIVEN SPACE ALLOWS FOR 3 VARIABLES AND 1069 VALUES FOR CODEBOOK *****

```

VAR012 ('20E2','20S1','20J5','20S2','20U1','20E3')=2000)
THIS RECODE CARD PUTS ALL 2000 A-H POWER UNITS INTO ONE GROUP
THE FOLLOWING CARD ENABLES THE RPT FOR A COMBINATION TO BE
SELECTED. IN THIS MANNER EACH POTENTIAL DIFFERENT RMDT PERIOD
IS DETERMINED.
(VAR007 EQ 103 AND VAR009 EQ 52 AND VAR012 EQ 2000) VAR069 = 1358
(VAR007 EQ 404 AND VAR009 EQ 54 AND VAR012 EQ 2000) VAR069 = 2152
(VAR069 IS RMDT IN JULIAN DATE FORMAT - THE FOLLOWING CARDS CREATE
NEW VARIABLE VAR069 WHICH IS RMDT CONVERTED INTO DAYS
(VAR069 GT 2000 AND VAR069 LE 1365) VAR069 = (VAR069 - 1000) + 305
THE FOLLOWING CARD CREATES NEW VARIABLE VAR069 WHICH IS
THE SCHEDULED NEXT RECHARGE DATE FROM THE SANDS WORK REPORT
LESS THE JULIAN WORK DATE, OR THE ANTICIPATED LIFE OF THE
BATTERY AS SEEN BY THE SERVICING UNIT.
VAR069=VAR069-VAR051
NEW VARIABLES VAR069 AND VAR069R REFLECT ERROR ADJUSTMENTS TO
BE TOLERATED RESPECTIVELY.
(VAR069=VAR069+9)
VAR069R=VAR069-9)
THE FOLLOWING SELECTION CARD IDENTIFIES THOSE SCHEDULED NEXT
RECHARGE DATES THAT DO NOT FALL WITHIN THE LIMITS SPECIFIED.
(VAR069 GT VAR069R OR VAR069 LT VAR069R)
THE FOLLOWING VAG CRUSSTAUTION CARD IDENTIFIES ALL AIDS BY
LIGHT LIST NUMBER SELECTED AS BEING IN ERROR.

```


APPENDIX C: CALCULATION OF RATED BATTERY DISCHARGE TIME FOR
A POWER UNIT, LAMP, AND FLASHER COMBINATION
WITH 2000 A-H CAPACITY, .55 AMP LAMPS, AND A
QKFL (0.3) CHARACTERISTIC

Sources:

(A) The duty cycle for a QKFL (0.3) characteristic is the ratio of the total time during which the flasher allows current to flow to the lamp during one period to the duration of one period, or 0.30 ampere-hour/day. This duty cycle requirement for a QKFL (0.3) flasher is contained in section 3.15.1 of the Flasher Specification (Purchase Description No. 181B), and must not differ from that specified by more than 5% at temperatures of 0° - 125°F.

(B) From Figure 14 in Visual Signally, the average current in amperes during the time that the contacts are closed for a .55 amp lamp with a 0.3 second contact closure time is 0.639 ampere. This average current during a flasher period is corrected for the initial surge effect of low voltage (12 volt) lamps and a cold filament, when heavy current is drawn.

(C) It is current Coast Guard policy to base all daylight controlled RBDT computations on a standard 13-hour day or an average of 13 hours of darkness per day during a year.

(D) Flasher dissipation is the maximum allowable dissipation in ampere-hours, based upon 13 hours a day operation at 60°F as specified in Purchase Description 181B.

(E)* The winter correction factor ranges from 0 to 60 days: 0 days for service lives within cycles of 365-390 days, 721-750 days, etc.; 60 days in the 541-570 day cycle, etc.

* For aids at variance from standard conditions the following additional reductions in RBDT apply (the cloud cover factor for the Thirteenth District was used in the selected studies):

- (1) Heavier than thin average daily cloud cover

Districts 1, 3, and 9	15 days per year
Districts 13 and 17	30 days per year
- (2) Average nighttime temperature less than 30°F during the last 3 or more months of RBDT

	15 days per year
--	------------------
- (3) Average daytime temperatures over 80° for entire RBDT

	30 days per year
--	------------------
- (4) Daylight control shaded at sunrise or sunset

	30 days per year
--	------------------
- (5) Daylight control shaded at both sunrise and sunset

	60 days per year
--	------------------

Equations: (The basic equations are contained in COMDTINST 10500.32A).

Daily current consumption	=	(B) Average lamp current	x	(A) Flasher duty cycle	x	(C) Hours of Operations	+	(D) Flasher dissi- pation
---------------------------------	---	--------------------------------	---	------------------------------	---	-------------------------------	---	---------------------------------

Service Life = $\frac{\text{Battery capacity}}{\text{Daily current consumption}}$

RBDT = Service life - (E) Winter correction factor + any applicable correction factors due to nonstandard conditions at aid location

Calculations:

(B)	Average lamp current		.639 ampere
(A)	Flasher duty cycle	x	.30 amp-hour/day
(C)	Hours of Darkness	x	13 hours/day
		=	2.492 ampere-hour/day
(D)	Flasher dissipation	+	.274 ampere-hour
	Daily current consumption	=	2.766 ampere-hour/day
	Battery capacity		2000 ampere-hour
	Daily current drain	÷	2.766
	Service life	=	723 days
(E)	Winter correction factor	-	0 days
	Rated Battery Discharge Time	=	723 days or 1358 in Julian format

APPENDIX D: AN ILLUSTRATION OF SANDS MONITORING AND
SEARCHING

From one of the initial runs made to determine SANDS reporting errors it was discovered that one RBDT error in COMDTINST 10500.32A (Primary Batteries for Aids to Navigation) existed among the aids examined. The aid in question was Coos Bay Channel Lighted Buoy 18 (LL 1279). This buoy had been recharged on 3221 (August 9, 1973) or after COMDTINST 10500.32A was in effect but before the change was issued. The RBDT period of 1003 was used to determine the new scheduled recharge date of 4192 (July 11, 1974), unknowingly in error.* At the time the error was discovered by the author, the Thirteenth CG District Aids to Navigation Office was contacted to relay information to the unit involved in the error, hopefully before this aid was recharged. As it turned out the buoy had already been recharged on 4189 (July 8, 1974), but the next scheduled recharge date was corrected.

Through simulated SANDS monitoring explained in the program (located at the end of this Appendix), it was determined that Coos Bay CH LB 18 had a scheduled recharge date not falling within the limits specified. The limits could have been 90 days or any period desired. In this example only the 2000 ampere-hour power unit, .55 amp lamp, and QKFL (0.3) characteristic combination RBDT of 1358 was used.

* For the Thirteenth CG District, the cloud cover factor reduced the RBDT by 30 days.

Any other standard flasher lamp combination could be included in this process through the use of additional cards, one card per combination.

In order to search out remaining aids of this combination without using the scheduled recharge date condition, three SPSS data selection cards were used. Thus, all aids under these identical circumstances were located. By subdividing all aids contained in each Light List into a separate subfile for service-wide implementation, each Light List number of a subfile would be unique and pertain to only one aid.

Through SANDS searching routines it was discovered that three aids in the buoys examined were equipped with the specific power, lamp, and characteristic combination in question but only Coos Bay CH LB 18 (or 33.3%) actually contained an RBDT error. The cost of unused battery capacity for this aid was computed. The special 30-day cloud cover factor solely used in the Thirteenth District was not considered in order to make a more reasonable extension of potential impact service-wide.

Value of 2000 Ampere-Hour Buoy Power Unit Capacity
Not Utilized with Coos Bay CH LB 18

- (A) 2000 a-h power from Union Carbide is made up of two 1000 a-h (S10A) units. Fiscal Year 1975 cost of a 1000 a-h unit is \$205.60.*

* Because of shipping cost variations, battery costs are slightly higher for West Coast and nonCONUS CG Districts.

- (B) 2000 a-h power from McGraw Edison is made up of two 1000 a-h (ST-1010) units. Fiscal Year 1975 cost of a 1000 a-h unit is \$191.23.*
- (C) RBDT Actual 723 days (1358) - RBDT Used 368 days (1003) = 355 days.
- (D) If all batteries were UCAR:
 $2 \times 205.60 \times \frac{355}{723} = \202
If all batteries were Edison:
 $2 \times 191.23 \times \frac{355}{723} = \188
Assuming 50% of the units were UCAR and 50% of the units were Edison \$195 worth of unused battery capacity was forgone, for this aid alone.
- (E) According to SANDS data of January, 1974, there were approximately 115 buoys in service with the 2000 ampere-hour battery power unit, .55 amp lamps, and QKFL (0.30) flasher characteristic combination.
- (F) Assuming that 33.3% of the 115 buoys were recharged in error, the value of power unit capacities not utilized service-wide would have been as follows:
 $195 \times 115 \times .333 = \$7475.$
- (G) Assuming that only 10% of these service-wide buoys were recharged early:
 $195 \times 115 \times .10 = \$2242.$
- (H) Cost of SPSS is approximately \$1000.00.

* Because of shipping cost variations, battery costs are slightly higher for West Coast and nonCONUS CG districts.

APPENDIX E: PROCEDURES UTILIZED IN COMPUTING FOR POWER
UNITS, THE PERCENTAGE OF EXPECTED TOTAL USEFUL
OPERATING LIFE CONSUMED AT THE TIME OF REPLACEMENT OR RETIREMENT

In order to determine the actual average percentage of expected total useful operating life realized at the time of power unit replacement, several special procedures were required. On page 3 of the run (After Breakdown Recording), is the internal program which was utilized to accomplish this objective. Comment explanations have been included. The first step involved converting RBDT's into a total number of days. For example, an RBDT of 2152 would be converted by subtracting 2000 and adding 730 or a total of 882 days. The second step involved consumption determination or Julian work date less the last recharge date (not indicated on the present work report and obtained from pre-test period SANDS data in some cases), and converting the difference into days. In the third step, certain reasons for the termination of a power unit's use were recoded so that they would be included in the evaluation. These reasons included seasonal withdrawals, discontinuance of an aid, and lighted buoys temporarily replaced by unlighted buoys. The fourth and last step, created a new variable, VARPER, percent of expected power unit life consumed. This new variable was rounded to the nearest whole percent through an automatic rounding capability feature of SPSS. All applicable flasher-lamp-battery combinations were examined except for aids equipped with non-standard flashers.

APPENDIX F: RESULTS FROM EXAMINATION OF 20 SOLID STATE
FLASHERS FOR 18 LIGHTED AIDS TO NAVIGATION
IN THE NINTH COAST GUARD DISTRICT (1967-1973)

Aid Light List Number	Flasher Type	Flasher Serial Number	Light Charac- teristic	Julian Date Org. Installed	Julian Date Replaced Withdrawn or End of Period	Duration Of Service in Years
Flashers remaining in service at the end of 1973 or installed upon Aids withdrawn during the 1973 Winter Season, and functioning normally at the time temporarily taken out of service:						
2148	CG-181	9613	FL 4 (0.4)	68036	73357	5.88
2199	S-1065	3917	FL 6 (1.0)	68065	73357	5.80
2413	VAPAIR	800055	Mo. A.4,2	69102	73351	4.68
2423	CG-181	111795	Mo. A.4,2	68265**	73351	5.24
2450	S-1065	4006	FL 4 (0.4)	67110	73304	6.53
2458	VAPAIR	3893	FL 4 (0.4)	67116	73346	6.63
2470	CG-181	11829	Mo. A.4,2	68283	73311	5.08
2481	VAPAIR	800056	Mo. A.4,2	69113	73346	4.64
2483	S-1065	3577	FL 4 (0.4)	67198	73341	6.39
2498*	VAPAIR	800092	FL 2.5(.5)	69079	73271	4.53
2501	S-1065	4026	FL 4 (0.4)	68203	73341	5.38
2502*	CG-181	15902	EI 6 (3.0)	69260	73365	4.29
2504	CG-181	11975	FL 2.5(.5)	69100	73341	4.66
AVERAGE TIME IN SERVICE						5.3638
Flashers replaced due to projects or other reasons not related to the flasher:						
2423	VAPAIR	800094	Mo. A.4,2	69111	70323	1.58
2424	S-1065	3655	FL 4 (0.4)	67143	73103	5.89
2477*	CG-181	12242	FL 6 (1.0)	69224	73200	3.93
2485*	VAPAIR	800090	FL 6 (1.0)	68256	72281	4.07
2503	VAPAIR	80111	FL 6 (1.0)	68184	72149	3.90
AVERAGE TIME IN SERVICE						3.8740
Flashers replaced due to failure.						
2477*	CG-181	28790	FL 6 (0.6)	73200	73260	0.16
2485*	CG-181	23346	FL 6 (1.0)	72281	73275	0.98
AVERAGE TIME IN SERVICE						0.5700

* Denotes Light Structure. No mark indicates Lighted Buoy

** Flasher was used on a different Aid for the 1969 Season

FILE ATONAV13 (CREATION DATE = 01/14/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGOIST

VARIABLE VAR030 TOTAL NUMBER OF VISITS TO EACH AID,72-73

VALUE LABEL	VALUE	ABSOLUTE FREQUENCY	RELATIVE FREQUENCY (PERCENT)	ADJUSTED FREQUENCY (PERCENT)	CUMULATIVE ADJ. FREQ (PERCENT)
1 VISIT	1.	1	0.4	1.0	1.0
2 VISITS	2.	21	7.8	21.0	22.0
3 VISITS	3.	23	8.6	23.0	45.0
4 VISITS	4.	25	9.3	25.0	70.0
5 VISITS	5.	10	3.7	10.0	80.0
6 VISITS	6.	9	3.4	9.0	89.0
7 VISITS	7.	5	1.9	5.0	94.0
8 VISITS	8.	3	1.1	3.0	97.0
9 VISITS	9.	3	1.1	3.0	100.0
	0.	168	62.7	MISSING	100.0
TOTAL		268	100.0	100.0	100.0

COMPUTER OUTPUT

MEAN	4.020	STD ERROR	0.183	MEDIAN	3.700
MODE	4.000	STD DEV	1.826	VARIANCE	3.333
KURTOSIS	0.304	SKEWNESS	0.911	RANGE	8.000
MINIMUM	1.000	MAXIMUM	9.000		
VALID OBSERVATIONS -	100				
MISSING OBSERVATIONS -	168				

VALUE LABEL	VALUE	ABSOLUTE FREQUENCY	RELATIVE FREQUENCY (PERCENT)	ADJUSTED FREQUENCY (PERCENT)	CUMULATIVE ADJ FREQ (PERCENT)
AID DISCONTINUED	0	1	1.0	1.0	1.0
PERMANENT AID	P	91	91.0	91.0	92.0
SEASONAL-NC REPT	S	4	4.0	4.0	96.0
WINTER REPLACEMENT	W	4	4.0	4.0	100.0
	TOTAL	100	100.0	100.0	100.0
VALID OBSERVATIONS -		100			
MISSING OBSERVATIONS -		0			

FILE ATONAV13 (CREATION DATE = 01/14/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGDIST

VARIABLE VAR003 LOCATION

VALUE LABEL	VALUE	ABSOLUTE FREQUENCY	RELATIVE FREQUENCY (PERCENT)	ADJUSTED FREQUENCY (PERCENT)	CUMULATIVE ADJ FREQ (PERCENT)
AID DISCONTINUED		1	1.0	1.0	1.0
EXPUSED SEA COAST	B	35	35.0	35.0	36.0
EXPUSED BAY, HARBOR	C	1	1.0	1.0	37.0
EXPUSED RIVER	D	5	5.0	5.0	42.0
SEMI-EXPD BAY, HARBOR	L	4	4.0	4.0	46.0
SEMI-EXPD RIVER	M	12	12.0	12.0	58.0
BAY, HARBOR PROTECTED	T	12	12.0	12.0	70.0
PROTECTED RIVER	U	30	30.0	30.0	100.0
	TOTAL	100	100.0	100.0	100.0

VALID OBSERVATIONS = 100

MISSING OBSERVATIONS = 0

01/14/75

VALUE LABEL	VALUE	ABSOLUTE FREQUENCY	RELATIVE FREQUENCY (PERCENT)	ADJUSTED FREQUENCY (PERCENT)	CUMULATIVE ADJ FREQ (PERCENT)
1,BALL INSTALLED	0.	1	1.0	1.0	1.0
2,BALLS INSTLD	1.	78	78.0	78.0	79.0
1 VENT ,NO BALLS	2.	1	1.0	1.0	80.0
2 VENTS,NO BALLS	3.	18	18.0	18.0	98.0
OTHER	4.	1	1.0	1.0	99.0
	5.	1	1.0	1.0	100.0
VALID OBSERVATIONS =		100			
MISSING OBSERVATIONS =		0			
			100.0	100.0	100.0

01/14/75

VALUE LABEL	VALUE	ABSOLUTE FREQUENCY	RELATIVE FREQUENCY (PERCENT)	ADJUSTED FREQUENCY (PERCENT)	CUMULATIVE ADJ FREQ (PERCENT)
GREEN		1	1.0	1.0	1.0
RED	G	17	17.0	17.0	18.0
WHITE	R	34	34.0	34.0	52.0
	W	48	48.0	48.0	100.0
VALID OBSERVATIONS =		100			
MISSING OBSERVATIONS =		0			
			100.0	100.0	100.0

FILE ATCNAV13 (CREATION DATE = 01/14/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGDIST

VARIABLE VAR009 LAMP TYPE

VALUE LABEL

VALUE	ABSOLUTE FREQUENCY	RELATIVE FREQUENCY (PERCENT)	ADJUSTED FREQUENCY (PERCENT)	CUMULATIVE ADJ FREQ (PERCENT)
0.	1	1.0	1.0	1.0
0.55 AMP 12VOLT	3	3.0	3.0	4.0
0.77 AMP 12VOLT	47	47.0	47.0	51.0
1.15 AMP 12VOLT	49	49.0	49.0	100.0
TOTAL	100	100.0	100.0	100.0

VALID OBSERVATIONS - 100
MISSING OBSERVATIONS - 0

FILE ATCNAV13 (CREATION DATE = 01/14/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGDIST

VARIABLE VAR010 LANTERN-OPTIC

VALUE LABEL

VALUE	ABSOLUTE FREQUENCY	RELATIVE FREQUENCY (PERCENT)	ADJUSTED FREQUENCY (PERCENT)	CUMULATIVE ADJ FREQ (PERCENT)
0.	1	1.0	1.0	1.0
155 MM ACRYLIC	79	79.0	79.0	80.0
200 MM P-GLASS	16	16.0	16.0	96.0
200 MM ALLOTHER	4	4.0	4.0	100.0
TOTAL	100	100.0	100.0	100.0

VALID OBSERVATIONS - 100
MISSING OBSERVATIONS - 0

FILE ATONAV13 (CREATION DATE = 01/14/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CDDIST

VARIABLE VAR012 POWER SOURCE-BATTERY

VALUE LABEL	VALUE	ABSOLUTE FREQUENCY	RELATIVE FREQUENCY (PERCENT)	ADJUSTED FREQUENCY (PERCENT)	CUMULATIVE ADJ FREQ (PERCENT)
1000 A-H,EDISON#2	10E2	1	1.0	1.0	1.0
1000 A-H,EDISON STA	10S1	28	28.0	28.0	29.0
1000 A-H,EDISON ST	10S2	4	4.0	4.0	33.0
2000 A-H,2EDISON#2	20E2	1	1.0	1.0	34.0
2000 A-H,2 ED5N STA	20S1	36	36.0	36.0	70.0
2000 A-H,2UN CARBIDE	20U1	7	7.0	7.0	77.0
2500 A-H,EDISON-OLD	25B1	1	1.0	1.0	78.0
3000 A-H,EDISON#2	30E2	3	3.0	3.0	81.0
5000A-H,EDISON-OLD	50B1	4	4.0	4.0	85.0
6000 A-H,2ED5N#2	60E2	1	1.0	1.0	86.0
6000 A-H,2 ED5N STA	60S1	12	12.0	12.0	98.0
VALID OBSERVATIONS -		2	2.0	2.0	100.0
MISSING OBSERVATIONS -		100	100.0	100.0	100.0
	TOTAL				

VALID OBSERVATIONS - 100
MISSING OBSERVATIONS - 0

FILE ATONAV13 (CREATION DATE = 01/14/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGDIST

VARIABLE VAR014 LAMPCHANGER

VALUE LABEL	VALUE	ABSOLUTE FREQUENCY	RELATIVE FREQUENCY (PERCENT)	ADJUSTED FREQUENCY (PERCENT)	CUMULATIVE ADJ FREQ (PERCENT)
0 LAMP, CG6P CRDC	0.	1	1.0	1.0	1.0
6 LAMP, CG6PVAPAR	65.	36	36.0	36.0	37.0
4 LAMP, FU-1297	66.	1	1.0	1.0	38.0
	97.	62	62.0	62.0	100.0
VALID OBSERVATIONS =		100	100.0	100.0	100.0
MISSING OBSERVATIONS =					

FILE ATONAV13 (CREATION DATE = 01/14/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGDIST

VARIABLE VAR015 FLASHER

VALUE LABEL	VALUE	ABSOLUTE FREQUENCY	RELATIVE FREQUENCY (PERCENT)	ADJUSTED FREQUENCY (PERCENT)	CUMULATIVE ADJ FREQ (PERCENT)
C-R S-1065 SS	0.	1	1.0	1.0	1.0
CG-181 C-R DEV.	65.	22	22.0	22.0	23.0
VAPAIR	81.	72	72.0	72.0	95.0
	83.	5	5.0	5.0	100.0
VALID OBSERVATIONS =		100	100.0	100.0	100.0
MISSING OBSERVATIONS =					

VARIABLE VAR016 SOUND SIGNAL

VALUE LABEL	VALUE	ABSOLUTE FREQUENCY	RELATIVE FREQUENCY (PERCENT)	ADJUSTED FREQUENCY (PERCENT)	CUMULATIVE ADJ FREQ (PERCENT)
NO SOUND SIGNAL	0.	56	56.0	56.0	56.0
ELECTRIC HORN850-02	40.	1	1.0	1.0	57.0
WHISTLE 2 BALL	78.	1	1.0	1.0	58.0
WHISTLE 4 BALL	79.	22	22.0	22.0	80.0
BELL PRE 1952 TPR	81.	5	5.0	5.0	85.0
BELL1952 TAPPER	82.	5	5.0	5.0	90.0
BELL1962 TAPPER	83.	7	7.0	7.0	97.0
GONG1962 TAPPER	86.	3	3.0	3.0	100.0
TOTAL		100	100.0	100.0	100.0

VALID OBSERVATIONS = 100
MISSING OBSERVATIONS = 0

VARIABLE VAR017 DAYLIGHT CONTROL

VALUE LABEL	VALUE	ABSOLUTE FREQUENCY	RELATIVE FREQUENCY (PERCENT)	ADJUSTED FREQUENCY (PERCENT)	CUMULATIVE ADJ FREQ (PERCENT)
CR-S1065-LS1	0.	1	1.0	1.0	1.0
C-CLEAR-ALL	11.	2	2.0	2.0	3.0
R-COLOR PLASTIC	31.	47	47.0	47.0	50.0
B-COLOR GLASS	32.	39	39.0	39.0	89.0
	33.	11	11.0	11.0	100.0
TOTAL		100	100.0	100.0	100.0

VALID OBSERVATIONS = 100
MISSING OBSERVATIONS = 0

01/14/75

CODEBOOK,MARGINALS,CROSSTABLATIONS BEFORE BREAKDOWN RECODING

FILE ATONAV13 (CREATION DATE = 01/14/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGOIST

VARIABLE VAR018 BOTTOM DESCRIPTION

VALUE LABEL	VALUE	ABSOLUTE FREQUENCY	RELATIVE FREQUENCY (PERCENT)	ADJUSTED FREQUENCY (PERCENT)	CUMULATIVE ADJ FREQ (PERCENT)
		1	1.0	1.0	1.0
GRAVEL	G	15	15.0	15.0	16.0
MUD	M	24	24.0	24.0	40.0
ROCK	R	9	9.0	9.0	49.0
SAND	S	51	51.0	51.0	100.0
	TOTAL	100	100.0	100.0	100.0

VALID OBSERVATIONS = 100
MISSING OBSERVATIONS = 0

01/14/75

CODEBOOK,MARGINALS,CROSSTABLATIONS BEFORE BREAKDOWN RECODING

FILE ATONAV13 (CREATION DATE = 01/14/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGOIST

VARIABLE VAR021 BRIDLE SIZE

VALUE LABEL	VALUE	ABSOLUTE FREQUENCY	RELATIVE FREQUENCY (PERCENT)	ADJUSTED FREQUENCY (PERCENT)	CUMULATIVE ADJ FREQ (PERCENT)
1" X12"	0.	1	1.0	1.0	1.0
1" X 15"	2.	9	9.0	9.0	10.0
1 1-4" X 15"	3.	2	2.0	2.0	12.0
1 1-2" X 18"	4.	63	63.0	63.0	75.0
1 1-2" X 26"	6.	11	11.0	11.0	86.0
	7.	14	14.0	14.0	100.0
	TOTAL	100	100.0	100.0	100.0

VALID OBSERVATIONS = 100
MISSING OBSERVATIONS = 0

VALUE LABEL	VALUE	ABSOLUTE FREQUENCY	RELATIVE FREQUENCY (PERCENT)	ADJUSTED FREQUENCY (PERCENT)	CUMULATIVE ADJ FREQ (PERCENT)
1 1-2" 3RD CLASS	0.	1	1.0	1.0	1.0
1 3-4" 2ND CLASS	2.	10	10.0	10.0	11.0
2" 1ST CLASS	3.	56	66.0	66.0	77.0
	4.	23	23.0	23.0	100.0
	TOTAL	100	100.0	100.0	100.0
VALID OBSERVATIONS =		100			
MISSING OBSERVATIONS =		0			

VALUE LABEL	VALUE	ABSOLUTE FREQUENCY	RELATIVE FREQUENCY (PERCENT)	ADJUSTED FREQUENCY (PERCENT)	CUMULATIVE ADJ FREQ (PERCENT)
1"	0.	1	1.0	1.0	1.0
1 1-4"	4.	1	1.0	1.0	2.0
1 1-2"	6.	27	27.0	27.0	29.0
1 5-8"AND LARGER	7.	36	36.0	36.0	65.0
	8.	35	35.0	35.0	100.0
	TOTAL	100	100.0	100.0	100.0
VALID OBSERVATIONS =		100			
MISSING OBSERVATIONS =		0			

FILE ATONAV13 (CREATION DATE = 01/14/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGDIST

***** C R O S S T A B U L A T I O N O F L O C A T I O N *****
***** OPERATION *****
***** VAR002 *****
***** VAR003 *****
***** PAGE 1 OF 1 *****

VAR003											
COUNT	PROTECTE	BAY, HARB	SEMI-EXP	SEMI-EXP	EXPOSED	EXPOSED	EXPOSED	AID DISC	ROW		
ROW PCT	D RIVER	OR, PROTE	D RIVER	D BAY, HA	RIVER	BAY, HARB	SEA CUAS	ONTINUED	TOTAL		
TOT PCT	U	T	M	L	D	C	B				
VAR002											
WINTER REPLACEME	0	0	0	0	0	0	4	0	4		
	0.0	0.0	0.0	0.0	0.0	0.0	100.0	0.0	4.0		
	0.0	0.0	0.0	0.0	0.0	0.0	11.4	0.0			
	0.0	0.0	0.0	0.0	0.0	0.0	4.0	0.0			
SEASONAL-NO REPC	0	0	0	0	0	0	4	0	4		
	0.0	0.0	0.0	0.0	0.0	0.0	100.0	0.0	4.0		
	0.0	0.0	0.0	0.0	0.0	0.0	11.4	0.0			
	0.0	0.0	0.0	0.0	0.0	0.0	4.0	0.0			
PERMANENT AID	30	12	12	4	5	1	27	0	91		
	33.0	13.2	13.2	4.4	5.5	1.1	29.7	0.0	91.0		
	100.0	100.0	100.0	100.0	100.0	100.0	77.1	0.0			
	30.0	12.0	12.0	4.0	5.0	1.0	27.0	0.0			
AID DISCONTINUED	0	0	0	0	0	0	0	1	1		
	0.0	0.0	0.0	0.0	0.0	0.0	0.0	100.0	1.0		
	0.0	0.0	0.0	0.0	0.0	0.0	0.0	100.0			
	0.0	0.0	0.0	0.0	0.0	0.0	0.0	1.0			
COLUMN TOTAL	30	12	12	4	5	1	35	1	100		
	30.0	12.0	12.0	4.0	5.0	1.0	35.0	1.0	100.0		

FILE ATGNV13 (CREATION DATE = 01/14/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGOIST

***** C R O S S T A B U L A T I O N O F *****
 ***** B U O Y S I Z E *****
 VAR004 ***** BY VAR003 LOCATION *****
 ***** PAGE 1 OF 2 *****

COUNT		VAR003										ROW TOTAL
ROW PCT	COL PCT	PROTECTE TO RIVER U	BAY, HARB OR PRUTE T	SEMI-EXP D RIVER M	SEMI-EXP J BAY, HA I	EXPOSED D RIVER O	EXPOSED BAY, HARB C	EXPOSED SEA COAS B	AID DISC ONTINUED			
VAR004	AID DISCONTINUED	0.0	0.0	0.0	0.0	0.0	0.0	0.0	1.0	1.0		
		0.0	0.0	0.0	0.0	0.0	0.0	0.0	100.0	100.0		
		0.0	0.0	0.0	0.0	0.0	0.0	0.0	1.0	1.0		
10 X 39	39.	0.0	0.0	0.0	0.0	0.0	0.0	5.0	0.0	5.0		
		0.0	0.0	0.0	0.0	0.0	0.0	100.0	0.0	100.0		
		0.0	0.0	0.0	0.0	0.0	0.0	14.3	0.0	14.3		
		0.0	0.0	0.0	0.0	0.0	0.0	5.0	0.0	5.0		
5 X 10	510.	0.0	100.0	0.0	0.0	0.0	0.0	0.0	0.0	1.0		
		0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0		
		0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0		
6 X 20	620.	66.7	11.1	22.2	0.0	0.0	0.0	0.0	0.0	9.0		
		20.0	8.3	16.7	0.0	0.0	0.0	0.0	0.0	0.0		
		6.0	1.0	2.0	0.0	0.0	0.0	0.0	0.0	0.0		
7 X 15	715.	7	38.5	0.0	7.7	0.0	0.0	0.0	0.0	13.0		
		53.8	41.7	0.0	25.0	0.0	0.0	0.0	0.0	0.0		
		22.3	5.0	0.0	1.0	0.0	0.0	0.0	0.0	0.0		
		7.0										
7 X 17	717.	6	36.4	0.0	9.1	0.0	0.0	0.0	0.0	11.0		
		54.5	33.3	0.0	25.0	0.0	0.0	0.0	0.0	0.0		
		20.0	4.0	0.0	1.0	0.0	0.0	0.0	0.0	0.0		
		6.0										
8 X 20	820.	0.0	0.0	0.0	100.0	0.0	0.0	0.0	0.0	1.0		
		0.0	0.0	0.0	25.0	0.0	0.0	0.0	0.0	0.0		
		0.0	0.0	0.0	1.0	0.0	0.0	0.0	0.0	0.0		
COLUMN TOTAL		30.0	12.0	12.0	4.0	5.0	1.0	35.0	1.0	100.0		

(CONTINUED)

(CONTINUED)

FILE AIGNAV13 (CREATION DATE = 01/14/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGOIST

***** C R O S S T A B U L A T I O N O F *****
 ***** BUOY SIZE *****
 ***** LOCATION *****
 ***** BY VAR003 *****
 ***** PAGE 2 OF 2 *****

VAR003										COUNT ROW PCT COL PCT TOT PCT	ROW TOTAL
PROJECTE O RIVER U	BAY, HARB OR PROTE I	SEMI-EXP O RIVER M	SEMI-EXP O BAY, HA L	EXPOSED RIVER D	EXPOSED BAY, HARB C	EXPOSED SEA COAS B	AID DISC ONTINUED				
VAR004 8 X 23	1 25.0 3.3 1.0	0 0.0 0.0 0.0	1 25.0 8.3 1.0	1 25.0 25.0 1.0	0 0.0 0.0 0.0	1 25.0 100.0 1.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0		4.0	
	9 25.7 30.0 9.0	0 0.0 0.0 0.0	9 25.7 75.0 9.0	0 0.0 0.0 0.0	1 2.9 20.0 1.0	0 0.0 0.0 0.0	16 45.7 45.7 16.0	0 0.0 0.0 0.0		35 35.0	
	1 10.0 3.3 1.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	2 20.0 40.0 2.0	0 0.0 0.0 0.0	7 70.0 20.0 7.0	0 0.0 0.0 0.0		10.0	
9 X 34	0 0.0 0.0 0.0	1 100.0 3.3 1.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0		1.0	
	0 0.0 0.0 0.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	2 22.0 40.0 2.0	0 0.0 0.0 0.0	7 77.8 20.0 7.0	0 0.0 0.0 0.0		9.0	
	30 30.0	12 12.0	4 4.0	5 5.0	1 1.0	35 35.0	1 1.0	1 1.0		100 100.0	
COLUMN TOTAL											

FILE ATCNV13 (CREATION DATE = 01/14/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGDIST

***** C R O S T A B U L A T I O N O F *****
 ***** VENT VALVES PER POCKET ***** LOCATION *****
 ***** VAR006 *****
 ***** PAGE 1 OF 1 *****

VAR003										
COUNT	PROTECTE	BAY, HARB	SEMI-EXP	SEMI-EXP	EXPOSED	EXPOSED	EXPOSED	EXPOSED	AID DISC	ROW
RUM PCT	U RIVER	OR PRUTE	D RIVER	P RAY, HA	RIVER	BAY, HARB	SEA COAS	SEA COAS	ONTINUED	TOTAL
TOT PCT				L	D	C	B	B		
0.	0	0	0	0	0	0	0	0	1	1.0
	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	100.0	
	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	100.0	
	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	1.0	
1. BALL INSTALLED	22	9	5.1	4	4	1	34	0	0	78
	28.2	11.5	80.0	100.0	80.0	100.0	97.1	0.0	0.0	78.0
	73.3	75.0	4.0	4.0	4.0	1.0	34.0	0.0	0.0	
	22.0	9.0						0.0	0.0	
2. BALLS INSTLD	0	1	0	0	0	0	0	0	0	1
	0.0	100.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	1.0
	0.0	8.3	0.0	0.0	0.0	0.0	0.0	0.0	0.0	
	0.0	1.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	
3. 1 VENT ,NO BALLS	8	1	44.4	0	1	0	0	0	0	18
	44.4	5.6	66.7	0.0	5.6	0.0	0.0	0.0	0.0	18.0
	26.7	8.3	8.0	0.0	20.0	0.0	0.0	0.0	0.0	
	8.0	1.0			1.0			0.0	0.0	
4. 2 VENTS,NO BALLS	0	1	0	0	0	0	0	0	0	1
	0.0	100.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	1.0
	0.0	8.3	0.0	0.0	0.0	0.0	0.0	0.0	0.0	
	0.0	1.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	
5. OTHER	0	0	0	0	0	0	1	0	0	1
	0.0	0.0	0.0	0.0	0.0	0.0	100.0	0.0	0.0	1.0
	0.0	0.0	0.0	0.0	0.0	0.0	2.9	0.0	0.0	
	0.0	0.0	0.0	0.0	0.0	0.0	1.0	0.0	0.0	
COLUMN TOTAL	30	12	12	4	5	1	35	1	1	100
	50.0	12.0	12.0	4.0	5.0	1.0	35.0	1.0	1.0	100.0

FILE ATONAV13 (CREATION DATE = 01/14/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGDIST

***** C R O S S T A B U L A T I O N O F *****
 VAR007 LIGHT CHARACTERISTIC ***** LOCATION *****
 ***** BY VAR003 *****
 ***** PAGE 1 OF 2 *****

VAR007		VAR003										ROW TOTAL	
COUNT		PROTECTE	BAY, HARB	SEMI-EXP	SEMI-EXP	EXP	EXP	EXP	EXP	EXP	AID DISC		
RJM PCT		D RIVER	OR PRUTE	D RIVER	D RIVER	D RIVER	D RIVER	D RIVER	D RIVER	D RIVER	ON		
CUL PCT		U											
TOT PCT													
0.		0	0	0	0	0	0	0	0	0	1	1.0	
		0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	100.0		
		0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	100.0		
		0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	1.0		
103.		5	2	2	2	7	1	0	0	0	0	13	
CK FL 0.3		18.5	15.4	15.4	16.7	20.0	20.0	0	0	0	0.0	13.0	
		16.7	16.7	16.7	16.7	20.0	20.0	0	0	0	0.0		
		5.0	2.0	2.0	2.0	1.0	1.0	0	0	0	0.0		
122.		0	0	0	0	0	0	0	0	0	0	1	
QK FL * ALLOTHER		0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	1.0	
		0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0		
		0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0		
145.		0	0	0	0	0	0	0	0	0	0	2	
MO A*FL.6EC,2.0		0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	2.0	
		0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0		
		0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0		
146.		0	0	0	0	0	0	0	0	0	0	6	
MO A*ALL OTHERS		0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	6.0	
		0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0		
		0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0		
251.		0	0	0	0	0	0	0	0	0	0	2	
FL 2.5 .05*		0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	2.0	
		0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0		
		0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0		
255.		0	1	0	0	0	0	0	0	0	0	1	
FL 2.5 .5*		0.0	100.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	1.0	
		0.0	8.3	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0		
		0.0	1.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0		
COLUMN TOTAL		30.0	12.0	12.0	12.0	4.0	5.0	1.0	35.0	1.0	1.0	100	
(CONTINUED)												100.0	

FILE ATONAV13 (CREATION DATE = 01/14/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGDIST

VAR007 LIGHT CHARACTERISTIC CROSTABULARITY LOCATION VAR003 PAGE 2 OF 2

VAR003									
COUNT	PROTECTE	BAY, HARB	SEMI-EXP	SEMI-EXP	EXPOSED	EXPOSED	EXPOSED	AID DISC	ROW
ROW PCT	TO RIVER	OR PROTE	D RIVER	D BAY, HA	RIVER	BAY, HARB	SEA COAS	ONTINUED	TOTAL
TOT PCT	U	T	M	L	D	C	B		
404.	25	9	10	3	4	1	21	0	73.0
	34.2	12.3	13.7	4.1	5.5	1.4	28.8	0.0	
	93.3	75.0	83.3	75.0	80.0	100.0	60.0	0.0	
	25.0	9.0	10.0	3.0	4.0	1.0	21.0	0.0	
630.	0	0	0	0	0	0	1	0	1.0
	0.0	0.0	0.0	0.0	0.0	0.0	100.0	0.0	
	0.0	0.0	0.0	0.0	0.0	0.0	2.9	0.0	
	0.0	0.0	0.0	0.0	0.0	0.0	1.0	0.0	
COLUMN	30.0	12.0	12.0	4.0	5.0	1.0	35	1	100
TOTAL	30.0	12.0	12.0	4.0	5.0	1.0	35.0	1.0	100.0

VAR08 LIGHT COLOR CROSS TABULATION BY VAR003 OF LOCATION

158

FILE ATCNAV13 (CREATION DATE = 01/14/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGDIST

***** C R O S S T A B U L A T I O N O F *****
***** L A M P T Y P E *****
***** VAR009 *****
***** BY VAR003 LOCATION *****
***** PAGE 1 OF 1 *****

VAR003										
COUNT	PROJECTE	BAY, HARB	SEMI-EXP	EXPOSED	EXPOSED	EXPOSED	EXPOSED	EXPOSED	AID DISC	ROW
ROW PCT	D RIVER	UR, PRUTE	D RIVER	D BAY, HA	RIVER	BAY, RIVER	BAY, HARB	SEA CGAS	ONTINUED	TOTAL
TOT PCT	U	T	M	L	D	C	B			
0.	0	0	0	0	0	0	0	0	1	1.0
	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	100.0	
	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	100.0	
	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	1.0	
52	0	2	0	1	0	0	0	0	0	3
0.55 AMP 12VOLT	0.0	66.7	0.0	33.3	0.0	0.0	0.0	0.0	0.0	3.0
	0.0	16.7	0.0	25.0	0.0	0.0	0.0	0.0	0.0	
	0.0	2.0	0.0	1.0	0.0	0.0	0.0	0.0	0.0	
53	27	4	12	2	2	0	0	0	0	47
0.77 AMP 12VOLT	57.4	8.5	25.5	4.5	4.5	0.0	0.0	0.0	0.0	47.0
	90.0	33.3	100.0	50.0	40.0	0.0	0.0	0.0	0.0	
	27.0	4.0	12.0	2.0	2.0	0.0	0.0	0.0	0.0	
54	3	6	0	1	3	1	1	35	0	49
1.15 AMP 12VOLT	6.1	12.2	0.0	2.0	6.1	2.0	0.0	71.4	0.0	49.0
	10.0	50.0	0.0	25.0	60.0	100.0	0.0	100.0	0.0	
	3.0	6.0	0.0	1.0	3.0	1.0	0.0	35.0	0.0	
COLUMN TOTAL	30	12	12	4	5	1	1	35	1	100
	30.0	12.0	12.0	4.0	5.0	1.0	1.0	35.0	1.0	100.0

VAR003									
COUNT	PROTECTE	BAY, HARB	SEMI-EXP	SEMI-EXP	EXPOSED	EXPOSED	EXPOSED	AID DISC	ROW
RUM PCT	D RIVER	OR PROTE	D RIVER	D RIVER	D BAY, HA	RIVER	BAY, HARB	CONTINUED	TOTAL
CUL PCT	U	I	M	M	L	D	C		
TOT PCT									
VAR012	0	0	0	0	0	0	0	0	2
6000 A-H,2 ED5N	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	2.0
	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	
60E2	2	0	0	0	0	1	0	0	12
6000 A-H,2ED5N#2	16.7	0.0	0.0	0.0	0.0	8.3	0.0	0.0	12.0
	2.0	0.0	0.0	0.0	0.0	1.0	0.0	0.0	
50BY	0	0	0	0	0	0	0	0	1
5000A-H,EDISON-0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	1.0
	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	
30E2	0	0	1	25	0	1	0	0	4
3000 A-H,EDISON#	0.0	0.0	0.0	0.0	0.0	20.0	0.0	0.0	4.0
	0.0	0.0	0.0	1.0	0.0	1.0	0.0	0.0	
25BY	0	1	0	0	0	0	0	0	3
2500 A-H,EDISON-	0.0	3.3	0.0	0.0	0.0	0.0	0.0	0.0	3.0
	0.0	6.3	0.0	0.0	0.0	0.0	0.0	0.0	
	0.0	1.0	0.0	0.0	0.0	0.0	0.0	0.0	
20U1	1	0	0	0	0	0	0	0	1
2000 A-H,2UN CAR	100.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	1.0
	3.3	0.0	0.0	0.0	0.0	0.0	0.0	0.0	
	1.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	
20S1	1	2	0	0	0	0	1	0	7
2000 A-H,2 ED5N	14.3	28.6	0.0	0.0	0.0	0.0	14.3	0.0	7.0
	3.3	16.7	0.0	0.0	0.0	0.0	100.0	0.0	
	1.0	2.0	0.0	0.0	0.0	0.0	1.0	0.0	
COLUMN	30	12	12	5	4	35	1	1	100
TOTAL	30.0	12.0	12.0	5.0	4.0	35.0	1.0	1.0	100.0

(CONTINUED)

***** C R O S S T A B U L A T I O N O F *****
***** LAMPCHANGER *****
***** BY VAR003 LOCATION *****
***** PAGE 1 OF 1 *****

VAR003

COUNT		PROTECTE	BAY, HARB	SEMI-EXP	SEMI-EXP	EXPOSED	EXPOSED	EXPOSED	EXPOSED	AID DISC	ROW
RUM PCT		U RIVER	CR PROTE	D M	D RIVER	D L	D HA	D RIVER	C BAY, HARB	SEA COAS	TOTAL
COL PCT		U									
TUT PCT											
0.		0	0	0	0	0	0	0	0	0	1
		0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	100.0	1.0
		0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	100.0	1.0
		0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	1.0	
65.		12	3	4	11.1	2.8	1	2.8	0	15	36
6 LAMP, CG6P CRDC		33.3	8.3	33.3	33.3	25.0	20.0	20.0	0.0	41.7	36.0
		40.0	25.0	4.0	4.0	1.0	1.0	1.0	0.0	42.9	
		12.0	3.0						0.0	15.0	
66.		0	0	0	0	0	0	0	0	1	1
6 LAMP, CG6PVAPAR		0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	100.0	1.0
		0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	2.9	
		0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	1.0	
97.		18	9	8	12.9	3	4	6.5	1	19	62
4 LAMP, FU-1297		29.0	14.5	12.9	68.7	4.8	80.0	80.0	1.6	30.6	62.0
		60.0	75.0	6.7	8.0	75.0	4.0	4.0	100.0	54.3	
		18.0	9.0			3.0			1.0	19.0	
COLUMN		30	12	12	12.0	4	5	5	1	35	100
TOTAL		30.0	12.0	12.0		4.0	5.0	5.0	1.0	35.0	100.0

FILE ATONAV13 (CREATION DATE = 01/14/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGOIST

VAR016 SOUND SIGNAL ***** C R O S S T A B U L A T I O N O F ***** LOCATION ***** PAGE 1 OF 2

VAR003

CGUNT	PROTECTE	BAY, HARB	SEMI-EXP	SEMI-EXP	EXPOSED	EXPOSED	EXPOSED	AID DISC	ROW
ROW PCT	U	OR T	D RIVER	D BAY, HA	RIVER	BAY, HARB	SEA COAS	ONTINUED	TOTAL
TOT PCT									
VAR016	27	12	8	3	1	0	4	1	56
NO SOUND SIGNAL	48.2	21.4	14.3	5.3	1.8	0.0	7.1	1.0	56.0
	99.0	100.0	66.7	75.0	20.0	0.0	11.4	100.0	
	27.0	12.0	8.0	3.0	1.0	0.0	4.0	1.0	
ELECTRIC HORN850	0	0	0	0	1	0	0	0	1
	0.0	0.0	0.0	0.0	20.0	0.0	0.0	0.0	1.0
	0.0	0.0	0.0	0.0	1.0	0.0	0.0	0.0	
WHISTLE 2 BALL	0	0	0	0	0	0	1	0	1
	0.0	0.0	0.0	0.0	0.0	0.0	100.0	0.0	1.0
	0.0	0.0	0.0	0.0	0.0	0.0	2.9	0.0	
	0.0	0.0	0.0	0.0	0.0	0.0	1.0	0.0	
WHISTLE 4 BALL	1	0	0	1	2	0	18	0	22
	4.5	0.0	0.0	4.5	9.1	0.0	81.8	0.0	22.0
	3.3	0.0	0.0	25.0	40.0	0.0	51.4	0.0	
	1.0	0.0	0.0	1.0	2.0	0.0	18.0	0.0	
BELL PRE 1952 TP	0	0	0	0	1	0	4	0	5
	0.0	0.0	0.0	0.0	20.0	0.0	80.0	0.0	5.0
	0.0	0.0	0.0	0.0	20.0	0.0	11.4	0.0	
	0.0	0.0	0.0	0.0	1.0	0.0	4.0	0.0	
BELL1952 TAPPER	0	0	3	0	0	1	1	0	5
	0.0	0.0	60.0	0.0	0.0	20.0	20.0	0.0	5.0
	0.0	0.0	25.0	0.0	0.0	100.0	2.9	0.0	
	0.0	0.0	3.0	0.0	0.0	1.0	1.0	0.0	
BELL1962 TAPPER	2	0	1	0	0	0	4	0	7
	28.9	0.0	14.3	0.0	0.0	0.0	57.1	0.0	7.0
	6.7	0.0	8.3	0.0	0.0	0.0	11.4	0.0	
	2.0	0.0	1.0	0.0	0.0	0.0	4.0	0.0	
COLUMN TOTAL	30	12	12	4	5	1	35	1	100
	30.0	12.0	12.0	4.0	5.0	1.0	35.0	1.0	100.0

(CONTINUED)

FILE ATONAV13 (CREATION DATE = 01/14/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGDIST

***** C R O S S T A B U L A T I O N O F L O C A T I O N *****
VAR017 DAYLIGHT CONTROL BY VAR003 ***** PAGE 1 OF 1

VAR003													
COUNT	I PROTECTE												
	U	RIVER	BAY, HARB	SEMI-EXP	SEMI-EXP	SEMI-EXP	SEMI-EXP	SEMI-EXP	SEMI-EXP	SEMI-EXP	SEMI-EXP	SEMI-EXP	SEMI-EXP
RUM PCT	U	RIVER	BAY, HARB	SEMI-EXP	SEMI-EXP	SEMI-EXP	SEMI-EXP	SEMI-EXP	SEMI-EXP	SEMI-EXP	SEMI-EXP	SEMI-EXP	SEMI-EXP
CUL PCT	U	RIVER	BAY, HARB	SEMI-EXP	SEMI-EXP	SEMI-EXP	SEMI-EXP	SEMI-EXP	SEMI-EXP	SEMI-EXP	SEMI-EXP	SEMI-EXP	SEMI-EXP
TOT PCT	U	RIVER	BAY, HARB	SEMI-EXP	SEMI-EXP	SEMI-EXP	SEMI-EXP	SEMI-EXP	SEMI-EXP	SEMI-EXP	SEMI-EXP	SEMI-EXP	SEMI-EXP
VAR017	O.												
	0	0	0	0	0	0	0	0	0	0	0	0	0
CR-S1065-LS1	11.												
	50.0	3.3	50.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
C-CLEAR-ALL	31.												
	11	23.4	2.1	5	10.6	41.7	50.0	2.0	2.1	2.1	1.0	1.0	1.0
R-COLOR PLASTIC	32.												
	17	43.6	12.8	7	17.9	58.3	7.0	1.0	3	7.7	60.0	3.0	3.0
B-COLOR GLASS	33.												
	1	9.1	45.5	5	0.0	0.0	0.0	1.0	1	9.1	20.0	1.0	1.0
COLUMN TOTAL													
30.0 12.0 12.0 4.0 5.0 1.0 1.0 1.0 1.0 1.0 1.0 1.0 1.0 1.0													
100.0													

FILE ATONAV13 (CREATION DATE = 01/14/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGDIST													
***** C R O S S T A B U L A T I O N O F *****													
***** BOTTOM DESCRIPTION *****													
***** BY VAR003 LOCATION *****													
***** PAGE 1 OF 1 *****													
VAR003													
CCOUNT	PROTECTE	BAY, HAR	SEMI-EXP	SEMI-EXP	EXPOSED	EXPOSED	EXPOSED	EXPOSED	SEA COAS	AID DISC	ROW		
ROW PCT	TO RIVER	OR PROTE	D RIVER	D RIVER	D BAY, HAR	D RIVER	BAY, HAR	BAY, HAR	B	ONTINUED	TOTAL		
CUL PCT	U	T	M	M	L	D	C	C					
TOT PCT													
VAR018 S	11	0	9	17.6	2	5.8	0	0	24	0	51		
SAND	21.6	0.0	17.6	75.0	3.9	9.8	0.0	0.0	47.1	0.0	51.0		
	36.7	0.0	75.0	9.0	50.0	100.0	0.0	0.0	68.6	0.0			
	11.0	0.0	9.0		2.0	5.0	0.0	0.0	24.0	0.0			
R	3	0	0	0.0	1	0	0	0	5	0	9		
ROCK	33.3	0.0	0.0	0.0	11.1	0.0	0.0	0.0	55.6	0.0	9.0		
	10.0	0.0	0.0	0.0	25.0	0.0	0.0	0.0	14.3	0.0			
	3.0	0.0	0.0	0.0	1.0	0.0	0.0	0.0	5.0	0.0			
H	16	5	2	8.3	0	0	0	0	1	0	24		
MUD	66.7	20.8	8.3	16.7	0.0	0.0	0.0	0.0	4.2	0.0	24.0		
	55.3	41.7	16.7	2.0	0.0	0.0	0.0	0.0	2.9	0.0			
	16.0	5.0	2.0		0.0	0.0	0.0	0.0	1.0	0.0			
G	0	7	1	6.7	1	0	1	1	5	0	15		
GRAVEL	0.0	46.7	6.7	8.3	6.7	0.0	6.7	100.0	33.3	0.0	15.0		
	0.0	58.3	8.3	1.0	25.0	0.0	1.0	1.0	14.3	0.0			
	0.0	7.0	1.0		1.0	0.0	0.0	0.0	5.0	0.0			
	0	0	0	0.0	0	0	0	0	0	1	1		
	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	100.0	1.0		
	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	100.0			
	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	1.0			
COLUMN	30.0	12	12	12	4	5	1	1	35	1	100		
TOTAL		12.0	12.0		4.0	5.0	1.0	1.0	35.0	1.0	100.0		

FILE ATNAV13 (CREATION DATE = 01/14/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGDIST

***** C R O S S T A B U L A T I O N O F LOCATION *****
 ***** BRIDLE SIZE *****
 ***** VAR021 *****
 ***** BY VAR003 *****
 ***** PAGE 1 OF 1 *****

COUNT		VAR003										ROW TOTAL
ROW PCT	COL PCT	PROTECTE D RIVER U	BAY, HARB OR PROTE T	SEMI-EXP D RIVER M	SEMI-EXP D BAY, HA L	EXPOSED RIVER D	EXPCSED BAY, HARB C	EXPOSED SEA COAS B	AID DISC ONTINUED			
0.		0 0.0 0.0 0.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	1 100.0 1.0	1.0		
1" X 12'	2.	66.7 20.0 6.0	22.2 16.7 2.0	11.1 8.3 1.0	0.0 0.0 0.0	0.0 0.0 0.0	0.0 0.0 0.0	0.0 0.0 0.0	0 0.0 0.0	9.0		
1" X 15'	3.	50.0 3.3 1.0	50.0 8.3 1.0	0.0 0.0 0.0	0.0 0.0 0.0	0.0 0.0 0.0	0.0 0.0 0.0	0.0 0.0 0.0	0 0.0 0.0	2.0		
1 1-4" X 15'	4.	22 34.9 73.3 22.0	12.7 66.7 8.0	11.1 17.5 91.7 11.0	4 6.3 100.0 4.0	1 1.6 20.0 1.0	1 1.6 100.0 1.0	16 25.4 45.7 16.0	0 0.0 0.0 0.0	63.0		
1 1-2" X 18'	6.	1 5.1 3.3 1.0	1 9.1 8.3 1.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	2 18.2 40.0 2.0	0 0.0 0.0 0.0	7 63.6 20.0 7.0	0 0.0 0.0 0.0	11.0		
1 1-2" X 26'	7.	0 0.0 0.0 0.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	2 14.3 40.0 2.0	0 0.0 0.0 0.0	12 65.7 34.3 12.0	0 0.0 0.0 0.0	14.0		
COLUMN TOTAL		30.0	12.0	12.0	4.0	5.0	1.0	35.0	1.0	100.0		

FILE ATONAV13 (CREATION DATE = 01/14/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGDIST

VAR022 *** SWIVEL SIZE AND NUMBER *** C R O S T A B U L A T I O N O F LOCATION *** VAR003 *** ** ** ** **

COUNT		VAR003										ROW TOTAL	
ROW PCT	COL PCT	PROTECTE D RIVER U	BAY, HARB OR PROTE I	SEMI-EXP D RIVER M	SEMI-EXP O BAY, HARB L	EXPOSED RIVER D	EXPOSED BAY, HARB C	EXPOSED SEA COAS B	AID DISC ONTINUED	ROW TOTAL			
0.		0	0	0	0	0	0	0	1	1.0	1.0		
		0.0	0.0	0.0	0.0	0.0	0.0	0.0	100.0	100.0	100.0		
		0.0	0.0	0.0	0.0	0.0	0.0	0.0	1.0	1.0	1.0		
1 1-2" 3RD CLASS	2.	6	30.0	10.0	0	0	0	0	0	10.0	10.0		
		60.0	25.0	8.3	0	0	0	0	0	10.0	10.0		
		20.0	3.0	1.0	0	0	0	0	0	10.0	10.0		
		6.0											
1 3-4" 2ND CLASS	3.	23	12.1	16.7	4	1	1	18	0	66.0	66.0		
		34.8	66.7	91.7	6.1	1.5	1.5	27.3	0.0	66.0	66.0		
		76.7	8.0	11.0	100.0	20.0	100.0	51.4	0.0	66.0	66.0		
		23.0			4.0	1.0	1.0	18.0	0.0	66.0	66.0		
2" 1ST CLASS	4.	1	4.3	0	0	4	0	17	0	23.0	23.0		
		4.3	8.3	0.0	0.0	17.4	0.0	73.9	0.0	23.0	23.0		
		3.3	1.0	0.0	0.0	80.0	0.0	48.6	0.0	23.0	23.0		
		1.0			0.0	4.0	0.0	17.0	0.0	23.0	23.0		
COLUMN TOTAL		30	12.0	12.0	4.0	5.0	1.0	35.0	1	100.0	100.0		

CODEBOOK, MARGINALS, CROSSTABULATIONS BEFORE BREAKDOWN RECODING

01/14/75

PAGE 53

FILE ATONAV13 (CREATION DATE = 01/14/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGDIST

***** C R O S T A B U L A T I O N O F *****
***** BUOY SIZE ***** LIGHT CHARACTERISTIC *****
***** VAR004 *****
***** PAGE 1 OF 2 *****

COUNT		VAR007		QK FL		QK FL *		MO A:4FL		MO A:ALL		FL 2.5		FL 2.5		FL 4 .4		E INT		ROW	
TOT PCF		0.		0.3		103.		122.		145.		251.		255.		404.		630.		TOTAL	
CUL PCF		100.0		0.0		0.0		0.0		0.0		0.0		0.0		0.0		0.0		1.0	
AID DISCONTINUED		1.0		0.0		0.0		0.0		0.0		0.0		0.0		0.0		0.0		0.0	
39.		0.0		0.0		0.0		0.0		0.0		0.0		0.0		0.0		0.0		5.0	
510.		0.0		0.0		0.0		0.0		0.0		0.0		0.0		0.0		0.0		1.0	
620.		0.0		0.0		0.0		0.0		0.0		0.0		0.0		0.0		0.0		9.0	
715.		0.0		0.0		0.0		0.0		0.0		0.0		0.0		0.0		0.0		13.0	
717.		0.0		0.0		0.0		0.0		0.0		0.0		0.0		0.0		0.0		11.0	
820.		0.0		0.0		0.0		0.0		0.0		0.0		0.0		0.0		0.0		1.0	
COLUMN TOTAL		1.0		13.0		1.0		2.0		6.0		2.0		1.0		73.0		1.0		100.0	

(CONTINUED)

FILE ATONAV13 (CREATION DATE = 01/14/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGOIST

***** C R O S S T A B U L A T I O N O F L I G H T C H A R A C T E R I S T I C *****
 ***** BUCY SIZE *****
 VAR004 *****
 ***** PAGE 2 OF 2 *****

VAR007

COUNT ROW PCT COL PCT TOT PCT	QK FL 0.3	QK FL 103.	OK FL ALLOTH	OK FL 122.	MO A-4FL 0.6EC/2.0	MO A-4FL 145.	MO A-4FL 146.	MD A-ALL OTHERS	FL 2.5 0.05*	FL 2.5 0.5*	FL 2.5 255.	FL 4.4 404.	E INT 6.30.	ROW TOTAL
VAR004														
8 X 23	823.	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	4.0	0.0	4.0
		0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	5.5	0.0	
		0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	4.0	0.0	
8 X 26	826.	0.0	3.0	0.0	0.0	0.0	0.0	0.0	2.0	0.0	0.0	29.0	1.0	35.0
		0.0	8.6	0.0	0.0	0.0	0.0	0.0	5.7	0.0	0.0	82.9	2.9	
		0.0	23.1	0.0	0.0	0.0	0.0	0.0	100.0	0.0	0.0	39.7	10.0	
		0.0	3.0	0.0	0.0	0.0	0.0	0.0	2.0	0.0	0.0	29.0	1.0	
9 X 32	932.	0.0	2.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	6.0	0.0	10.0
		0.0	20.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	60.0	0.0	
		0.0	15.4	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	8.2	0.0	
		0.0	2.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	6.0	0.0	
9 X 34	934.	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	1.0	0.0	1.0
		0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	100.0	0.0	
		0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	4.4	0.0	
		0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	1.0	0.0	
9 X 38	938.	0.0	2.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	5.0	0.0	9.0
		0.0	22.2	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	55.6	0.0	
		0.0	15.4	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	6.8	0.0	
		0.0	2.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	5.0	0.0	
COLUMN TOTAL	1.0	13.0	1.0	1.0	2.0	2.0	6.0	6.0	2.0	1.0	1.0	73.0	1.0	100.0

FILE ATGNV13 (CREATION DATE = 01/14/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGDIST

***** C R O S S T A B U L A T I O N O F *****
***** BUOY SIZE ***** SOUND SIGNAL *****
***** VAR004 ***** BY VAR016 *****
***** PAGE 1 OF 2 *****

VAR016									
COUNT	IND SOUND	ELECTRIC	WHISTLE	WHISTLE	BELL PRE	BELL1952	BELL1962	GONG1962	ROW
ROW PCT	SIGNAL	HURN850	2 BALL	4 BALL	1952 TP	TAPPER	TAPPER	TAPPER	TOTAL
TOT PCT	U.	40.	78.	79.	81.	82.	83.	86.	
VAR004									
AID DISCONTINUED	1	0	0	0	0	0	0	0	1
	100.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	1.0
	1.8	0.0	0.0	0.0	0.0	0.0	0.0	0.0	
	1.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	
10 X 39	0	0	0	5	0	0	0	0	5
	0.0	0.0	0.0	100.0	0.0	0.0	0.0	0.0	5.0
	0.0	0.0	0.0	22.7	0.0	0.0	0.0	0.0	
	0.0	0.0	0.0	5.0	0.0	0.0	0.0	0.0	
5 X 10	1	0	0	0	0	0	0	0	1
	100.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	1.0
	1.8	0.0	0.0	0.0	0.0	0.0	0.0	0.0	
	1.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	
6 X 20	8	0	0	0	0	1	0	0	9
	84.9	0.0	0.0	0.0	0.0	11.1	0.0	0.0	9.0
	14.3	0.0	0.0	0.0	0.0	20.0	0.0	0.0	
	8.0	0.0	0.0	0.0	0.0	1.0	0.0	0.0	
7 X 15	13	0	0	0	0	0	0	0	13
	100.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	13.0
	23.2	0.0	0.0	0.0	0.0	0.0	0.0	0.0	
	13.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	
7 X 17	11	0	0	0	0	0	0	0	11
	100.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	11.0
	19.6	0.0	0.0	0.0	0.0	0.0	0.0	0.0	
	11.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	
8 X 20	1	0	0	0	0	0	0	0	1
	100.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	1.0
	1.8	0.0	0.0	0.0	0.0	0.0	0.0	0.0	
	1.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	
COLUMN	56	1	1	22	5	5	7	3	100
TOTAL	56.0	1.0	1.0	22.0	5.0	5.0	7.0	3.0	100.0
(CONTINUED)									

FILE ATONAV13 (CREATION DATE = 01/14/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGOIST

***** C R O S S T A B U L A T I O N O F S O U N D S I G N A L *****
***** B U O Y S I Z E *****
VAR004 ***** PAGE 2 OF 2

VAR016											ROW TOTAL
CCOUNT	NO SOUND SIGNAL	ELECTRIC HORN650	WHISTLE 2 BALL	WHISTLE 4 BALL	BELL PRE 1952 TP	BELL1952 TAPPER	BELL1962 TAPPER	CONGL1962 TAPPER			
ROW PCT COL PCT TOT PCT	0.	40.	78.	79.	81.	82.	83.	86.			
823.	2 50.0 3.6 2.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	1 25.0 4.5 1.0	0 0.0 0.0 0.0	1 25.0 20.0 1.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0		4.0	
826.	18 51.4 32.1 18.0	0 0.0 0.0 0.0	1 2.9 100.0 1.0	2 5.7 9.1 2.0	1 2.9 20.0 1.0	3 6.6 60.0 3.0	7 20.0 100.0 7.0	3 8.6 100.0 3.0		35 35.0	
932.	0 0.0 0.0 0.0	1 10.0 100.0 1.0	0 0.0 0.0 0.0	5 50.0 22.7 5.0	4 40.0 80.0 4.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0		10.0	
934.	1 100.0 1.8 1.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0		1.0	
938.	0 0.0 0.0 0.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	9 100.0 40.9 9.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0		9.0	
COLUMN TOTAL	56 56.0	1 1.0	1 1.0	22 22.0	5 5.0	5 5.0	7 7.0	3 3.0		100 100.0	

01/14/75

FILE ATONAV13 (CREATION DATE = 01/14/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGOIST

***** C R O S S T A B U L A T I O N O F *****
 ***** B U O Y S I Z E *****
 VAR004 ***** BY VAR023 *****
 ***** FIRST CHAIN SIZE *****
 ***** PAGE 1 OF 2 *****

COUNT		1"		1 1-4"		1 1-2"		1 5-8" AND LARGER		ROW TOTAL
VAR004	ROW PCT COL PCT TOT PCT	0.	1	4.	6.	7.	8.			
AID DISCONTINUED	0.	100.0 100.0 1.0	0.0 0.0 0.0	0.0 0.0 0.0	0.0 0.0 0.0	0.0 0.0 0.0	0.0 0.0 0.0	0.0 0.0 0.0	1.0 1.0	1.0
10 X 39	39.	0.0 0.0 0.0	0.0 0.0 0.0	0.0 0.0 0.0	0.0 0.0 0.0	20.0 2.8 1.0	4.0 11.4 4.0	80.0 11.4 4.0	5.0 5.0	5.0
5 X 10	510.	0.0 0.0 0.0	0.0 0.0 0.0	100.0 3.7 1.0	0.0 0.0 0.0	0.0 0.0 0.0	0.0 0.0 0.0	0.0 0.0 0.0	1.0 1.0	1.0
6 X 20	620.	0.0 0.0 0.0	11.1 100.0 1.0	88.9 29.6 8.0	0.0 0.0 0.0	0.0 0.0 0.0	0.0 0.0 0.0	0.0 0.0 0.0	9.0 9.0	9.0
7 X 15	715.	0.0 0.0 0.0	0.0 0.0 0.0	69.2 34.3 9.0	23.1 8.3 3.0	7.7 2.9 1.0	1.0 2.9 1.0	13.0 13.0	13.0 13.0	13.0
7 X 17	717.	0.0 0.0 0.0	0.0 0.0 0.0	63.6 25.9 7.0	36.4 11.1 4.0	0.0 0.0 0.0	0.0 0.0 0.0	11.0 11.0	11.0 11.0	11.0
8 X 20	820.	0.0 0.0 0.0	0.0 0.0 0.0	0.0 0.0 0.0	100.0 2.8 1.0	0.0 0.0 0.0	0.0 0.0 0.0	1.0 1.0	1.0 1.0	1.0
(CONTINUED)	COLUMN TOTAL	1.0	1.0	27.0	36.0	35.0	100.0	100.0	100.0	100.0

FILE ATCNAV13 (CREATION DATE = 01/14/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGOIST

***** CROSSTABULATION OF DAYLIGHT CONTROL *****
VAR010 LANTERN-OPTIC BY VAR017 *****
***** PAGE 1 OF 1 *****

COUNT		VAR017		CR-S1065		C-CLEAR-		R-COLOR		B-COLOR		ROW TOTAL
ROW PCT	TOT PCT	0.	1	-LS1	ALL	31.	32.	33.	33.	33.		
VAR010												
0.	0.	100.0	100.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	1.0	
16.	16.	0.0	0.0	2.5	39	49.4	39	2	39	2	79	
155 MM ACRYLIC	0.0	0.0	100.0	0.0	0.0	83.0	45.6	2.5	18.2	2.5	79.0	
	0.0	0.0	2.0	2.0	39.0	36.0	36.0	2.0	2.0	2.0	79.0	
	20.	0.0	0.0	0.0	7	43.8	18.8	3	37.5	6	16	
200 MM P. GLASS	0.0	0.0	0.0	0.0	14.9	7.7	17.7	3	54.5	6.0	16.0	
	0.0	0.0	0.0	0.0	7.0	3.0	3.0	3	6.0	6.0	16.0	
	23.	0.0	0.0	0.0	1	25.0	0	0	3	3	4	
200 MM ALLOTHER	0.0	0.0	0.0	0.0	2.1	0.0	0.0	0.0	75.0	27.3	4.0	
	0.0	0.0	0.0	0.0	1.0	0.0	0.0	0.0	3.0	3.0	4.0	
	COLUMN TOTAL	1.0	1.0	2.0	47	47.0	39	39	11	11.0	100.0	

01/14/75

CCDEBOOK,MARGINALS,CROSSTABULATIONS BEFORE BREAKDOWN RECODING

FILE ATONAV13 (CREATION DATE = 01/14/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGDIST

VARIABLE VAR005 CONSTRUCTION

CODE	0.	11.	12.	17.	18.
ABSOLUTE FREQUENCY					
RELATIVE FREQUENCY (PERCENT)	1	72	3	6	2
CUMULATIVE FREQUENCY (PERCENT)	1.0	72.0	76.0	82.0	84.0
CODE	51.	52.	54.	57.	58.
ABSOLUTE FREQUENCY					
RELATIVE FREQUENCY (PERCENT)	7	1	1	5	2
CUMULATIVE FREQUENCY (PERCENT)	7.0	1.0	1.0	5.0	2.0
	91.0	92.0	93.0	98.0	100.0

VALID OBSERVATIONS = 100 OR 0.0 PERCENT OF TOTAL
MISSING OBSERVATIONS = 0

01/14/75

FILE ATCNAV13 (CREATION DATE = 01/14/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGDIST

VARIABLE VAR024 FIRST CHAIN LENGTH IN FATHOMS

CODE	0.	7.	15.	17.	18.
ABSOLUTE FREQUENCY					
RELATIVE FREQUENCY (PERCENT)	1	2	36	1	1
CUMULATIVE FREQUENCY (PERCENT)	1.0	2.0	36.0	1.0	1.0
		3.0	39.0	40.0	41.0
CODE	20.	22.	23.	24.	25.
ABSOLUTE FREQUENCY					
RELATIVE FREQUENCY (PERCENT)	2	5	4	1	4
CUMULATIVE FREQUENCY (PERCENT)	2.0	5.0	4.0	1.0	4.0
	43.0	48.0	52.0	53.0	57.0
CODE	26.	28.	30.	33.	38.
ABSOLUTE FREQUENCY					
RELATIVE FREQUENCY (PERCENT)	1	2	16	1	1
CUMULATIVE FREQUENCY (PERCENT)	1.0	2.0	16.0	1.0	1.0
	58.0	60.0	76.0	77.0	78.0
CODE	44.	45.	48.	50.	52.
ABSOLUTE FREQUENCY					
RELATIVE FREQUENCY (PERCENT)	1	8	1	3	1
CUMULATIVE FREQUENCY (PERCENT)	1.0	8.0	1.0	3.0	1.0
	79.0	87.0	88.0	91.0	92.0
CODE	57.	58.	60.	88.	99.
ABSOLUTE FREQUENCY					
RELATIVE FREQUENCY (PERCENT)	1	1	4	1	1
CUMULATIVE FREQUENCY (PERCENT)	1.0	1.0	4.0	1.0	1.0
	93.0	94.0	98.0	99.0	100.0

VALID OBSERVATIONS - 100 OR 0.0 PERCENT OF TOTAL
MISSING OBSERVATIONS - 0

FILE ATONAV13 (CREATION DATE = 01/14/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGDIST

VARIABLE VAR071 POWER UNIT,S REPLACED WITH REASON

VALUE LABEL	VALUE	ABSOLUTE FREQUENCY	RELATIVE FREQUENCY (PERCENT)	ADJUSTED FREQUENCY (PERCENT)	CUMULATIVE ADJ FREQ (PERCENT)
	42A	1	0.4	0.8	0.8
	42C	1	0.4	0.8	1.6
	42DX	3	1.1	2.4	4.0
	42DY	1	0.4	0.8	4.8
	42E	8	3.0	6.5	11.3
	42FC	4	1.5	3.2	14.5
	42FD	1	0.4	0.8	15.3
	42FI	1	0.4	0.8	16.1
	42FP	2	0.7	1.6	17.7
	42FS	1	0.4	0.8	18.5
	42G	2	0.7	1.6	20.2
	42K	8	3.0	6.5	26.6
	42L	7	2.6	5.6	32.3
	42M	2	0.7	1.6	33.9
	42QE	2	0.7	1.6	35.5
	42QM	1	0.4	0.8	36.3
	42S	41	15.3	33.1	69.4
	42T	6	2.2	4.8	74.2
	42TB	2	0.7	1.6	75.8
	42W	22	8.2	17.7	93.5
	42X	1	0.4	0.8	94.4
	81DX	1	0.4	0.8	95.2
	81DZ	1	0.4	0.8	96.0
	81FC	5	1.9	4.0	100.0

CODEBOOK, MARGINALS, CROSSTABULATIONS BEFORE BREAKDOWN RECODING 01/14/75
 FILE ATONAV13 (CREATION DATE = 01/14/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGOIST
 VARIABLE VAR071 POWER UNIT,S REPLACED WITH REASON

VALUE LABEL	VALUE	ABSOLUTE FREQUENCY	RELATIVE FREQUENCY (PERCENT)	ADJUSTED FREQUENCY (PERCENT)	CUMULATIVE ADJ. FREQ (PERCENT)
	42A	1	0.4	0.8	0.8
	42C	1	0.4	0.8	1.6
	42DX	3	1.1	2.4	4.0
	42DY	1	0.4	0.8	4.8
	42E	8	3.0	6.5	11.3
	42FC	4	1.5	3.2	14.5
	42FD	1	0.4	0.8	15.3
	42FI	1	0.4	0.8	16.1
	42FP	2	0.7	1.6	17.7
	42FS	1	0.4	0.8	18.5
	42G	2	0.7	1.6	20.2
	42K	8	3.0	6.5	26.6
	42L	7	2.6	5.6	32.3
	42M	2	0.7	1.6	33.9
	42QE	2	0.7	1.6	35.5
	42QM	1	0.4	0.8	36.3
	42S	41	15.3	33.1	69.4
	42T	6	2.2	4.8	74.2
	42TB	2	0.7	1.6	75.8
	42W	22	8.2	17.7	93.5
	42X	1	0.4	0.8	94.4
	81DX	1	0.4	0.8	95.2
	81DZ	1	0.4	0.8	96.0
	81FC	5	1.9	4.0	100.0

01/14/75

MISSING	100.0
-----	-----
53.7	100.0
-----	-----
TOTAL	268

VALID OBSERVATIONS - 124
MISSING OBSERVATIONS - 144

01/14/75

MISSING	100.0
-----	-----
53.7	100.0
-----	-----
TOTAL	268

VALID OBSERVATIONS - 66
MISSING OBSERVATIONS - 202

01/14/75

FILE ATONAV13 (CREATION DATE = 01/14/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGUIST

***** C R O S S T A B U L A T I O N O F *****
VAR072 BUOY RELIEVED WITH REASON BY VAR004 BUOY SIZE *****
***** PAGE 1 OF 1 *****

VAR004										
COUNT	16 X 20	7 X 15	7 X 17	8 X 26	9 X 32	9 X 38	ROW TOTAL			
ROW PCT	620.1	715.1	717.1	826.1	932.1	938.1				
COL PCT	40.0	20.0	20.0	0.0	0.0	20.0				
TOT PCT	100.0	100.0	100.0	0.0	0.0	33.3				
VAR072 CSE	2	1	1	0	0	1				
COLLISION	7.4	3.7	3.7	0.0	0.0	3.7				
CSE	0	0	0	18	2	2				
WEATHER	0.0	0.0	0.0	81.8	9.1	9.1				
COLUMN TOTAL	7.4	3.7	3.7	66.7	7.4	11.1				

FILE ATONAV13 (CREATION DATE = 01/14/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGDIST

***** C R O S S T A B U L A T I O N O F P E R C E N T E X P E C T E D B A T T E R Y L I F E U S E D *****
 VAR072 BUOY RELIEVED WITH REASON BY VARPER *****
 ***** PAGE 1 OF 2 *****

VARPER

 COUNT
 ROW PCT
 COL PCT
 TOT PCT

	10.00	30.00	50.00	65.00	75.00	85.00	95.00	115.00	150.00	ROW TOTAL
VAR072 87PJ	0 0.0 0.0 0.0	2 100.0 20.0 6.7	0 0.0 0.0 0.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	6.7
84W	0 0.0 0.0 0.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	1 100.0 50.0 3.3	0 0.0 0.0 0.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	3.3
43W	6 42.9 60.0 20.0	8 57.1 80.0 26.7	0 0.0 0.0 0.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	14 46.7
43S	0 0.0 0.0 0.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	1 100.0 100.0 3.3	0 0.0 0.0 0.0	3.3
43R	2 100.0 20.0 6.7	0 0.0 0.0 0.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	6.7
43PH	1 100.0 10.0 3.3	0 0.0 0.0 0.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	3.3
43M	0 0.0 0.0 0.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	1 50.0 50.0 3.3	0 0.0 0.0 0.0	1 50.0 50.0 3.3	0 0.0 0.0 0.0	0 0.0 0.0 0.0	6.7
COLUMN TOTAL	10 33.3	10 33.3	1 3.3	1 3.3	2 6.7	2 6.7	2 6.7	1 3.3	1 3.3	30 100.0

(CONTINUED)

FILE ATONAV13 (CREATION DATE = 01/14/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGDIST

***** C R O S S T A B U L A T I O N O F P E R C E N T E X P E C T E D B A T T E R Y L I F E U S E D *****
VAR072 BUOY RELIEVED WITH REASON BY VARPER *****
***** PAGE 2 OF 2 *****

VARPER

COUNT											ROW TOTAL
ROW PCT											
COL PCT											
TOT PCT											
VAR072	43L	43K	43G	43FP	43C	33.3	10.0	33.3	10.0	33.3	100.0
	13.3 10.0 3.3	0.0 0.0 0.0	0.0 0.0 0.0	0.0 0.0 0.0	0.0 0.0 0.0	0.0 0.0 0.0	0.0 0.0 0.0	0.0 0.0 0.0	0.0 0.0 0.0	33.3 100.0 3.3	10.0
	0.0 0.0 0.0	0.0 0.0 0.0	0.0 0.0 0.0	0.0 0.0 0.0	0.0 0.0 0.0	0.0 0.0 0.0	0.0 0.0 0.0	0.0 0.0 0.0	0.0 0.0 0.0	0.0 0.0 0.0	3.3
	0.0 0.0 0.0	0.0 0.0 0.0	100.0 100.0 3.3	0.0 0.0 0.0	0.0 0.0 0.0	0.0 0.0 0.0	0.0 0.0 0.0	0.0 0.0 0.0	0.0 0.0 0.0	0.0 0.0 0.0	3.3
	0.0 0.0 0.0	0.0 0.0 0.0	0.0 0.0 0.0	0.0 0.0 0.0	0.0 0.0 0.0	100.0 50.0 3.3	0.0 0.0 0.0	0.0 0.0 0.0	0.0 0.0 0.0	0.0 0.0 0.0	3.3
	0.0 0.0 0.0	0.0 0.0 0.0	0.0 0.0 0.0	0.0 0.0 0.0	0.0 0.0 0.0	100.0 50.0 3.3	0.0 0.0 0.0	0.0 0.0 0.0	0.0 0.0 0.0	0.0 0.0 0.0	3.3
	10.0 33.3 3.3	10.0 33.3 3.3	10.0 33.3 3.3	10.0 33.3 3.3	10.0 33.3 3.3	10.0 33.3 3.3	10.0 33.3 3.3	10.0 33.3 3.3	10.0 33.3 3.3	10.0 33.3 3.3	100.0

NUMBER OF MISSING OBSERVATIONS = 238

FILE ATUNAV13 (CREATION DATE = 01/14/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGOIST

VARIABLE VAR073 FLASHER REPLACED WITH REASON

VALUE LABEL	VALUE	ABSOLUTE FREQUENCY	RELATIVE FREQUENCY (PERCENT)	ADJUSTED FREQUENCY (PERCENT)	CUMULATIVE ADJ FREQ (PERCENT)
	46C	1	0.4	1.1	1.1
	46DN	1	0.4	1.1	2.1
	46DZ	4	1.5	4.3	6.4
	46E	8	3.0	8.5	14.9
	46FC	5	1.9	5.3	20.2
	46FD	1	0.4	1.1	21.3
	46FI	2	0.7	2.1	23.4
	46FW	1	0.4	1.1	24.5
	46G	2	0.7	2.1	26.6
	46J	2	0.7	2.1	28.7
	46K	17	6.3	18.1	46.8
	46L	12	4.5	12.8	59.6
	46M	4	1.5	4.3	63.8
	46N	4	1.5	4.3	68.1
	46O	2	0.7	2.1	70.2
	46R	4	1.5	4.3	74.5
	46TB	2	0.7	2.1	76.6
	46VB	1	0.4	1.1	77.7
	46W	20	7.5	21.3	98.9
	46ZG	1	0.4	1.1	100.0
	TOTAL	174	64.9	MISSING	100.0
		268	100.0	100.0	100.0

VALID OBSERVATIONS = 94
MISSING OBSERVATIONS = 174

CCDEBOOK,MARGINALS,CROSSTABULATIONS BEFORE BREAKDOWN RECODING

PAGE 86

01/14/75

FILE ATONAV13 (CREATION DATE = 01/14/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGDIST

VARIABLE VAR070 NG.BURNED OUT LAMPS REPLACED

CODE	0.	1.	2.	3.	4.
ABSOLUTE FREQUENCY	103	24	18	9	62
RELATIVE FREQUENCY (PERCENT)	38.4	9.0	6.7	3.4	23.1
CUMULATIVE FREQUENCY (PERCENT)	38.4	47.4	54.1	57.5	80.6
CODE	5.	6.	7.	8.	10.
ABSOLUTE FREQUENCY	9	36	2	1	1
RELATIVE FREQUENCY (PERCENT)	3.4	13.4	0.7	0.4	0.4
CUMULATIVE FREQUENCY (PERCENT)	84.0	97.4	98.1	98.5	98.9
CODE	11.	13.	16.		
ABSOLUTE FREQUENCY	1	1	1		
RELATIVE FREQUENCY (PERCENT)	0.4	0.4	0.4		
CUMULATIVE FREQUENCY (PERCENT)	99.3	99.6	100.0		

VALID OBSERVATIONS - 268 OR 0.0 PERCENT OF TOTAL
MISSING OBSERVATIONS - 0

01/14/75

FILE ATONAV13 (CREATION DATE = 01/14/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGOIST

VARIABLE VAR074 LAMPCHANGER REPLACED WITH REASON

CODE	47C	47DN	47DZ	47E	47FC
ABSOLUTE FREQUENCY	1	1	4	8	7
RELATIVE FREQUENCY (PERCENT)	1.1	1.1	4.4	8.8	7.7
CUMULATIVE FREQUENCY (PERCENT)	1.1	2.2	6.6	15.4	23.1
CODE	47FI	47FR	47G	47J	47K
ABSOLUTE FREQUENCY	1	1	2	1	17
RELATIVE FREQUENCY (PERCENT)	1.1	1.1	2.2	1.1	18.7
CUMULATIVE FREQUENCY (PERCENT)	24.2	25.3	27.5	28.6	47.3
CODE	47L	47M	47N	47O	47R
ABSOLUTE FREQUENCY	12	4	4	2	2
RELATIVE FREQUENCY (PERCENT)	13.2	4.4	4.4	2.2	2.2
CUMULATIVE FREQUENCY (PERCENT)	80.4	64.8	69.2	71.4	73.6
CODE	47TB	47VB	47W	47ZG	
ABSOLUTE FREQUENCY	2	1	20	1	
RELATIVE FREQUENCY (PERCENT)	2.2	1.1	22.0	1.1	
CUMULATIVE FREQUENCY (PERCENT)	75.8	76.9	98.9	100.0	

MISSING VALUES..

CODE

ABSOLUTE FREQUENCY

177

VALID OBSERVATIONS -

91

177 OR 66.0 PERCENT OF TOTAL

MISSING OBSERVATIONS -

FILE ATCNAV13 (CREATION DATE = 01/14/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGDIST

CROSS TABULATION OF LIGHT LIST NUMBER
VAR076 LANTERN-OPTIC REP.WITH REASON BY VAR001
***** PAGE 1 OF 1

COUNT		VAR001													ROW TOTAL
ROW PCT	COL PCT	1420.00	1432.00	1447.00	1449.00	1451.00	1460.00	1480.00	1502.00	1509.00	1514.00				
VAR076	DL%	100.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	10.0			
	OPORDER 067-71	100.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	10.0			
	DM%	0.0	11.1	11.1	11.1	11.1	11.1	11.1	11.1	11.1	11.1	90.0			
	OPORDER 152-72	0.0	100.0	100.0	100.0	100.0	100.0	100.0	100.0	100.0	100.0	90.0			
	COLUMN TOTAL	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	100.0			

FILE ATONAV13 (CREATION DATE = 01/14/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGDIST

VARIABLE VAR078 MAIN CAUSE FOR FAILURE OR RELATED NOTE

VALUE LABEL	VALUE	ABSOLUTE FREQUENCY	RELATIVE FREQUENCY (PERCENT)	ADJUSTED FREQUENCY (PERCENT)	CUMULATIVE ADJ FREQ (PERCENT)
POWER-BATTERY	22.	13	4.9	10.6	10.6
TARDY SERVICE	23.	1	0.4	0.8	11.4
FLOODED	26.	6	2.2	4.9	16.3
WEATHER	28.	41	15.3	33.3	49.6
COLLISION	30.	19	7.1	15.4	65.0
VANDALISM	31.	2	0.7	1.6	66.7
UNKNOWN	33.	8	3.0	6.5	73.2
ALL LAMPS	45.	7	2.6	5.7	78.9
FLASHER	46.	8	3.0	6.5	85.4
LAMPCHANGER	47.	6	2.2	4.9	90.2
WIRING	58.	5	1.9	4.1	94.3
FIRST CHAIN	61.	2	0.7	1.6	95.9
SINKER	63.	2	0.7	1.6	97.6
BUGY DETIORATION	69.	3	1.1	2.4	100.0
NONE	0.	145	54.1	MISSING	100.0
	TOTAL	268	100.0	100.0	100.0
VALID OBSERVATIONS -		123			
MISSING OBSERVATIONS -		145			

01/14/75

CODEBOOK,MARGINALS,CROSSTABULATIONS BEFORE BREAKDOWN RECODING

FILE ATONAV13 (CREATION DATE = 01/14/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGOIST

VARIABLE VAR079 MAIN CAUSE FOR FAILURE OR RELATED NOTE

VALUE LABEL	VALUE	ABSOLUTE FREQUENCY	RELATIVE FREQUENCY (PERCENT)	ADJUSTED FREQUENCY (PERCENT)	CUMULATIVE ADJ FREQ (PERCENT)
FALSE ALARM	3.	8	3.0	13.1	13.1
PERSONNEL ERROR	24.	9	3.4	14.8	27.9
WGRN-BKN MOORINGS	25.	8	3.0	13.1	41.0
UNKNOWN	33.	2	0.7	3.3	44.3
DAYLIGHT CTRL	50.	7	2.6	11.5	55.7
LANTERN	51.	1	0.4	1.6	57.4
SOUND SIGNAL	52.	1	0.4	1.6	59.0
SHACKLE	59.	1	0.4	1.6	60.7
MOORINGS RPLD PVUS	70.	3	1.1	4.9	65.6
POCK COV MSG	72.	1	0.4	1.6	67.2
COBN WX,YDZ,UKN,PE	81.	3	1.1	4.9	72.1
2ND CONSCV DISCY	84.	4	1.5	6.6	78.7
3RC + CONSCV DISCY	85.	12	4.5	19.7	98.4
VEE BAND	92.	1	0.4	1.6	100.0
NONE	0.	207	77.2	MISSING	100.0
TOTAL		268	100.0	100.0	100.0

VALID OBSERVATIONS - 61
MISSING OBSERVATIONS - 207

FILE ATONAV13 (CREATION DATE = 01/14/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGOIST
 VARIABLE VAR080 COMPONENT LOST-DAMAGED DURING SERVICING

VALUE LABEL	VALUE	ABSOLUTE FREQUENCY	RELATIVE FREQUENCY (PERCENT)	ADJUSTED FREQUENCY (PERCENT)	CUMULATIVE ADJ FREQ (PERCENT)
BUOY LOST NOT SALVGD	BL	7	2.6	29.2	29.2
BY FOUND OR SALVGD	BY	13	4.9	54.2	83.3
LOST MOORINGS	LM	3	1.1	12.5	95.8
BUOY NOT FOUND	MI	1	0.4	4.2	100.0
		244	91.0	MISSING	100.0
	TOTAL	268	100.0	100.0	100.0

VALID OBSERVATIONS = 24
 MISSING OBSERVATIONS = 244

01/15/75

FILE ATONAV13 (CREATION DATE = 01/15/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGDIST
VARIABLE VAR071 POWER UNIT,S REPLACED WITH REASON

VALUE LABEL	VALUE	ABSOLUTE FREQUENCY	RELATIVE FREQUENCY (PERCENT)	ADJUSTED FREQUENCY (PERCENT)	CUMULATIVE ADJ FREQ (PERCENT)
ROUTINE SERVICING	421.	43	34.7	34.7	34.7
ENVKRM TL HAZARDS	422.	37	29.8	29.8	64.5
TECH- ADMIN ERRORS	423.	1	0.8	0.8	65.3
PERSONNEL ERRORS	424.	15	12.1	12.1	77.4
CONVENIENCE-FOLLOWUP	426.	18	14.5	14.5	91.9
MANUFACTRG ERRORS	427.	10	8.1	8.1	100.0
	0.	0	0.0	MISSING	100.0
TOTAL		124	100.0	100.0	100.0

FILE ATCNV13 (CREATION DATE = 01/15/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGDIST

***** CROSSTABULATION OF *****
***** POWER UNITS REPLACED WITH REASON BY VAR007 LIGHT CHARACTERISTIC *****
***** VAR071 *****
***** PAGE 1 OF 1 *****

VAR007

COUNT		QK FL	MO A-4FL	MO A-ALL	FL 2.5	FL 2.5	FL 2.5	FL 4 .4	E INT	ROW TOTAL
ROW PCT		10.3	.6EC 2.0	OTHERS 1.46	.05* 251	.5** 255	404	6 3.0	630	
TUT PCT		103	145	146	251	255	404	630		
VAR071										
ENVANMTL HAZARDS		422	5	0	2	0	26	2	37	59.7
		13.5	5.4	0.0	5.4	0.0	70.3	5.4		
		45.5	100.0	0.0	100.0	0.0	61.9	100.0		
		8.1	3.2	0.0	3.2	0.0	41.9	3.2		
PERSONNEL ERRORS		424	5	0	0	1	9	0	15	24.2
		33.3	0.0	0.0	0.0	6.7	60.0	0.0		
		45.5	0.0	0.0	0.0	100.0	21.4	0.0		
		8.1	0.0	0.0	0.0	1.6	14.5	0.0		
MANUFACTG ERRORS		427	1	2	0	0	7	0	10	16.1
		10.0	0.0	20.0	0.0	0.0	70.0	0.0		
		9.1	0.0	100.0	0.0	0.0	16.7	0.0		
		1.6	0.0	3.2	0.0	0.0	11.3	0.0		
COLUMN TOTAL		17.7	3.2	3.2	3.2	1.6	67.7	3.2	62	100.0

VAR003												
COUNT	PROTEC	BAY, HAR	SEMI-EXP	SEMI-EXP	SEMI-EXP	EXPOSED	EXPOSED	EXPOSED	EXPOSED	EXPOSED	EXPOSED	ROW
RUM PCT	D RIVER	OR PROTE	D RIVER	D RIVER	D BAY, HA	RIVER	RIVER	RIVER	RIVER	RIVER	RIVER	TOTAL
TOT PCT	U	I	M	L	L	D	D	D	D	D	D	
422.	6	1	0	0	0	0	0	0	0	0	0	37
ENVRNMTL HAZARDS	16.2	2.7	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	59.7
	42.9	25.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	
	9.7	1.6	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	
424.	4	2	3	3	1	1	1	1	1	1	1	15
PERSONNEL ERRORS	26.7	13.3	20.0	6.7	6.7	13.3	13.3	13.3	13.3	13.3	13.3	24.2
	28.6	50.0	75.0	100.0	100.0	40.0	40.0	40.0	40.0	40.0	40.0	
	6.5	3.2	4.8	1.6	1.6	3.2	3.2	3.2	3.2	3.2	3.2	
427.	4	1	1	0	0	0	0	0	0	0	0	10
MANUFCTRG ERRORS	40.0	10.0	10.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	16.1
	28.6	25.0	25.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	
	6.5	1.6	1.6	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	
COLUMN	14	4	4	4	1	1	1	1	1	1	1	62
TOTAL	22.6	6.5	6.5	6.5	1.6	1.6	1.6	1.6	1.6	1.6	1.6	100.0

FILE ATONAV13 (CREATION DATE = 01/15/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGOIST

***** C R O S S T A B U L A T I O N O F *****
 VAR071 POWER UNIT,S REPLACED WITH REASON BY VAR004 BUOY SIZE *****
 ***** PAGE 1 OF 1 *****

VAR004

COUNT		10 X 39	5 X 10	6 X 20	7 X 15	7 X 17	8 X 20	8 X 23	8 X 26	9 X 32	9 X 38	ROW TOTAL
ROW PCT	422.	39.	510.	620.	715.	717.	820.	823.	826.	932.	938.	
COL PCT	422.	2.7	0.0	8.1	5.4	5.4	2.7	0.0	62.2	5.4	8.1	37
TOT PCT	422.	50.0	0.0	50.0	33.3	50.0	100.0	0.0	82.1	40.0	42.9	59.7
ENVRNMTL HAZARDS		1.6	0.0	4.8	3.2	3.2	1.6	0.0	37.1	3.2	4.8	
PERSONNEL ERRORS		0.0	0.0	13.3	6.7	13.3	0.0	13.3	26.7	13.3	13.3	15
MANUFACTG ERRORS		0.0	0.0	33.3	16.7	50.0	0.0	100.0	14.3	40.0	28.6	24.2
COLUMN TOTAL		0.0	0.0	3.2	1.6	3.2	0.0	3.2	6.5	3.2	3.2	
		10.0	1.0	10.0	30.0	0.0	0.0	0.0	10.0	10.0	20.0	10
		50.0	100.0	16.7	50.0	0.0	0.0	0.0	3.6	20.0	28.6	16.1
		1.6	1.6	1.6	4.8	0.0	0.0	0.0	1.6	1.6	3.2	
		3.2	1.6	9.7	9.7	6.5	1.6	3.2	28	8.1	11.3	62
									45.2			100.0

FILE ATCNV13 (CREATION DATE = 01/15/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGOIST

***** C R O S S T A B U L A T I O N O F V E N T V A L V E S P E R P O C K E T *****
VAR071 POWER UNIT,S REPLACED WITH REASON BY VAR006 ***** PAGE 1 OF 1

VAR006						ROW TOTAL
COUNT	1, BALL INSTALLED	2, BALLS INSTLD	1 VENT NO BALLS			
ROW PCT	1.1	2.1	3.1			
FUT PCT	1.1	2.1	3.1			
VAR071						
ENVRNMTL HAZARDS						
422.	35	0	2			37
	94.6	0.0	5.4			59.7
	62.5	0.0	40.0			
	56.5	0.0	3.2			
PERSONNEL ERRORS						
424.	13	0	2			15
	86.7	0.0	13.3			24.2
	23.2	0.0	40.0			
	21.0	0.0	3.2			
MANUFCTRG ERRORS						
427.	8	1	1			10
	80.0	10.0	10.0			16.1
	14.3	100.0	20.0			
	12.9	1.6	1.6			
COLUMN TOTAL						
	90.3	1.6	5.1			62
						100.0

***** C R O S S T A B U L A T I O N U F P O W E R S O U R C E - B A T T E R Y *****
***** VAR071 POWER UNIT,S REPLACED WITH REASON *****
***** VAR071 *****
***** PAGE 1 OF 1 *****

VAR012												
CGUNT	6000 A-H ,2EDISON#2 60E2	5000A-H EDISON-0 50BY	3000 A-H ,EDISON# 30E2	2500 A-H ,EDISON- 25BY	2000 A-H ,2EDSN 20S1	1000 A-H ,2EDISON 20JS	2000 A-H ,2EDISON 20E2	1000 A-H ,EDISON# 10E2	ROW TOTAL			
422.	4	3	2	3	1	1	21	2	37			
ENVNRMIL HAZARDS	10.8	8.1	5.4	8.1	2.7	2.7	56.8	5.4	59.7			
	60.7	42.9	66.7	42.9	100.0	25.0	72.4	40.0				
	8.5	4.8	3.2	4.8	1.6	1.6	33.9	3.2				
424.	1	2	1	3	0	0	6	2	15			
PERSONNEL ERRORS	6.7	15.3	6.7	20.0	0.0	0.0	40.0	13.3	24.2			
	16.7	28.6	33.3	42.9	0.0	0.0	20.7	40.0				
	1.6	3.2	1.6	4.8	0.0	0.0	9.7	3.2				
427.	1	2	0	1	0	3	2	1	10			
MANUFCTRG ERRORS	10.0	20.0	0.0	10.0	0.0	30.0	20.0	10.0	16.1			
	16.7	28.6	0.0	14.3	0.0	75.0	6.9	20.0				
	1.6	3.2	0.0	1.6	0.0	4.8	3.2	1.6				
COLUMN TOTAL	9.7	11.3	4.8	11.3	1.6	6.5	46.8	8.1	100.0			
	6	7	3	7	1	4	29	5	62			

FILE ATCNAV13 (CREATION DATE = 01/15/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGDIST

***** POWER UNIT,S REPLACED WITH REASON C R O S S T A B U L A T I O N O F *****
***** VAR071 ***** BY VAR014 LAMPCHANGER *****
***** PAGE 1 OF 1 *****

VAR014				ROW TOTAL	
COUNT					
ROW PCT					
CUL PCT					
TOT PCT					
422:					
ENVKMHIL HAZARDUS					
424:					
PERSONNEL ERRORS					
427:					
MANUFCTRG ERRORS					
COLUMN TOTAL					
15 LAMP,C 4 LAMP,F					
GUP CRUC U-1297					
65.					
10					
27.0					
76.9					
16.1					
43.5					
3					
20.0					
23.1					
4.8					
12					
80.0					
24.5					
19.4					
0					
0.0					
0.0					
0.0					
10					
100.0					
20.4					
16.1					
13					
21.0					
49					
79.0					
62					
100.0					

CCODEBOOK, MARGINALS, CROSS TABULATIONS AFTER BREAKDOWN RECODING

FILE ATCNAV13 (CREATION DATE = 01/15/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGOIST.

VAR071 POWER UNIT, S REPLACED WITH REASON C R Q S S T A B U L A T I O N F L A S H E R
VAR015 BY VAR015

VAR015		COUNT	C-R S-10	CG-181	C	VAPAIR	ROW
			65 SS	-R Dev.			TOTAL
VAR071	HAZARDS	422	5	32	0	83	37
			13.3	86.5	0.0		59.7
			38.5	68.1	0.0		
PERSONNEL	ERRORS	424	4	9	2		15
			26.7	60.0	13.3		24.2
			30.8	19.1	100.0		
MANUFACTRG	ERRORS	427	4	6	0		10
			40.0	60.0	0.0		16.1
			30.8	12.8	0.0		
	COLUMN TOTAL		13	47	2		62
			21.0	75.8	3.2		100.0

***** C R O S S T A B U L A T I O N O F S O U N D S I G N A L *****
***** POWER UNIT, S REPLACED WITH REASON *****
***** VAR071 *****

VAR016											
COUNT	NO SOUND	ELECTRIC	WHISTLE	BELL PRE	BELL 1952	BELL 1962	GONG 1952	GONG 1962	ROW		
ROW PCT	SIGNAL	HORN	4 BALL	1952 TP	TAPPER	TAPPER	TAPPER	TAPPER	TOTAL		
TOT PCT	0.	40.	79.	81.	82.	83.	85.	86.			
VAR071	422.	15	0	0	3	3	1	5	37		
	HAZARDS	40.5	0.0	0.0	8.1	8.1	2.7	13.5	59.7		
		53.6	0.0	0.0	75.0	75.0	100.0	83.3			
	24.2	0.0	16.1	0.0	4.8	4.8	1.6	8.1			
PERSONNEL	424.	7	1	0	1	1	0	1	15		
	ERRORS	46.7	6.7	0.0	6.7	6.7	0.0	6.7	24.2		
		25.3	100.0	0.0	25.0	25.0	0.0	16.7			
	11.3	1.6	6.5	0.0	1.6	1.6	0.0	1.6			
MANUFACTRG	427.	6	0	1	0	0	0	0	10		
	ERRORS	60.0	0.0	10.0	0.0	0.0	0.0	0.0	16.1		
		21.4	0.0	100.0	0.0	0.0	0.0	0.0			
	9.7	0.0	4.8	1.6	0.0	0.0	0.0	0.0			
COLUMN	428.	28	1	1	4	4	1	9	62		
	TOTAL	45.2	1.6	17	1.6	6.5	1.6	9.7	100.0		
			27.4								

FILE ATONAV13 (CREATION DATE = 01/15/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGDIST

VAR071 POWER UNIT,S REPLACED WITH REASON C R O S S T A B U L A T I O N O F DAYLIGHT CONTROL BY VAR017 *** PAGE 1 OF 1

VAR017						
COUNT	CR-S1065	C-CLEAR-	R-COLOR	B-COLOR	ROW	
ROW PCT	LS MNTD	ALL	PLASTIC	GLASS	TOTAL	
422.	13.	31.	32.	33.	37	
CUL PCT					59.7	
TOT PCT						
VAR071						
ENVNRMTL HAZARDS						
424.	2.7	19	13	4		
PERSONNEL ERRORS	100.0	51.4	35.1	10.8		
	1.6	63.3	55.0	36.4		
		30.6	21.0	6.5		
	0	4	6	5		
	0.0	26.7	40.0	33.3		
	0.0	13.3	30.0	45.5		
	0.0	6.5	9.7	8.1		
MANUFCTRG ERRORS						
427.	0	7	1	2		
	0.0	70.0	10.0	20.0		
	0.0	23.3	5.0	18.2		
	0.0	11.3	1.6	3.2		
	1	30	20	11		
	1.6	48.4	32.3	17.7		
COLUMN TOTAL					62	
					100.0	

FILE ATONAV13 (CREATION DATE = 01/15/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGDIST

***** C R O S S T A B U L A T I O N O F B O T T O M D E S C R I P T I O N *****
VAR071 POWER UNIT, S REPLACED WITH REASON *****
***** BY VAR018 *****
***** PAGE 1 OF 1 *****

		VAR018				ROW TOTAL	
		COUNT	SAND	ROCK	MUD	GRAVEL	
		RUM PCT	S	R	M	G	
		COL PCT					
		TOT PCT					
VAR071	ENVKRM TL HAZARDS	422	25	6	4	2	37
			67.6	16.2	10.8	5.4	59.7
			65.8	85.7	30.8	50.0	
			40.3	9.7	6.5	3.2	
	PERSONNEL ERRORS	424	9	1	4	1	15
			90.0	6.7	26.7	6.7	24.2
			23.7	14.3	30.8	25.0	
			14.5	1.6	6.5	1.6	
	MANUFACTG ERRORS	427	4	0	5	1	10
			40.0	0.0	50.0	10.0	16.1
			10.5	0.0	38.5	25.0	
			6.5	0.0	8.1	1.6	
	COLUMN TOTAL		38	7	13	4	62
			91.3	11.3	21.0	6.5	100.0

FILE ATONAV13 (CREATION DATE = 01/15/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGDIST

***** POWER UNIT, S REPLACED WITH REASON C R O S S T A B U L A T I O N O F B R I D L E S I Z E *****
***** VAR071 ***** BY VAR021 ***** PAGE 1 OF 1

VAR021									
COUNT	1"	X12"	1"	X 15"	1"	1-4"	X 18"	1-2"	X 26"
ROW PCT	2.1	2.1	1.1	3.1	15.1	4.1	6.1	7.1	7.1
CUL PCT	2.1	2.1	1.1	3.1	15.1	4.1	6.1	7.1	7.1
TOT PCT	2.1	2.1	1.1	3.1	15.1	4.1	6.1	7.1	7.1
422.	2	5.4	2.7	1	28	2	2	4	37
ENVRNMTL HAZARDS	40.0	100.0	100.0	66.7	75.7	5.4	33.3	10.8	59.7
	3.2	1.6	1.6	45.2	66.7	3.2	3.2	50.0	
								6.5	
424.	1	6.7	0.0	0	10	2	2	2	15
PERSONNEL ERRORS	20.0	0.0	0.0	66.7	66.7	13.3	33.3	15.3	24.2
	1.6	0.0	0.0	22.8	22.8	3.2	3.2	25.0	
				16.1	16.1	3.2	3.2	3.2	
427.	2	20.0	0.0	0	4	2	2	2	10
MANUFCTRG ERRORS	40.0	0.0	0.0	40.0	40.0	20.0	33.3	20.0	16.1
	3.2	0.0	0.0	9.5	9.5	3.2	3.2	25.0	
				6.5	6.5	3.2	3.2	3.2	
COLUMN TOTAL	5	8.1	1.6	42	67.7	9.7	9.7	12.9	62
									100.0

FILE ATONAV13 (CREATION DATE = 01/15/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGDIST

***** C R O S S T A B U L A T I O N O F *****
***** P O W E R U N I T S R E P L A C E D W I T H R E A S O N *****
***** V A R O 2 3 B Y V A R O 2 3 F I R S T C H A I N S I Z E *****
***** P A G E 1 O F 1 *****

VAR023

COUNT		1	1-4"	1	1-2"	1	5-8"AN	ROW
RUM PCT		1	1-4"	1	1-2"	1	5-8"AN	TOTAL
COL PCT		6.1	7.1	7.1	7.1	7.1	8.1	
TOT PCT		6.1	7.1	7.1	7.1	7.1	8.1	
VAR071	ENVIRONMTL HAZARDS	6	16.2	18.9	50.0	64.9	24	37
		40.0	50.0	72.7	38.7	40.0	15	59.7
		9.7	11.3	33.3	18.2	19.7	24.2	
PERSONNEL ERRORS		4	26.7	33.3	40.0	6	15	24.2
		26.7	33.3	40.0	6	15	24.2	
		6.5	8.1	9.7	10	16.1		
MANUFACTG ERRORS		5	50.0	20.0	30.0	3	10	16.1
		33.3	14.3	14.3	9.1	4.8	10	16.1
		8.1	3.2	3.2	4.8	33	62	
COLUMN TOTAL		15	24.2	22.6	53.2	100.0		

FILE ATCNAV13 (CREATION DATE = 01/15/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGOIST

***** C R O S S T A B U L A T I O N O F *****
***** POWER UNIT,S REPLACED WITH REASON *****
***** VAR071 ***** BY VAR065 *****
***** RATED BATTERY DISCHARGE TIME *****
***** PAGE 1 OF 2 *****

VAR069

COUNT		1054.	1066.	1083.	1298.	2025.	2152.	2163.	2197.	2210.	2250.	ROW TOTAL
ROW PCT	422.	0	1	0	1	1	20	1	2	1	0	31
COL PCT	HAZARDS	0.0	3.2	0.0	3.2	3.2	64.5	3.2	6.5	3.2	0.0	58.5
TOT PCT		0.0	34.5	0.0	33.3	33.3	74.1	100.0	50.0	100.0	0.0	
		0.0	1.9	0.0	1.9	1.9	37.7	1.9	3.8	1.9	0.0	
PERSONNEL		1	2	1	1	2	3	0	1	0	0	14
424.	ERRORS	7.1	14.3	7.1	7.1	14.3	21.4	0.0	7.1	0.0	0.0	26.4
		100.0	66.7	100.0	33.3	66.7	11.1	0.0	25.0	0.0	0.0	
		1.9	3.8	1.9	1.9	3.8	5.7	0.0	1.9	0.0	0.0	
MANUFACTRG		0	0	0	1	0	4	0	1	0	1	8
427.	ERRORS	0.0	0.0	0.0	12.5	0.0	50.0	0.0	12.5	0.0	12.5	15.1
		0.0	0.0	0.0	33.3	0.0	14.8	0.0	25.0	0.0	100.0	
		0.0	0.0	0.0	1.9	0.0	7.5	0.0	1.9	0.0	1.9	
COLUMN TOTAL		1	3	1	3	3	27	1	4	1	1	53
		1.9	5.7	1.9	5.7	5.7	50.9	1.9	7.5	1.9	1.9	106.0

(CONTINUED)

VAR071 POWER UNIT, S REPLACED WITH REASON OF R O S S T A B U L A T I O N O F R A T E D B A T T E R Y D I S C H A R G E T I M E

		VAR069		ROW TOTAL	
		COUNT	ROW PCT	COUNT	ROW PCT
VAR071		COUNT	ROW PCT	COUNT	ROW PCT
ENVRNMTL HAZARDS		422.		3000.	
		1	3.2	3	31
		100.0	9.7	9.7	59.5
		1.9	42.9	5.7	
PERSONNEL ERRORS		424.		3	14
		0.0	21.4	21.4	26.4
		0.0	42.9	5.7	
MANUFACTRG ERRORS		427.		1	8
		0.0	12.5	12.5	15.1
		0.0	14.3	1.9	
		0.0	1.9	1.9	
COLUMN TOTAL				7	53
		1.9	13.2	100.0	

NUMBER OF MISSING OBSERVATIONS = 9

FILE ATONAV13 ICREATION DATE = 01/15/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGDIST

VARIABLE VARPER PERCENT EXPECTED BATTERY LIFE USED

CODE	3.00	4.00	6.00	7.00	9.00
ABSOLUTE FREQUENCY	2	1	2	3	1
RELATIVE FREQUENCY (PERCENT)	2.1	1.0	2.1	3.1	1.0
CUMULATIVE FREQUENCY (PERCENT)	2.1	3.1	5.2	8.3	9.4
CODE	11.00	16.00	19.00	22.00	24.00
ABSOLUTE FREQUENCY	3	1	1	1	2
RELATIVE FREQUENCY (PERCENT)	3.1	1.0	1.0	1.0	2.1
CUMULATIVE FREQUENCY (PERCENT)	12.5	13.5	14.6	15.6	17.7
CODE	25.00	27.00	29.00	31.00	32.00
ABSOLUTE FREQUENCY	2	1	3	1	2
RELATIVE FREQUENCY (PERCENT)	2.1	1.0	3.1	1.0	2.1
CUMULATIVE FREQUENCY (PERCENT)	19.8	20.8	24.0	25.0	27.1
CODE	33.00	34.00	35.00	36.00	41.00
ABSOLUTE FREQUENCY	1	2	1	1	1
RELATIVE FREQUENCY (PERCENT)	1.0	2.1	1.0	1.0	1.0
CUMULATIVE FREQUENCY (PERCENT)	28.1	30.2	31.2	32.3	33.3
CODE	42.00	43.00	47.00	51.00	52.00
ABSOLUTE FREQUENCY	1	1	2	1	1
RELATIVE FREQUENCY (PERCENT)	1.0	1.0	2.1	1.0	1.0
CUMULATIVE FREQUENCY (PERCENT)	34.4	35.4	37.5	38.5	39.6
CODE	58.00	59.00	64.00	65.00	67.00
ABSOLUTE FREQUENCY	2	1	2	2	1
RELATIVE FREQUENCY (PERCENT)	2.1	1.0	2.1	2.1	1.0
CUMULATIVE FREQUENCY (PERCENT)	41.7	42.7	44.8	46.9	47.9
CODE	68.00	72.00	73.00	75.00	77.00
ABSOLUTE FREQUENCY	1	1	2	1	2
RELATIVE FREQUENCY (PERCENT)	1.0	1.0	2.1	1.0	2.1
CUMULATIVE FREQUENCY (PERCENT)	49.0	50.0	52.1	53.1	55.2

CODEBOOK, MARGINALS, CROSSTABULATIONS AFTER BREAKDOWN RECODING

PAGE 30

01/15/75

CODE	79.00	82.00	83.00	84.00	85.00
ABSOLUTE FREQUENCY	2	1	3	1	1
RELATIVE FREQUENCY (PERCENT)	2.1	1.0	3.1	1.0	1.0
CUMULATIVE FREQUENCY (PERCENT)	57.3	58.3	61.5	62.5	63.5
CODE	86.00	87.00	88.00	89.00	91.00
ABSOLUTE FREQUENCY	2	2	1	2	3
RELATIVE FREQUENCY (PERCENT)	2.1	2.1	1.0	2.1	3.1
CUMULATIVE FREQUENCY (PERCENT)	65.6	67.7	68.7	70.8	74.0
CODE	92.00	94.00	95.00	96.00	98.00
ABSOLUTE FREQUENCY	1	4	1	1	1
RELATIVE FREQUENCY (PERCENT)	1.0	4.2	1.0	1.0	1.0
CUMULATIVE FREQUENCY (PERCENT)	75.0	79.2	80.2	81.2	82.3
CODE	100.00	101.00	103.00	105.00	107.00
ABSOLUTE FREQUENCY	5	1	1	1	1
RELATIVE FREQUENCY (PERCENT)	5.2	1.0	1.0	1.0	1.0
CUMULATIVE FREQUENCY (PERCENT)	87.5	88.5	89.6	90.6	91.7
CODE	108.00	110.00	111.00	113.00	115.00
ABSOLUTE FREQUENCY	1	2	1	1	1
RELATIVE FREQUENCY (PERCENT)	1.0	2.1	1.0	1.0	1.0
CUMULATIVE FREQUENCY (PERCENT)	92.7	94.8	95.8	96.9	97.9
CODE	121.00	164.00			
ABSOLUTE FREQUENCY	1	1			
RELATIVE FREQUENCY (PERCENT)	1.0	1.0			
CUMULATIVE FREQUENCY (PERCENT)	99.0	100.0			

MISSING VALUES..

CODE 0.0

ABSOLUTE FREQUENCY 172

CCDEBOOK,MARGINALS,CROSSTABULATIONS AFTER BREAKDOWN RECODING

FILE ATONAV13 (CREATION DATE = 01/15/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGOIST

01/15/75

PAGE 31

DESIRED STATISTICS..

MEAN	63.823	STU ERROR	3.670	MEDIAN	72.500
MODE	100.000	STD DEV	35.955	VARIANCE	1292.758
KURTOSIS	-0.864	SKEWNESS	-0.069	RANGE	161.000
MINIMUM	3.000	MAXIMUM	164.000		

VALID OBSERVATIONS - 96

MISSING OBSERVATIONS - 172 OR 64.2 PERCENT OF TOTAL

FILE ATONAV13 (CREATION DATE = 01/15/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGDIST

***** C R O S S T A B U L A T I O N O F *****
***** LOCATION ***** BY VARPER ***** PERCENT EXPECTED BATTERY LIFE USED *****
***** VAR003 *****
***** PAGE 1 OF 1 *****

		VARPER											ROW TOTAL
		10.00	30.00	50.00	65.00	75.00	85.00	95.00	105.00	115.00	150.00		
VAR003	COUNT ROW PCT COL PCT TOT PCT												
	PROTECTED RIVER	2 6.7 14.3 2.1	3 10.0 17.6 3.1	2 6.7 20.0 2.1	3 10.0 50.0 3.1	3 10.0 37.5 3.1	7 23.3 53.8 7.3	6 20.0 37.5 6.3	2 6.7 28.6 2.1	1 3.3 25.0 1.0	1 3.3 100.0 1.0	30 31.3	
T	BAY,HARBO R PROTE	0.0 0.0 0.0 0.0	0.0 0.0 0.0 0.0	20.0 20.0 2.1	10.0 16.7 1.0	20.0 25.0 2.1	10.0 17.7 1.0	20.0 12.5 2.1	10.0 14.3 1.0	10.0 25.0 1.0	0.0 0.0 0.0	10.4	
	SEMI-EXPD RIVER	0.0 0.0 0.0 0.0	20.0 11.8 2.1	0.0 0.0 0.0	0.0 0.0 0.0	0.0 0.0 0.0	20.0 15.4 2.1	50.0 31.3 5.2	10.0 14.3 1.0	0.0 0.0 0.0	0.0 0.0 0.0	10.4	
L	SEMI-EXPC BAY,HA	33.3 7.1 1.0	0.0 0.0 0.0	0.0 0.0 0.0	0.0 0.0 0.0	0.0 0.0 0.0	33.3 7.7 1.0	33.3 6.3 1.0	0.0 0.0 0.0	0.0 0.0 0.0	0.0 0.0 0.0	3.1	
	EXPOSED RIVER	40.0 14.3 2.1	0.0 0.0 0.0	0.0 0.0 0.0	0.0 0.0 0.0	10.0 12.5 1.0	20.0 7.7 1.0	0.0 0.0 0.0	20.0 14.3 1.0	0.0 0.0 0.0	0.0 0.0 0.0	5.2	
C	EXPOSED BAY,HARB	0.0 0.0 0.0 0.0	0.0 0.0 0.0 0.0	0.0 0.0 0.0	0.0 0.0 0.0	0.0 0.0 0.0	0.0 0.0 0.0	0.0 0.0 0.0	100.0 14.3 1.0	0.0 0.0 0.0	0.0 0.0 0.0	1.0	
	EXPOSED SEA COAS	24.3 64.3 5.4	12 52.4 70.8 12.5	6 16.2 60.0 6.3	2 5.4 33.3 2.1	2 5.0 25.0 2.1	1 2.7 7.7 1.0	2 5.4 12.5 2.1	1 2.7 14.3 1.0	2 5.4 50.0 2.1	0.0 0.0 0.0	37 38.5	
COLUMNS TOTAL		14 14.6	17 17.7	10 10.4	6 6.3	8 8.3	13 13.5	16 16.7	7 7.3	4 4.2	1 1.0	96 100.0	

NUMBER OF MISSING OBSERVATIONS = 172

FILE ATONAV13 (CREATION DATE = 01/15/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGOIST

***** C R O S S T A B U L A T I O N O F P E R C E N T E X P E C T E D B A T T E R Y L I F E U S E D *****
VAR004 BUCY SIZE *****

PAGE 1 OF 2

		VARPER											ROW TOTAL	
		COUNT	10.001	30.001	50.001	65.001	75.001	85.001	95.001	105.001	115.001	150.001	1.0	1.0
VAR004	10 X 39	ROW PCT COL PCT TOT PCT	10.001	30.001	50.001	65.001	75.001	85.001	95.001	105.001	115.001	150.001		
	39.		0.0	0.0	0.0	100.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
			0.0	0.0	0.0	16.7	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
			0.0	0.0	0.0	1.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
	510.		0.0	0.0	0.0	100.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
			0.0	0.0	0.0	16.7	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
			0.0	0.0	0.0	1.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
	620.		1.1	11.1	0.0	22.2	0.0	33.3	0.0	11.1	11.1	0.0	0.0	0.0
			17.1	5.9	0.0	33.3	0.0	23.1	0.0	14.3	25.0	0.0	0.0	0.0
			1.0	1.0	0.0	2.1	0.0	3.1	0.0	1.0	1.0	0.0	0.0	0.0
	715.		0.0	0.0	1.3	8.3	2	25.0	16.7	8.3	8.3	1	8.3	1
			0.0	0.0	10.0	16.7	25.0	23.1	12.5	14.3	25.0	100.0	1.0	1.0
			0.0	0.0	1.0	1.0	2.1	3.1	2.1	1.0	1.0	1.0	1.0	1.0
	717.		0.0	20.0	10.0	0.0	20.0	20.0	20.0	10.0	0.0	0.0	0.0	0.0
			0.0	11.8	10.0	0.0	25.0	15.4	12.5	14.3	0.0	0.0	0.0	0.0
			0.0	2.1	1.0	0.0	2.1	2.1	2.1	1.0	0.0	0.0	0.0	0.0
	820.		0.0	1	0.0	0.0	0.0	0.0	1	0.0	0.0	0.0	0.0	0.0
			0.0	50.0	0.0	0.0	0.0	0.0	50.0	0.0	0.0	0.0	0.0	0.0
			0.0	1.0	0.0	0.0	0.0	0.0	1.0	0.0	0.0	0.0	0.0	0.0
	823.		1	0.0	0.0	0.0	0.0	1	0.0	2	0.0	0.0	0.0	0.0
			25.0	0.0	0.0	0.0	0.0	25.0	0.0	50.0	0.0	0.0	0.0	0.0
			7.1	0.0	0.0	0.0	0.0	7.7	0.0	28.6	0.0	0.0	0.0	0.0
			1.0	0.0	0.0	0.0	0.0	1.0	0.0	2.1	0.0	0.0	0.0	0.0
	COLUMN TOTAL		14	17.7	10.4	6.3	8.3	13.3	16.7	7.3	4.2	1	4.2	1.0
	TOTAL		14.6	17.7	10.4	6.3	8.3	13.3	16.7	7.3	4.2	1	4.2	1.0

(CONTINUED)

FILE ATONAV13 (CREATION DATE = 01/15/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGDIST

***** C R O S S T A B U L A T I O N O F P E R C E N T E X P E C T E D B A T T E R Y L I F E U S E D *****
VAR004 BUOY SIZE BY VARPER

		VARPER											ROW TOTAL
		10.00	30.00	50.00	55.00	75.00	85.00	95.00	105.00	115.00	150.00		
VAR004	COUNT												
	ROW PCI TOT PCI												
8 X 26	826.	10	12	3	0	4	2	9	1	0	0	41	
		24.4	29.3	7.3	0.0	9.8	4.9	22.0	2.4	0.0	0.0	42.7	
		71.4	70.6	30.0	0.0	50.0	15.4	56.3	14.3	0.0	0.0		
		10.4	12.5	3.1	0.0	4.2	2.1	9.4	1.0	0.0	0.0		
9 X 32	932.	1	0	2	1	0	1	1	0	2	0	8	
		12.5	0.0	25.0	12.5	0.0	12.5	12.5	0.0	25.0	0.0	8.3	
		17.1	0.0	20.0	16.7	0.0	7.7	6.3	0.0	50.0	0.0		
		1.0	0.0	2.1	1.0	0.0	1.0	1.0	0.0	2.1	0.0		
9 X 34	934.	0	0	1	0	0	0	0	0	0	0	1	
		0.0	0.0	100.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	1.0	
		0.0	0.0	10.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0		
		0.0	0.0	1.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0		
9 X 38	938.	1	1	2	0	0	1	1	1	0	0	7	
		14.3	14.3	28.0	0.0	0.0	14.3	14.3	14.3	0.0	0.0	7.3	
		7.1	5.9	20.0	0.0	0.0	7.7	6.3	14.3	0.0	0.0		
		1.0	1.0	2.1	0.0	0.0	1.0	1.0	1.0	0.0	0.0		
COLUMNS TOTAL		14	17	10	6	8	13	16	7	4	1	98	
		14.6	17.7	10.4	6.3	8.3	13.3	16.7	7.5	4.2	1.0	100.0	

NUMBER OF MISSING OBSERVATIONS = 172

FILE ATONAV13 (CREATION DATE = 01/15/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGDIST

***** C R O S S T A B U L A T I O N O F P E R C E N T E X P E C T E D B A T T E R Y L I F E U S E D *****
VAR006 VENT VALVES PER POCKET *****
***** PAGE 1 OF 1

		VARPER												ROW TOTAL
COUNT		10.00	30.00	50.00	65.00	75.00	85.00	95.00	105.00	115.00	150.00			
ROW PCT	COL PCT													
TOT PCT														
VAR006	1. BALL INSTALLED	13 16.0 92.9 13.5	16 19.8 94.1 16.7	10 12.3 100.0 10.4	5 6.2 83.3 5.2	6 7.4 75.0 6.3	11 13.6 84.6 11.5	11 13.6 68.8 11.5	3 3.7 75.0 3.1	5 6.2 71.4 5.2	0 0.0 0.0 0.0	1 1.2 100.0 1.0	81 84.4	
	2. BALLS INSTLD	0 0.0 0.0	0 0.0 0.0	0 0.0 0.0	1 100.0 16.7 1.0	0 0.0 0.0	0 0.0 0.0	0 0.0 0.0	0 0.0 0.0	0 0.0 0.0	0 0.0 0.0	0 0.0 0.0	1.0	
	3. VENT ,NO BALLS	7 7.7 1.0	7 7.7 1.0	0 0.0 0.0	0 0.0 0.0	2 15.4 25.0 2.1	2 15.4 15.4 2.1	5 38.5 31.2 5.2	1 7.7 14.3 1.0	1 7.7 14.3 1.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	13 13.5	
VAR006	2 VENTS,NO BALLS	0 0.0 0.0	0 0.0 0.0	0 0.0 0.0	0 0.0 0.0	0 0.0 0.0	0 0.0 0.0	0 0.0 0.0	1 100.0 14.3 1.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	1.0	
	COLUMN TOTAL	14 14.6	17 17.7	10 10.4	6 6.3	8 8.3	13 13.5	16 16.7	7 7.3	4 4.2	1 1.0	96 100.0		

NUMBER OF MISSING OBSERVATIONS = 172

FILE ATONAV13 (CREATION DATE = 01/15/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGDIST

***** CROSSTABULATION OF *****
***** LIGHT CHARACTERISTIC *****
***** BY VARPER *****
***** PERCENT EXPECTED BATTERY LIFE USED *****
***** PAGE 1 OF 1 *****

		VARPER											ROW TOTAL
		10.00	30.00	50.00	65.00	75.00	85.00	95.00	105.00	115.00	150.00		
VAR007	CCOUNT	1	1	5	1	1	2	1	1	1	1	18	
	ROW PCT	5.6	5.6	27.8	5.6	5.6	11.1	5.6	22.2	5.6	5.6	18.8	
	CUL PCT	7.1	5.9	50.0	16.7	12.5	15.4	6.3	57.1	25.0	100.0		
	TOT PCT	1.0	1.0	5.2	1.0	1.0	2.1	1.0	4.2	1.0	1.0		
QK FL 0.3													
MO A.4FL.6EC,2.0	145.	0	0	0	1	0	0	0	0	0	0	1.0	
		0.0	0.0	0.0	100.0	0.0	0.0	0.0	0.0	0.0	0.0		
		0.0	0.0	0.0	13.7	0.0	0.0	0.0	0.0	0.0	0.0		
		0.0	0.0	0.0	1.0	0.0	0.0	0.0	0.0	0.0	0.0		
FL 2.5 .5#													
FL 2.5 .5#	255.	0	0	0	0	1	0	0	0	0	0	1.0	
		0.0	0.0	0.0	0.0	100.0	0.0	0.0	0.0	0.0	0.0		
		0.0	0.0	0.0	0.0	12.5	0.0	0.0	0.0	0.0	0.0		
		0.0	0.0	0.0	0.0	1.0	0.0	0.0	0.0	0.0	0.0		
FL 4 .4	404.	13	16	5	4	6	11	15	3	5	0	76	
		17.1	21.1	6.6	5.3	7.9	14.5	15.7	3.9	3.9	0.0		
		92.9	94.1	50.0	66.7	75.0	84.8	93.8	42.9	75.0	0.0		
	13.5	16.7	5.2	4.2	6.3	11.5	15.6	3.1	3.1	0.0	79.2		
COLUMN TOTAL													
TOTAL		14	17	10	6	8	13	16	7	4	1	96	
		14.6	17.7	10.4	6.3	8.3	13.5	16.7	7.3	4.2	1.0		

NUMBER OF MISSING OBSERVATIONS = 172

VARPER													ROW TOTAL
CCOUNT													
ROW PCT													
COL PCT													
TOT PCT													
VAR12	60S1	10.00	30.00	50.00	65.00	75.00	85.00	95.00	105.00	115.00	150.00		
6000 A-H,2 EDSN	100.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	1.0	
	7.1	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	
	1.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	
60E2	0.0	1	0	0	0	0	0	0	0	0	0	0	4.2
6000 A-H,2EDSN#2	0.0	25.0	75.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	
	0.0	5.9	30.1	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	
	0.0	1.0	3.1	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	
50BY	0.0	0	2	0	1	0	0	1	1	0	0	0	5.2
5000A-H,EDISON-C	0.0	0.0	40.0	0.0	20.0	0.0	0.0	20.0	20.0	0.0	0.0	0.0	
	0.0	0.0	20.0	2.1	16.7	0.0	0.0	9.3	14.3	0.0	0.0	0.0	
	0.0	0.0	0.0	1.0	1.0	0.0	0.0	1.0	1.0	0.0	0.0	0.0	
30E2	0.0	33.3	0	0	33.3	0	0	33.3	0.0	0.0	0.0	0	3.1
3000 A-H,EDISON#	0.0	5.9	0.0	0.0	16.7	0.0	0.0	6.3	0.0	0.0	0.0	0.0	
	0.0	1.0	0.0	0.0	1.0	0.0	0.0	1.0	0.0	0.0	0.0	0.0	
25BY	0.0	0	1	0	0	3	20.0	7	1	0	0	0	15.6
2500 A-H,EDISON-	0.0	0.0	0.0	6.7	0.0	20.0	23.1	46.7	16.7	0.0	0.0	0.0	
	0.0	0.0	0.0	10.0	0.0	37.5	3.1	48.8	14.3	0.0	0.0	0.0	
	0.0	0.0	0.0	1.0	0.0	3.1	0.0	7.3	1.0	0.0	0.0	0.0	
20S1	0.0	100.0	0	0	0	0	0	0	0	0	0	0	1.0
2000 A-H,2 EDSN	0.0	5.9	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	
	0.0	1.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	
20JS	0.0	0	0	1	1	1	0	2	0	1	0	0	6.3
1000 A-H,2EDISON	0.0	0.0	16.7	16.7	16.7	16.7	0.0	33.3	0.0	16.7	0.0	0.0	
	0.0	0.0	10.0	10.0	10.0	12.5	0.0	12.5	0.0	25.0	0.0	0.0	
	0.0	0.0	0.0	1.0	1.0	1.0	0.0	2.1	0.0	1.0	0.0	0.0	
COLUMN TOTAL	14	17.7	10	6	8	13	13.5	16	7	4	1	96	
	14.6	17.7	10.4	6.3	8.3	13.5	13.5	16.7	7.3	4.2	1.0	100.0	

(CONTINUED)

FILE ATONAV13 (CREATION DATE = 01/15/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGDIST

***** C R O S T A B U L A T I O N O F P E R C E N T E X P E C T E D B A T T E R Y L I F E U S E D *****
VAR012 POWER SOURCE-BATTERY BY VARPER *****

		VARPER													ROW TOTAL
		10.00	30.00	50.00	65.00	75.00	85.00	95.00	105.00	115.00	150.00				
COUNT															
ROW PCT															
COL PCT															
TOT PCT															
VAR012	20E2	10	12	2	2	2	9	1	3	1	1	43			
2000	A-H,2EDISON	23.3	27.9	4.7	4.7	4.7	20.9	2.3	7.0	2.3	2.3	44.8			
		71.4	70.6	20.0	33.3	25.0	69.2	6.3	42.9	25.0	100.0				
		10.4	12.5	2.1	2.1	2.1	9.4	1.0	3.1	1.0	1.0				
1000	10JS	0	0	1	0	0	0	1	0	0	0	2			
1000	A-H,EDISONJ	0.0	0.0	50.0	0.0	0.0	0.0	50.0	0.0	0.0	0.0	2.1			
		0.0	0.0	10.0	0.0	0.0	0.0	6.3	0.0	0.0	0.0				
		0.0	0.0	1.0	0.0	0.0	0.0	1.0	0.0	0.0	0.0				
1000	10E2	3	2	0	1	2	1	3	2	2	0	16			
1000	A-H,EDISON#	18.8	12.5	0.0	6.3	12.5	6.3	18.8	12.5	12.5	0.0	16.7			
		21.4	11.8	0.0	16.7	25.0	7.7	18.8	24.6	50.0	0.0				
		3.1	2.1	0.0	1.0	2.1	1.0	3.1	2.1	2.1	0.0				
COLUMN	TOTAL	14	17	10	6	8	13	16	7	4	1	96			
		14.6	17.7	10.4	6.3	8.3	13.5	16.7	7.3	4.2	1.0	100.0			

NUMBER OF MISSING OBSERVATIONS = 172

FILE ATONAV13 (CREATION DATE = 01/15/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGOIST

***** C R O S S T A B U L A T I O N O F P E R C E N T E X P E C T E D B A T T E R Y L I F E U S E D *****
VAR014 ***** LAMPCHANGER *****
***** PAGE 1 OF 1 *****

VARPER														ROW TOTAL
COUNT	10.00	30.00	50.00	65.00	75.00	85.00	95.00	105.00	115.00	150.00				
VAR014	4	7	0	0	0	5	1	0	1	0				18
6 LAMP,CG6P CRDC	22.2	38.9	0.0	0.0	0.0	27.8	5.6	0.0	5.6	0.0				18.8
	28.6	41.2	0.0	0.0	0.0	39.5	6.3	0.0	25.0	0.0				
	4.2	7.3	0.0	0.0	0.0	5.2	1.0	0.0	1.0	0.0				
4 LAMP,FU-1297	10	10	10	6	8	10	15	7	3	1				78
	12.8	12.8	12.8	7.7	10.3	10.3	19.2	9.0	3.8	1.3				81.3
	71.4	58.8	100.0	100.0	100.0	61.5	93.8	100.0	75.0	100.0				
	10.4	10.4	10.4	6.3	8.3	8.3	15.6	7.3	3.1	1.0				
COLUMN TOTAL	14	17	10	6	8	13	16	7	4	1				96
	14.6	17.7	10.4	6.3	8.3	13.5	16.7	7.3	4.2	1.0				100.0

NUMBER OF MISSING OBSERVATIONS = 172

FILE ATCNAV13 (CREATION DATE = 01/15/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGDISF

V	A	R	I	O	L	S
F	L	A	S	H	E	R
C	R	O	S	T	A	B
A	L	B	A	T	I	O
N	B	A	T	E	D	
P	E	R	C	E	N	T
O	F	E	X	P	E	C
T	E	D	E	D	B	A
B	A	T	T	E	R	
L	I	F	E			
P	A	G	E			
U	S	E	D			

LIFE USED
PAGE 1 OF 1

COUNT		VARPER										VARPIS										ROW TOTAL
COL PCT	ROW PCT	10.00	30.00	50.00	65.00	75.00	85.00	95.00	105.00	115.00	150.00	10.00	30.00	50.00	65.00	75.00	85.00	95.00	105.00	115.00	150.00	
VAR015		1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1
C-R S-1065 SS		3	1	4	2	4	1	5	3	1	0	3	5	4	8	16	20	20	12	4	0	25
		12.0	4.0	16.0	8.0	16.0	4.0	20.0	12.0	4.0	0.0	36.0	32.0	16.0	32.0	32.0	32.0	32.0	42.9	4.0	0.0	26.0
		21.4	5.9	50.0	33.1	50.0	33.1	38.5	42.9	25.0	0.0	61.6	61.6	50.0	61.6	61.6	61.6	61.6	57.1	25.0	0.0	
		3.1	1.0	4.2	2.1	4.2	2.1	5.2	3.1	1.0	0.0	5.2	5.2	4.2	5.2	5.2	5.2	5.2	3.1	1.0	0.0	
CG-181 C-R DEV		11	16	8	4	2	4	3	4	3	1.5	11	11	2	5	2	11	16	5.9	3	1.5	68
		16.2	23.5	11.8	5.9	2.9	6.6	11.8	16.2	16.2	1.5	16.2	16.2	2.9	11.8	2.9	16.2	23.5	5.9	4.4	1.5	70.8
		78.6	94.1	80.0	66.7	25.0	66.7	66.7	94.1	94.1	100.0	94.1	94.1	25.0	94.1	25.0	94.1	94.1	57.1	75.0	100.0	
		11.5	16.7	8.3	4.2	2.1	4.2	8.3	11.5	11.5	1.0	11.5	11.5	2.1	11.5	2.1	11.5	11.5	4.2	3.1	1.0	
VAPAIR		0	0	1	0	2	0	0	0	0	0	0	0	2	0	2	0	0	0	0	0	3
		0.0	0.0	33.3	0.0	66.7	0.0	0.0	0.0	0.0	0.0	0.0	0.0	66.7	0.0	66.7	0.0	0.0	0.0	0.0	0.0	3.1
		0.0	0.0	10.0	0.0	25.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	25.0	0.0	25.0	0.0	0.0	0.0	0.0	0.0	
		0.0	0.0	1.0	0.0	2.1	0.0	0.0	0.0	0.0	0.0	0.0	0.0	2.1	0.0	2.1	0.0	0.0	0.0	0.0	0.0	
COLUMN TOTAL		14	17	10	6	8	6	13	7	4	1	16	16	8	13	8	13	16	7	4	1	96
		14.6	17.7	10.4	6.3	8.3	6.3	13.5	7.3	4.2	1.0	16.7	16.7	8.3	13.5	8.3	13.5	16.7	7.3	4.2	1.0	100.0

NUMBER OF MISSING OBSERVATIONS = 172

FILE ATCNV13 (CREATION DATE = 01/15/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGDIST

VAR16 ** CROSS TABULATION OF ** ** ** PERCENT EXPECTED BATTERY LIFE USED ** ** **
SOUND SIGNAL ** ** ** BY VARPER ** ** ** PAGE 1 OF 1

		VARPER										ROW TOTAL
COUNT ROW PCT COL PCT TUT PCT		10-00	30-00	50-00	65-00	75-00	85-00	95-00	105-00	115-00	150-00	
VAR16	NO SOUND SIGNAL	6 10.5 42.9 6.3	7 12.3 41.2 7.2	5 8.8 50.0 5.2	4 7.0 66.7 4.2	6 10.5 75.0 6.3	10 17.5 76.9 10.4	12 21.1 75.0 12.5	4 7.0 57.1 4.2	2 3.5 50.0 2.1	1 1.8 100.0 1.0	57 59.4
	WHISTLE 4 BALL	2 16.7 14.3 2.1	1 8.3 5.9 1.0	3 25.0 30.0 3.1	1 9.3 16.7 1.0	0 0.0 0.0 0.0	2 16.7 15.4 2.1	1 8.3 6.3 1.0	1 1.8 14.3 1.0	1 1.8 25.0 1.0	0 0.0 0.0 0.0	12 12.5
	BELL PRE 1952 TAP	1 16.7 7.1 1.0	0 0.0 0.0 0.0	1 16.7 10.0 1.0	1 16.7 16.7 1.0	0 0.0 0.0 0.0	1 16.7 7.7 1.0	1 16.7 6.3 1.0	0 0.0 0.0 0.0	1 1.8 25.0 1.0	0 0.0 0.0 0.0	6 6.3
	BELL 1952 TAPPER	1 20.0 7.1 1.0	3 60.0 17.6 3.1	0 0.0 0.0 0.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	1 20.0 14.3 1.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	5 5.2
	BELL 1962 TAPPER	0 0.0 0.0 0.0	2 25.0 11.8 2.1	1 12.5 10.0 1.0	0 0.0 0.0 0.0	2 25.0 25.0 2.1	0 0.0 0.0 0.0	2 25.0 12.5 2.1	1 12.5 14.3 1.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	8 8.3
	GONG 1952 TAPPER	0 0.0 0.0 0.0	1 100.0 5.9 1.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	1 1.0
	GONG 1962 TAPPER	4 57.1 28.6 4.2	3 42.9 17.6 3.1	0 0.0 0.0 0.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	7 7.3
	COLUMN TOTAL	14 14.6	17 17.7	10 10.4	6 6.3	8 8.3	13 13.5	16 16.7	7 7.3	4 4.2	1 1.0	96 100.0

NUMBER OF MISSING OBSERVATIONS = 172

VARPER													
COUNT ROW PCT COL PCT TOT PCT	VARPER												
	10.00	30.00	50.00	65.00	75.00	85.00	95.00	105.00	115.00	150.00	ROW TOTAL		
VAR017													
CR-S1065-LS1	11.	0	0	0	1	50.0	1	0	0	0	0	2.1	
		0.0	0.0	0.0	50.0	7.7	0.0	0.0	0.0	0.0	0.0	2.1	
		0.0	0.0	0.0	1.0	1.0	0.0	0.0	0.0	0.0	0.0		
CR-S1065-LS MNTD	13.	0	0	0	0	0	0	1	0	0	0	3	
		0.0	6.7	0.0	0.0	0.0	33.3	0	0.0	0.0	0.0	3.1	
		0.0	11.8	0.0	0.0	0.0	6.3	0.0	0.0	0.0	0.0		
C-CLEAR-ALL	31.	5	6	3	5	10.5	4	6	2	2	0	38	
		13.2	15.8	7.9	13.2	37.5	15.8	10.5	5.3	50.0	0.0	39.6	
		35.7	35.3	30.0	83.3	31.1	37.5	57.1	2.1	2.1	0.0		
R-COLOR PLASTIC	32.	6	7	3	0	2	6	7	2	2	1	36	
		16.7	19.4	8.3	0.0	5.6	16.7	19.4	5.6	5.6	2.8	37.5	
		42.9	41.2	30.0	0.0	25.0	46.2	43.8	28.6	2.1	100.0		
8-COLOR GLASS	33.	3	2	4	1	2	2	2	1	0	0	17	
		17.6	11.8	23.5	5.9	11.8	11.8	11.8	5.9	0.0	0.0	17.7	
		21.4	11.8	40.0	16.7	25.0	15.4	12.5	14.3	0.0	0.0		
COLUMN TOTAL		17	10	6	8	13	16	7	4	1	100.0		
	14.6	17.7	10.4	6.3	8.3	13.5	16.7	7.3	4.2	1.0			

NUMBER OF MISSING OBSERVATIONS = 172

FILE ATGNAV13 (CREATION DATE = 01/15/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGDIST

***** CROSSTABULATION OF PERCENT EXPECTED BATTERY LIFE USED *****
VAR018 BOTTOM DESCRIPTION *****

		VARPER										ROW TOTAL	
		10.00	30.00	50.00	65.00	75.00	85.00	95.00	105.00	115.00	150.00		
VAR018	S	COUNT ROW PCT COL PCT TOT PCT	12 22.2 85.7 12.5	14 25.9 82.4 14.6	5 9.3 50.0 5.2	2 3.7 33.3 2.1	3 5.6 37.5 3.1	4 7.4 30.8 4.2	11 20.4 68.0 11.5	2 3.7 28.6 2.1	1 1.9 25.0 1.0	0 0.0 0.0 0.0	54 56.3
	ROCK	14.3 17.1 1.0	0.0 0.0 0.0	3 42.9 30.0 3.1	1 14.3 16.7 1.0	0 0.0 0.0 0.0	2 28.6 15.4 2.1	0 0.0 0.0 0.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	0 0.0 0.0 0.0	7 7.3
MUD	3.6 7.1 1.0	10.7 17.6 3.1	1 3.6 10.0 1.0	3 10.7 50.0 3.1	3 10.7 37.5 3.1	7 25.0 53.8 7.3	5 17.9 31.3 5.2	3 13.7 42.9 3.1	1 5.6 25.0 1.0	1 3.6 100.0 1.0	29 29.2		
	GRAVEL	0 0.0 0.0	0 0.0 0.0	1 14.3 10.0 1.0	0 0.0 0.0 0.0	2 28.6 25.0 2.1	0 0.0 0.0 0.0	0 0.0 0.0 0.0	2 28.6 28.6 2.1	2 28.6 50.0 2.1	0 0.0 0.0 0.0	7 7.3	
COLUMN TOTAL		14.6 17.7 10.4	17.7 17.7 10.4	6.3 10.4	6.3 10.4	8.3 10.4	13.5 13.5	16.7 16.7	7.3 7.3	4.2 4.2	1.0 1.0	96 100.0	

NUMBER OF MISSING OBSERVATIONS = 172

FILE ATONAV13 (CREATION DATE = 01/15/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGUIST

***** C R O S S T A B U L A T I O N O F P E R C E N T E X P E C T E D B A T T E R Y L I F E U S E D *****
 VAR022 SWIVEL SIZE AND NUMBER *****
 ***** PAGE 1 OF 1

		VARPER													ROW TOTAL
COUNT		10.001	30.001	50.001	65.001	75.001	85.001	95.001	105.001	115.001	150.001				
ROW PCT	TOT PCT														
1 1-2" 3RD CLASS		8.3	25.0	8.3	19.7	0.0	15.7	16.7	0.0	25.0	0.0				12.5
		7.1	17.6	10.0	33.3	0.0	15.4	12.5	0.0	25.0	0.0				12.5
		1.0	3.1	1.0	2.1	0.0	2.1	2.1	0.0	1.0	0.0				
1 3-4" 2ND CLASS		11	13	4	2	8	9	12	6	2	1				68
		16.2	19.1	5.9	2.9	11.8	13.2	17.6	8.8	2.9	1.5				70.8
		76.6	76.5	40.0	33.3	100.0	69.2	75.0	85.7	50.0	100.0				
		11.5	13.5	4.2	2.1	8.3	9.4	12.5	6.3	2.1	1.0				
2" 1ST CLASS		2	1	5	2	0	2	2	1	1	0				16.7
		12.5	6.3	31.3	12.5	0.0	12.5	12.5	6.3	25.0	0.0				
		14.3	5.9	50.0	33.3	0.0	15.4	12.5	14.3	25.0	0.0				
		2.1	1.0	5.2	2.1	0.0	2.1	2.1	1.0	1.0	0.0				
COLUMN TOTAL		14	17	10	6	8	13	16	7	4	1				96
		14.6	17.7	10.4	6.3	8.3	13.5	16.7	7.3	4.2	1.0				130.0

NUMBER OF MISSING OBSERVATIONS = 172

		VARPER											ROW TOTAL
		CCOUNT	10.00	30.00	50.00	65.00	75.00	85.00	95.00	105.00	115.00	150.00	
		ROW PCT											
		COL PCT											
		TOT PCT											
VAR023		6.	1	3	2	4	2	8	5	2	1	1	29
1 1-4"			3.4	10.3	6.9	13.8	6.9	27.6	17.2	6.9	3.4	3.4	30.2
			7.1	17.6	20.0	66.7	25.0	61.5	31.3	28.6	25.0	100.0	
			1.0	3.1	2.1	4.2	2.1	8.3	5.2	2.1	1.0	1.0	
		7.	3	3	0	1	4	2	9	2	2	0	26
1 1-2"			11.5	11.5	0.0	3.8	15.4	7.7	34.6	7.7	7.7	0.0	27.1
			21.4	17.6	0.0	16.7	50.0	15.4	56.3	26.6	50.0	0.0	
			3.1	3.1	0.0	1.0	4.2	2.1	9.4	2.1	2.1	0.0	
		8.	10	11	8	1	2	3	2	3	1	0	41
1 5-8"AND LARGER			24.4	26.8	19.5	2.4	4.9	7.3	4.9	7.3	2.4	0.0	42.7
			71.4	54.7	80.0	16.7	25.0	23.1	12.5	42.9	25.0	0.0	
			10.4	11.5	8.3	1.0	2.1	3.1	2.1	3.1	1.0	0.0	
		COLUMN TOTAL	14	17	10	6	8	13	16	7	4	1	96
			14.6	17.7	10.4	6.3	8.3	13.5	16.7	7.3	4.2	1.0	100.0

NUMBER OF MISSING OBSERVATIONS = 172

FILE ATCNAV13 (CREATION DATE = 01/15/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGDIST

***** C R O S S T A B U L A T I O N O F *****
***** R A T E D B A T T E R Y D I S C H A R G E T I M E *****
***** V A R P E R *****
***** P E R C E N T E X P E C T E D B A T T E R Y L I F E U S E D *****
***** P A G E 1 O F 2 *****

VARPER													ROW TOTAL
CCOUNT	10.001	30.001	50.001	55.001	75.001	85.001	95.001	105.001	115.001	150.001			
VAR069	1054.												6.3
	16.7	0.0	0.0	0.0	16.7	0.0	16.7	33.3	16.7	0.0			
	7.1	0.0	0.0	0.0	12.5	0.0	6.3	28.6	25.0	0.0			
	1.0	0.0	0.0	0.0	1.0	0.0	1.0	2.1	1.0	0.0			
	0.0	0.0	0.0	100.0	0.0	0.0	0.0	0.0	0.0	0.0			1.0
	0.0	0.0	0.0	16.7	0.0	0.0	0.0	0.0	0.0	0.0			
	0.0	0.0	0.0	1.0	0.0	0.0	0.0	0.0	0.0	0.0			
	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0			1.0
	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0			
	0.0	0.0	0.0	0.0	14.3	28.6	0.0	28.6	14.3	14.3			7.3
	0.0	0.0	0.0	0.0	12.5	15.4	0.0	28.6	25.0	100.0			
	0.0	0.0	0.0	0.0	1.0	2.1	0.0	2.1	1.0	1.0			
	0.0	0.0	0.0	0.0	100.0	0.0	0.0	0.0	0.0	0.0			1.0
	0.0	0.0	0.0	0.0	12.5	0.0	0.0	0.0	0.0	0.0			
	0.0	0.0	0.0	0.0	1.0	0.0	0.0	0.0	0.0	0.0			
	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0			1.0
	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0			
	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0			13.5
	15.4	15.4	7.7	7.7	7.7	7.7	23.1	7.7	7.7	0.0			
	14.3	11.8	10.0	16.7	12.5	7.7	18.8	14.3	25.0	0.0			
	2.1	2.1	1.0	1.0	1.0	1.0	3.1	1.0	1.0	0.0			
	0.0	0.0	0.0	0.0	0.0	0.0	1.0	1.0	0.0	0.0			4.2
	0.0	0.0	50.0	0.0	0.0	0.0	25.0	25.0	0.0	0.0			
	0.0	0.0	20.0	0.0	0.0	0.0	6.3	14.3	0.0	0.0			
	0.0	0.0	2.1	0.0	0.0	0.0	1.0	1.0	0.0	0.0			
	9	13	3	1	1	3	2	0	1	0			33
	27.3	39.4	9.1	3.0	3.0	9.1	6.1	0.0	3.0	0.0			
	64.3	76.5	30.0	16.7	12.5	23.1	12.5	0.0	25.0	0.0			34.4
	9.4	13.5	3.1	1.0	1.0	3.1	2.1	0.0	1.0	0.0			
	14	17.7	10	6	8.3	13	16.7	7.3	4.2	1			96
	14.6		10.4	6.3	8.3	13.5	16.7	7.3	4.2	1.0			130.0
COLUMN TOTAL													

(CONTINUED)

FILE ATONAV13 (CREATION DATE = 01/15/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGDIST

***** CROSSTABULATION OF *****
***** RATED BATTERY DISCHARGE TIME BY VARPER PERCENT EXPECTED BATTERY LIFE USED *****
***** VAR069 *****
***** PAGE 2 OF 2 *****

		VARPER										ROW TOTAL
		10.00	30.00	50.00	65.00	75.00	85.00	95.00	105.00	115.00	150.00	
VAR069	CCOUNT											
	ROW PCT											
	CUL PCT											
	TOT PCT											
	2169.	0.0	0.0	0.0	100.0	0.0	0.0	0.0	0.0	0.0	0.0	1.0
		0.0	0.0	0.0	16.7	0.0	0.0	0.0	0.0	0.0	0.0	
		0.0	0.0	0.0	1.0	0.0	0.0	0.0	0.0	0.0	0.0	
	2197.	20.0	20.0	60.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	5.2
		7.1	5.9	30.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	
		1.0	1.0	3.1	0.0	0.0	0.0	0.0	0.0	0.0	0.0	
	2210.	0.0	0.0	0.0	100.0	0.0	0.0	0.0	0.0	0.0	0.0	1.0
		0.0	0.0	0.0	16.7	0.0	0.0	0.0	0.0	0.0	0.0	
		0.0	0.0	0.0	1.0	0.0	0.0	0.0	0.0	0.0	0.0	
	2250.	0.0	0.0	0.0	25.0	0.0	50.0	25.0	0.0	0.0	0.0	4.2
		0.0	0.0	0.0	16.7	0.0	15.4	6.3	0.0	0.0	0.0	
		0.0	0.0	0.0	1.0	0.0	2.1	1.0	0.0	0.0	0.0	
	2330.	100.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	1.0
		7.1	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	
		1.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	
	3000.	0.0	5.3	5.3	0.0	15.8	26.3	42.1	5.3	0.0	0.0	19.8
		0.0	1.9	10.0	0.0	17.5	39.5	50.0	14.3	0.0	0.0	
		0.0	1.0	1.0	0.0	3.1	5.2	8.3	1.0	0.0	0.0	
COLUMN TOTAL		14.6	17.7	10.4	6.3	8.3	13.5	16.7	7.3	4.2	1.0	96
												100.0

NUMBER OF MISSING OBSERVATIONS = 172

FILE ATCNAV13 (CREATION DATE = 01/15/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGOIST

***** C R O S S T A B U L A T I O N O F *****
***** P O W E R U N I T S R E P L A C E D W I T H R E A S O N *****
***** V A R P E R *****
***** P E R C E N T E X P E C T E D B A T T E R Y L I F E U S E D *****
***** P A G E 1 O F 1 *****

		VARPER											ROW TOTAL	
		10.001	30.001	50.001	65.001	75.001	85.001	95.001	105.001	115.001	150.001			
VAR071	COUNT													
	RCW PCT													
	TOT PCT													
ROUTINE SERVICE														
	421.	0	0	3	0	2	5	13	6	3	0		32	
		0.0	0.0	9.4	0.0	6.3	15.6	40.6	18.8	9.4	0.0		35.2	
		0.0	0.0	30.0	0.0	25.0	38.5	81.3	85.7	103.0	0.0			
ENVRNMTL HAZARDS														
	422.	8	14	3	2	1	0	0	0	0	1		29	
		27.6	48.3	10.3	6.9	3.4	0.0	0.0	0.0	0.0	3.4		31.9	
		66.7	87.5	30.0	40.0	12.5	0.0	0.0	0.0	0.0	100.0			
		8.8	15.4	3.3	2.2	1.1	0.0	0.0	0.0	0.0	1.1			
TECH- ADMIN ERR														
	423.	0	1	0	0	0	0	0	0	0	0		1.1	
		0.0	100.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0			
		0.0	6.3	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0			
		0.0	1.1	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0			
PERSONNEL ERRORS														
	424.	1	7	3	0	3	30	0	1	0	0		13	
		7.7	7.7	23.1	0.0	23.1	30.8	0.0	7.7	0.0	0.0		14.3	
		8.3	6.3	30.0	0.0	37.5	30.8	0.0	14.3	0.0	0.0			
		1.1	1.1	3.3	0.0	3.3	4.4	0.0	1.1	0.0	0.0			
CONVENIENCE-FOLL														
	426.	3	0	0	0	1	2	2	0	0	0		8.8	
		37.5	0.0	0.0	0.0	12.5	25.0	25.0	0.0	0.0	0.0			
		25.0	0.0	0.0	0.0	12.5	15.4	12.5	0.0	0.0	0.0			
		3.3	0.0	0.0	0.0	1.1	2.2	2.2	0.0	0.0	0.0			
MANUFACTRG ERRORS														
	427.	0	0	1	3	1	2	1	0	0	0		8.8	
		0.0	0.0	12.5	37.5	12.5	25.0	12.5	0.0	0.0	0.0			
		0.0	0.0	10.0	60.0	12.5	15.4	6.3	0.0	0.0	0.0			
		0.0	0.0	1.1	3.3	1.1	2.2	1.1	0.0	0.0	0.0			
COLUMN TOTAL														
		12	16	10	5	8	13	16	7	3	1		91	
		13.2	17.6	11.0	5.5	8.8	14.3	17.6	7.7	3.3	1.1		100.0	

NUMBER OF MISSING OBSERVATIONS = 177

01/15/75

CODEBOOK, MARGINALS, CROSSTABULATIONS AFTER BREAKDOWN RECODING

FILE ATCNAV13 (CREATION DATE = 01/15/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGOIST

VARIABLE VAR073 FLASHER REPLACED WITH REASON

VALUE LABEL	VALUE	ABSOLUTE FREQUENCY	RELATIVE FREQUENCY (PERCENT)	ADJUSTED FREQUENCY (PERCENT)	CUMULATIVE ADJ FREQ (PERCENT)
ROUTINE SERVICING	461.	4	4.3	4.3	4.3
ENVIRNMTL HAZARDS	462.	40	42.6	42.6	46.8
PERSONNEL ERRORS	464.	19	20.2	20.2	67.0
CAUSED BY CTR CMPNT	465.	2	2.1	2.1	69.1
CONVENIENCE-FOLLOWUP	466.	17	18.1	18.1	87.2
MANUFACTRG ERRORS	467.	7	7.4	7.4	94.7
CORROSION	468.	4	4.3	4.3	98.9
PROJECTS-EXPERIMNTL	469.	1	1.1	1.1	100.0
	0.	0	0.0	MISSING	100.0
TOTAL		94	100.0	100.0	100.0

VAR004					
COUNT	1	19	X	38	
ROW PCT	1	1	1	1	
COL PCT	1	1	1	1	
TOT PCT	1	1	1	1	93.8
VAR073					
462	1	1	1	1	3
ENVNMTL HAZARDS	1	1	1	1	7.5
	1	1	1	1	60.0
	1	1	1	1	4.5
PERSONNEL ERRORS					
464	1	1	1	1	2
	1	1	1	1	10.5
	1	1	1	1	40.0
	1	1	1	1	3.0
MANUFACTRG ERRORS					
467	1	1	1	1	0
	1	1	1	1	0.0
	1	1	1	1	0.0
	1	1	1	1	0.0
COLUMN TOTAL	1	1	1	1	5
	1	1	1	1	7.6
	1	1	1	1	66
	1	1	1	1	100.0

FILE AICNAV13 (CREATION DATE = 01/15/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGDIST

***** C R O S T A B U L A T I O N O F *****
VAR073 FLASHER REPLACED WITH REASON *****
***** BY VAR010 LANTERN-OPTIC *****
***** PAGE 1 OF 1 *****

		VAR010				ROW TOTAL
COUNT		155 MM A	200 MM P	200 MM	ALLOTHER	
ROW PCT	CUL PCT	CRYLIC	GLASS	ALLOTH	23.	
TOT PCT		16.	20.			
VAR073						
ENVRNMTL HAZARDS						
462.		31	9		0	40
		77.5	22.3		0.0	60.6
		62.0	64.3		0.0	
		47.0	13.6		0.0	
PERSONNEL ERRORS						
464.		12	5		2	19
		63.2	26.3		10.5	28.8
		24.0	35.7		100.0	
		18.2	7.6		3.0	
MANUFACTURING ERRORS						
467.		7	0		0	7
		100.0	0.0		0.0	10.6
		14.0	0.0		0.0	
		10.6	0.0		0.0	
COLUMN TOTAL						
		50	14		2	66
		75.8	21.2		3.0	100.0

***** C R O S S T A B U L A T I O N O F *****
***** FLASHER REPLACED WITH REASON *****
***** VAR073 BY VAR014 LAMPCHANGER *****
***** PAGE 1 OF 1 *****

VAR014					ROW TOTAL
COUNT	LAMP, C	LAMP, F	LAMP, F	ROW	
ROW PCI	66P	CRCC	U-1297	U-1297	
TOT PCI	65	65	97	97	
VAR073					
402	16	24	24	40	
ENVIRNMTL HAZARDS	40.0	60.0	60.0	60.6	
	69.6	55.0	55.0		
	24.2	36.4	36.4		
PERSONNEL ERRORS					
464	4	15	15	19	
	21.1	78.9	78.9	28.8	
	17.4	34.9	34.9		
	6.1	22.7	22.7		
MANUFACTRG ERRORS					
467	3	4	4	7	
	42.9	57.1	57.1	10.6	
	13.0	9.3	9.3		
	4.5	6.1	6.1		
COLUMN TOTAL					
	23	43	43	66	
	34.8	65.2	65.2	100.0	

FILE ATCNV13 (CREATION DATE = 01/15/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGOIST

***** C R O S S T A B U L A T I O N O F *****
***** FLASHER REPLACED WITH REASON *****
***** BY VAR015 *****
***** OF FLASHER *****
***** PAGE 1 OF 1 *****

		VAR015				ROW TOTAL	
COUNT		IC-R	S-10	CG-181	C VAPAIR		
ROW PCT	CUL PCT	165	SS	-R Dev.	83.1		
TOT PCT		65.1			83.1		
VAR073							
ENVRNMTL HAZARDS							
462.		5	12.5	34	1	40	
			50.0	85.0	2.5	60.6	
			7.6	64.2	33.3		
				51.5	1.5		
PERSONNEL ERRORS							
464.		4	21.1	14	1	19	
			40.0	73.7	5.5	28.8	
			6.1	26.4	33.3		
				21.2	1.5		
MANUFACTG ERRORS							
467.		1	14.3	5	1	7	
			10.0	71.4	14.3	10.6	
			1.5	9.4	33.3		
				7.6	1.5		
COLUMN TOTAL		10	15.2	53	3	66	
				80.3	4.5	100.0	

FILE ATONAV13 (CREATION DATE = 01/15/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGDIST

***** C R O S S T A B U L A T I O N O F *****
VAR073 FLASHEK REPLACED WITH REASON BY VAR016 SOUND SIGNAL *****
***** PAGE 1 OF 1 *****

VAR016

COUNT		NO SOUND		WHISTLE		BELL PRE		BELL1952		BELL1962		GONG1952		GONG1962		ROW TOTAL
ROW PCT	TOT PCT	SIGNAL	4 BALL	79.	1952 TP	81.	TAPPER	82.	TAPPER	83.	TAPPER	85.	TAPPER	86.	TAPPER	
VAR073																
ENVRNMTL HAZARDS		462.	22	55.0	6	15.0	2.5	1	10.0	4	2.5	1	100.0	1	12.5	5
			64.7	35.3	9.1	33.3	1.5	80.0	6.1	100.0	1.5	100.0	1.5	100.0	7.6	60.6
			33.3													
PERSONNEL ERRORS		464.	9	47.4	7	36.8	10.5	2	5.3	1	0.0	0	0.0	0	0.0	0
			26.5	41.2	41.2	66.7	66.7	20.0	1.5	0.0	0.0	0.0	0.0	0.0	0.0	19
			13.6		10.6	3.0				0.0	0.0					28.8
MANUFCTRG ERRORS		467.	3	42.9	4	57.1	0.0	0	0.0	0	0.0	0	0.0	0	0.0	0
			8.8	23.5	23.5	6.1	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	7
			4.5				0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	10.6
COLUMN TOTAL			34	51.5	17	25.8	4.5	3	7.6	5	1.5	1	1.5	1	7.6	66
																100.0

FILE ATONAV13 (CREATION DATE = 01/15/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGOIST

VARIABLE VAR074 LANPCHANGER REPLACED WITH REASON

VALUE LABEL	VALUE	ABSOLUTE FREQUENCY	RELATIVE FREQUENCY (PERCENT)	ADJUSTED FREQUENCY (PERCENT)	CUMULATIVE ADJ FREQ (PERCENT)
ROUTINE SERVICING	471.	4	4.4	4.4	4.4
ENVNMTL HAZARDS	472.	40	44.0	44.0	48.4
PERSONNEL ERRORS	474.	19	20.9	20.9	69.2
CAUSED BY CTHR CMPNT	475.	2	2.2	2.2	71.4
CONVENIENCE-FULLOWP	476.	16	17.6	17.6	89.0
MANUFCTRG ERRORS	477.	7	7.7	7.7	96.7
CORROSION	478.	2	2.2	2.2	98.9
PROJECTS-EXPERIMNTL	479.	1	1.1	1.1	100.0
	0.	0	0.0	MISSING	100.0
TOTAL		91	100.0	100.0	100.0

FILE ATCNAV13 (CREATION DATE = 01/15/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGDIST

***** C R O S S T A B U L A T I O N O F L A M P T Y P E *****
VAR074 LAMPCHANGER REPLACED WITH REASON BY VAR009 *****
***** PAGE 1 OF 1 *****

		VAR009				ROW TOTAL
COUNT		0.55 AMP 12VOLT	0.77 AMP 12VOLT	1.15 AMP 12VOLT		
ROW PCT	CUL PCT					
TOT PCT		52.	53.	54.		
VAR074						
ENVRNMIL HAZARDS						
472.		0	10	30		40
		0.0	25.0	75.0		60.6
		0.0	58.8	63.8		
		0.0	15.2	45.5		
PERSONNEL ERRORS						
474.		0	7	12		19
		0.0	36.8	93.2		28.8
		0.0	41.2	25.5		
		0.0	10.6	18.2		
MANUFACTRG ERRORS						
477.		2	0	5		7
		20.6	0.0	71.4		10.6
		100.0	0.0	10.6		
		3.0	0.0	7.6		
COLUMN TOTAL						
		2	17	47		66
		3.0	25.8	71.2		100.0

FILE ATCNAV13 (CREATION DATE = 01/15/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGDIST

***** C R O S S T A B U L A T I O N O F *****
***** LAMPCHANGER REPLACED WITH REASON BY VAR016 *****
***** VAR074 ***** SOUND SIGNAL *****
***** PAGE 1 OF 1 *****

VAR016

COUNT		NO SOUND	WHISTLE	BELL PRE	BELL 1952	BELL 1962	GONG 1952	GONG 1962	ROW
KUL PCT		SIGNAL	4 BALL	1952 TP	TAPPER	TAPPER	TAPPER	TAPPER	TOTAL
TOT PCT		0.	79.	81.	82.	83.	85.	86.	
VAR074	472.	22	6	1	4	1	1	5	40
	ENVRNMTL HAZARDS	55.0	15.0	2.5	10.0	2.5	2.5	12.5	60.6
		64.7	46.2	20.0	80.0	33.3	100.0	100.0	
	474.	33.3	9.1	1.5	6.1	1.5	1.5	7.6	19
	PERSONNEL ERRORS	10	6	2	1	0	0	0	28.8
		52.6	31.6	10.5	5.3	0.0	0.0	0.0	
	477.	29.4	46.2	40.0	20.0	0.0	0.0	0.0	7
	MANUFACTRG ERRORS	15.2	9.1	3.0	1.5	0.0	0.0	0.0	10.6
		2	1	2	0	2	0	0	
COLUMN		28.6	14.3	28.6	0.0	28.6	0.0	0.0	66
	TOTAL	5.9	7.7	40.0	0.0	60.7	0.0	0.0	100.0
		3.0	1.5	3.0	0.0	3.0	0.0	0.0	
		34	13	5	5	3	1	5	
		51.5	19.7	7.6	7.6	4.5	1.5	7.6	

FILE ATUNAV13 (CREATION DATE = 01/15/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGDIST

VARIABLE VAR075 DAYLIGHT CONTROL REP. WITH REASON

VALUE LABEL	VALUE	ABSOLUTE FREQUENCY	RELATIVE FREQUENCY (PERCENT)	ADJUSTED FREQUENCY (PERCENT)	CUMULATIVE ADJ. FREU (PERCENT)
ROUTINE SERVICING	501.	6	7.1	7.1	7.1
ENVIRONMENTAL HAZARDS	502.	36	42.4	42.4	49.4
PERSONNEL ERRORS	504.	10	11.8	11.8	61.2
CAUSED BY OTHER COMPONENT	505.	3	3.5	3.5	64.7
CONVENIENCE-FOLLOWUP	506.	23	27.1	27.1	91.8
MANUFACTURING ERRORS	507.	6	7.1	7.1	98.8
CORROSION	508.	1	1.2	1.2	100.0
	0.	0	0.0	MISSING	100.0
TOTAL		85	100.0	100.0	100.0

FILE ATGNAV13 (CREATION DATE = 01/15/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGDIST

VARIABLE	VAR075	DAYLIGHT CONTROL	REP.WITH REASON
1	1	1	1
2	1	1	1
3	1	1	1
4	1	1	1
5	1	1	1
6	1	1	1
7	1	1	1
8	1	1	1
9	1	1	1
10	1	1	1
11	1	1	1
12	1	1	1
13	1	1	1
14	1	1	1
15	1	1	1
16	1	1	1
17	1	1	1
18	1	1	1
19	1	1	1
20	1	1	1
21	1	1	1
22	1	1	1
23	1	1	1
24	1	1	1
25	1	1	1
26	1	1	1
27	1	1	1
28	1	1	1
29	1	1	1
30	1	1	1
31	1	1	1
32	1	1	1
33	1	1	1
34	1	1	1
35	1	1	1
36	1	1	1
37	1	1	1
38	1	1	1
39	1	1	1
40	1	1	1
41	1	1	1
42	1	1	1
43	1	1	1
44	1	1	1
45	1	1	1
46	1	1	1
47	1	1	1
48	1	1	1
49	1	1	1
50	1	1	1
51	1	1	1
52	1	1	1
53	1	1	1
54	1	1	1
55	1	1	1
56	1	1	1
57	1	1	1
58	1	1	1
59	1	1	1
60	1	1	1
61	1	1	1
62	1	1	1
63	1	1	1
64	1	1	1
65	1	1	1
66	1	1	1
67	1	1	1
68	1	1	1
69	1	1	1
70	1	1	1
71	1	1	1
72	1	1	1
73	1	1	1
74	1	1	1
75	1	1	1
76	1	1	1
77	1	1	1
78	1	1	1
79	1	1	1
80	1	1	1
81	1	1	1
82	1	1	1
83	1	1	1
84	1	1	1
85	1	1	1
86	1	1	1
87	1	1	1
88	1	1	1
89	1	1	1
90	1	1	1
91	1	1	1
92	1	1	1
93	1	1	1
94	1	1	1
95	1	1	1
96	1	1	1
97	1	1	1
98	1	1	1
99	1	1	1
100	1	1	1

[illegible]

***** DAYLIGHT CONTROL REP. WITH REASON ***** C R O S S T A B U L A T I O N O F L I G H T C O L O R *****
***** VAR075 ***** BY VAR008 ***** PAGE 1 OF 1

		VAR008				ROW TOTAL
COUNT		WHITE	RED	GREEN		
ROW	PCI	W	R	G		
VAR075		14	16	6		36
ENVRNMTL HAZARDS	502.	38.9	44.4	16.7		69.2
		77.8	64.0	66.7		
		26.9	30.8	11.5		
PERSONNEL ERRORS		3	5	2		10
MANUFACTRG ERRORS	504.	30.0	50.0	20.0		19.2
		16.7	20.0	22.2		
		5.8	9.6	3.6		
COLUMN TOTAL		18	25	9		52
		34.6	48.1	17.3		100.0

CHI SQUARE = 1.39950 WITH 4 DEGREES OF FREEDOM SIGNIFICANCE = 0.8443

CRAMER'S V = 0.11603
CONTINGENCY COEFFICIENT = 0.16189
KENDALL'S TAU B = 0.10828 SIGNIFICANCE = 0.1236
KENDALL'S TAU C = 0.08765 SIGNIFICANCE = 0.1745
GAMMA = 0.20102
SOMER'S D = 0.09438

FILE ATONAV13 (CREATION DATE = 01/15/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGOIST

***** DAYLIGHT CONTROL REP. WITH REASON C R O S S T A B U L A T I O N O F *****
***** VAR075 ***** BY VAR010 ***** LANTERN-OPTIC *****
***** PAGE 1 OF 1 *****

		VAR010					
COUNT		155 MM A	200 MM P	200 MM	ALLOTHER	ROW	
RUM PCT	CUL PCT	CRYLIC	GLASS	CRYLIC	ALLOTHER	TOTAL	TOTAL
502	502	27	9	0	0	36	
ENVRNMTL HAZARDS		75.0	25.0	0.0	0.0	69.2	
		67.5	81.8	0.0	0.0		
		51.9	17.3	0.0	0.0		
504	504	7	2	1	1	10	
PERSONNEL ERRORS		70.0	20.0	10.0	0.0	19.2	
		17.5	18.2	100.0	0.0		
		13.5	3.8	1.9	0.0		
507	507	6	0	0	0	6	
MANUFACTG ERRORS		100.0	0.0	0.0	0.0	11.5	
		15.0	0.0	0.0	0.0		
		11.5	0.0	0.0	0.0		
COLUMN	TOTAL	40	11	1	1	52	
		76.9	21.2	1.9	0.0	100.0	

CHI SQUARE = 6.22227 WITH 4 DEGREES OF FREEDOM SIGNIFICANCE = 0.1832

CRAMER'S V = 0.24460
CONTINGENCY COEFFICIENT = 0.32691
KENDALL'S TAU B = -0.08053 SIGNIFICANCE = 0.1947
KENDALL'S TAU C = -0.04993 SIGNIFICANCE = 0.2968
GAMMA = -0.20000
SOMER'S D = -0.09165

FILE ATCNAV13 (CREATION DATE = 01/15/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGDIST

***** C R O S S T A B U L A T I O N O F S O U N D S I G N A L *****
VAR075 DAYLIGHT CONTROL REP. WITH REASON BY VAR016 *****
***** PAGE 1 OF 1 *****

VAR016

COUNT	NO SOUND	WHISTLE	BELL	PRES	BELL1952	BELL1962	GONG1952	GONG1962	ROW
ROW PCT	SIGNAL	4 BALL	1952 TP	TP	TAPPER	TAPPER	TAPPER	TAPPER	TOTAL
TOT PCT	0.	79.	81.	82.	83.	85.	86.		
502.	19	6	1	3	1	1	5	36	
ENVRNMTL HAZARDS	52.8	16.7	2.8	8.3	2.8	2.8	13.9	69.2	
	63.3	60.0	100.0	100.0	50.0	100.0	100.0		
	36.5	11.5	1.9	5.8	1.9	1.9	9.6		
504.	7	2	0	0	1	0	0	10	
PERSONNEL ERRORS	70.0	20.0	0.0	0.0	10.0	0.0	0.0	19.2	
	23.3	20.0	0.0	0.0	50.0	0.0	0.0		
	13.5	3.8	0.0	0.0	1.9	0.0	0.0		
507.	4	2	0	0	0	0	0	6	
MANUFCTRG ERRORS	66.7	33.3	0.0	0.0	0.0	0.0	0.0	11.5	
	13.3	20.0	0.0	0.0	0.0	0.0	0.0		
	17.7	3.8	0.0	0.0	0.0	0.0	0.0		
COLUMN	30	10	1	3	2	1	5	52	
TOTAL	57.7	19.2	1.9	5.8	3.8	1.9	9.6	100.0	

CHI SQUARE = 7.01036 WITH 12 DEGREES OF FREEDOM SIGNIFICANCE = 0.8569

CRAMER'S V = 0.25963
CONTINGENCY COEFFICIENT = 0.34467
KENDALL'S TAU B = 0.0262
KENDALL'S TAU C = 0.0388
GAMMA = 0.0388
SOMER'S D = 0.15805

01/15/75

FILE ATCNAV13 (CREATION DATE = 01/15/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGDIST
VARIABLE VAR076 LANTERN-OPTIC REP.WITH REASON

VALUE LABEL

VALUE	ABSOLUTE FREQUENCY	RELATIVE FREQUENCY (PERCENT)	ADJUSTED FREQUENCY (PERCENT)	CUMULATIVE ADJ FREQ (PERCENT)
ENVRNMTL HAZARDS				
512.	40	46.0	46.0	46.0
PERSONNEL ERRORS				
514.	8	9.2	9.2	55.2
CONVENIENCE-FOLLOWUP				
516.	17	19.5	19.5	74.7
MANUFACTRG ERRORS				
517.	1	1.1	1.1	75.9
CORROSION				
518.	1	1.1	1.1	77.0
PROJECTS-EXPERIMNTL				
519.	20	23.0	23.0	100.0
0.	0	0.0	MISSING	100.0
TOTAL	87	100.0	100.0	100.0

FILE ATCNAV13 (CREATION DATE = 01/15/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGOIST

***** C R O S S T A B U L A T I O N O F *****
***** LANTERN-OPTIC REP. WITH REASON *****
***** VAR076 BY VAR010 OF LANTERN-OPTIC *****
***** PAGE 1 OF 1 *****

		VAR010				ROW TOTAL
COUNT		155 MM CRYLIC	200 MM A	200 MM P	200 MM ALLOTHER	
ROW PCT	TOT PCT	16.1	20.1	20.1	23.1	
VAR076						
ENVRNMTL HAZARDS						
512.		31	9		0	40
		77.5	22.5		0.0	81.6
		23.8	81.8		0.0	
		65.3	16.4		0.0	
PERSONNEL ERRORS						
514.		5	2		1	8
		62.5	25.0		12.5	16.3
		13.5	18.2		100.0	
		10.2	4.1		2.0	
MANUFCTRG ERRORS						
517.		1	0		0	1
		100.0	0.0		0.0	2.0
		2.7	0.0		0.0	
		2.0	0.0		0.0	
COLUMN TOTAL						
37		11			1	49
75.5		22.4			2.0	100.0

CHI SQUARE = 5.65245 WITH 4 DEGREES OF FREEDOM SIGNIFICANCE = 0.2267

FILE ATCNAV13 (CREATION DATE = 01/15/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGOIST

***** C R O S S T A B U L A T I O N O F *****
 ***** LANTERN-CPTIC REP. WITH REASON *****
 ***** BY VAR016 *****
 ***** SOUND SIGNAL *****
 ***** PAGE 1 OF 1 *****

VAR016

COUNT	NO SOUND	WHISTLE	BELL PRE	BELL 1952	BELL 1962	GONG 1952	GONG 1962	ROW
ROW PCT	NO SIGNAL	4 BALL	1952 TP	TAPPER	TAPPER	TAPPER	TAPPER	TOTAL
COL PCT	0.1	79.1	81.1	82.1	83.1	85.1	86.1	
TOT PCT								
VAR076	22	6	1	4	1	1	5	40
ENVNRMTL HAZARDS	55.0	15.0	2.5	10.0	2.5	2.5	12.5	81.6
	55.7	54.5	33.3	80.0	100.0	100.0	100.0	
	44.9	12.2	2.0	8.2	2.0	2.0	10.2	
PERSONNEL ERRORS	1	4	2	1	0	0	0	8
	12.5	50.0	25.0	12.5	0.0	0.0	0.0	16.3
	4.3	36.4	66.7	20.0	0.0	0.0	0.0	
	2.0	8.2	4.1	2.0	0.0	0.0	0.0	
MANUFCTRG ERRORS	0	1	0	0	0	0	0	1
	0.0	100.0	0.0	0.0	0.0	0.0	0.0	2.0
	0.0	9.1	0.0	0.0	0.0	0.0	0.0	
	0.0	2.0	0.0	0.0	0.0	0.0	0.0	
COLUMN TOTAL	23	11	3	5	1	1	5	49
	46.9	22.4	6.1	10.2	2.0	2.0	10.2	100.0

CHI SQUARE = 16.71225 WITH 12 DEGREES OF FREEDOM SIGNIFICANCE = 0.1607

FILE ATCNAV13 (CREATION DATE = 01/15/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGDIST

***** C R O S S T A B U L A T I O N O F L O C A T I O N *****
VAR077 MOCRINGS SP-CODE REP WITH REASON BY VAR003 LOCATION *****
***** PAGE 1 OF 1 *****

VAR003

CGUNT	PROTECTE	SEMI-EXP	EXPOSED	ROW
ROW PCT	D RIVER	M	SEA COAS	TOTAL
CUL PCT	U		B	
TOT PCT				
774.	1	0	0	1
LAMP-PERS ERRORS	100.0	0.0	0.0	12.5
	25.0	0.0	0.0	
	12.5	0.0	0.0	
777.	3	1	3	7
LAMP-MNFG ERRORS	42.9	14.3	42.9	87.5
	75.0	100.0	100.0	
	37.5	12.5	37.5	
COLUMN TOTAL	4	1	3	8
	50.0	12.5	37.5	100.0

CHI SQUARE = 1.14286 WITH 2 DEGREES OF FREEDOM SIGNIFICANCE = 0.5647

FILE ATCNAV13 (CREATION DATE = 01/15/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGDIST

***** C R O S S T A B U L A T I O N O F B U O Y S I Z E *****
VAR077 MOCRINGS SP-CODE REP WITH REASON BY VAR004 BUOY SIZE *****
***** PAGE 1 OF 1 *****

VAR004

CGUNT	7 X 17	8 X 23	8 X 26	9 X 32	9 X 38	RCW
ROW PCT						TOTAL
CUL PCT						
TOT PCT						
774.	717.1	823.1	826.1	932.1	938.1	
LAMP-PERS ERRORS	0	1	0	0	0	1
	0.0	100.0	0.0	0.0	0.0	12.5
	0.0	100.0	0.0	0.0	0.0	
	0.0	12.5	0.0	0.0	0.0	
777.	1	0	4	1	1	7
LAMP-MNFG ERRORS	14.3	0.0	57.1	14.3	14.3	87.5
	100.0	0.0	100.0	100.0	100.0	
	12.5	0.0	50.0	12.5	12.5	
COLUMN TOTAL	1	1	4	1	1	8
	12.5	12.5	50.0	12.5	12.5	100.0

CHI SQUARE = 8.00000 WITH 4 DEGREES OF FREEDOM SIGNIFICANCE = 0.0916

FILE ATUNAV13 (CREATION DATE = 01/15/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGDIST

CROSS TABULATION OF LAMP TYPE
VAR077 MCCRINGS SP-CODE REP WITH REASON BY VAR009 LAMP TYPE

VAR009				
COUNT	10.77 AMP ROW PCT	1.15 AMP COL PCT	12VOLT TOT PCT	ROW TOTAL
VAR077	53.1	54.1	54.1	
LAMP-PERS ERRORS	1	0	0	12.5
	100.0	0.0	0.0	
	20.0	0.0	0.0	
	12.5			
LAMP-MNFG ERRORS	4	3	3	7
	57.1	42.9	37.5	87.5
	80.0	100.0		
	50.0	37.5		
COLUMN TOTAL	62.5	37.5		100.0

FISHER'S EXACT TEST = 0.62500

FILE ATUNAV13 (CREATION DATE = 01/15/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGDIST

CROSS TABULATION OF LANTERN-OPTIC
VAR077 MCCRINGS SP-CODE REP WITH REASON BY VAR010 LANTERN-OPTIC

VAR010				
COUNT	1155 MM ACRYLIC	200 MM P GLASS	ROW TOTAL	
VAR077	16.1	20.1		
LAMP-PERS ERRORS	1	0	1	12.5
	100.0	0.0		
	16.7	0.0		
	12.5	0.0		
LAMP-MNFG ERRORS	5	2	7	87.5
	71.4	28.6		
	83.3	100.0		
	62.5	25.0		
COLUMN TOTAL	75.0	25.0		100.0

FISHER'S EXACT TEST = 0.75000

FILE ATONAV13 (CREATION DATE = 01/15/75) 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGOIST

***** C R O S S T A B U L A T I O N O F S O U N D S I G N A L *****
VAR077 MOORINGS SP-CODE REP WITH REASON *****
***** VAR016 ***** PAGE 1 OF 1

		VAR016					
		CCOUNT	NO SOUND	WHISTLE	BELL1962		
		ROW PCT	SIGNAL	4 BALL	TAPPER		
		TOT PCT	0.	79.	83.		
VAR077	LAMP-PERS ERRORS	774.	100.0	0.0	0.0	1	12.5
			25.0	0.0	0.0		
			12.5	0.0	0.0		
LAMP-MNFG ERRORS		777.	42.9	28.6	28.6	2	87.5
			75.0	100.0	100.0		
			37.5	25.0	25.0		
COLUMN TOTAL			50.0	25.0	25.0	8	100.0

CHI SQUARE = 1.14286 WITH 2 DEGREES OF FREEDOM SIGNIFICANCE = 0.5647

RUN NAME CODEBOOK, MARGINALS, CROSS TABULATIONS, BEEDRE BREAKDOWN RECORDING
FILE NAME ATONAV13, 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CSDIST
VARIABLE LIST VAR001 TO VAR090
INPUT MEDIUM CARD
OF CASES 268
INPUT FORMAT FIXED (F6.2, 2X, A1, A1, 1X, F3.0, 1X, F2.0, F1.0, 1X, F3.0, 1X, A1, 1X, F2.0,

ACCORDING TO YOUR INPUT FORMAT, VARIABLES ARE TO BE READ AS FOLLOWS

VARIABLE	FORMAT	RECORD	COLUMNS
VAR001	F 6	1	6
VAR002	A 1	1	9
VAR003	A 1	1	10
VAR004	3	1	14
VAR005	2	1	17
VAR006	1	1	18
VAR007	3	1	22
VAR008	A 1	1	24
VAR009	F 2	1	26
VAR010	F 2	1	27
VAR011	A 1	1	29
VAR012	A 1	1	30
VAR013	A 1	1	31
VAR014	A 1	1	35
VAR015	2	1	36
VAR016	2	1	38
VAR017	2	1	41
VAR018	A 1	1	44
VAR019	A 1	1	47
VAR020	A 2	1	49
VAR021	A 2	1	50
VAR022	1	1	51
VAR023	1	1	52
VAR024	1	1	54
VAR025	1	1	56
VAR026	1	1	58
VAR027	1	1	61
VAR028	1	1	63
VAR029	1	1	66
VAR030	1	1	68
VAR031	1	1	71
VAR032	2	1	73
VAR033	2	1	76
		1	78
		1	79
		1	81
		1	83
		1	85
		1	87
		1	89
		1	91
		1	93
		1	95
		1	97
		1	99
		1	101
		1	103
		1	105
		1	107
		1	109
		1	111
		1	113
		1	115
		1	117
		1	119
		1	121
		1	123
		1	125
		1	127
		1	129
		1	131
		1	133
		1	135
		1	137
		1	139
		1	141
		1	143
		1	145
		1	147
		1	149
		1	151
		1	153
		1	155
		1	157
		1	159
		1	161
		1	163
		1	165
		1	167
		1	169
		1	171
		1	173
		1	175
		1	177
		1	179
		1	181
		1	183
		1	185
		1	187
		1	189
		1	191
		1	193
		1	195
		1	197
		1	199
		1	201
		1	203
		1	205
		1	207
		1	209
		1	211
		1	213
		1	215
		1	217
		1	219
		1	221
		1	223
		1	225
		1	227
		1	229
		1	231
		1	233
		1	235
		1	237
		1	239
		1	241
		1	243
		1	245
		1	247
		1	249
		1	251
		1	253
		1	255
		1	257
		1	259
		1	261
		1	263
		1	265
		1	267
		1	269
		1	271
		1	273
		1	275
		1	277
		1	279
		1	281
		1	283
		1	285
		1	287
		1	289
		1	291
		1	293
		1	295
		1	297
		1	299
		1	301
		1	303
		1	305
		1	307
		1	309
		1	311
		1	313
		1	315
		1	317
		1	319
		1	321
		1	323
		1	325
		1	327
		1	329
		1	331
		1	333
		1	335
		1	337
		1	339
		1	341
		1	343
		1	345
		1	347
		1	349
		1	351
		1	353
		1	355
		1	357
		1	359
		1	361
		1	363
		1	365
		1	367
		1	369
		1	371
		1	373
		1	375
		1	377
		1	379
		1	381
		1	383
		1	385
		1	387
		1	389
		1	391
		1	393
		1	395
		1	397
		1	399
		1	401
		1	403
		1	405
		1	407
		1	409
		1	411
		1	413
		1	415
		1	417
		1	419
		1	421
		1	423
		1	425
		1	427
		1	429
		1	431
		1	433
		1	435
		1	437
		1	439
		1	441
		1	443
		1	445
		1	447
		1	449
		1	451
		1	453
		1	455
		1	457
		1	459
		1	461
		1	463
		1	465
		1	467
		1	469
		1	471
		1	473
		1	475
		1	477
		1	479
		1	481
		1	483
		1	485
		1	487
		1	489
		1	491
		1	493
		1	495
		1	497
		1	499
		1	501
		1	503
		1	505
		1	507
		1	509
		1	511
		1	513
		1	515
		1	517
		1	519
		1	521
		1	523
		1	525
		1	527
		1	529
		1	531
		1	533
		1	535
		1	537
		1	539
		1	541
		1	543
		1	545
		1	547
		1	549
		1	551
		1	553
		1	555
		1	557
		1	559
		1	561
		1	563
		1	565
		1	567
		1	569
		1	571
		1	573
		1	575
		1	577
		1	579
		1	581
		1	583
		1	585
		1	587
		1	589
		1	591
		1	593
		1	595
		1	597
		1	599
		1	601
		1	603
		1	605
		1	607
		1	609
		1	611
		1	613
		1	615
		1	617
		1	619
		1	621
		1	623
		1	625
		1	627
		1	629
		1	631
		1	633
		1	635
		1	637
		1	639
		1	641
		1	643
		1	645
		1	647
		1	649
		1	651
		1	653
		1	655
		1	657
		1	659
		1	661
		1	663
		1	665
		1	667
		1	669
		1	671
		1	673
		1	675
		1	677
		1	679
		1	681
		1	683
		1	685
		1	687
		1	689
		1	691
		1	693
		1	695
		1	697
		1	699
		1	701
		1	703
		1	705
		1	707
		1	709
		1	711
		1	713
		1	715
		1	717
		1	719
		1	721
		1	723
		1	725
		1	727
		1	729
		1	731
		1	733
		1	735
		1	737
		1	739
		1	741
		1	743
		1	745
		1	747
		1	749
		1	751
		1	753
		1	755
		1	757
		1	759
		1	761
		1	763
		1	765
		1	767
		1	769
		1	771
		1	773
		1	775
		1	777
		1	779
		1	781
		1	783
		1	785
		1	787
		1	789
		1	791
		1	793
		1	795
		1	797
		1	799
		1	801
		1	803
		1	805
		1	807
		1	809
		1	811
		1	813
		1	815
		1	817
		1	819
		1	821
		1	823
		1	825
		1	827
		1	829
		1	831
		1	833
		1	835
		1	837
		1	839
		1	841
		1	843
		1	845
		1	847
		1	849
		1	851
		1	853
		1	855
		1	857
		1	859
		1	861
		1	863
		1	865
		1	867
		1	869
		1	871
		1	873
		1	875
		1	877
		1	879
		1	881
		1	883
		1	885
		1	887
		1	889
		1	891
		1</	

ACCORDING TO YOUR INPUT FORMAT, VARIABLES ARE TO BE READ AS FOLLOWS

VARIABLE	FORMAT	RECORD	COLUMNS
VAR034	F 2:	0	6-
VAR035	F 2:	3	7
VAR036	F 2:	A	10
VAR037	F 2:	0	11-
VAR038	F 2:	0	12
VAR039	F 2:	0	14
VAR040	F 2:	0	16
VAR041	F 2:	0	18
VAR042	F 2:	0	20
VAR043	F 2:	0	22
VAR044	F 2:	0	24
VAR045	F 2:	0	26
VAR046	F 2:	0	28
VAR047	F 2:	0	30
VAR048	F 1:	0	31-
VAR049	F 1:	0	32
VAR050	F 4:	0	33
VAR051	F 4:	0	35-
VAR052	F 4:	0	36
VAR053	F 4:	0	39
VAR054	F 4:	0	40-
VAR055	F 4:	0	41
VAR056	F 4:	0	44
VAR057	F 4:	0	47
VAR058	F 4:	0	51
VAR059	F 4:	0	54
VAR060	F 4:	0	55
VAR061	F 4:	0	56
VAR062	F 4:	0	58
VAR063	F 4:	0	60
VAR064	F 4:	0	61
VAR065	F 4:	0	64
VAR066	F 4:	0	67
VAR067	F 4:	0	68
VAR068	F 4:	0	69
VAR069	F 4:	0	70
VAR070	F 4:	0	71
VAR071	F 4:	0	74
VAR072	F 4:	0	75
VAR073	F 4:	0	79
VAR074	F 4:	0	81
VAR075	F 4:	0	82
VAR076	F 4:	0	83
VAR077	F 4:	0	84
VAR078	F 4:	0	85
VAR079	F 4:	0	86
VAR080	F 4:	0	87
VAR081	F 4:	0	88
VAR082	F 4:	0	89
VAR083	F 4:	0	90
VAR084	F 4:	0	91
VAR085	F 4:	0	92
VAR086	F 4:	0	93
VAR087	F 4:	0	94
VAR088	F 4:	0	95
VAR089	F 4:	0	96
VAR090	F 4:	0	97
VAR091	F 4:	0	98
VAR092	F 4:	0	99
VAR093	F 4:	0	100
VAR094	F 4:	0	101
VAR095	F 4:	0	102
VAR096	F 4:	0	103
VAR097	F 4:	0	104
VAR098	F 4:	0	105
VAR099	F 4:	0	106
VAR100	F 4:	0	107
VAR101	F 4:	0	108
VAR102	F 4:	0	109
VAR103	F 4:	0	110
VAR104	F 4:	0	111
VAR105	F 4:	0	112
VAR106	F 4:	0	113
VAR107	F 4:	0	114
VAR108	F 4:	0	115
VAR109	F 4:	0	116
VAR110	F 4:	0	117
VAR111	F 4:	0	118
VAR112	F 4:	0	119
VAR113	F 4:	0	120
VAR114	F 4:	0	121
VAR115	F 4:	0	122
VAR116	F 4:	0	123
VAR117	F 4:	0	124
VAR118	F 4:	0	125
VAR119	F 4:	0	126
VAR120	F 4:	0	127
VAR121	F 4:	0	128
VAR122	F 4:	0	129
VAR123	F 4:	0	130
VAR124	F 4:	0	131
VAR125	F 4:	0	132
VAR126	F 4:	0	133
VAR127	F 4:	0	134
VAR128	F 4:	0	135
VAR129	F 4:	0	136
VAR130	F 4:	0	137
VAR131	F 4:	0	138
VAR132	F 4:	0	139
VAR133	F 4:	0	140
VAR134	F 4:	0	141
VAR135	F 4:	0	142
VAR136	F 4:	0	143
VAR137	F 4:	0	144
VAR138	F 4:	0	145
VAR139	F 4:	0	146
VAR140	F 4:	0	147
VAR141	F 4:	0	148
VAR142	F 4:	0	149
VAR143	F 4:	0	150
VAR144	F 4:	0	151
VAR145	F 4:	0	152
VAR146	F 4:	0	153
VAR147	F 4:	0	154
VAR148	F 4:	0	155
VAR149	F 4:	0	156
VAR150	F 4:	0	157
VAR151	F 4:	0	158
VAR152	F 4:	0	159
VAR153	F 4:	0	160
VAR154	F 4:	0	161
VAR155	F 4:	0	162
VAR156	F 4:	0	163
VAR157	F 4:	0	164
VAR158	F 4:	0	165
VAR159	F 4:	0	166
VAR160	F 4:	0	167
VAR161	F 4:	0	168
VAR162	F 4:	0	169
VAR163	F 4:	0	170
VAR164	F 4:	0	171
VAR165	F 4:	0	172
VAR166	F 4:	0	173
VAR167	F 4:	0	174
VAR168	F 4:	0	175
VAR169	F 4:	0	176
VAR170	F 4:	0	177
VAR171	F 4:	0	178
VAR172	F 4:	0	179
VAR173	F 4:	0	180
VAR174	F 4:	0	181
VAR175	F 4:	0	182
VAR176	F 4:	0	183
VAR177	F 4:	0	184
VAR178	F 4:	0	185
VAR179	F 4:	0	186
VAR180	F 4:	0	187
VAR181	F 4:	0	188
VAR182	F 4:	0	189
VAR183	F 4:	0	190
VAR184	F 4:	0	191
VAR185	F 4:	0	192
VAR186	F 4:	0	193
VAR187	F 4:	0	194
VAR188	F 4:	0	195
VAR189	F 4:	0	196
VAR190	F 4:	0	197
VAR191	F 4:	0	198
VAR192	F 4:	0	199
VAR193	F 4:	0	200
VAR194	F 4:	0	201
VAR195	F 4:	0	202
VAR196	F 4:	0	203
VAR197	F 4:	0	204
VAR198	F 4:	0	205
VAR199	F 4:	0	206
VAR200	F 4:	0	207
VAR201	F 4:	0	208
VAR202	F 4:	0	209
VAR203	F 4:	0	210
VAR204	F 4:	0	211
VAR205	F 4:	0	212
VAR206	F 4:	0	213
VAR207	F 4:	0	214
VAR208	F 4:	0	215
VAR209	F 4:	0	216
VAR210	F 4:	0	217
VAR211	F 4:	0	218
VAR212	F 4:	0	219
VAR213	F 4:	0	220
VAR214	F 4:	0	221
VAR215	F 4:	0	222
VAR216	F 4:	0	223
VAR217	F 4:	0	224
VAR218	F 4:	0	225
VAR219	F 4:	0	226
VAR220	F 4:	0	227
VAR221	F 4:	0	228
VAR222	F 4:	0	229
VAR223	F 4:	0	230
VAR224	F 4:	0	231
VAR225	F 4:	0	232
VAR226	F 4:	0	233
VAR227	F 4:	0	234
VAR228	F 4:	0	235
VAR229	F 4:	0	236
VAR230	F 4:	0	237
VAR231	F 4:	0	238
VAR232	F 4:	0	239
VAR233	F 4:	0	240
VAR234	F 4:	0	241
VAR235	F 4:	0	242
VAR236	F 4:	0	243
VAR237	F 4:	0	244
VAR238	F 4:	0	245
VAR239	F 4:	0	246
VAR240	F 4:	0	247
VAR241	F 4:	0	248
VAR242	F 4:	0	249
VAR243	F 4:	0	250
VAR244	F 4:	0	251
VAR245	F 4:	0	252
VAR246	F 4:	0	253
VAR247	F 4:	0	254
VAR248	F 4:	0	255
VAR249	F 4:	0	256
VAR250	F 4:	0	257
VAR251	F 4:	0	258
VAR252	F 4:	0	259
VAR253	F 4:	0	260
VAR254	F 4:	0	261
VAR255	F 4:	0	262
VAR256	F 4:	0	263
VAR257	F 4:	0	264
VAR258	F 4:	0	265
VAR259	F 4:	0	266
VAR260	F 4:	0	267
VAR261	F 4:	0	268
VAR262	F 4:	0	269
VAR263	F 4:	0	270
VAR264	F 4:	0	271
VAR265	F 4:	0	272
VAR266	F 4:	0	273
VAR267	F 4:	0	274
VAR268	F 4:	0	275
VAR269	F 4:	0	276
VAR270	F 4:	0	277
VAR271	F 4:	0	278
VAR272	F 4:	0	279
VAR273	F 4:	0	280
VAR274	F 4:	0	281
VAR275	F 4:	0	282
VAR276	F 4:	0	283
VAR277	F 4:	0	284
VAR278	F 4:	0	285
VAR279	F 4:	0	286
VAR280	F 4:	0	287
VAR281	F 4:	0	288
VAR282	F 4:	0	289
VAR283	F 4:	0	290
VAR284	F 4:	0	291
VAR285	F 4:	0	292
VAR286	F 4:	0	293
VAR287	F 4:	0	294
VAR288	F 4:	0	295
VAR289	F 4:	0	296
VAR290	F 4:	0	297
VAR291	F 4:	0	298
VAR292	F 4:	0	299
VAR293	F 4:	0	300
VAR294	F 4:	0	301
VAR295	F 4:	0	302
VAR296	F 4:	0	303
VAR297	F 4:	0	304
VAR298	F 4:	0	305
VAR299	F 4:	0	306
VAR300	F 4:	0	307
VAR301	F 4:	0	308
VAR302	F 4:	0	309
VAR303	F 4:	0	310
VAR304	F 4:	0	311
VAR305	F 4:	0	312
VAR306	F 4:	0	313
VAR307	F 4:	0	314
VAR308	F 4:	0	315
VAR309	F 4:	0	316
VAR310	F 4:	0	317
VAR311	F 4:	0	318
VAR312	F 4:	0	319
VAR313	F 4:	0	320
VAR314	F 4:	0	321
VAR315	F 4:	0	322
VAR316	F 4:	0	323
VAR317	F 4:	0	324
VAR318	F 4:	0	325
VAR319	F 4:	0	326
VAR320	F 4:	0	327
VAR321	F 4:	0	328
VAR322	F 4:	0	329
VAR323	F 4:	0	330
VAR324	F 4:	0	331
VAR325	F 4:	0	332
VAR326	F 4:	0	333
VAR327	F 4:	0	334
VAR328	F 4:	0	335
VAR329	F 4:	0	336
VAR330	F 4:	0	

ACCORDING TO YOUR INPUT FORMAT, VARIABLES ARE TO BE READ AS FOLLOWS

VARIABLE	FORMAT	RECORD	COLUMNS
VAR074	A 4	3	46- 49
VAR075	A 4	3	50- 53
VAR076	A 4	3	54- 57
VAR077	A 4	3	58- 61
VAR078	F 2: 0 0	3	62- 63
VAR079	F 2: 0 0	3	64- 65
VAR080	A 2	3	66- 67
VAR081	A 1	3	68- 68
VAR082	A 1	3	69- 69
VAR083	A 1	3	70- 70
VAR084	F 1: 0 0	3	71- 71
VAR085	F 2: 0 0	3	72- 73
VAR086	F 2: 0 0	3	74- 75
VAR087	A 1	3	76- 76
VAR088	A 1	3	77- 77
VAR089	A 1	3	78- 78
VAR090	A 2	3	79- 80

THE INPUT FORMAT PROVIDES FOR 90 VARIABLES. 90 WILL BE READ
IT PROVIDES FOR 3 RECORDS ('CARDS') PER CASE. A MAXIMUM OF 80 *COLUMNS* ARE USED ON A RECORD.

COMMENT ONE - PROGRAM TO CALCULATE PERCENT EXPECTED BATTERY
LIFE USED AT THE TIME A BATTERY WAS REPLACED.

COMMENT
IF
IF
IF
IF
COMMENT
IF
COMPUTE
IF
IF
IF
IF
COMMENT
IF

VAR069 IS RBDT IN JULIAN DATE FORMAT - THE FOLLOWING CARDS CREATE
NEW VARIABLE VARBDT WHICH IS RBDT CONVERTED INTO DAYS
(VAR069 GT 0 AND VAR069 LE 365) VARBDT = VAR069
(VAR069 GE 1000 AND VAR069 LE 1365) VARBDT = (VAR069 - 1000) +365
(VAR069 GE 2000 AND VAR069 LE 2365) VARBDT = (VAR069 - 2000) +730
(VAR069 GE 3000 AND VAR069 LE 3365) VARBDT = (VAR069 - 3000) +1095
THE FOLLOWING CARDS CREATE NEW VARIABLE VARUSE WHICH IS THE TIME
BATTERY HAS BEEN IN SERVICE IN JULIAN FORMAT AND VARDAY THE SAME
TIME CONVERTED INTO DAYS - VARDAT IS WORK DATE JULIAN EQUIVALENT
(VAR051 - VAR062) GE 366) VARDAT = (VAR051 - 1000) +365
VARUSE = VARDAT - VAR062
(VARUSE GE 0 AND VARUSE LE 730) VARDAY = VARUSE
(VARUSE GE 999 AND VARUSE LE 1730) VARDAY = (VARUSE - 1000) +365
(VARUSE GE 1999 AND VARUSE LE 2730) VARDAY = (VARUSE - 2000) +730
(VAR051 - VAR062) GE 0 AND (VAR051 - VAR062) LT 366)
VARDAY = VAR051 - VAR062
VARPER IS NEW VARIABLE PERCENT OF EXPECTED BATTERY LIFE CONSUMED
AS OF THE WORK DATE BASED UPON RBDT - WHERE THE BATTERY WAS
REPLACED ON THE WORK DATE THE PERCENT INDICATES SURVIVAL
PERFORMANCE OF THE OLD BATTERY.
(VAR071 NE .) VARPER = RND((VARDAY/VARBDT)*100)

01/14/75

MISSING VALUES

VAR059,VAR060,VAR081 TO VAR083,VAR087 TO VAR089(,)/
 VAR080(,)/VAR035(,)/
 VAR065,VAR067,VAR071,)/VAR030,
 VAR033,VAR034,VAR037 TO VAR077(,)/VAR030,
 VAR066,VAR068,VAR069,VAR078,VAR079,VAR084 TO VAR086,VARPER(0)

VAR LABELS

VAR001,LIGHT LIST NUMBER/
 VAR002,OPERATION/
 VAR003,LOCCATION/
 VAR004,BOUY SIZE/
 VAR005,CNS TRUCTION/
 VAR006,VENT VALVES PER POCKET/
 VAR007,LIGHT CHARACTERISTIC/
 VAR008,LIGHT COLOR/
 VAR009,LAMP TYPE/
 VAR010,LAMP TERN-UP TIC/
 VAR011,AVAILABLE SPARE CODE/
 VAR012,POWER SOURCE BATTERY/
 VAR013,BATTERY REUSE CODE/
 VAR014,LAMP CHARACTER/
 VAR015,FLASHER/
 VAR016,SOUND SIGNAL/
 VAR017,DAYLIGHT CONTROL/
 VAR018,BUTTON DESCRIPTION/
 VAR019,BUTTON CHARACTERISTIC/
 VAR020,DEPTH OF WATER IN FEET/
 VAR021,BRIDGE SIZE/
 VAR022,SWIVEL SIZE AND NUMBER/
 VAR023,FIRST CHAIN SIZE/
 VAR024,FIRST CHAIN LENGTH IN FATHOMS/
 VAR025,SECOND CHAIN SIZE/
 VAR026,SECOND CHAIN LENGTH/
 VAR027,NUMBER OF SINKERS/
 VAR028,TOTAL SINKER WEIGHT-RIPRAP DIST./
 VAR029,AID CONTROL NUMBER/
 VAR030,TOTAL NUMBER OF VISITS TO EACH AID,72-73/
 VAR031,WORK REASON/
 VAR032,INITIAL CONDITION OF AID/
 VAR033,INITIAL CONDITION OF AID/
 VAR034,INITIAL CONDITION OF AID/
 VAR035,DISTANCE CLOS, YARDS OFF STATION/
 VAR036,WORK PERFORMED/
 VAR037,WORK PERFORMED/
 VAR038,WORK PERFORMED/
 VAR039,WORK PERFORMED/
 VAR040,WORK PERFORMED/
 VAR041,WORK PERFORMED/
 VAR042,WORK PERFORMED/
 VAR043,WORK PERFORMED/
 VAR044,WORK PERFORMED/
 VAR045,WORK PERFORMED/
 VAR046,WORK PERFORMED/
 VAR047,TIME SPENT ON SITE-TENTHS HOURS/
 VAR048,TOTAL NO. OF DISCREPANCIES OF AID/
 VAR049,JULIAN DATE CG INFORMED DISCREP/

VAR050, HOUR CG INFORMED OF DISCREPANCY/
 VAR051, J DATE WORK PERFORMED-OR 336SEND/
 VAR052, HOUR WORK PERFORMED/
 VAR053, DAYS INITIAL NUTN TIL NEXT VISIT/
 VAR054, FINAL CONDITION OF AID/
 VAR055, FINAL CONDITION OF AID/
 VAR056, CLOSED CIRCUIT VOLT NEW BATTERY/
 VAR057, CLOSED VOLT OLD-EXISTING BATTERY/
 VAR058, UNIT WORK PERFORMED BY/
 VAR059, PRIMARY METHOD OF POSITIONING/
 VAR060, PRIMARY CAUSE OF FAILURE-SANDS/
 VAR061, JULIAN DATE LAST RECHARGED/
 VAR062, EXTPA CODE/
 VAR063, SCHEDULED SERVICE DATE/
 VAR064, DAYS SERVICE IN VARIANCE SCHED/
 VAR065, SCHEDULED RELIEF-WITHDRAWL DATE/
 VAR066, DAYS RELIEF IN VARIANCE SCHED/
 VAR067, SCHEDULED RECHARGE DATE/ TIME/
 VAR068, RATED BATTERY DISCHARGE TIME/
 VAR069, NO. TURNED OUT LAMPS REPLACED/
 VAR070, POWER UNIT'S REPLACED WITH REASON/
 VAR071, BULB RELIEVED WITH REASON/
 VAR072, FLASHER REPLACED WITH REASON/
 VAR073, LAMP CHANGER REPLACED WITH REASON/
 VAR074, DAYLIGHT CONTROL REP. WITH REASON/
 VAR075, LANTERN-OPTIC REP. WITH REASON/
 VAR076, MOUNTING SP-CODE REP WITH REASON/
 VAR077, MAIN CAUSE FOR FAILURE OR RELATED NOTE/
 VAR078, MAIN CAUSE FOR FAILURE OR RELATED NOTE/
 VAR079, COMPONENT LOST-DAMAGED DURING SERVICE/
 VAR080, REASON DELAY IF DISCREP REPORTED/
 VAR081, NATURE OF SERVICE/
 VAR082, REASON WHY IF TEMPORARY/ DISCREP/
 VAR083, NO VISITS RELATED TO EACH DISCREP/
 VAR084, CORRECTION REQUIRED IF TEMPORARY/
 VAR085, DAYS TIME TO EFFECT PERM SERVICE/
 VAR086, COMMENT AND ERROR CODES/
 VAR087, COMMENT AND ERROR CODES/
 VAR088, ANALYSIS CARD CODE/
 VAR089, PERCENT EXPECTED BATTERY LIFE USED/
 VAR090, (1279) COUS BY CH LB 18/
 VAR091, (P) PERMANENT AID (T) TEMPORARY AID (S) SEASONAL-NU REPT
 (W) INTER PLACEMENT (U) AID DISCONTINUED/
 (C) EXPOSED BAY, HARBOR (D) EXPOSED
 RIVER (E) EXPOSED BREAKWATER (F) EXPOSED ASHORE (K) SEMI-EXPD SEA
 COAST (L) SEMI-EXPD BAY, HARBOR (M) SEMI-EXPD RIVER (N) SEMI-EXPD
 BREAKWATER (O) SEMI-EXPD ASHORE (P) PROTECTED SEA COAST (T) BAY;
 HARBOR PROTECTED (U) PROTECTED RIVER (V) PROTECTED BREAKWATER (W)
 PROTECTED ASHORE (X) AID DISCONTINUED/
 VAR004 (510) X 10 (51) 5 X 20 (715) 7 X 15 (717) 7 X 17
 (820) 8 X 20 (823) 8 X 23 (826) 8 X 26 (932) 9 X 32 (934) 9 X 34
 (958) 9 X 38 (039) 10 X 39 (0) AID DISCONTINUED/

VALUE LABELS

269

RY(23)TARDY SERVICE(24)PERSONNEL ERROR(25)HORN-BKN MOORINGS(26)FL
OOED(27)CAUGHT DOWN(28)WEATHER(29)ICE(30)COLLISION(31)VANDALISM
(32)UNKNOWN(45)ALL LAMPS(46)FLASHER(47)LAMPCHANGER(50)DAYLIGHT CO
NTRUL(51)LANERN(52)SOUND SIGNAL(53)TAPERS(58)WIRING(59)SHACKLE
(60)BRIDLE(61)FIRST CHAIN(62)SECOND CHAIN(63)SINKER(67)MOORINGS
(69)BUOY DETILURATION(70)MOORINGS RPLD PVUS(72)POCK COV MSG(73)PE
RSNL BELVD PM REQ(81)CBN WX,V02,UKN,PE18(72)2ND CONSCV DISCY(85)3R
D + CONSCV DISCY(83)SWIVEL(92)VEE BAND/
VAR080 (.LM.)LOST MOORINGS(.DB.)DAMAGED BATTERIES(.MI.) BUOY NOT
FOUND(.BY.)BY FOUND OR SALVGD(.BL.)BUOY LOST NOT SALVGD/
VAR002,VAR003,VAR008,VAR011 TO VAR013,VAR018 TO VAR020,VAR031,
VAR035,VAR059,VAR060,VAR065,VAR067,VAR071 TO VAR077,
VAR099 TO VAR083, (AT)VAR001 (2)/VAR004 TO VAR007,VAR009,VAR010,
VAR087 TO VAR090,VAR021 TO VAR030,VAR032 TO VAR034,
VAR014 TO VAR017,VAR048 TO VAR056,VAR061 TO VAR064,VAR066,
VAR036 TO VAR046,VAR048 TO VAR056,VAR061 TO VAR064,VAR066,
VAR068 TO VAR070,VAR078,VAR079,VAR084 TO VAR086 (O)/VAR047,
VAR057,VAR058 (1)
VAR030
+
ALL

PRINT FORMAT

CODEBOOK
OPTIONS
STATISTICS

COMMENT	TWO -	EXPLANATION OF BASIC CODES USED FOR INDICATING REASON FOR COMPONENT REPLACEMENT.
A -	RECHARGED, ERROR COMDT INST 10500.32A	
B -	DAMAGED BY SOUND DEVICE	
C -	CONVENIENCE	
E -	BUOY WAS RELIEVED EARLY	
G -	MISSING BUOY	
H -	DUE TO POOR PAST PERFORMANCE, TRIED A NEW TYPE	
I -	ICE	
J -	LIGHTED BUOY TEMPORARILY RELIEVED BY AN UNLIGHTED BUOY	
K -	NO INDICATED REASON	
L -	COLLISION	
M -	PREVNT MAINTENANCE	
N -	PREPLANNED LANTERN REPLACEMENT	
O -	LANTERN WAS CRACKED OR THE LANTERN GASKET LEAKED	
R -	CORUSION	
S -	ROUTINE SERVICING	
T -	RECHARGED FOLLOWING TEMPORARY HOTPACK	
U -	SEASONAL LIGHTED BUOY COMMISSIONED	
V -	WEATHER, WIND, STORM	
W -	LIGHTED BUOY RESET FOLLOWING A TEMPORARY DISCREPANCY	
X -	POLICY - ECONOMIZE	
Y -	SINKING	
DN -	MISSING, FLOODED	
DX -	VEE BAND MISSING, FLOODED	
DL -	POCKET COVER MISSING, FLOODED	
FI -	WATER DAMAGE	
FP -	IMPROPER INSTALLATION	
	IMPROPER PROGRAMMING	

ES- TARDY SERVICING
 ER- WRONG REPAIR
 FA- ENTIRE LANTERN ASSEMBLY REPLACED
 FO- DEFECTIVE
 FW- WORKN OUT
 FU- UNKNOWN
 FC- COMBINATION- DEFECTIVE WORN OUT OR UNKNOWN
 FL- LOUSE LENS- VOLTS
 FV- BELUM 10.8-72
 PA- OPURD 134-71
 PB- OPURD 160-71
 PC- OPURD 127-73
 PD- OPURD 094-72
 PE- OPURD 054-73
 PF- OPURD 067-71
 PG- OPURD 132-72
 PH- OPURD 180-73
 PI- OPURD 161-72
 PJ- OPURD 185-73
 PK- RECHARGED 90 OR MORE DAYS BEFORE SCHEDULED DATE
 QM- RECHARGED MORE THAN 90 DAYS BEYOND SCHEDULED DATE
 TO- TEMPORARY UNLIGHTED BUOY RELIEF
 TH- COMPONENTS REPLACED FOLLOWING TEMPORARY UNL BUOY
 VA- CC013 INST
 VB- CG-4500 11ST
 VC- CG018F201802ZJUN72
 ZF- VANDALISM-FORCE
 ZG- VANDALISM-GUN
 ZI- VANDALISM-THEFT

COMMENT THREE - EXPLANATION OF COMPONENT NUMBERING CODES. USING FOR
 EXAMPLE, '43FD', THE '46' INDICATES THAT A FLASHER WAS
 REPLACED AND THE 'FD' INDICATES THAT THE FLASHER WAS
 REPLACED BECAUSE IT WAS DEFECTIVE. NUMBERS RELATE TO
 SANDS COLUMNS AND COING WHERE POSSIBLE. BASIC COLUMNS
 ARE 42, 43, 45, 46, 47, 50, 51, 64.
 42 BATTERIES REPLACED
 43 BUOY RELIEVED
 45 LAMPS REPLACED (PROJECT OR PRIMARY CAUSE OF FAILURE)
 46 FLASHER REPLACED
 47 LAMP CHANGER REPLACED
 50 DAYLIGHT LANTERN REPLACED
 51 REPLACED LANTERN
 58 REWIRED (64 CUL)
 59 REPLACED SHACKLE(S) (64 CUL)
 60 REPLACED BRIDLE (64 CUL)
 61 REPLACED FIRST CHAIN (64 CUL)
 62 REPLACED SECOND CHAIN (64 CUL)
 63 REPLACED SINKER (64 CUL)
 64 REPLACED ENTIRE MOORING
 67 CHANGED TYPE CHARACTERISTIC (NON-SEASONAL CHANGE ONLY)
 70 BUOY ESTABLISHED PERMANENTLY (43 CUL)

71 COMMISSIONED (NON-SEASONAL CHANGE ONLY) (43 COL)
72 DISCONTINUED PERMANENTLY (42 COL)
73 BUOY WITHDRAWN-REPLACED BY UNLIGHTED WINTER MARKER,
(43 COL) CHANGES INDICATED (43 COL)
74 MOORING CHANGES INDICATED (43 COL)
75 RELIEVED BUOY AND REPLACE ENTIRE MOORING (43,64 COL)
76 REPLACED LANTERN AND ALL INTERNAL COMPONENTS (51 COL)
77 REPLACED SHACKLE(S) AND SECOND CHAIN (64 COL)
78 REPLACED SHACKLE(S) AND FIRST CHAIN (64 COL)
79 REPLACED BRIDLE FIRST CHAIN (64 COL)
80 REMOVED SOUND SIGNAL (50 COL)
81 INSTALLED-REPLACED SOUND SIGNAL (50 COL)
82 INSTALLED-REPLACED REASON FOR BATTERY REPLACEMENT GIVEN
(42 COL)
83 REPLACED SECOND CHAIN AND SINKER (64 COL)
84 COMPLETED SEASONAL BUOY-REPLACED UNLIGHTED WINTER
MARKER, MARKING CHANGES INDICATED (43 COL)
85 BUOY TEMPORARILY REPLACED BY UNLIGHTED BUOY (43 COL)
86 REPLACED BRIDLE, SWIVEL, SECOND CHAIN (64 COL)
87 COMPLETED SEASONAL BUOY-COMMISSIONED AS NO WINTER
MARKER WAS USED, INCLUDES MOORINGS (43 COL)
88 BUOY WITHDRAWN -NOT REPLACED BY WINTER MARKER (43 COL)
89 REPLACED SWIVEL (64 COL)
90 BUOY TEMPORARILY RELIEVED BY UNLIGHTED BUOY WAS RESET
(43 COL)

READ INPUT DATA

***** GIVEN SPACE ALLOWS FOR 1 VARIABLES AND 1498 VALUES FOR CODEBOOK *****

*SELECT IF
CODEBOOK (VAR051 EQ 3365)
VAR002,VAR003,VAR006,VAR008 TO VAR010,VAR012,VAR014 TO VAR018,
VAR021 TO VAR023

COMMENT

THE ABOVE CARDS ARE USED TO INDICATE THE NUMBER OF AIDS AND AID
COMPONENTS IN SERVICE AS OF 31 DECEMBER 1973. SANDS MANUAL CODES
ARE UTILIZED. ONE AID WAS DISCONTINUED DURING 1973 AND APPEARS
AS CODE 0,0, OR BLANK.

01/14/75

PAGE 30

***** GIVEN SPACE ALLOWS FOR 15 VARIABLES AND 392 VALUES FOR CODEBOOK *****

*SELECT IF
CROSSTABS(VAR051, EQ 3365)
VAR002, VAR004, VAR006 TO VAR010, VAR012, VAR014 TO VAR018, VAR021 TO
VAR023 BY VAR003/VAR004 BY VAR006, VAR007, VAR016, VAR023/VAR015 BY
VAR007/VAR010 BY VAR017

COMMENT

* NON-STANDARD FLASHER ** FL 2.5 (0.5) AND FL 6.0 (1.0)
FLASHERS WERE TO BE PERMANENTLY REPLACED BY FL 2.5 (0.3) AND
FL 6.0 (0.6) FLASHERS RESPECTIVELY COMMENCING IN 1973

01/14/75

PAGE 61

***** GIVEN SPACE ALLOWS FOR 3749 CELLS AND 2 DIMENSIONS FOR CROSSTABS *****

*SELECT IF
MARGINALS(VAR051, EQ 3365)
VAR005, VAR024

COMMENT

BUOY CONSTRUCTION CODE 11 INDICATES THAT A BUOY IS WELDED AND
EQUIPPED WITH A RADAR REFLECTOR, STANDARD POCKETS, AND LARGE
VENTS.

CODEBOOK,MARGINALS,CROSSTABLATIONS BEFORE BREAKDOWN RECODING	01/14/75	PAGE 64
***** GIVEN SPACE ALLOWS FOR 2 VARIABLES AND 2142 VALUES FOR MARGINALS *****		
CODEBOOK	VAR071,VAR072	
COMMENT	USE CODE TABLE ON PROGRAM PAGES 8 AND 9 AS REFERENCE FOR LABELS.	
CODEBOOK,MARGINALS,CROSSTABLATIONS BEFORE BREAKDOWN RECODING	01/14/75	PAGE 69
***** GIVEN SPACE ALLOWS FOR 2 VARIABLES AND 1248 VALUES FOR CODEBOOK *****		
*RECODE	VAR072 ('43W','84W','43L','43L'='433)	
*SELECT IF	((VAR072 EQ 433 OR VAR072 EQ 435) AND VAR004 NE 0 AND VAR004 NE 620)	
CROSSTABS	VAR072 BY VAR004	
CODEBOOK,MARGINALS,CROSSTABLATIONS BEFORE BREAKDOWN RECODING	01/14/75	PAGE 71
***** GIVEN SPACE ALLOWS FOR 3749 CELLS AND 2 DIMENSIONS FOR CROSSTABS *****		
*RECODE	VARPER (1 THRU 20=10)(21 THRU 40=30)(41 THRU 60=50) (61 THRU 70=65)(71 THRU 80=75)(81 THRU 90=85) (91 THRU 100=95)(101 THRU 110=105)(111 THRU 121=115) (122 THRU HIGHEST=150)	
CROSSTABS	VAR072 BY VARPER	
COMMENT	THE ABOVE CARDS REGROUP PERCENT OF BATTERY LIVES REALIZED. FOR EXAMPLE, POWER UNITS THAT CONSUMED 71% TO 80% OF THEIR EXPECTED TOTAL USEFUL LIVES ARE ALL CLASSIFIED AS HAVING 75% CONSUMPTION AT THE TIME OF REPLACEMENT.	

CODEBOOK,MARGINALS,CROSSTABULATIONS BEFORE BREAKDOWN RECODING

PAGE 74

01/14/75

***** GIVEN SPACE ALLOWS FOR 3749 CELLS AND 2 DIMENSIONS FOR CROSSTABS *****

*RECODE
*SELECT IF
CROSSTABS
VAR072 ('43L'=433)('43W','84W'=435)
(VAR072 EQ 433 OR VAR072 EQ 435)
VAR072 BY VAR003

CODEBOOK,MARGINALS,CROSSTABULATIONS BEFORE BREAKDOWN RECODING

PAGE 76

01/14/75

***** GIVEN SPACE ALLOWS FOR 3749 CELLS AND 2 DIMENSIONS FOR CROSSTABS *****

*RECODE
*SELECT IF
CROSSTABS
VAR072 ('43L'=433)('43W','84W'=435)
(VAR072 EQ 433 OR VAR072 EQ 435) AND VAR051 NE 3365)
VAR072 BY VAR051

CODEBOOK,MARGINALS,CROSSTABULATIONS BEFORE BREAKDOWN RECODING

PAGE 80

01/14/75

***** GIVEN SPACE ALLOWS FOR 3749 CELLS AND 2 DIMENSIONS FOR CROSSTABS *****

CODEBOOK
VAR073

CODEBOOK, MARGINALS, CROSSTABLATIONS BEFORE BREAKDOWN RECODING

01/14/75

PAGE 82

***** GIVEN SPACE ALLOWS FOR 1 VARIABLES AND 1498 VALUES FOR CODEBOOK *****

*RECODE
*SELECT IF
CROSSTABS
VAR073 ('46L'=466)
(VAR073 EQ 466)
VAR073 BY VAR001

COMMENT

THE PREVIOUS TABULATION REVEALED THAT 12 FLASHERS WERE
REPLACED BECAUSE THE BUOY THEY WERE EACH INSTALLED UPON WAS
INVOLVED IN A COLLISION WITH A PASSING VESSEL. THE ABOVE CARDS
ENABLE EACH COLLISION TO BE IDENTIFIED WITH AID LIGHT LIST
NUMBERS TO LOCATE ANY AID THAT IS COLLISION PRONE.

CODEBOOK, MARGINALS, CROSSTABLATIONS BEFORE BREAKDOWN RECODING

01/14/75

PAGE 85

***** GIVEN SPACE ALLOWS FOR 3749 CELLS AND 2 DIMENSIONS FOR CROSSTABS *****

MARGINALS
VAR070, VAR074

CODEBOOK, MARGINALS, CROSSTABLATIONS BEFORE BREAKDOWN RECODING

01/14/75

PAGE 88

***** GIVEN SPACE ALLOWS FOR 2 VARIABLES AND 2142 VALUES FOR MARGINALS *****

*RECODE
*SELECT IF
CROSSTABS
VAR076 ('51PG'=5200) ('51PF'=5100)
(VAR076 EQ 5200 OR VAR076 EQ 5100)
VAR076 BY VAR001

COMMENT

THE ABOVE CARDS ARE USED TO INDICATE THOSE LANTERNS REPLACED
AS A RESULT OF DISTRICT PROJECTS, REPLACING GLASS WITH ACRYLIC
LANTERNS FOR EXAMPLE.

CODEBOOK,MARGINALS,CROSSTABULATIONS BEFORE BREAKDOWN RECODING 01/14/75 PAGE 90

***** GIVEN SPACE ALLOWS FOR 3749 CELLS AND 2 DIMENSIONS FOR CROSSTABS *****

CODEBOOK VAR078,VAR079

COMMENT IN THE FOLLOWING TABLES,CAUSES OF AID FAILURES OR RELATED NOTES
ARE PRESENTED.

CODEBOOK,MARGINALS,CROSSTABULATIONS BEFORE BREAKDOWN RECODING 01/14/75 PAGE 93

***** GIVEN SPACE ALLOWS FOR 2 VARIABLES AND 1248 VALUES FOR CODEBOOK *****

CODEBOOK VAR080

CODEBOOK,MARGINALS,CROSSTABULATIONS BEFORE BREAKDOWN RECODING 01/14/75 PAGE 95

***** GIVEN SPACE ALLOWS FOR 1 VARIABLES AND 1498 VALUES FOR CODEBOOK *****

FINISH

RUN NAME CODEBOOK, MARGINALS, CROSSTABULATIONS AFTER BREAKDOWN RECODING
 FILE NAME ATONAV13 100 LIGHTED BUOYS FOR CAL YEARS 72-73 IN 13TH CGU1ST
 VARIABLE LIST VAR001 TO VAR090
 INPUT MEDIUM CARD
 # OF CASES 268
 INPUT FORMAT FIXED (F6-2,2X,A1,A1,1X,F3-0,1X,F2-0,F1-0,1X,F3-0,1X,A1,1X,F2-0,

ACCORDING TO YOUR INPUT FORMAT, VARIABLES ARE TO BE READ AS FOLLOWS

VARIABLE	FORMAT	RECORD	COLUMNS
VAR001	F 6.	1	1-
VAR002	F 6.	1	9-
VAR003	A 1	1	10-
VAR004	A 1	1	12-
VAR005	F 3.0	1	14-
VAR006	F 3.0	1	16-
VAR007	F 3.0	1	18-
VAR008	F 3.0	1	20-
VAR009	F 2.0	1	22-
VAR010	F 2.0	1	24-
VAR011	F 2.0	1	26-
VAR012	A 1	1	27
VAR013	A 1	1	28
VAR014	A 1	1	29
VAR015	F 2.0	1	31
VAR016	F 2.0	1	32
VAR017	F 2.0	1	33
VAR018	F 2.0	1	35
VAR019	F 2.0	1	36
VAR020	A 1	1	37
VAR021	A 2	1	38
VAR022	A 2	1	39
VAR023	A 2	1	40
VAR024	A 2	1	41
VAR025	A 2	1	42
VAR026	A 2	1	43
VAR027	A 2	1	44
VAR028	A 2	1	45
VAR029	A 2	1	46
VAR030	A 2	1	47
VAR031	A 2	1	48
VAR032	A 2	1	49
VAR033	A 2	1	50
VAR034	A 2	1	51
VAR035	A 2	1	52
VAR036	A 2	1	53
VAR037	A 2	1	54
VAR038	A 2	1	55
VAR039	A 2	1	56
VAR040	A 2	1	57
VAR041	A 2	1	58
VAR042	A 2	1	59
VAR043	A 2	1	60
VAR044	A 2	1	61
VAR045	A 2	1	62
VAR046	A 2	1	63
VAR047	A 2	1	64
VAR048	A 2	1	65
VAR049	A 2	1	66
VAR050	A 2	1	67
VAR051	A 2	1	68
VAR052	A 2	1	69
VAR053	A 2	1	70
VAR054	A 2	1	71
VAR055	A 2	1	72
VAR056	A 2	1	73
VAR057	A 2	1	74
VAR058	A 2	1	75
VAR059	A 2	1	76
VAR060	A 2	1	77
VAR061	A 2	1	78
VAR062	A 2	1	79
VAR063	A 2	1	80
VAR064	A 2	1	81
VAR065	A 2	1	82
VAR066	A 2	1	83
VAR067	A 2	1	84
VAR068	A 2	1	85
VAR069	A 2	1	86
VAR070	A 2	1	87
VAR071	A 2	1	88
VAR072	A 2	1	89
VAR073	A 2	1	90
VAR074	A 2	1	91
VAR075	A 2	1	92
VAR076	A 2	1	93
VAR077	A 2	1	94
VAR078	A 2	1	95
VAR079	A 2	1	96
VAR080	A 2	1	97
VAR081	A 2	1	98
VAR082	A 2	1	99
VAR083	A 2	1	100
VAR084	A 2	1	101
VAR085	A 2	1	102
VAR086	A 2	1	103
VAR087	A 2	1	104
VAR088	A 2	1	105
VAR089	A 2	1	106
VAR090	A 2	1	107

ACCORDING TO YOUR INPUT FORMAT, VARIABLES ARE TO BE READ AS FOLLOWS

VARIABLE	FORMAT	RECORD	COLUMNS
VAR034	F 2	0	7
VAR035	F 2	A 3	10
VAR036	F 2	0 0	12
VAR037	F 2	0 0	14
VAR038	F 2	0 0	16
VAR039	F 2	0 0	18
VAR040	F 2	0 0	20
VAR041	F 2	0 0	22
VAR042	F 2	0 0	24
VAR043	F 2	0 0	26
VAR044	F 2	0 0	28
VAR045	F 2	0 0	30
VAR046	F 2	0 0	32
VAR047	F 2	0 1	34
VAR048	F 1	0 0	3.0,3F2.0,2F3.1,2A1,F2.0,F4.0,6X/F1.0,F4.0,A4,
VAR049	F 4	0 0	35
VAR050	F 4	0 0	36
VAR051	F 4	0 0	37
VAR052	F 4	0 0	40
VAR053	F 3	0 0	41
VAR054	F 2	0 0	44
VAR055	F 2	0 0	45
VAR056	F 2	0 0	46
VAR057	F 2	0 0	47
VAR058	F 2	0 0	48
VAR059	F 2	0 0	49
VAR060	F 2	0 0	50
VAR061	F 2	0 0	51
VAR062	F 2	0 0	52
VAR063	F 2	0 0	53
VAR064	F 2	0 0	54
VAR065	F 2	0 0	55
VAR066	F 4	0 0	56
VAR067	F 4	0 0	57
VAR068	F 4	0 0	58
VAR069	F 4	0 0	59
VAR070	F 4	0 0	60
VAR071	F 4	0 0	61
VAR072	F 4	0 0	62
VAR073	F 4	0 0	63
VAR074	F 4	0 0	64
VAR075	F 4	0 0	65
VAR076	F 4	0 0	66
VAR077	F 4	0 0	67
VAR078	F 4	0 0	68
VAR079	F 4	0 0	69
VAR080	F 4	0 0	70
VAR081	F 4	0 0	71
VAR082	F 4	0 0	72
VAR083	F 4	0 0	73
VAR084	F 4	0 0	74
VAR085	F 4	0 0	75
VAR086	F 4	0 0	76
VAR087	F 4	0 0	77
VAR088	F 4	0 0	78
VAR089	F 4	0 0	79
VAR090	F 4	0 0	80
VAR091	F 4	0 0	81
VAR092	F 4	0 0	82
VAR093	F 4	0 0	83
VAR094	F 4	0 0	84
VAR095	F 4	0 0	85
VAR096	F 4	0 0	86
VAR097	F 4	0 0	87
VAR098	F 4	0 0	88
VAR099	F 4	0 0	89
VAR100	F 4	0 0	90
VAR101	F 4	0 0	91
VAR102	F 4	0 0	92
VAR103	F 4	0 0	93
VAR104	F 4	0 0	94
VAR105	F 4	0 0	95
VAR106	F 4	0 0	96
VAR107	F 4	0 0	97
VAR108	F 4	0 0	98
VAR109	F 4	0 0	99
VAR110	F 4	0 0	100
VAR111	F 4	0 0	101
VAR112	F 4	0 0	102
VAR113	F 4	0 0	103
VAR114	F 4	0 0	104
VAR115	F 4	0 0	105
VAR116	F 4	0 0	106
VAR117	F 4	0 0	107
VAR118	F 4	0 0	108
VAR119	F 4	0 0	109
VAR120	F 4	0 0	110
VAR121	F 4	0 0	111
VAR122	F 4	0 0	112
VAR123	F 4	0 0	113
VAR124	F 4	0 0	114
VAR125	F 4	0 0	115
VAR126	F 4	0 0	116
VAR127	F 4	0 0	117
VAR128	F 4	0 0	118
VAR129	F 4	0 0	119
VAR130	F 4	0 0	120
VAR131	F 4	0 0	121
VAR132	F 4	0 0	122
VAR133	F 4	0 0	123
VAR134	F 4	0 0	124
VAR135	F 4	0 0	125
VAR136	F 4	0 0	126
VAR137	F 4	0 0	127
VAR138	F 4	0 0	128
VAR139	F 4	0 0	129
VAR140	F 4	0 0	130
VAR141	F 4	0 0	131
VAR142	F 4	0 0	132
VAR143	F 4	0 0	133
VAR144	F 4	0 0	134
VAR145	F 4	0 0	135
VAR146	F 4	0 0	136
VAR147	F 4	0 0	137
VAR148	F 4	0 0	138
VAR149	F 4	0 0	139
VAR150	F 4	0 0	140
VAR151	F 4	0 0	141
VAR152	F 4	0 0	142
VAR153	F 4	0 0	143
VAR154	F 4	0 0	144
VAR155	F 4	0 0	145
VAR156	F 4	0 0	146
VAR157	F 4	0 0	147
VAR158	F 4	0 0	148
VAR159	F 4	0 0	149
VAR160	F 4	0 0	150
VAR161	F 4	0 0	151
VAR162	F 4	0 0	152
VAR163	F 4	0 0	153
VAR164	F 4	0 0	154
VAR165	F 4	0 0	155
VAR166	F 4	0 0	156
VAR167	F 4	0 0	157
VAR168	F 4	0 0	158
VAR169	F 4	0 0	159
VAR170	F 4	0 0	160
VAR171	F 4	0 0	161
VAR172	F 4	0 0	162
VAR173	F 4	0 0	163
VAR174	F 4	0 0	164
VAR175	F 4	0 0	165
VAR176	F 4	0 0	166
VAR177	F 4	0 0	167
VAR178	F 4	0 0	168
VAR179	F 4	0 0	169
VAR180	F 4	0 0	170
VAR181	F 4	0 0	171
VAR182	F 4	0 0	172
VAR183	F 4	0 0	173
VAR184	F 4	0 0	174
VAR185	F 4	0 0	175
VAR186	F 4	0 0	176
VAR187	F 4	0 0	177
VAR188	F 4	0 0	178
VAR189	F 4	0 0	179
VAR190	F 4	0 0	180
VAR191	F 4	0 0	181
VAR192	F 4	0 0	182
VAR193	F 4	0 0	183
VAR194	F 4	0 0	184
VAR195	F 4	0 0	185
VAR196	F 4	0 0	186
VAR197	F 4	0 0	187
VAR198	F 4	0 0	188
VAR199	F 4	0 0	189
VAR200	F 4	0 0	190
VAR201	F 4	0 0	191
VAR202	F 4	0 0	192
VAR203	F 4	0 0	193
VAR204	F 4	0 0	194
VAR205	F 4	0 0	195
VAR206	F 4	0 0	196
VAR207	F 4	0 0	197
VAR208	F 4	0 0	198
VAR209	F 4	0 0	199
VAR210	F 4	0 0	200
VAR211	F 4	0 0	201
VAR212	F 4	0 0	202
VAR213	F 4	0 0	203
VAR214	F 4	0 0	204
VAR215	F 4	0 0	205
VAR216	F 4	0 0	206
VAR217	F 4	0 0	207
VAR218	F 4	0 0	208
VAR219	F 4	0 0	209
VAR220	F 4	0 0	210
VAR221	F 4	0 0	211
VAR222	F 4	0 0	212
VAR223	F 4	0 0	213
VAR224	F 4	0 0	214
VAR225	F 4	0 0	215
VAR226	F 4	0 0	216
VAR227	F 4	0 0	217
VAR228	F 4	0 0	218
VAR229	F 4	0 0	219
VAR230	F 4	0 0	220
VAR231	F 4	0 0	221
VAR232	F 4	0 0	222
VAR233	F 4	0 0	223
VAR234	F 4	0 0	224
VAR235	F 4	0 0	225
VAR236	F 4	0 0	226
VAR237	F 4	0 0	227
VAR238	F 4	0 0	228
VAR239	F 4	0 0	229
VAR240	F 4	0 0	230
VAR241	F 4	0 0	231
VAR242	F 4	0 0	232
VAR243	F 4	0 0	233
VAR244	F 4	0 0	234
VAR245	F 4	0 0	235
VAR246	F 4	0 0	236
VAR247	F 4	0 0	237
VAR248	F 4	0 0	238
VAR249	F 4	0 0	239
VAR250	F 4	0 0	240
VAR251	F 4	0 0	241
VAR252	F 4	0 0	242
VAR253	F 4	0 0	243
VAR254	F 4	0 0	244
VAR255	F 4	0 0	245
VAR256	F 4	0 0	246
VAR257	F 4	0 0	247
VAR258	F 4	0 0	248
VAR259	F 4	0 0	249
VAR260	F 4	0 0	250
VAR261	F 4	0 0	251
VAR262	F 4	0 0	252
VAR263	F 4	0 0	253
VAR264	F 4	0 0	254
VAR265	F 4	0 0	255
VAR266	F 4	0 0	256
VAR267	F 4	0 0	257
VAR268	F 4	0 0	258
VAR269	F 4	0 0	259
VAR270	F 4	0 0	260
VAR271	F 4	0 0	261
VAR272	F 4	0 0	262
VAR273	F 4	0 0	263
VAR274	F 4	0 0	264
VAR275	F 4	0 0	265
VAR276	F 4	0 0	266
VAR277	F 4	0 0	267
VAR278	F 4	0 0	268
VAR279	F 4	0 0	269
VAR280	F 4	0 0	270
VAR281	F 4	0 0	271
VAR282	F 4	0 0	272
VAR283	F 4	0 0	273
VAR284	F 4	0 0	274
VAR285	F 4	0 0	275
VAR286	F 4	0 0	276
VAR287	F 4	0 0	277
VAR288	F 4	0 0	278
VAR289	F 4	0 0	279
VAR290	F 4	0 0	280
VAR291	F 4	0 0	281
VAR292	F 4	0 0	282
VAR293	F 4	0 0	283
VAR294	F 4	0 0	284
VAR295	F 4	0 0	285
VAR296	F 4	0 0	286
VAR297	F 4	0 0	287
VAR298	F 4	0 0	288
VAR299	F 4	0 0	289
VAR300	F 4	0 0	290
VAR301	F 4	0 0	291
VAR302	F 4	0 0	292
VAR303	F 4	0 0	293
VAR304	F 4	0 0	294
VAR305	F 4	0 0	295
VAR306	F 4	0 0	296
VAR307	F 4	0 0	297
VAR308	F 4	0 0	298
VAR309	F 4	0 0	299
VAR310	F 4	0 0	300
VAR311	F 4	0 0	301
VAR312	F 4	0 0	302
VAR313	F 4	0 0	303
VAR314	F 4	0 0	304
VAR315	F 4	0 0	305
VAR316	F 4	0 0	306
VAR317	F 4	0 0	307
VAR318	F 4	0 0	308
VAR319	F 4	0 0	309
VAR320	F 4	0 0	310
VAR321	F 4	0 0	311
VAR322	F 4	0 0	312
VAR323	F 4	0 0	313
VAR324	F 4	0 0	314
VAR325	F 4	0 0	315
VAR326	F 4	0 0	316
VAR327	F 4	0 0	317
VAR328	F 4	0 0	318
VAR329	F 4	0 0	319
VAR330	F 4	0 0	320
VAR331	F 4	0 0	321
VAR332	F 4	0 0	322
VAR333	F 4	0 0	323
VAR334	F 4	0 0	324
VAR335	F 4	0 0	325
VAR336	F 4	0 0	326
VAR337	F 4	0 0	327
VAR338	F 4	0 0	328
VAR339	F 4	0 0	329
VAR340	F 4	0 0	330
VAR341	F 4	0 0	331
VAR342	F 4	0 0	332
VAR343	F 4	0 0	333
VAR344	F 4	0 0	334
VAR345	F 4	0 0	335
VAR346	F 4	0 0	336
VAR347	F 4	0 0	337
VAR348	F 4	0 0	338
VAR349	F 4	0 0	339
VAR350	F 4	0 0	340
VAR351	F 4	0 0	341
VAR352	F 4	0 0	342
VAR353	F 4	0 0	343
VAR354	F 4	0 0	344
VAR355	F 4	0 0	345
VAR356	F 4	0 0	346
VAR357	F 4	0 0	347
VAR358	F 4	0 0	348
VAR359	F 4	0 0	349
VAR360	F 4	0 0	350
VAR361	F 4	0 0	351
VAR362</			

ACCORDING TO YOUR INPUT FORMAT, VARIABLES ARE TO BE READ AS FOLLOWS

VARIABLE	FORMAT	RECORD	COLUMNS
VAR074	A 4	3	46-
VAR075	A 4	3	49
VAR076	A 4	3	50-
VAR077	A 4	3	54-
VAR078	A 2	3	57
VAR079	A 2	3	58-
VAR080	A 2	3	61
VAR081	A 2	3	62-
VAR082	A 1	3	63
VAR083	A 1	3	64-
VAR084	A 1	3	65
VAR085	F 1	3	66-
VAR086	F 2	3	67
VAR087	F 2	3	68
VAR088	A 1	3	69
VAR089	A 1	3	70-
VAR090	A 2	3	71
			72-
			73
			74-
			75
			76-
			77
			78-
			79
			80

THE INPUT FORMAT PROVIDES FOR 90 VARIABLES. 90 WILL BE READ
IT PROVIDES FOR 3 RECORDS ('CARDS') PER CASE. A MAXIMUM OF 80 'COLUMNS' ARE USED ON A RECORD.

COMMENT

UNE - PROGRAM TO CALCULATE PERCENT EXPECTED BATTERY
LIFE USED AT THE TIME A BATTERY WAS REPLACED.

COMMENT

VAR069 IS RBDT IN JULIAN DATE FORMAT - THE FOLLOWING CARDS CREATE
NEW VARIABLE VARBDT WHICH IS RBDT CONVERTED INTO DAYS
(VAR069 GT 0 AND VAR069 LE 365) VARBDT = VAR069
(VAR069 GE 1000 AND VAR069 LE 1365) VARBDT = (VAR069 - 1000) + 365
(VAR069 GE 2000 AND VAR069 LE 2365) VARBDT = (VAR069 - 2000) + 730
(VAR069 GE 3000 AND VAR069 LE 3365) VARBDT = (VAR069 - 3000) + 1095
THE FOLLOWING CARDS CREATE NEW VARIABLES VARUSE WHICH IS THE TIME
BATTERY HAS BEEN IN SERVICE IN JULIAN FORMAT AND VARDAY THE SAME
TIME CONVERTED INTO DAYS - VARBDT IS WORK DATE JULIAN EQUIVALENT
(VAR051 - VAR062) GE 360) VARBDT = (VAR051 - 1000) + 365
(VARUSE = VARBDT - VAR062)
(VARUSE GE 0 AND VARUSE LE 730) VARDAY = VARUSE
(VARUSE GE 999 AND VARUSE LE 1730) VARDAY = (VARUSE - 1000) + 365
(VARUSE GE 1999 AND VARUSE LE 2730) VARDAY = (VARUSE - 2000) + 730
(VAR051 - VAR062) GE 0 AND (VAR051 - VAR062) LT 365)
VARDAY = VAR051 - VAR062
VARPER IS NEW VARIABLE PERCENT OF EXPECTED BATTERY LIFE CONSUMED
AS OF THE WORK DATE BASED UPON RBDT - WHERE THE BATTERY WAS
REPLACED ON THE WORK DATE THE PERCENT INDICATES SURVIVAL
PERFORMANCE OF THE OLD BATTERY. VAR072 VALUES WERE RECODED
SO THAT BATTERIES REPLACED BECAUSE OF WITHDRAWALS FOR EXAMPLE,
WOULD BE INCLUDED.
VAR072 ('84W', '84X', '84S', '87W', '87X', '87S', '73W', '73X', '73S',

RECODE

01/15/75

```

IF      ('72PI'=7887)
(VAR071 NE 1 OR VAR072 EQ 7887) VARPER = RND((VARDAY/VARBOT)
*100)

RECODE  VAR071  ('42X','42TB','42T','42E','42C'='426)
('42M','42S'='421)('42O'='425)('42A'='423)
('42L','42G','42DY','42DX','81DZ','81DX'='422)
('81EC','42FU','42FC'='427)
('42C','42G','42K','42FS','42FP','42FI'='424)
('48J','48E','46C','46TB','46N'='466)
('46ZG','46W','46L','46G','46DZ','46DN'='462)
('45N'='461)('46U'='465)('46R'='468)('46VB'='469)
('45K','46F','46FI'='464)('46FW','46FD','46FC'='467)
('47M'='471)('47ZG','47F','47L','47G','47DZ','47DN'='472)
('47K','47FK','47FI'='474)('47U'='475)('47R'='478)
('47TB','47N','47J','47E','47C'='477)
('47V8'='479)
('50M'='501)('50W','50L','50J','50DZ'='502)
('50K','50FR'='504)('50O'='505)('50FU','50FC'='507)
('50Y','50TB','50N','50J','50E'='506)
('50R'='50A)
('51L','51W','51G','51DZ','51DN'='512)
('51K','51FR'='514)('51Y','51B','51J','51E','51C'='516)
('51FL'='517)('51R'='518)
('51P','51PE','51VB','51VA','51H'='519)
('49W','49D','49FU','49FL','45FD','45FC'='777)
('45FI','45EP','45ER','45FS'='774)
('64M'='771)('64W'='772)
VAR059,VAR060,VAR081 TO VAR083,VAR087 TO VAR089( ' ')/
VAR079,VAR080,VAR081,VAR083( ' ')/
VAR065,VAR067,VAR071 TO VAR077( ' ')/
VAR033,VAR034,VAR037 TO VAR047,VAR055,VAR061,VAR064,
VAR066,VAR068,VAR069,VAR084 TO VAR086,VARPER(0)
VAR001,LIGHT LIST NUMBER/
VAR002,OPERATION/
VAR003,LOCALITY/
VAR004,BODY SIZE/
VAR005,CONSTRUCTION/PER POCKET/
VAR006,VENT VALVES PER POCKET/
VAR007,LIGHT CHARACTERISTIC/
VAR008,LIGHT COLOR/
VAR009,LAMP TYPE/
VAR010,LANTERN-OPTIC/
VAR011,AVAILABLE SPARE CODE/
VAR012,PUMP SOURCE-BATTERY/
VAR013,BATTERY REUSE CODE/
VAR014,LAMPCHANGER/
VAR015,FLASHER/
VAR016,SOUND SIGNAL/
VAR017,DAYLIGHT CONTROL/
VAR018,BOTTOM DESCRIPTION/
VAR019,BOTTOM CHARACTERISTIC/
VAR020,DEPTH OF WATER IN FEET/

```


VAR021, BRIDLE SIZE/ AND NUMBER/
 VAR022, SWIVEL SIZE/
 VAR023, FIRST CHAIN LENGTH IN FATHOMS/
 VAR024, FIRST CHAIN SIZE/
 VAR025, SECOND CHAIN LENGTH/
 VAR026, SECOND CHAIN SIZE/
 VAR027, NUMBER OF SINKERS/
 VAR028, TOTAL SINKER WEIGHT-T-RIPRAP DIST./
 VAR029, AID CONTROL NUMBER/
 VAR030, TOTAL NUMBER OF VISITS 1972-1973/
 VAR031, WORK REASON/
 VAR032, INITIAL CONDITION OF AID/
 VAR033, INITIAL CONDITION OF AID/
 VAR034, INITIAL CONDITION OF AID/
 VAR035, DISTANCE 10'S YARDS OFF STATION/
 VAR036, WORK PERFORMANCE/
 VAR037, WORK PERFORMANCE/
 VAR038, WORK PERFORMANCE/
 VAR039, WORK PERFORMANCE/
 VAR040, WORK PERFORMANCE/
 VAR041, WORK PERFORMANCE/
 VAR042, WORK PERFORMANCE/
 VAR043, WORK PERFORMANCE/
 VAR044, WORK PERFORMANCE/
 VAR045, WORK PERFORMANCE/
 VAR046, WORK PERFORMANCE/
 VAR047, TIME SPENT AT SITE-TENTHS HOURS/
 VAR048, TOTAL NO. OF DISCREPANCIES OF AID/
 VAR049, JULIAN DATE OF INFERRED DISCREP/
 VAR050, HOUR CO. INFERRED OF DISCREPANCY/
 VAR051, J. DATE WORK PERFORMED-OR 3365END/
 VAR052, HOUR WORK PERFORMED/
 VAR053, DAYS INITIAL NO. IN NEXT VISIT/
 VAR054, FINAL CONDITION OF AID/
 VAR055, FINAL CONDITION OF AID/
 VAR056, FINAL CONDITION OF AID/
 VAR057, CLOSED CIRCUIT VOLT NEW BATTERY/
 VAR058, CLOSED CIRCUIT VOLT OLD-EXISTING BATTERY/
 VAR059, UNIT WORK PERFORMED BY/
 VAR060, PRIMARY REASON OF POSITIONING/
 VAR061, PRIMARY CAUSE OF FAILURE-SANDS/
 VAR062, JULIAN DATE LAST RECHARGED/
 VAR063, EXTRA CODE/
 VAR064, SCHEDULED SERVICE DATE/
 VAR065, DAYS SERVICE IN VARIANCE SCHED/
 VAR066, SCHEDULED RELIEF WITHURAL DATE/
 VAR067, DAYS RELIEF VARIANCE SCHED/
 VAR068, SCHEDULED RECHARGE DATE/
 VAR069, RATED BATTERY DISCHARGE TIME/
 VAR070, NO. BURNED OUT LAMPS REPLACED/
 VAR071, POWER UNIT'S REPLACED WITH REASON/
 VAR072, BUOY RELIEVED WITH REASON/
 VAR073, FLASHER REPLACED WITH REASON/
 VAR074, LAMPCHANGER REPLACED WITH REASON/

VAR056 (00)NORMAL (01)LIGHT EXTENSCHD-DIM (02)IMPROPER LT CHAR (03)SOUND SIG DISCRP (04)RADIOEAC DISCRP (05)OFF STATION (6)AGROUND (07)SINKING (10)DAMAGED (11)DESTROYED (12)MISSING (54)SOUND DEV NOTING EFFECT (55)BUOY BADLY DETERIATED (69)POCKET COVER MSG (08)POCKET FLOODED (90)LANTR FLOODED (91)BAD WIRING (93)LT FLS DAYLIGHT (94)XLT HUKAWN (95)SUNK (96)ADRIFT (97)POCKET COVER MISSING (98)LAMPCHGR KONT ROTATE (99)JTHLN/ (00)OTHER/

VAR059 (01)PIPIKARYE (S) SECONDARY (N) OTHER/

VAR060 (S)SEXTANT ANGLES (V)VISUAL BEARINGS (R)RADAR

VAR061 (00)NORMAL (01)UMITTED-DISCR (02)COLCID 452-04DMGS (03)FALSE ALARM (22)BATTERY FAILURE (23)TARDY SERVICE (24)PERS ERROR (26)FLOODED (27)CAUGHT DOWN (28)WEATHER (29)ICE (30)COLLISION (31)VANDALISM (33)UNKNOWN (45)LAMPS (51)LANTRN (52)SOUND SIGNAL (53)TAPPERS (58)WIRING (59)SHACKLE (60)BRIDLE (61)FIRST CHAIN (62)SECOND CHAIN (63)SINKER/

VAR071 (42)ROUTINE SERVICING (422)ENVRNMTL HAZARDS (423)TECH-ADMIN ERRORS (424)PERSONNEL ERRORS (425)CAUSED BY OTHER CMPNT (426)CONVENIENCE-FULLOHP (427)MANUFACTURING ERRORS (428)CORROSION (429)PROJECTS-EXPERIMNTL/

VAR073 (461)ROUTINE SERVICING (462)ENVRNMTL HAZARDS (463)TECH-ADMIN ERRORS (464)PERSONNEL ERRORS (465)CAUSED BY OTHER CMPNT (466)CONVENIENCE-FULLOHP (467)MANUFACTURING ERRORS (468)CORROSION (469)PROJECTS-EXPERIMNTL/

VAR074 (471)ROUTINE SERVICING (472)ENVRNMTL HAZARDS (473)TECH-ADMIN ERRORS (474)PERSONNEL ERRORS (475)CAUSED BY OTHER CMPNT (476)CONVENIENCE-FULLOHP (477)MANUFACTURING ERRORS (478)CORROSION (479)PROJECTS-EXPERIMNTL/

VAR075 (501)ROUTINE SERVICING (502)ENVRNMTL HAZARDS (503)TECH-ADMIN ERRORS (504)PERSONNEL ERRORS (505)CAUSED BY OTHER CMPNT (506)CONVENIENCE-FULLOHP (507)MANUFACTURING ERRORS (508)CORROSION (509)PROJECTS-EXPERIMNTL (791)ROUTINE SERVICING (792)ENVRNMTL HAZARDS (793)TECH-ADMIN ERRORS (794)PERSONNEL ERRORS (795)CAUSED BY OTHER CMPNT (796)CONVENIENCE-FULLOHP (797)MANUFACTURING ERRORS (798)CORROSION (799)PROJECTS-EXPERIMNTL (801)ROUTINE SERVICING (802)ENVRNMTL HAZARDS (803)TECH-ADMIN ERRORS (804)CONVENIENCE-FULLOHP ERRORS (805)CORROSION (809)PROJECTS-EXPERIMNTL/

VAR076 (511)ROUTINE SERVICING (512)ENVRNMTL HAZARDS (513)TECH-ADMIN ERRORS (514)PERSONNEL ERRORS (515)CAUSED BY OTHER CMPNT (516)CONVENIENCE-FULLOHP (517)MANUFACTURING ERRORS (518)CORROSION (519)PROJECTS-EXPERIMNTL (751)ROUTINE SERVICING (752)ENVRNMTL HAZARDS (753)TECH-ADMIN ERRORS (754)PERSONNEL ERRORS (755)CAUSED BY OTHER CMPNT (756)CONVENIENCE-FULLOHP (757)MANUFACTURING ERRORS (758)CORROSION (759)PROJECTS-EXPERIMNTL (520)UPORD 152-72 (5100)UPORD 06 7-71/

VAR077 (771)PRVNT MAINTENANCE (772)WX-WIND-STURM (774)LAMP-PLRS ERR DFC (777)LAMP-MNG ERRORS/

VAR078 (00)NONE (01)UMITTED-DISCY (03)FALSE ALARM (22)POWER-BATTERY (43)TARDY SERVICE (24)PERSONNEL ERROR (25)WRN-HKN MARKINGS (26)FL OODES (27)CAUGHT DOWN (28)WEATHER (29)ICE (30)COLLISION (31)VANDALISM (33)UNKNOWN (45)ALL LAMPS (46)FLASHER (47)LAMPCHGR (50)DAYLIGHT CO NTROL (51)LANTRN (52)SOUND SIGNAL (53)TAPPERS (58)WIRING (59)SHACKLE (60)BRIDLE (61)FIRST CHAIN (62)SECOND CHAIN (63)SINKER (67)MURKINS

(69)BUOY DETICATION(70)MOURINGS RPLD PVCS(72)POCK CQV MSG(73)PE
RSNL BELVO PM REQ(81)CCRN WX,V02,UKN,PE(84)12ND CUNSCV DISCY(85)3R
D + CUNSCV DISCY(88)SWIVEL(92)VEE BAND/
VAR079(CO)NONE (01) OMITTED-DISCY(U3)FALSE ALARM(22)POWER-BATTE
RY(23)TARDY SERVICE(24)PERSSUNNEL ERROR(25)TURN-BKN MOORINGS(26)FL
CQVED(27)CAUGHT DOWN(28)WEATHER(29)ICE(30)COLLISION(31)VANDALISM
(33)UNKNOWN(45)ALL LAMPS(46)FLASHER(47)LAMPCHANGER(53)DAYLIGHT CO
NTRUL(54)LANTRN(52)SOUND SIGNAL(53)TAPPER(58)WIKING(59)SHACKLE
(60)BRIDLE(61)FIRST CAHIN(62)SECOND CHAIN(63)SINKER(67)MOORINGS
(69)BUOY DETICATION(70)MOURINGS RPLD PVCS(72)POCK CQV MSG(73)PE
RSNL BELVO PM REQ(81)CCRN WX,V02,UKN,PE(84)12ND CUNSCV DISCY(85)3R
D + CUNSCV DISCY(88)SWIVEL(92)VEE BAND/
VAR002,VAR003,VAR008,VAR011 TO VAR013,VAR018 TO VAR020,VAR031,
VAR035,VAR059,VAR060,VAR063,VAR067,VAR078 TO VAR083,
VAR087 TO VAR090 (A)/VAR01 (2)/VAR004 TO VAR007,VAR009,VAR010,
VAR014 TO VAR017,VAR021 TO VAR030,VAR032 TO VAR034,VAR066 (1)
VAR036 TO VAR046,VAR048 TO VAR056,VAR061 TO VAR064,VAR066 (1)
VAR069 TO VAR077,VAR084 TO VAR086 (10)/VAR047,VAR057,VAR058 (1)
(VAR071 GE 421 AND VAR071 LE 425)
VAR071
4

PRINT FORMAT

*SELECT IF
CODEBOOK
OPTIONS

COMMENT

REASONS FOR REPLACEMENTS CAN BE REGROUPED INTO THE FOLLOWING CATEGORIES:

- 1. CODES S,M : ROUTINE SERVICING, PREVENT MAINTENANCE.
- 2. CODES DN,DX,DY,DZ : HAZARDS OF WATER DAMAGE, MISSING AIDS.
- 3. CODES G,I,L,W,ZF : ICE, COLLISION, WEATHER, AND VANDALISM.
- 4. CODES A,FI,FP,FR : TECHNICAL OR ADMINISTRATIVE ERRORS.
- 5. CODES FS,K,CN,QE : PERSONNEL ERRORS IN INSTALLATION.
- 6. CODES B,J : SCHEDULING, REPAIRS, OR TARDY SERVICING.
- 7. CODES C,E,J,N,T : FAILURES CAUSED BY ANOTHER COMPONENT.
- 8. CODES TB,TH,TO,U : SUCH AS SOUND DEVICE, LANTERN DEFECTS.
- 9. CODE P-,V-,H : CONVENIENT OR CONJUNCTIVE SERVICING.

READ INPUT DATA

***** GIVEN SPACE ALLOWS FOR 1 VARIABLES AND 1498 VALUES FOR CODEBOOK *****

*SELECT IF
CROSSTABS

(VAR071 EQ 422 OR VAR071 EQ 424 OR VAR071 EQ 427)
VAR071 BY VAR007,VAR003,VAR004,VAR006,VAR012,VAR014 TO VAR018,
VAR021 TO VAR023,VAR069

COMMENT

* NON-STANDARD FLASHER ** FL 2.5 (0.5) AND FL 6.0 (1.0)
FLASHERS WERE TO BE PERMANENTLY REPLACED BY FL 2.5 (0.3) AND
FL 6.0 (0.6) FLASHERS, RESPECTIVELY COMMENCING IN 1973

COMMENT

ON OUTPUT PAGE 26, RATED BATTERY DISCHARGE TIME IS IN JULIAN
FORMAT. FOR EXAMPLE, 2152 REPRESENTS 2 YEARS AND 152 DAYS OR
882 DAYS.

***** GIVEN SPACE ALLOWS FOR 3749 CELLS AND 2 DIMENSIONS FOR CROSSTABS *****

MARGINALS
STATISTICS

VARPER
ALL

COMMENT

SEE PROGRAM PAGE 3 FOR EXPLANATION OF THE PROCEDURE INVOLVED
IN DETERMINING PERCENT EXPECTED POWER UNIT LIFE USED AT THE
TIME OF REPLACEMENT.

01/15/75

PAGE 32

***** GIVEN SPACE ALLOWS FOR 1 VARIABLES AND 2999 VALUES FOR MARGINALS *****

*RECODE

VARPER (1 THRU 20=10)(21 THRU 40=30)(41 THRU 60=50)
 (61 THRU 70=60)(71 THRU 80=75)(81 THRU 90=85)
 (91 THRU 100=90)(101 THRU 110=105)(111 THRU 121=115)
 (122 THRU HIGHEST=150)
 VAR003,VAR004,VAR006,VAR007,VAR012,VAR014 TO VAR018,VAR021 TO
 VAR023,VAR069,VAR071 BY VARPER

CROSSTABS

CCOEBOOK,MARGINALS,CROSSTABULATIONS AFTER BREAKDOWN RECODING

01/15/75

PAGE 51

***** GIVEN SPACE ALLOWS FOR 3749 CELLS AND 2 DIMENSIONS FOR CROSSTABS *****

*SELECT IF
 CCOEBOOK
 OPTIONS

(VAR073 GE 461 AND VAR073 LE 469)
 4

CCOEBOOK,MARGINALS,CROSSTABULATIONS AFTER BREAKDOWN RECODING

01/15/75

PAGE 54

***** GIVEN SPACE ALLOWS FOR 1 VARIABLES AND 1498 VALUES FOR CODEBOOK *****

*SELECT IF
 CROSSTABS

(VAR073 EQ 462 OR VAR073 EQ 464 OR VAR073 EQ 467)
 VAR073 BY VAR004,VAR010,VAR014 TO VAR016

CCOEBOOK,MARGINALS,CROSSTABULATIONS AFTER BREAKDOWN RECODING

01/15/75

PAGE 61

***** GIVEN SPACE ALLOWS FOR 3749 CELLS AND 2 DIMENSIONS FOR CROSSTABS *****

*SELECT IF
 CCOEBOOK
 OPTIONS

(VAR074 GE 471 AND VAR074 LE 479)
 4

CODEBOOK,MARGINALS,CROSSTABULATIONS AFTER BREAKDOWN RECODING

PAGE 64

01/15/75

***** GIVEN SPACE ALLOWS FOR 1 VARIABLES AND 1498 VALUES FOR CODEBOOK *****

*SELECT IF
CROSSTABS
(VAR074 EQ 472 OR VAR074 EQ 474 OR VAR074 EQ 477)
VAR074 BY VAR009,VAR016

CODEBOOK,MARGINALS,CROSSTABULATIONS AFTER BREAKDOWN RECODING

PAGE 67

01/15/75

***** GIVEN SPACE ALLOWS FOR 3749 CELLS AND 2 DIMENSIONS FOR CROSSTABS *****

*SELECT IF
CODEBOOK
OPTIONS
(VAR075 GE 501 AND VAR075 LE 509)
VAR075
4

CODEBOOK,MARGINALS,CROSSTABULATIONS AFTER BREAKDOWN RECODING

PAGE 70

01/15/75

***** GIVEN SPACE ALLOWS FOR 1 VARIABLES AND 1498 VALUES FOR CODEBOOK *****

*SELECT IF
CROSSTABS
STATISTICS
(VAR075 EQ 502 OR VAR075 EQ 504 OR VAR075 EQ 507)
VAR075 BY VAR008,VAR010,VAR016
ALL

CODEBOOK,MARGINALS,CROSSTABULATIONS AFTER BREAKDOWN RECODING

PAGE 74

01/15/75

***** GIVEN SPACE ALLOWS FOR 3749 CELLS AND 2 DIMENSIONS FOR CROSSTABS *****

*SELECT IF
CODEBOOK
OPTIONS
(VAR076 GE 511 AND VAR076 LE 519)
VAR076
4

***** GIVEN SPACE ALLOWS FOR 1 VARIABLES AND 1498 VALUES FOR CODEBOOK *****

*SELECT IF
CROSSTABS
STATISTICS
(VAR076 EQ 512 OR VAR076 EQ 514 OR VAR076 EQ 517)
VAR076 BY VAR003,VAR010,VAR016
1

***** GIVEN SPACE ALLOWS FOR 3749 CELLS AND 2 DIMENSIONS FOR CROSSTABS *****

*SELECT IF
CROSSTABS
STATISTICS
(VAR077 EQ 774 OR VAR077 EQ 777)
VAR077 BY VAR003,VAR004,VAR009,VAR010,VAR016
1

***** GIVEN SPACE ALLOWS FOR 3749 CELLS AND 2 DIMENSIONS FOR CROSSTABS *****

*SELECT IF
CROSSTABS
(VAR077 EQ 771 OR VAR077 EQ 772)
VAR077 BY VAR003/VAR077 BY VAR018

***** GIVEN SPACE ALLOWS FOR 3749 CELLS AND 2 DIMENSIONS FOR CROSSTABS *****

FINISH

BIBLIOGRAPHY

- Aids to Navigation Division, Office of Marine Environment & Systems, U.S. Coast Guard, Light List Volume III, Pacific Coast and Pacific Islands, 9 December 1972.
- Aids to Navigation Division, Office of Marine Environment & Systems, U.S. Coast Guard, Aids to Navigation Manual, Book One, "Administration" (CG-222-1), 17 May 1972.
- Aids to Navigation Division, Office of Marine Environment & Systems, U.S. Coast Guard, Aids to Navigation Manual, Book Two, "Seamanship" (CG-222-2), 12 June 1973.
- Aids to Navigation Division, Office of Marine Environment & Systems, U.S. Coast Guard, Appendix D to Aids to Navigation Manual (CG-222), "SANDS Manual" revised 26 September 1969.
- Aids to Navigation Division, Office of Marine Environment & Systems, U.S. Coast Guard, Aids to Navigation Bulletin, (April-June 1970), (July-September 1970), (October-December 1970), (January-March 1971), (April-September 1971), (October 1971-March 1972), (April-November 1972), (December 1972-April 1973), (May-December 1973).
- Aids to Navigation School, U.S. Coast Guard Training Center, Governors Island, N.Y., A Buoy Tender Manual, April 1971.
- Aids to Navigation School, U.S. Coast Guard Training Center, Governors Island, N.Y., Minor Light Servicing Handbook, May 1971.
- Barlow, Richard E. and Proscher, Frank, Statistical Theory of Reliability and Life Testing, Volume: I: Probability Models, Florida State University, April 1973.
- Bierman, Harold, Jr., Bonini, Charles P., and Hausman, Warren H., Quantitative Analysis for Business Decisions, p. 172-195, Richard D. Irwin, Inc., 1973.
- Booz, Allen Applied Research, Inc., Evaluation of Plastic versus Steel for Buoy Hulls, Contract Number DOT-CG-90506-A, 7 January 1970.
- Booz, Allen Applied Research, Inc., Evaluation of Minor Marine Structures versus Buoys, Contract Number DOT-CG-90506-A, 15 May 1970.

- Booz, Allen Applied Research, Inc., Servicing System for Short-Range-Aids to Navigation, Contract Number DOT-CG-90506-A, 7 November 1970.
- Castler, R., Kissinger, J., and Pokress, R., Development of an Optimal Inventory System for Selected Aids to Navigation Components of the United States Coast Guard Supply System, M.S. Thesis, George Washington University, July 1974.
- Chapman, Charles F., Piloting Seamanship and Small Boat Handling, The Hearst Corporation, 1961.
- Civil Engineering Division, Office of Engineering, U.S. Coast Guard, Purchase Description No. 195A, "12 Volt, Six-Place Lampchanger for Maritime Aids to Navigation," April 1971.
- Civil Engineering Division, Office of Engineering, U.S. Coast Guard, Purchase Description No. 181B, "12 Volt, Solid-State, Flasher for Maritime Aids to Navigation," 13 May 1968.
- Committee on the Judiciary of the House of Representatives, United States Code, 1970 Edition Supplement III, 21 January 1971 to 20 January 1974, Volume One, U.S. Government Printing Office 1974.
- Encyclopedia Americana, Volume 17, p. 506, Grolier Enterprises 1969.
- Fisher, Gene H., Cost Considerations in Systems Analysis, American Elsevier Publishing Company, Inc., 1971.
- Goodwin, M.J., "Lighted Buoy Design - Progress for the Future," Coast Guard Engineer's Digest (CG-133), Number 176, p. 26-33, (July-August-September 1972).
- Howard, Ronald A., Decision Analysis in Systems Engineering, paper presented at the "Systems Concepts for the Private and Public Sectors" Seminar Series at the California Institute of Technology, 13 April 1971.
- Lapin, Lawrence L., Statistics for Modern Business Decisions, Harcourt Brace Jovanovich, Inc., 1973.
- Learmouth, G.P., Statistical Resources of the W. R. Church Computer Center, Monterey, California: W. R. Church Computer Center, Naval Postgraduate School, March 1974.

Martin, E. W. Jr., and Perkins, William C., Computers and Information Systems, an Introduction, Richard D. Irwin, Inc., and The Dorsey Press, 1973.

National Archives and Records Service, Code of Federal Regulations, Title 33, Navigation and Navigable Waters Parts 1-199, Chapter 1, "Coast Guard, Department of Transportation," U.S. Government Printing Office, revised, 1 July 1974.

Nie, Norman H., Bent, Dale H., and Hull, C. Hadlai, Statistical Package for the Social Sciences, McGraw-Hill Book Company, 1970.

Ocean Engineering Division, Office of Engineering, U.S. Coast Guard, Purchase Description No. 243, "Marine Signal Lamps," April 1973.

Ocean Engineering Division, Office of Engineering, U.S. Coast Guard, Purchase Description No. 234, "CG-234 Daylight Controls for Solid-State Flashers," February 1973.

Ocean Engineering Division, Office of Engineering, U.S. Coast Guard, Purchase Description No. 205B, "Buoy Lantern for Maritime Aids to Navigation," March 1972.

Ocean Engineering Division, Office of Engineering, U.S. Coast Guard, Purchase Description No. 191A, "Primary Batteries for Aids to Navigation," 14 February 1974.

Ocean Engineering Division, Office of Engineering, U.S. Coast Guard, Ocean Engineering Report No. 37, "Visual Signalling: 22 June 1970.

Ocean Engineering Division, Office of Engineering, U.S. Coast Guard, Ocean Engineering Report No. 38B, "Buoy Classification and Description," 9 September 1969.

Ocean Engineering Division, Office of Engineering, U.S. Coast Guard, Ocean Engineering Report No. 40, "Minor Aids to Navigation Systems Handbook," 21 November 1969.

Ocean Engineering Division, Office of Engineering, U.S. Coast Guard, Commandant Instruction 10500.32A, "Primary Batteries for Aids to Navigation," 1 August 1973.

Raiffa, Howard, Decision Analysis: Introductory Lectures on Choices Under Uncertainty, Addison-Wesley, 1970.

Singer, Neil M., Public Microeconomics, Little, Brown and Company, 1972.

INITIAL DISTRIBUTION LIST

	No. of Copies
Defense Documentation Center Cameron Station Alexandria, Virginia	2
Library, Code 0212 Naval Postgraduate School Monterey, California 93940	2
Department Chairman Department of Operations Research and Administrative Sciences Naval Postgraduate School Monterey, California 93940	2
Asst. Prof. W. C. Giaugue, Code 55Gi Department of Operations Research and Administrative Sciences Naval Postgraduate School Monterey, California 93940	1
LCDR Robert M. Stephan, Jr., USCG U.S. Coast Guard Supply Center 31st Street and 3rd Avenue Brooklyn, N.Y. 11232	1
Commandant (G-WAN) U.S. Coast Guard 400 Seventh Street Washington, D.C. 20590	2
Commandant (G-PTP-1/72) U.S. Coast Guard 400 Seventh Street Washington, D.C. 20590	2
Commandant (G-EOE-3/61) U.S. Coast Guard 400 Sevent Street Washington, D.C. 20590	1
Commandant (G-C/SC/84) U.S. Coast Guard 400 Seventh Street Washington, D.C. 20590	1

Commanding Officer 1
U.S. Coast Guard Training Center
Aids to Navigation School
Governors Island
New York, N.Y. 10004

Commander (oan) 1
Ninth Coast Guard District
1240 East 9th Street
Cleveland, Ohio 44199

Commander (oan) 1
Thirteenth Coast Guard District
618 2nd Avenue
Seattle, Washington 98104

9 DEC 77

24656

Thesis 160844
S6919 Stephan
c.1 Development of a
modified Aids to
Navigation Management
Information System for
the United States Coast
Guard with an illustra-
ted application through
cost-effectiveness and
malfunction analyses...

9 DEC 77

24656

Thesis 160844
S6919 Stephan
c.1 Development of a
modified Aids to
Navigation Management
Information System for
the United States Coast
Guard with an illustra-
ted application through
cost-effectiveness and
malfunction analyses.

thesS6919

Development of a modified Aids to Naviga



3 2768 002 02263 4

DUDLEY KNOX LIBRARY